

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHD 5483R - AXA**Candy***Not Authorised*
11 Sep 81000

Vehicle No.:

SHD 5483R - Candy

Chassis No.:

JTDGJ20W505002423

Vehicle Make:

TOYOTA

Vehicle Model:

WISH 2.0 BI-FUEL

Date of Accident :

18.06.16

Third Party Insurer :

AXA

		PART		LIST
1	1	Rear fender LH	\$	<i>R</i> 1,216.32 <i>X</i>
2	1	Rear fender inner cowling LH	\$	<i>Sn</i> 278.52 <i>X</i>
3	1	Tail lamp LH	\$	<i>Sn</i> 595.72 <i>X</i>
4	1	Tailgate reflector LH	\$	<i>Sn</i> 128.40 <i>X</i>
5	1	Rear bumper	\$	<i>Bu</i> 585.36 <i>✓</i>
6	1	Rear bumper side retainer LH	\$	<i>D.I</i> 68.76 <i>✓</i>
7	1	Rear bumper reflectors LH	\$	<i>Sn</i> 66.00 <i>X</i>
8	1	Rear bumper stay LH	\$	<i>Sn</i> 82.08 <i>X</i>

TOTAL \$ 3,021.1625% \$ 755.29\$ 2,265.87**Special Nett**

1	1 Set	Rear Bumper Fastener Clip	\$	<i>Ru</i> 30.00 <i>✓</i>
2	1 Set	Rear Bumper Parking Sensor	\$	<i>Sn</i> 300.00 <i>X</i>
3	1	CNG Sticker	\$	<i>Ru</i> 30.00 <i>15Sn</i>
4	1 Set	Rear fender Liner clip	\$	<i>Ru</i> 30.00 <i>X</i>
5	1	Tyre RR LH	\$	<i>Sn</i> 180.00 <i>X</i>
6	1	Tyre Rim RR LH	\$	<i>Sn</i> 120.00 <i>X</i>

TOTAL \$ 690.00TOTAL PARTS \$ 2,955.87

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,800.00 *3000*

Putty And Spray Painting Of The Affected
Portion.

\$ 2,700.00 *4000*

TRANS-CAB AUTO SERVICES PTE LTD**Candy**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CQ/GST REG NO.201019626G

SHD 5483R - AXA

To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	120.00 <i>15/</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Remove And Refit Rear 1/4 Glass And To Facilitate Bodywork Repair.	\$	<i>nn</i> 380.00 <i>X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>
	\$	6,510.00
TOTAL	\$	9,465.87

REPAIR DAYS**10 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: