

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number :	PA 6619G	Date :	23.06.2016
Vehicle Model :	TOYOTA HIACE	Chassis :	KDH2010176942
Accident Date :	14.06.2016	TP Ins.	CHINA
Original Reg Date :	02.11.2015		

SUPPLEMENTARY

Special Nett

3 pcs	Rear Seats (Last Roll)	800.00	2,400.00
-------	------------------------	--------	----------

bt. 1pc 600?

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : PA 6619G
Vehicle Model : TOYOTA HIACE
Accident Date : 14.06.2016
Original Reg Date : 02.11.2015

Date : 23.06.2016
Chassis : KDH2010176942
TP Ins. CHINA

ESTIMATE

1	1 pc	Tailgate	hrt ✓	1,650.90
2	1 pc	Tailgate Badge	hrt ✓	62.00
3	1 pc	Tailgate Sticker HIACE	hrt ✓	56.00
4	1 pc	Tailgate Windscreen Inner Seal	hrt ✓	450 50.00
5	1 pc	Tailgate Inner Lock	hrt ✓	461.60
6	1 pc	Tailgate Auto Lock Actuator	?	456.20
7	1 pc	Tailgate Lock Mechanism	hrt x	235.10
8	1 pc	Tailgate Lock Catch	R. x	42.00
9	1 pc	Tailgate Weatherstrip	hrt ✓	381.90
10	1 pc	Tailgate Side Stopper (Male) LH	hrt x	36.00
11	1 pc	Tailgate Side Stopper (Female) LH	hrt x	39.00
12	2 pcs	Tailgate Side Rubber	hrt 32.00 ✓	64.00
13	2 pcs	Taillamps	org 297.20 ✓	594.40
14	2 pcs	Taillamps Inner Sealer	30.00 ?	60.00
15	2 set	Taillamps Clips	25.00 x	50.00
16	1 pc	Rear Corner Garnish LH	hrt ✓	161.00
17	1 set	Rear Corner Garnish Retainers LH	hrt ✓	30.00
18	1 pc	Rear Bumper	hrt ✓	423.50
19	1 pc	Rear Bumper Step Panel	?	319.60
20	2 pcs	Rear Bumper Side Retainers	hrt 69.20 ✓	138.40
21	4 pcs	Rear Bumper Stay	hrt 2pc 18.00	72.00 36
22	1 set	Rear Bumper Clips	hrt ✓	50.00 40
23	1 pc	End Panel (Inner)	?	994.80
24	1 pc	End Panel (Outer)	?	426.50
25	1 pc	End Panel Top Plate	hrt ✓	172.00
26	1 pc	Spare Tyre Carrier	?	223.60
27	1 pc	Spare Tyre Carrier Bolt	?	58.20
28	1 pc	Spare Tyre Carrier Nut	?	69.50
29	1 pc	Rear Side Panel LH	hrt ✓	1,892.50
30	1 pc	Rear Side Panel Glass Inner Seal LH	hrt ✓	46 50.00

9,320.70

Less 25% 2,330.18

6,990.53

C/F 6,990.53

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : PA 6619G

B/F

6,990.53

Special Nett

1	1 pc	Tailgate Sticker 70km/h	NA	✓	15.00
2	1 pc	Tailgate Sticker EMERGENCY DOOR	NA	✓	25.00
3	1 pc	Rear Windscreen Sealant	NA	✓	60.00
4	1 pc	Side Glass Sealant	NA	✓	60.00
5	1 set	Body Panel Joint Sealer	NA	✓	120.00

80

Labour charge

Panel Beating		1,600.00
Spray painting		1,400.00
Check Wiring		50.00
Anti rust		100.00
Remove and install rear winscreen.		140.00
Remove and install rear side panel glass.		140.00
Remove and install tailgate parts.		90.00
Remove and install carpet and seat.		150.00
Remove and install reverse camera.		150.00

\$ 11,090.53

Not Authorized
MSD Regur
ATA - PATA Photo
23/6/2016 @ 14:52
Let Auto WA
8- wday 8