

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vale Oh

Date: 01 Jul 2016

Preliminary Advice

Insured Vehicle No : SHF665E

TP Vehicle No : SJG7191E

Make : HONDA STREAM

Date of Inspection : 29/06/2016

Inspection At : EM-1 AUTO PTE LTD

Accident Date : 24/06/2016

Assignment Date : 28/06/2016

Est. Duration of Repair : 8 /Days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...Rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,430.16
Revised Amount	:S\$	7,848.72
Check Items (Estimated)	:S\$	1,293.84
Total	:S\$	9,142.56

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :We have not authorized repairs.