

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AXA Insurance (S) Pte Ltd

Third Party

Policy No: _____

02.07.2016

Date: _____

Accident Date : 28.06.2016

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Renault Megane" Reg. No. SJU1426U Claiming Against Your Insured Veh. No. XE463L			
1pc	Front Bumper <i>dis</i>		
10pcs	Front Bumper Clips <i>an</i>		
1pc	Front Bumper Bracket LH <i>dis</i>		
1pc	Front Bumper Reinforcement		
1pc	Front Bumper Center Air Grille <i>dis</i>		
1pc	Front Bumper Fog Lamp LH		
1pc	Front Bumper Fog Lamp Cover LH <i>dis</i>		
2pcs	Front Bumper Top Retainers <i>dis</i>		
1pc	Front Bumper Emblem <i>dis</i>		
2pcs	Front Bumper Corner Holders <i>dis</i>		
1pc	Front Bumper Cover LH <i>dis</i>		
1pc	Front Bumper Lower Cover LH <i>dis</i>		
2pcs	Grilles <i>1pc. NS mis.</i>		
1pc	Grille Holder LH		
1pc	Grille Garnish LH <i>mis</i>		
1pc	Headlamp Assy LH <i>an</i>		
1pc	Support Panel <i>dis</i>		
1pc	Air Con Condenser		
1pc	Radiator		
1pc	Front Fender LH <i>dis</i>		
1pc	Front Fender Shield <i>dis</i>		
10pcs	Front Fender Shield Clips <i>an</i>		
1pc	Front Wheel Rim LH <i>an</i>		
1pc	Front Shock Absorber		
1pc	Front Knuckle Arm		
1pc	Front Knuckle Arm Bearing		
1pc	Front Lower Arm		
1pc	Front Door Wing Mirror LH <i>an</i>		
1pc	Boot <i>an</i>		
1pc	Boot Center Emblem <i>an</i>		
1pc	Boot Badge "Megane" <i>an</i>		
1pc	Boot Lock <i>an</i>		
1pc	Boot Lock Catch <i>an</i>		
1pc	Boot Weatherstrip <i>dis</i>		
2pcs	Boot Hinges <i>an</i>		
2pcs	Boot Hinge Dampers		
2pcs	Boot Hinge Lift Motors		
2pcs	Boot Hinge Lift Motor Cables		
1pc	Boot Hinge Lift Motor Module		
		C/F	-

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AXA Insurance (S) Pte Ltd

Accident Date : 28.06.2016

Third Party

Policy No: _____

02.07.2016

Date: _____

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Renault Megane" Reg. No. SJU1426U Claiming Against Your Insured Veh. No. XE463L			
		B/F	-
1pc	✓ Boot Hinge Lift Motor Module Wire Harness <i>arc</i>		
1pc	✓ Boot Hinge Lift Motor Module ECU <i>arc</i>		-
2pcs	✓ Boot Hinge Brackets		
1pc	✓ Boot Lower Latch Sensor		
1pc	✓ Boot Trim Board		-
4pcs	✓ Boot Lower Stoppers <i>arc</i>		-
1pc	✓ Boot Outer Garnish <i>dis</i>		-
2pcs	✓ Taillamps Assy <i>arc</i>		-
2pcs	✓ Taillamp Gaskets		-
2pcs	✓ Taillamp Panels <i>arc</i>		-
2pcs	✓ Rear Joint Panels (Taillamp-fender)		-
2pcs	✓ Rear Number Plate Lamps <i>arc</i>		-
1pc	✓ Rear Bumper <i>dis</i>		-
10pcs	✓ Rear Bumper Clips <i>arc</i>		
1pc	✓ Rear Bumper Bracket <i>dis</i>		
1pc	✓ Rear Bumper Bracket Sponge <i>dis</i>		
1pc	✓ Rear Bumper Reinforcement <i>arc</i>		
1pc	✓ Rear Bumper Top Beam <i>dis</i>		
1pc	✓ Rear Bumper Top Center Cover <i>dis</i>		-
2pcs	✓ Rear Bumper Side Covers <i>dis</i>		
1pc	✓ Rear Bumper Tow Point Cover <i>dis</i>		-
2pcs	✓ Rear Bumper Top Retainers <i>dis</i>		-
2pcs	✓ Rear Bumper Corner Holders <i>dis</i>		-
1pc	✓ End Panel <i>arc</i>		-
2pcs	✓ End Panel Inner Side Locks		
1pc	✓ End Panel Garnish		
1pc	✓ End Panel Garnish Center Cover		
1pc	✓ End Panel Inner Panel		
1pc	✓ End Panel Center Boot Filt Hinge		
1pc	✓ End Panel Center Boot Filt Hinge Motor		
1pc	✓ Trunk Compartment Lamp		
1pc	✓ Rear Fender RH <i>arc</i>		-
2pcs	✓ Rear Fender Inner Trim Boards		-
		C/F	-

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AXA Insurance (S) Pte Ltd

Accident Date : 28.06.2016

Third Party
Policy No: _____
Date: 02.07.2016

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Renault Megane" Reg. No. SJU1426U Claiming Against Your Insured Veh. No. XE463L		
		B/F	-
1pc	Spare Tyre Panel		
1pc	Spare Tyre Top Board		
1pc	Spare Tyre Panel Insulation		
1pc	Rear Trunk Separator Shade		
1pc	Rear Windscreen Lower Drip Weatherstrip		
1pc	Front Number Plate		45.00 SN
1pc	Rear Number Plate		45.00 SN
1pc	Rear Bumper Reverse Sensor		280.00 SN
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		30.00
	To Remove / Refit Air Con Condenser & Refill Gas		160 120.00
	To Bleed Radiator System, Refill Coolant		20 45.00
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		X 250.00
	To Conduct Computerize Wheel Alignment Test		80.00
	To Provide Transportation (Towing) (Off Road)		110 160.00
	To Supply Rear Panel Joint Sealant		80.00
	To Dismantle / Transfer Rear Spare Tyre Panel Inner Trims Boards / Garnish and Rear Fenders Inner Trims Boards / Garnish to Facilitate Repair		80.00
	To Dismantle / Refit Fuel Tank Inlet Pipes, Hoses Etc		X 100.00
	To Conduct Rear Electrical Check, Replace Reverse Sensors, Module, Rewiring Etc		60 120.00
			1,435.00
		C/F	1,435.00

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AXA Insurance (S) Pte Ltd

Accident Date : 28.06.2016

Third Party
Policy No: _____
Date: 02.07.2016

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Renault Megane" Reg. No. SJU1426U Claiming Against Your Insured Veh. No. XE463L		
		B/F	1,435.00
	To Dismantle / Replace Trunk Lid Lift Motors, Hinges, Sensors, Module, Adjustment of Roof Panel For Fine Operation		500 600.00
	To Dismantle / Replace Trunk Lid ECU Reprogram / Adaptation		800.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		60 150.00
	To Mount Vehicle on Car "O" Liner Chassis Alignment Equipment/ Workbench for Chassis Alignment to Facilitate Repair		X 350.00
	Labour Charge - Panel Beating, Repairing Of Front Chassis Member, Fender Inner Panel, Rear Chassis Member Inner Panel, Floor Panel, Rear N/S Fender Etc. Cnt, Weld End Panel, Rear Fender, Spare Tyre Panel and Parts Replacement		2200 2,800.00
	To Respray Affected Areas		1700. 1,800.00
		Total :	<u>7,935.00</u>

Not Dethaw
48 Repairs
After paint, Under
Lack Anti Rust
4/7/2016
18 wday 8