

Zayyer (LKKAUTO)

From: Zayyer (LKKAUTO)
Sent: Tuesday, 26 September, 2017 3:32 PM
To: 'HQ TPT Safety Branch'; Hsiao Tong (LKKAUTO)
Cc: Merlin Koh
Subject: RE: Requesting to close IOD FY 16/17/0061 and no COR for MID 34651 & MID 34034

Hi Sir,

We duly noted the below email and will follow up the necessary action accordingly. thanks.

Best Regards,

Zayer | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841 2409, email: zayyer@lkkauto.com fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: HQ TPT Safety Branch [mailto:tptsafety@gmail.com]
Sent: Monday, 25 September, 2017 2:24 PM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Zayyer (LKKAUTO) <zayyer@lkkauto.com>
Cc: Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>; Merlin Koh <merlinkoh@gmail.com>
Subject: Re: Requesting to close IOD FY 16/17/0061 and no COR for MID 34651 & MID 34034

Good day Tong and Zayer,

Please reply to this email as soon as possible.

Thanks.

Regards

On Tue, Sep 12, 2017 at 10:48 AM, HQ TPT Safety Branch <tptsafety@gmail.com> wrote:

Good Day Tong,

We would like to close the case FY 16/17/0061:

1. MID 34708 was involved in an accident with civilian lorry (YL 7909) grazed a F550 Ambulance on 21st Jan 2017. There is no visible damage to the combat ambulance and the civilian vehicle drove off after the incident happened thus no particulars are obtained. If there is no 3rd party claim for this case in the month of September, please proceed to close the case.

The following 2 vehicles was involved in a past incident however it was not booked in to the workshop as there were no visible damage, as a result, there is no cost of repair. We would like you to help to proceed with the following cases.

1. MID 34034 was involved in an incident where the OUV reversed and scratched the front left door of a civilian van (PC 2721J). The vehicle was not booked in as there were no visible damage on the OUV.
FY 17/18/0007
2. MID 34651 was involved in an incident where the F550 ambulance reversed into a civilian van, GV 7813B on 4th May 2016. The F550 did not sustain any damage in the incident and thus was not booked into the workshop. As a result, there is no final cost of repair.
FY 16/17/0009

Please reply as soon as possible.

--

Best Regards,

1WO Rajah

HQ TPT Safety

Tel: 63074040

--

Best Regards,

REC Zhou Zhefang

HQ TPT Safety

Tel: 63074040