-17		71
9 189000	Janet 1 - 2 - 130412	2 Kipas / Inac
INS. CASE OWNER	L CC 3 /FOHCO 13/1/W	2 / K1905 / IDAC
	El a 1 Contraction of the Contra	
***************************************	- DOI: ASSIGNMENT	12.02.16
Surveyor:	DOE	Linic Tallic
B	A manual control of the control of t	Registered in Merimen:
Pre-assign / CCU		
Insured Vehicle No	PA 5439R	151 No. : PM1640 01485 JJT
7	Manay 70 mg & MARIL Pla	OmcCHD1C mall2
Name of Insured	Posterial feeding of activity 1 to be	oney 140.
Insured Tel No.		inke/Model: Toyro TA HACE
Excess Sec II :SS	D.O.A: 12.07-16 Ph	Ince of Accident: KNOSKON KOAO
Is driver the owner		
DRIVE SCHOOL STATE	All I goodly MIACL	2
If NO, Driver Nar	210-1	IGIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Driver Tel		sured Liability: % Final? Yes / No
SHB 3883 7		
INSRS:		INSRS: INSRS:
WSP: LOLG (T 7	WSP: WSP:
Tel : Liability :	11 14 D D	Tel: Tel:
RMKS:	[0 -b]	Liability: Liability: RMKS: RMKS:
0.000.00V	LIVING.	RMKS: RMKS:
Date/Time		
20/2/16	SAR 38837 X ; PA 54398 X	STAGE DATE / PIC
10/11	Mission I was historia. Ve	Non-Reporting ltr (1st):
CH1		Non-Reporting ltr (2nd): Non-Reporting ltr (Final):
, –	Habilty unclear to chort if any victor	Power (Notification ltr (if non-pickup):
12011 - 11 - 2	3	Call Of:
51716@1253pm	called OlD, Mr Chin He and not aware	Of the After call ltr to OI:
	collision	Documentation Check List: Handler Typist
	- Miled to get video from TP.	Notification ltr (if non-pickup)
	- NO CCTV from TV	After call ltr to Ol:
-	- NO COLV TOWN IT.	Authorisation To Act: Release Voucher:
18716 CHITD	n called OID, Mrchin He adament th	
	no collision betw both cars. The damage	
	his van ic pre-existing change.	Towing Invoice
	The said is a second of the said .	LTA/GIA:
18 8116 -	called Janut to discuss. She will their	
	Ol's procerde aduse	PIR:
24 8-18-@ 2-34bm		Mandate/Reject Instruction
614 ACTI. 130M	COLOC CAD. HP 6-49	LOD
16/14 @ 4. Tepan	COILED OID, HP 040.	Payment Breakdown Form:
LIMINARY ADVICE	Date/Time: Sent By:	Post-Repair Photos:
	DE DANGE	Others:
ALIZATION	Date/Time: Confirm with:	Confirm by:
air Cost;	SS (days) Reduction: %	Email Call
AL SETTLEMENT	Date/Time: Confirm with	Email Call
al Liability:	% (Agreed / Assessed) BOLA S/N No.	If NO or B 28, Ass. Lia:
eair Cost:	SS	
s of Rental (LOR):	SS (days)	
s of Use (LOU):	SS (\$ x days)	S AST US
s of Income (LOI):	SS (\$ x days)	X 3.9
R only LOU only LTA Search	LOR+LOU LOR+LOI [Tick only one]	V [V
dical:	S\$	1) Claim status: Normal/Rejoc/Private Settle
bursement	S\$ (e.g. Tow/ Independent.)	2) Report Format:
al Cost	SS (e.g. Tow/ Independent)	3) Survey fee: #4000
nl:	SS Global Sum SS:	III INC. V.
AL PAYMENT	Date/Time: Confirm with:	Email Call
oc 1:	S\$ Name I:	
ee 2: (Strike if N.A.)	SS Name 2	No.
vec 3: (Strike if N.A.)	SS Name 3	

(OBN1/f3) wef	REF:			
ASS. REC. BY:	REF			
Hann	. <u>AS</u>	SSIGNMENT		
From: Henry	Date	Veh No: SHB 388 3	3 T Yr Regn: 08/20	12
Estimated Cost		Type: M.Car / M.Cycle / Bus / Van		10
OD/TP/WS/TP RES/OD RES/EV	A / INV / MV	Truck / Trailer or		
To Inspect Vehicle No:	23.00.7.00		Benz 00 2184	_
at Workshop m/s		Colour	C: (insured / Std / NI / N	JA.
of			12 T/Radio: Insured / Std / NI / N	
Insured:		Eng/No:	C IMado misgred rate / Mili	MA.
Policy No.			0062A 65236	7
Claims No.		Gen. Cond /Good/ Fair / Poor / Bu		>
	-00000000	-		
South annexes	xcess:	Steering/norder / Jammed / Leak	CONTOCIDATO CONTOCIDAD	
(Client's Record) Make of Veh:		Brake: Inorder / Jammed / Leak		
make of yet.		Modi: Nil S/Rim / STD A/Rim		_
(Dallace Constitution)		Tyre Size: F: 205/6	00 KILL	(
(Policy Condition)	NIO 010	R:	1	
Remark: The veh had commenced its repair at the time of inspecti	7. (Sec.)	- DOT DOTATIONATION TO THE		
20 07 	1011	TOYO/YOKO OF we	stake	
Bal. or Market Value:	V. 1200 C	<u>Front</u>	Rear	
	sistent?: Yes or No	R/Bal. 4 mm	R/Bal. 5	nm.
CONTRACTOR OF THE PROPERTY OF	sistent? : Yes or No	L/Bal. 4 mm	L/Bal. 5 m	nm
	Res.: Yes or No	D.O.A. 12/7/16	D.O.I. 12/7/16	
Lum Sum; 20 %	3 Val.: Yes or No	Survey held at CDG	Elvyang	
CA / REV / REP. / 24 HRS		Des. of Damages : Frt / Rear / O/		
Date: Person Contacte	Vehicle: IN / OU			
Date / Time Action / Instruction	10.	The U/C / Chassis frame / Bo	dy Structure affected due to collision	on.
111. 0	vey photo up	los las		-
18/7/16 Finatized an	/ / / / / / / / / / / /	DOD with 2 work	a day with tay	21.
Sall Interpreted Co.	11 12 -1 100	VIV MAN S NOTHA	of day with tay	y
		(Ree As 10	189,9 1 4370	
			1 (9	
		7		
Date/Time, File Pass to? : Preli.	Report	Days Of Repair:	9	
t) : Final I	Report	Resurvey No. of Trip:	Survey Fee:	\neg
Date/Time, File Return to?			Transportation:	
2)	Add Fe	ee: Site Insp (\$)S+RSSI	
		: Interview (\$) Photos	
Report Format :		: Tech. Invs (\$) Others	
Lump Sum / I.B.I: (\$)	: Weekend (\$	3)	
			TOTAL	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

EO	INSURANCE COM	PANYITO	Ref : CC3/EQI1601:	3042/H1na3			
	INSUITAINEL COM	FAMI LID	nor . Gooleanoon	ou terripuo			
#17	AXWELL ROAD -00 TOWER BLOC D COMPLEXSING		Date: 14-07-2016				
			Code: EQI				
1.		Policy Partice	lars :- THIRD PARTY CLA	MI			
	Insured Veh.	PA 5439R	Veh. Inspected	SHB 3883T			
	Policy No.	DMCFHQ15-000113	Coverage (\$)	0.00			
	Claim No.	DM16HO01485/JT	Excess (\$)	0.00			
	Assign From		Assign Date	14/07/2016			
2.		Vehicle	Particulars & Condition				
	Make & Model		c.c	0			
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.		Colour				
	Odometer	*	Steering				
	Brakes		Modification				
	General						
3.		Co	onditions of Tyres				
		Size	Make	Balance			
	R/H Front Tyre			mm			
	L/H Front Tyre			mm			
	R/H Rear Tyre			mm			
	L/H Rear Tyre			mm			
4.		Desc	cription of Damages				
	1						
5.	1		eneral Information				
	Accident Date	12/07/2016	Inspection Date	12/07/2016			
	Survey held at		INEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969					
5a.			Remarks				

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

TBA

Our ref:

CC3/EQI16013042/H1pa3

Date:

15.07.2016

The Motor Claims Department

M/s EQ INSURANCE COMPANY LTD

Attn: Janet

Dear Janet,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB 3883T

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12.07.2016 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Loyang) and have the following to report:-

Workshop Estimate Amount	: S\$	4,639.92
Revised Estimate Amount	: S\$	3,290.64
"Check" Items Amount	: S\$	(*)
Market Value	: SS	7/2
LTA Reimbursement Value	: SS	()
Nett Value	: S\$	

Description of Damage: The vehicle sustained damages at the

O/S Front portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

HENRY NG

Licensed Appraiser

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6363 6280 Facsimilie +65 6280 9755

> > ga.moo.egbo,www

Company Registration No: 199508048W

Date Time of Fax: Our Ref

Workshop6

Braddell 205 Braddoll Road Singapore 579701

Loyang 59 Loyang Driva Singapore 508969

Sin kling 383 Sin Ming Drive Singapore 575717

Pandan 45 Pandan Road Singapore 609286

Ubl 320 Ubi Road 3 Singapore 406649

Banoko 24 Senoko Loop Singapore 758158

Sungel Kedut Sungel Kedut Way Singapore 728791

5 Datu Avenue 1 Singapore 539537

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

This is to inform you that our client has engaged us to repair the above vehicle and submit claims against your insured vehicle involved accident

Our MVA will call to arrange for the survey of this vehicle:-

Lim Kwok Eng

Tel: 6214 8316

Jumani Masudin

Tel: 6214 8315 Tel: 6214 8314

 Chiang Liat Choon Lim Tien Siong

Tel: 6214 8398

Larry Ng Nyuk Phin

Tel: 6214-8315

Fauzy Bin Mokhtan

Tel: 6214 8319

Our MVA shall be forwarding to you the entire necessary document for your follow up action.

Yours faithfully

for Vice President Crash Repairs & Claims Recovery







Text size +

100% 75% 25% 50%

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name E04

12 Jul 2016 / 08:00:00 Successful

EQ INSURANCE COMPANY LTD

OK Previous

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution.

Copyright © 2016 LTA | Privacy Statement | Terms of Use | Disclaimer | State the Wobrito

SHB 3883T

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

Key Invide Taxi

ComfortDelGro Engineering Pte Ltd

205 Braddolf Road Singapore \$78701 Marrine + 65 6383 6380 Facarrile - 85 6280 9755

24 Senoiro Loop Singapore 758156 7 Sungai Kabut Way Singapore 735781 6 Defu Avenue 1 Singapore 539532

Workshope 59 Loyang Direc Singapore 508969 24 283 Sim Ming Direc Singapore 575717 75 45 Paintain Rusid Singapore 608288 6D 220 Uto Rusid 3 Singapore 408648 220 Uto Rusid 3 Singapore 408648 10 12 . 0 7 . 2016 15:34

Page : 1

JOB CARD JC NO.304931385 Sales Order: 3676064 ARC Repair TP(CFSO)1 STOMER REGN NO.: MILEAGE SHB3883T CITYCAR PTK LTD FUEL 28.81 MAKE: 7010070 MERCEDES BENZ STOMER NO. E 1/2 383 SIN MING DRIVE DATE/TIME IN MODEL Singapore SINGAPORK 575717 K220CDI (K5) 12,07,2016 10:24 65551188 TARGET DATE YR OF MANU. (FI) 31.08.2012 (P) CHASSIS CODE COMPLETION DATE/TIME: WDB2110062A652363 COUNT CARD NO.

Accident Date: 12.07.2016 MATURK: ACC: 12.07.16/C

H/M:

DARON CORR

					•	
		= ,				
R					CUSTOMER'S SIGNATU	JRE
		Exit Pass	?		8	
PALECY	19()	Vehicle No.:		SHB3883T		
collection	Signature/Date	NEWS BUILDING NO			Date	
		PALIKY 193	Exit Pass Vehicle No.: Signature/Date Name of Service A	Exit Pass Vehicle No.: Value 193 Signature/Date Name of Service Advisor	Exit Pass Vehicle No.: SHM3883T Signature/Date Name of Service Advisor	Exit Pass Vehicle No.: Signature/Date Name of Service Advisor Date

CITY CAB PTE LTD REPAIR ESTIMATE*

VEHICLE NO: SHB 3883T

MAKE





DATE: 12/7/2016 15:30

Qty	Parts Description/ Labour	Type	Unit Price	92	Amount
	Bumper Assy, Frt CYO			S	1,345.0
	Bumper Bracket, Frt/RH ALC			5	41.8
	Head Lamp Assy (RH)51			S	976.6
	Fender, Frt/RH dented			S	878.5
	Fender Splashshield', Frt/RH (Front) ton	\		5	133.0
	Wheel Rim unt			S	552.5
	Tyre 205/60R16 Yokohama RHSLC			\$	310.0
	SUB T	OTAL		s	4,237.4
	LES	S 20%	A 1000	S	847.4
	DISCOUNTED T	OTAL	2360.64	S	3,389.9
	Labour Charge Panel Beating Spray Painting Charge Wiring Charge Tuff Kote TOTAL LA Solve 3 day 45 LKK Henry 9788 4060 12/7/16 1600hs. LKKA the Re * To rese		500 400 30 X	s s s s s	500.0 500.0 50.0 1,250.0 4,639.5
	Parts; Third; No die Supple suc)	uto Consultants hence pairer of the following unvey beforelatter spray purity damaged part(s) during moes are subject to confinely survey is on a "Withougal modification(s) in allow ementary (ten(s) must be act to final approval from the ladged by Repairer ne:	anting ig resurvey mation of Prejudice" basis ed escryoyed and		

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

From:

Hsiao Tong (LKKAuto)

Sent:

Saturday, 13 August, 2016 11:08 AM

To:

'andrewgoh@cdge.com.sg'

Subject:

<Request for Evidence>Your Ref: CC16070469/SHB 3883T/ AG (J) *Our Ref: CC3/EQI16013042/H1pa3 [ACCIDENT INVOLVING PA 5439R & SHB 3883T ON

12/07/2016]

Attachments:

Statement of PA 5439R.pdf

Your Ref: CC16070469/SHB 3883T/ AG (J)

Our Ref: CC3/EQI16013042/H1pa3

Without Prejudice

Dear Sirs.

ACCIDENT INVOLVING PA 5439R & SHB 3883T ON 12/07/2016

We refer to the above matter.

Attached here with a copy of our insured's accident report for your easy reference. We have spoken to our insured driver to verify the nature of accident. However he informed us that he is not aware of the collision/accident.

In view of this, we would like to request video footage/ witness statement (if any) in order for us to look into the matter.

Appreciate an early reply.

Best Regards.

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

Andrew Cornelius Goh Cheng Chuan <andrewgoh@cdge.com.sg>

Sent:

Monday, 15 August, 2016 2:59 PM

To:

Hsiao Tong (LKKAuto)

Subject:

Re: <Request for Evidence>Your Ref: CC16070469/SHB 3883T/ AG (J) *Our Ref. CC3/EQI16013042/H1pa3 [ACCIDENT INVOLVING PA 5439R & SHB 3883T ON

12/07/2016]

Follow Up Flag:

Follow up Completed

Flag Status:

Without Prejudice

Dear Hsiao Tong

No records of CCTV footage in our file.

Best Regards Andrew Goh

Claims Department / ComfortDelGro Engineering Pte Ltd

Off: 6214 8734 / Fax: 6214 1843

Fram: "Hsiao Tong (LKKAuto)" <chewht@lkkauto.com> "andrewgoh@cdge.com.sg" <andrewgoh@cdge.com.sg> Date: 13-08-2016 11:08 AM Subject: <Reen 11:08 AM

<Request for Evidence>Your Ref: CC16070469/SHB 3883T/ AG (J) *Our Ref: CC3/EQ116013042/H1pa3 (ACCIDENT INVOLVING PA 5439R & SHB 3883T ON 12/07/2016]

Your Ref: CC16070469/SHB 3883T/ AG (J)

Our Ref: CC3/EQI16013042/H1pa3

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING PA 5439R & SHB 3883T ON 12/07/2016

We refer to the above matter.

Attached here with a copy of our insured's accident report for your easy reference. We have spoken to our insured driver to verify the nature of accident. However he informed us that he is not aware of the collision/accident.

In view of this, we would like to request video footage/ witness statement (if any) in order for us to look into the matter.

Appreciate an early reply.

COMFORTDELGRO ENGINEERING

Our Job Ref No 304931385 15 07 2016

ComfortDelGra Engineering Pte Ltd

				Fax: 654	ng Drive Singapore 508969 6 8156		
FINA	LIZAT	TON FORM					
To	LKK			Fax:			
Attn	:	HENRY					
Vehi	de Reg	No. : SHB3883T		Date of Accident :	12.07.2016		
The	survey	and estimates of the repairs of the above-me	ntioned ve	hicle are as follows:-			
1.	The	repair job shall bill to:	EQ	-	PA 5439R		
2.	The	finalized amount shall be:					
	(a)	Spare Parts after List discount			\$0.00		
	(b)	Labour Charges			\$0.00		
		Total for Part-By-Part Repair Cost			\$0.00		
	(c.)	Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost		20%	\$2,650.00 \$2,650.00		
3.	Estir	nated normal period for repairs:	3	working days.			
3.	Wes	nated normal period for repairs: shall treat the above amount as Correct a			ly from you within		
557.L 66	We s	shall treat the above amount as Correct a					
4.	We s	shall treat the above amount as Correct a orking days		med if there is no rep We confirm the est	imates and		
4.	We s	shall treat the above amount as Correct a orking days nk you for your assistance ature:		med if there is no rep We confirm the est finalized amount			
4.	We s 7 wo Than	shall treat the above amount as Correct a orking days nk you for your assistance ature:	nd Confir	wed if there is no rep We confirm the est finalized amount Signature:	imates and		

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
LTA Search Fee				
 Medical Fees (on behalf of driver, if applicable) 				
6 Overrun				

Remarks:						
-						

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHB 3883T



DATE: 12/7/2016 15:30

Qty	Parts Description/ Labour	Type	Unit Price	1	Amount
	Bumper Assy, Frt CYTA			S	1,345.00
	Bumper Bracket, Frt/RH A&C			\$	41.80
	Head Lamp Assy (RH)54			S	976.60
	Fender, Frt/RH. dented >91			S	878.50
	Fender Splashshield, Frt/RH (Front) +on			S	133.00
	Wheel Rim und			S	552.50
	Tyre 205/60R16 Yokohama RH SLC			s	310.00
	SUB TOTAL			s	4,237.40
	LESS 20%			S	847.48
	DISCOUNTED TOTAL			S	3,389.92
	Labour Charge Panel Beating Spray Painting Charge Wiring Charge Tuff Kote		500 400 30 X	s s s	580.00 500.00 50.00
	TOTAL LABOUR			s	1,250.00
	3 day 45 ESTIMATE TOTAL			s	4,639.93
	THE ME				
	9788 4060				
	9788 4060 12/7/16 1600hs.				
	1214/16 1000103				
	1- 4 2650 00			1	
	L/3 \$ 2650.00				
	2				
				1	

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Mei Kwan (LKK Auto)

From:

Janet Tan <janet.tan@eginsurance.com.sg>

Sent:

Friday, 15 July, 2016 3:12 PM

To:

Mei Kwan (LKK Auto)

Cc:

KKLau; Hsiao Tong; Vivian Lau; Zayyer, Admin A

Subject:

RE: Direct Settlement - Accident Involving PA5439R (OI : EQI - DM16HO01485/JT)

AND SHB3883T (TP: LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Attachments:

OI.pdf

Follow Up Flag:

Follow up Flagged

Flag Status: Categories:

нмк

Dear Mei Kwan

OI report as attached.

Please establish liability first before settlement.

Best Regards

Janet Tan

Claims Executive

EQ Insurance Company Limited

5 Maxwell Road,

#17-00 Tower Block,

MND Complex

Singapore 069110

6223 9433 (Tel)

6496 9032 (DID)

6223 4190 (Fax)

Website: www.eginsurance.com.sg

Disclaimer: Privileged/Confidential information may be cantained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Mei Kwan (LKK Auto) [mailto:Meikwan@lkkauto.com]

Sent: Friday, July 15, 2016 11:22 AM

To: Janet Tan

Cc: KKLau; Hsiao Tong; Vivian Lau; Zayyer; Admin A

Subject: Direct Settlement - Accident Involving PA5439R (OI: EQI - TBA) AND SHB3883T (TP: LKK REF -

CC3/EQI16013042/H1pa3) on 12.07.2016

WITHOUT PREJUDICE

Dear Janet,

We refer to the above matter.

This is a TP direct settlement case.

From:

Hsiao Tong (LKKAuto)

Sent:

Thursday, 18 August, 2016 5:12 PM

To:

'Janet Tan'

Subject:

RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT)

AND SHB3883T (TP: LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Janet,

We refer to the above matter.

Third party reported that he was travelling along Henderson Road towards Jalan Bukit Merah, Suddenly our insured's driver cut into his lane and touched his taxi right front portion. It did not stop and just simply drove away. Third party followed our insured until after one bus-stop away.

Our insured's driver reported that he was driving straight along Henderson Road when suddenly third party claimed that he had collided onto his taxi.

There was no video footage from both parties.

As per our tele-conversation earlier, we had contacted our insured driver, Mr Chin to verify the nature of accident. He adamant that there was no collision between both vehicles. The damages to his van was pre-existing damage.

In view of the above, we seek your instruction In order for us to proceed further.

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [mailto:janet.tan@eginsurance.com.sq]

Sent: Friday, 15 July, 2016 3:12 PM

To: Mei Kwan (LKK Auto)

Cc: KKLau; Hsiao Tong; Vivian Lau; Zayyer; Admin A

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI : EQI - DM16HO01485/JT) AND SHB3883T (TP :

LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Mei Kwan

OI report as attached.

Please establish liability first before settlement.

Best Regards

From:

Janet Tan <janet.tan@eqinsurance.com.sg>

Sent:

Wednesday, 24 August, 2016 2:31 PM

To:

Hsiao Tong (LKKAuto)

Subject:

RE: Direct Settlement - Accident Involving PA5439R (OI : EQI - DM16HO01485/JT)

AND SHB3883T (TP: LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Attachments:

thirdparty.pdf

Dear Hsiao Tong,

Attach complete set of third party report from Merimen for your reference.

Where is the accident impact? The scene photos did not shed light on any possible collision and the last scene photo in the report seen to have been taken from a video footage.

You may write to insured at Deway Travel & Coach Pte Ltd, 10 Phoenix Road, Phoenix Heights, Singapore 668161 or email them at sinulian@singnet.com.sg for more information and /or evidence.

In the absence of any evidence, please proceed to reject the claims if insured /insured driver persist.

We await your further update.

) AS YOU KNOW TO TAKE DAVER HAS FORMULATED A DAMAGE CLAM

AGAINST YOUR MOTOR POLICY IN COMMECTION WITH THE ABOVE ACCIDENT

Best Regards

2) DURING OUR TELECONIVERSATIONS WHEREBY YOU HAS MENTIONE

Janet Tan

THAT YOU WERE NOT AGARE OF ANY COLLISION WITH TIP TAKE THE VISIBLE

Claims Executive EQ Insurance Company Limited

GRAZED LINE DAMAGE WAS PREEXISTING DAMAGEIN NATURE

5 Maxwell Road,

3) TO FACILIATE US PROCEEDING FURTHER KINDLY CONFIRM

#17-00 Tower Block,

THAT THERE WAS MUSED NO COLLISION INVOLVED YOUR BUS WITH T/P TAXI

MND Complex

Singapore 069110

AT THE MATERIAL TIME

6223 9433 (Tel)

6496 9032 (DID)

6223 4190 (Fax)

Website: www.eginsurance.com.sg

Disclaimer : Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

sender immediately and delete all copies of it.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Thursday, August 18, 2016 5:12 PM

To: Janet Tan

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP:

LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Janet.

We refer to the above matter.

Third party reported that he was travelling along Henderson Road towards Jalan Bukit Merah. Suddenly our insured's driver cut into his lane and touched his taxi right front portion. It did not stop and just simply drove away. Third party followed our insured until after one bus-stop away.

Our insured's driver reported that he was driving straight along Henderson Road when suddenly third party claimed that he had collided onto his taxi.

There was no video footage from both parties.

As per our tele-conversation earlier, we had contacted our insured driver, Mr Chin to verify the nature of accident. He adamant that there was no collision between both vehicles. The damages to his van was pre-existing damage.

In view of the above, we seek your instruction In order for us to proceed further.

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]

Sent: Friday, 15 July, 2016 3:12 PM

To: Mei Kwan (LKK Auto)

Cc: KKLau; Hsiao Tong; Vivian Lau; Zayyer; Admin A

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP:

LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Mei Kwan

OI report as attached.

Please establish liability first before settlement.

Best Regards

Janet Tan
Claims Executive
EQ Insurance Company Limited
5 Maxwell Road,
#17-00 Tower Block,
MND Complex
Singapore 069110
6223 9433 (Tel)
6496 9032 (DID)

6223 4190 (Fax)

Website: www.eginsurance.com.sg

Disclaimer - Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it. From: Mei Kwan (LKK Auto) [mailto:Meikwan@lkkauto.com]

Sent: Friday, July 15, 2016 11:22 AM

To: Janet Tan

Cc: KKLau; Hsiao Tong; Vivian Lau; Zayyer; Admin A

Subject: Direct Settlement - Accident Involving PA5439R (OI: EQI - TBA) AND SHB3883T (TP: LKK REF -

CC3/EQI16013042/H1pa3) on 12.07.2016

WITHOUT PREJUDICE

Dear Janet.

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHB 3883T at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Hsiao Tong and she can be contacted at DID: 6742 3197.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: <u>MeiKwan@lkkauto.com</u> | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

Hsiao Tong (LKKAuto)

Sent:

Monday, 29 August, 2016 4:33 PM

To:

'sinulian@singnet.com.sg'

Subject:

ACCIDENT INVOLVING PA 5439R & SHB 3883T ON 12/07/2016

Your Ref: PA 5439R

Our Ref: CC3/EQI16013042/H1pa3

Dear Sirs/Madam,

ACCIDENT INVOLVING PA 5439R & SHB 3883T ON 12/07/2016

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ Insurance Company Ltd to deal with the third party claim against your policy.

We have received a claim from ComfortDelgro Engineering Pte Ltd acting on behalf of the owner of SHB 3883T against your motor insurance policy.

During our tele-conversation with you driver, Mr Chin Swee Ming whereby he had mentioned that he was not aware of any collision with third party taxi. The visible grazed line damage on your van's left rear body was pre-existing damage in nature.

To facilitate us proceeding further, kindly confirm that there was indeed no collision involved your vehicle with third party taxi at the material time.

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@lkkauto.com.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

Hsiao Tong (LKKAuto)

Sent:

Friday, 28 October, 2016 5:53 PM

To:

'sinulian@singnet.com.sg'

Subject:

RE: ACCIDENT INVOLVING PA 5439R & SHB 3883T ON 12/07/2016

Dear Sirs.

We refer to our email dated 29/08/2016.

Kindly let us hear from you soon as third party is chasing fro outcome.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Monday, 29 August, 2016 4:33 PM

To: 'sinulian@singnet.com.sg' <sinulian@singnet.com.sg>

Subject: ACCIDENT INVOLVING PA 5439R & SHB 3883T ON 12/07/2016

Your Ref: PA 5439R

Our Ref: CC3/EQI16013042/H1pa3

Dear Sirs/Madam,

ACCIDENT INVOLVING PA 5439R & SHB 3883T ON 12/07/2016

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ Insurance Company Ltd to deal with the third party claim against your policy.

We have received a claim from ComfortDelgro Engineering Pte Ltd acting on behalf of the owner of SHB 3883T against your motor insurance policy.

During our tele-conversation with you driver, Mr Chin Swee Ming whereby he had mentioned that he was not aware of any collision with third party taxi. The visible grazed line damage on your van's left rear body was pre-existing damage in nature.

To facilitate us proceeding further, kindly confirm that there was indeed no collision involved your vehicle with third party taxi at the material time.

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at chewht@kkauto.com.

From:

Hsiao Tong (LKKAuto)

Sent:

Saturday, 25 February, 2017 1:09 PM

To:

'Janet Tan'

Subject:

RE: Direct Settlement - Accident Involving PA5439R (OI : EQI - DM16HO01485/JT)

AND SHB3883T (TP: LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Attachments:

RE: ACCIDENT INVOLVING PA 5439R & SHB 3883T ON 12/07/2016

Dear Janet,

We refer to the above matter.

We have send an email to our insured(sinulian@singnet.com.sa) for clarification. Kindly refer to the attached email.

However there was no response from them up-to-date.

In view of the above, kindly advise if we may proceed to reject third party claim.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]

Sent: Wednesday, 24 August, 2016 2:31 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK

REF - CC3/EQJ16013042/H1pa3) on 12.07.2016

Dear Hsiao Tong,

Attach complete set of third party report from Merimen for your reference.

Where is the accident impact? The scene photos did not shed light on any possible collision and the last scene photo in the report seen to have been taken from a video footage.

You may write to insured at Deway Travel & Coach Pte Ltd, 10 Phoenix Road, Phoenix Heights, Singapore 668161 or email them at singnet.com.sg for more information and /or evidence.

In the absence of any evidence, please proceed to reject the claims if insured /insured driver persist.

We await your further update.

From:

Janet Tan <janet.tan@eqinsurance.com.sg>

Sent:

Tuesday, 11 April, 2017 10:16 AM

To:

Tan Wei Yin

Cc:

Hsiao Tong (LKKAuto)

Subject:

FW: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT)

AND SHB3883T (TP: LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Attachments:

RE: ACCIDENT INVOLVING PA 5439R & SHB 3883T ON 12/07/2016

WY,

Your case. You decide @

Regards.

Janet Tan



EQ Insurance Company Limited

muck Road #17-00 Yower Block MMD Complex Singapore 089110 did 51 (459 9010) tel 65 9023 9433 (51 / fax 95 6223 4190



you've got a friend ProvingedyConfidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Monday, April 10, 2017 10:29 AM

To: Janet Tan < janet.tan@eqinsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI : EQI - DM16HO01485/JT) AND SHB3883T (TP : LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Janet.

We refer to our email dated 25/02/2017.

Kindly advise if we may proceed to reject third party claim.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

Hsiao Tong (LKKAuto)

Sent:

Tuesday, 23 May, 2017 3:57 PM

To:

'Tan Wei Yin'

Subject:

RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT)

AND SHB3883T (TP: LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Hi Wei Yin,

We refer to your below email.

We have maintain rejection as per your instruction.

Third party will escalate the matter to GIA DRM for resolution.

Kindly confirm that EQ acknowledge the intention.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Uhi Industrial Park, Uhi Avenue 1, #02-25 | S(408933) 33/4/A@AOSPM Was You called in Pls assist to check vim OD

-) . Why his steetchplan indicated. CONTACT? on both vehicus.

From: Tan Wei Yin [mailto:weiyin.tan@eqinsurance.com.sg]

Sent: Monday, 8 May, 2017 4:12 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving PAS439R (OI : EQI - DM16HO01485/JT) AND SHB3883T (TP : LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Hsiao Tong,

We refer to your email below.

Please maintain rejection.

The burden of proof lies on the party making the allegation.

Insured driver reported that he was travelling straight. Unless there is evidence to prove otherwise, our stand remains the same.

Moreover, looking at the photos taken by all parties, we note that there are lots of old damages all over insured vehicle.

From:

Jim Wong See Pah <jimwong@cdge.com.sg>

Sent:

Wednesday, 12 April, 2017 9:18 AM

To:

Hsiao Tong (LKKAuto)

Subject:

Re: Your Ref: CC16070469/SHB 3883T/ AG (J) *Our Ref: CC3/EQI16013042/H1pa3

[ACCIDENT INVOLVING PA 5439R(EQ) & SHB 3883T ON 12/07/2016]

Attachments:

Statement of PA 5439R.PDF; DSCF6144JPG; DSCF6145JPG; DSCF6146JPG;

DSCF6147.JPG: DSCF6150.JPG: DSCF6151.JPG: DSCF6152.JPG

Dear Ms Chew,

We refer your rejective mail as below.

Apparently, your client reported unaware of accident and not no contact of vehicles. Furthermore, your client's sketch plan indicated the contact point scenario that happened at merging lane and damaging taxi was being surveyed by your appointed surveyor.

In view of conflicting version report, we propose 50/50 to resolve our property damage claim amicably.

Please respond favourably.

Best Regards Jim Wong

Claims Department / ComfortDelgro Engineering Pte Ltd

Off: 62148374 / Fax: 62141843

"Hsiao Tong (LKKAuto)" <chewht@lkkauto.com> Jim Wong See Pah <jimwong@cdge.com.sg>

Date 11/04/2017 05:35 PM Subsect Your Ref: CC16070469/SHB 3883T/ AG (J) *Our Ref: CC3/EQI16013042/H1pa3 [ACCIDENT INVOLVING PA 5439R(EQ) & SHB 3883T ON 12/07/2016]

Your Ref: CC16070469/SHB 3883T/ AG (J)

Our Ref: CC3/EQ116013042/H1pa3

Without Prejudice

Dear Sirs.

ACCIDENT INVOLVING PA 5439R(EQ) & SHB 3883T ON 12/07/2016

We refer to the above matter.

Attached here with a copy of our insured's accident report for your easy reference.

Our insured driver adamant that there was no collision/ contact between both vehicles.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

From:

Hsiao Tong (LKKAuto)

Sent:

Tuesday, 11 April, 2017 5:36 PM

To:

'Jim Wong See Pah'

Subject:

Your Ref: CC16070469/SHB 3883T/ AG (J) *Our Ref: CC3/EQI16013042/H1pa3

[ACCIDENT INVOLVING PA 5439R(EQ) & SHB 3883T ON 12/07/2016]

Attachments:

Statement of PA 5439R.PDF

Your Ref: CC16070469/SHB 3883T/ AG (J)

Our Ref: CC3/EQI16013042/H1pa3

Without Prejudice

Dear Sirs.

ACCIDENT INVOLVING PA 5439R(EQ) & SHB 3883T ON 12/07/2016

We refer to the above matter.

Attached here with a copy of our insured's accident report for your easy reference.

Our insured driver adamant that there was no collision/ contact between both vehicles.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>

Sent:

Tuesday, 11 April, 2017 10:24 AM

To:

Hsiao Tong (LKKAuto)

Subject:

RE: Direct Settlement - Accident Involving PA5439R (OI : EQI - DM16HO01485/JT)

AND SHB3883T (TP: LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Hsiao Tong,

Please proceed to reject.

Thank you.

Regards,

Tan Wei Yin

Executive I Claims



EQ Insurance Company Limited

Manual Appr #17:00 Tower Block AND Complex Singapore 069110
 did 91-8486 9800 | tel 65-6223-9437-ext 882 | fax 85-6223-4190

A summer of Course

you've got a friend

Printegral/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Monday, April 10, 2017 10:29 AM

To: Janet Tan < janet.tan@eqinsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI : EQI - DM16HO01485/JT) AND SHB3883T (TP : LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Janet,

We refer to our email dated 25/02/2017.

Kindly advise if we may proceed to reject third party claim.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd.

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Tuesday, 21 March, 2017 12:46 PM

To: 'janet.tan@eqinsurance.com.sg' < janet.tan@eqinsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI : EQI - DM16HO01485/JT) AND SHB3883T (TP : LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Janet.

We refer to our email dated 25/02/2017.

Kindly advise if we may proceed to reject third party claim.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 25 February, 2017 1:09 PM

To: 'Janet Tan' < janet.tan@eqinsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI : EQI - DM16HO01485/JT) AND SHB3883T (TP : LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Janet,

We refer to the above matter.

We have send an email to our insured(<u>sinulian@singnet.com.sa</u>) for clarification. Kindly refer to the attached email.

However there was no response from them up-to-date.

In view of the above, kindly advise if we may proceed to reject third party claim.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]

Sent: Wednesday, 24 August, 2016 2:31 PM

To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving PAS439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Hsiao Tong,

Attach complete set of third party report from Merimen for your reference.

Where is the accident impact? The scene photos did not shed light on any possible collision and the last scene photo in the report seen to have been taken from a video footage.

You may write to insured at Deway Travel & Coach Pte Ltd, 10 Phoenix Road, Phoenix Heights, Singapore 668161 or email them at singulater.com.sg for more information and /or evidence.

In the absence of any evidence, please proceed to reject the claims if insured /insured driver persist.

We await your further update.

Best Regards

Janet Tan
Claims Executive
EQ Insurance Company Limited
5 Maxwell Road,
#17-00 Tower Block,
MND Complex
Singapore 069110
6223 9433 (Tel)
6496 9032 (DID)
6223 4190 (Fax)

Website: www.eginsurance.com.sg

Disclaimer: Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Thursday, August 18, 2016 5:12 PM

To: Janet Tan

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Janet.

We refer to the above matter.

Third party reported that he was travelling along Henderson Road towards Jalan Bukit Merah. Suddenly our insured's driver cut into his lane and touched his taxi right front portion. It did not stop and just simply drove away. Third party followed our insured until after one bus-stop away.

Our insured's driver reported that he was driving straight along Henderson Road when suddenly third party claimed that he had collided onto his taxi.

There was no video footage from both parties.

As per our tele-conversation earlier, we had contacted our insured driver, Mr Chin to verify the nature of accident. He adamant that there was no collision between both vehicles. The damages to his van was pre-existing damage.

In view of the above, we seek your instruction In order for us to proceed further.

Best Regards.

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]

Sent: Friday, 15 July, 2016 3:12 PM

To: Mei Kwan (LKK Auto)

Cc: KKLau; Hsiao Tong; Vivian Lau; Zayyer; Admin A

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI : EQI - DM16HO01485/JT) AND SHB3883T (TP :

LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Mei Kwan

OI report as attached.

Please establish liability first before settlement.

Best Regards

Janet Tan
Claims Executive
EQ Insurance Company Limited
5 Maxwell Road,
#17-00 Tower Block,
MND Complex
Singapore 069110

6223 9433 (Tel) 6496 9032 (DID) 6223 4190 (Fax)

Website: www.eginsurance.com.sg

Disclaimer: Privileged/Confidential Information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Mei Kwan (LKK Auto) [mailto:Meikwan@lkkauto.com]

Sent: Friday, July 15, 2016 11:22 AM

To: Janet Tan

Cc: KKLau; Hsiao Tong; Vivian Lau; Zayyer; Admin A

Subject: Direct Settlement - Accident Involving PA5439R (OI ; EQI - TBA) AND SHB3883T (TP : LKK REF -

CC3/EQI16013042/H1pa3) on 12.07.2016

WITHOUT PREJUDICE

Dear Janet,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHB 3883T at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Hsiao Tong and she can be contacted at DID: 6742 3197.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Our	Ref :	CC16070469 / SHB 3883T	/ AG (J)				
Ďate	1	10-Aug-16				OMFO	RIDELGRO
1275		C	_	CDGE Taxi Clair	ns Depart	term many term	INEERING
		Company Limited		59 Loyang Drive		-110	JII ALLINII AC
	axwell Ro	775		4th floor		ComfortDelGr	o Engineering Pie Lis
		Block, MND Complex		Singapore 50896			
Sing	gapore 069	110		Fax: 6214 1843			Aprillaria +65 6383 628 comilia +65 6280 975
	: Motor C	Claims Department	WITHOU	T PREJUDICI	E		
ACC		VOLVING OUR TAXI 5439R OTHERS	SHE	3883T	YOUR	12.07.16	Workshop Braddel 205 Braddel Ros
SHE	3883T	norised repair workshop for Ci which was involved in the	captioned ad	cident with y	our ins	ured vehicle.	Singapore 57970 Loyang Se Loyang Dru- Singapore 60888
assi	st them in p	ner and the taxi driver cond presenting their claims again from the damage to the vehic	st the party				Sin Ming Sin Sin Ming Date Engagon 57571
As th	ne accident	was caused by the negligent	act of your in			PA 5439R	45 Pandan Rose Singapom Wazak
	re submittin	ng this claim for your consider	ation on behi	alf of the claim	nants.		326 Util Fand . Singapom 40864
1	Cost of R				S\$	2835.50	Sanak
2		days Loss of Rental @\$	159.43	per day	S\$	637.72	23 Senois Los Engapon 75810
3			by M/s LKK		S\$	-	Sungel Katu
4	LTA Sea	rch Fees			S\$	5.35	7 Surgin Kirdut Ww
5		ice Report Fees			S\$		Singspose 72879
6	Towing /	Medical / Transporation Fees		Sub Total :	S\$ S\$	3.478.57	E Ouris Avenue Encomon 53057
HIR	ER'S CLAI	M		Sub rotar.	30	3,470.07	Yahan
1	4	days Loss of Income @\$	80.00	per days	S\$	320.00	righue maustral Park?
			9	Total Claims	S\$	3,798.57	381GADO10 1001 G
We		erewith the following docu	ments to su	pport the cla	ims: -		
a)	100	epair bill.				100	pcs
b)		ch slip/s of :		5439R 3883T			
d)		ice report/s of : authority from owner / hirer / c		30031			
u)	() Photo	copie/s of Accident Scene Photo ss statement/s (x) Rental Rate	vis.	() Traffic Po wntime/Mileage		ult	
	ly look into	the matter and let us hear from	m you on the	settlement of	the said	d claims as	
Pleas to ar expe Pleas this land Accide and to not be 2 we acqui	se note that ny personal enses are close note that, for the tetter as our in dent Litigation his claim is no een complied irking days fa	t it is a condition of any settler injury claim (if any) of the taxical aimed herewith and part of the for the time being, we are not maken the time being, we are not maken tention to file a claim in court according ("NIMA") protocol and further, you eferred to solicitors you shall not a with. If you disagree with this coulding which we shall proceed to ne said condition by your conduct.	driver. This of a settlement on this claim visording to the pour agree that if raise any object addition please of the pour settlement of the property of the	condition shall reached. ia solicitors pro- rovisions of the negotiations shat tion that the NIM reply in writing v	vided you Non-Inju ould brea IA protoc within the	even if medical u treat ery Motor ukdown ool has u next	
And	new Goh or Claims S	pecialist					



Tel 6214 8734 Fax : 6214 1843 Email : andrewgoh@cdge.com.sg

CDGE Claims Department







LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

ALONG

MERCEDES E220 SHB3883T , PA5439R

HENDERSON ROAD

ON 12-Jul-16 08:00

I / We

KHOO TIAN HOCK

(Hirer) NRIC No.:

S0188150G

and/or

HO KIM CHARN

(Relief) NRIC No.: S1436476E

Taxi Number

SHB3883T

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of

"ComfortDelGro Engineering Pte Ltd".

Date

12-Jul-2016

Name of Hirer

KHOO TIAN HOCK

Hirer NRIC

S0188150G

Signature

Address

836 HOUGANG CENTRAL #10-543

530836

Contact No.

91189217

Name of Relief

HO KIM CHARN

Relief NRIC

S1436476E

Signature:

Address

641C PUNGGOL DRIVE #10-311

823641

Contact No.

COMFORTDELGRO ENGINEERING

A member of COMFORIDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

SP Livery Drew By purch foreign \$63 Sin Along Crise Singapore 57777 IS Pandar Hand Singapore 500088

24 Sirmiko Liniar Simpapore 758 156 7 Songei Kadut Way Bingapore 728791

COMPANY REG. NO.: 199506048W

Page: 1

8010325

EQ INSURANCE COMPANY LIMITED

#17-00 5 MAXWELL ROAD TOWER BLOCK SINGAPORE 069110

CONTACT NO: 62239433

VICILIE NO SHB3883"

INV. NO/DATK 91254110 28.07.2016

MERCEDES BENZ

JOB NO. 304931385

MODEL E220CDT(E5)

ODOMETER READING

DATE OF REG 31.08.2012

CHASSIS CODE WDB21.1.0062A652363

JOB TYPE

Description : ACC: 12.07.16/C

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt 7.000 %

2,650.00

185,50

Total Invoice amount

2,835.50

: KATHERINETAN 28.07.2016 09:31:04

Issued by : KATHKKINETAN 28
Repair Type : CFSO/57/57
Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd A member of COMFORTCHECKS

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No. INVOICE No. **AMOUNT** BANK/CHQ No.

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CC16070469

Date: 25 July 2016



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

12/07/2016 @ 08:00 hrs

ALONG

HENDERSON ROAD

INVOLVING

PA5439R

We refer to the above-mentioned accident and wish to inform that CityCab Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHB3883T (the "Taxi"). The Taxi was hired to KHOO TIAN HOCK IC NO S0188150G a registered hirer-operator of CityCab Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$159.43 per day (inclusive of GST).

Please be advised that the Taxi was insured with First Capital Insurance Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Executive, Fleet Safety

This is a computer generated letter. No signature is required.

NAME OF DRIVER

Text tize + -0% 100% 25% 50% 75%

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

12 Jul 2016 / 08:00:00 Successful

EQ INSURANCE COMPANY LTD

Previous OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may after the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2016 LTA | Privacy Statement | Terms of Use | Disclaimer | Rate the Website

https://vrl.lta.gov.sg/lta/vrl/action/insPartDetailByAA?FUNCTION_ID=F1801043ET

From:

Sally Tan <sally.tan@eginsurance.com.sg>

Sent:

Monday, 9 July 2018 10:32 AM

To:

Hsiao Tong (LKKAuto)

Subject:

RE: Direct Settlement - Accident Involving (OI: EQI - DM16HO01485/FN) AND

SHB3883T (TP: LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Hsiao Tong

We have reviewed the matter further and would like to maintain our rejection of the third party claim from SHB3883T.

Please inform the claimant accordingly on our behalf.

Regards

Sally Tan

EQ Insurance Company Limited Email: sally.tan@eqinsurance.com.sg

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Saturday, July 7, 2018 11:54 AM

To: Francis Ng; Janet Tan

Subject: RE: Direct Settlement - Accident Involving (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK REF -

CC3/EQI16013042/H1pa3) on 12.07.2016

Hi Sirs/ Mdm.

07/7/18

04/07/18

Further to the below email.

Kindly let us have your further instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 2 June 2018 1:28 PM

To: 'Francis Ng' <francis.ng@eqinsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK REF -

CC3/EQI16013042/H1pa3) on 12.07.2016

Hi Francis,

Further to the below email.

Kindly let us have your further instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Monday, 30 April 2018 2:51 PM

To: 'Francis Ng' <francis.ng@eqinsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK REF -

CC3/EQI16013042/H1pa3) on 12.07.2016

Hi Francis.

Noted with thanks.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Francis Ng [mailto:francis.ng@eginsurance.com.sg]

Sent: Monday, 30 April 2018 10:15 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK REF -

CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Hsiao Tong,

We have written to the insured about our intention to settle this claim at 50:50 liability.

Please note that that insured must reply within 7 days if they have any valid objections.

Regards, Francis Ng Executive | Claims

		-	
EQ	Insurance	Company	Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190 www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Saturday, April 28, 2018 3:20 PM

To: Francis Ng <francis.ng@eginsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK REF -

CC3/EQI16013042/H1pa3) on 12.07.2016

Hi Francis,

Further to our below email.

Kindly let us have your further instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Wednesday, 21 March 2018 3:40 PM

To: Francis Ng < francis.ng@eqinsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Hi Francis.

We refer to the above matter.

We have contacted our insured driver Mr Chin again on this matter. He adamant that there was no collision/ no contact between both vehicles.

In view of the above, kindly let us have your further instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Tuesday, 23 May 2017 3:57 PM

To: 'Tan Wei Yin' <weiyin.tan@eginsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Hi Wei Yin,

We refer to your below email.

We have maintain rejection as per your instruction.

Third party will escalate the matter to GIA DRM for resolution.

Kindly confirm that EQ acknowledge the intention.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Wei Yin [mailto:weiyin.tan@eginsurance.com.sg]

Sent: Monday, 8 May, 2017 4:12 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Hsiao Tong,

We refer to your email below.

Please maintain rejection.

The burden of proof lies on the party making the allegation.

Insured driver reported that he was travelling straight. Unless there is evidence to prove otherwise, our stand remains the same.

Moreover, looking at the photos taken by all parties, we note that there are lots of old damages all over insured vehicle.

Thank you.

Regards,

Tan Wei Yin

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9882 | tel 65 6223 9433 ext 882 | fax 65 6223 4190 www.eginsurance.com.sg



Privileged/Confidential Information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

you've got a friend

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Saturday, May 6, 2017 2:04 PM

To: Tan Wei Yin <weiyin.tan@eginsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Hi Wei Yin,

We refer to the above matter.

We have rejected third party claim as per instruction. However third party appealed to resolve the matter at 50/50 due to conflicting version.

For your instruction please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Tuesday, 11 April, 2017 10:41 AM

To: 'Tan Wei Yin' <weiyin.tan@eginsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Wei Yin.

Contents noted.

We will proceed to reject third party claim.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Wei Yin [mailto:weiyin.tan@eqinsurance.com.sg]

Sent: Tuesday, 11 April, 2017 10:24 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Hsiao Tong,

Please proceed to reject.

Thank you.

Regards,

Tan Wei Yin

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9882 | tel 65 6223 9433 ext 882 | fax 65 6223 4190 www.eginsurance.com.sg





Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Monday, April 10, 2017 10:29 AM

To: Janet Tan < janet.tan@eqinsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Janet.

We refer to our email dated 25/02/2017.

Kindly advise if we may proceed to reject third party claim.

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Tuesday, 21 March, 2017 12:46 PM

To: 'janet.tan@eqinsurance.com.sg' <janet.tan@eqinsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI : EQI - DM16HO01485/JT) AND SHB3883T (TP : LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Janet,

We refer to our email dated 25/02/2017.

Kindly advise if we may proceed to reject third party claim.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 25 February, 2017 1:09 PM
To: 'Janet Tan' <janet.tan@eqinsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP: LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Janet,

We refer to the above matter.

We have send an email to our insured (sinulian@singnet.com.sg) for clarification. Kindly refer to the attached email.

However there was no response from them up-to-date.

In view of the above, kindly advise if we may proceed to reject third party claim.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [mailto:janet.tan@eginsurance.com.sg]

Sent: Wednesday, 24 August, 2016 2:31 PM

To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI : EQI - DM16HO01485/JT) AND SHB3883T (TP : LKK

REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Hsiao Tong,

Attach complete set of third party report from Merimen for your reference.

Where is the accident impact? The scene photos did not shed light on any possible collision and the last scene photo in the report seen to have been taken from a video footage.

You may write to insured at Deway Travel & Coach Pte Ltd, 10 Phoenix Road, Phoenix Heights, Singapore 668161 or email them at sinulian@singnet.com.sg for more information and /or evidence.

In the absence of any evidence, please proceed to reject the claims if insured /insured driver persist.

We await your further update.

Best Regards

Janet Tan
Claims Executive
EQ Insurance Company Limited
5 Maxwell Road,
#17-00 Tower Block,
MND Complex
Singapore 069110
6223 9433 (Tel)
6496 9032 (DID)
6223 4190 (Fax)

Website: www.eginsurance.com.sg

Disclaimer: Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Thursday, August 18, 2016 5:12 PM

To: Janet Tan

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP:

LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Janet.

We refer to the above matter.

Third party reported that he was travelling along Henderson Road towards Jalan Bukit Merah. Suddenly our insured's driver cut into his lane and touched his taxi right front portion. It did not stop and just simply drove away. Third party followed our insured until after one bus-stop away.

Our insured's driver reported that he was driving straight along Henderson Road when suddenly third party claimed that he had collided onto his taxi.

There was no video footage from both parties.

As per our tele-conversation earlier, we had contacted our insured driver, Mr Chin to verify the nature of accident. He adamant that there was no collision between both vehicles. The damages to his van was pre-existing damage.

In view of the above, we seek your instruction In order for us to proceed further.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [mailto:janet.tan@eginsurance.com.sq]

Sent: Friday, 15 July, 2016 3:12 PM

To: Mei Kwan (LKK Auto)

Cc: KKLau; Hsiao Tong; Vivian Lau; Zayyer; Admin A

Subject: RE: Direct Settlement - Accident Involving PA5439R (OI: EQI - DM16HO01485/JT) AND SHB3883T (TP:

LKK REF - CC3/EQI16013042/H1pa3) on 12.07.2016

Dear Mei Kwan

OI report as attached.

Please establish liability first before settlement.

Best Regards

Janet Tan

Claims Executive

EQ Insurance Company Limited

5 Maxwell Road,

#17-00 Tower Block,

MND Complex

Singapore 069110

6223 9433 (Tel)

6496 9032 (DID)

6223 4190 (Fax)

Website: www.eqinsurance.com.sg

Disclaimer: Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

sender immediately and delete all copies of it.

From: Mei Kwan (LKK Auto) [mailto:Meikwan@lkkauto.com]

Sent: Friday, July 15, 2016 11:22 AM

To: Janet Tan

Cc: KKLau; Hsiao Tong; Vivian Lau; Zayyer; Admin A

Subject: Direct Settlement - Accident Involving PA5439R (OI : EQI - TBA) AND SHB3883T (TP : LKK REF -

CC3/EQI16013042/H1pa3) on 12.07.2016

WITHOUT PREJUDICE

Dear Janet,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHB 3883T at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge Hsiao Tong and she can be contacted at DID: 6742 3197.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Saturday, 28 July 2018 10:39 AM

To:

'Jim Wong See Pah'

Subject:

RE: Your Ref: CC16070469/SHB 3883T/ AG (J) *Our Ref: CC3/EQI16013042/H1pa3

[ACCIDENT INVOLVING PA 5439R(EQ) & SHB 3883T ON 12/07/2016]

Without Prejudice

Hi Mr Jim,

We refer to the above matter.

We have appealed your matter to our principal for further review. However we regret to inform you that we have our principal instruction to maintain rejection.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jim Wong See Pah <jimwong@cdge.com.sg>

Sent: Monday, 22 May 2017 3:57 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Your Ref: CC16070469/SHB 3883T/ AG (J) *Our Ref: CC3/EQI16013042/H1pa3 [ACCIDENT INVOLVING

PA 5439R(EQ) & SHB 3883T ON 12/07/2016]

Dear Ms Chew

We refer the your mail as below.

Please let us have your and /or your principal's consent to escalate our property damage claim to GIA for resolution by 05.06.2017.

Best Regards

Jim Wong

Claims Department / ComfortDelgro Engineering Pte Ltd

Off: 62148374 / Fax: 62141843

"Hsiao Tong (LKKAuto)" <chewht@ikkauto.com> From Jim Wong See Pah <jimwong@cdge.com.sg> To: Date:

20/05/2017 11:05 AM

Subject: RE: Your Ref. CC16070469/SHB 3883T/ AG (J) *Our Ref. CC3/EQI16013042/H1pa3 [ACCIDENT INVOLVING PA 5439R(EQ) & SHB 3883T ON 12/07/2016]

Without Prejudice

Hi Mr Jim.

We refer to your below email.

We have appealed your matter to our principal for further review. However we regret to inform you that we have our principal instruction to maintain rejection as our insured driver adamant that there was no collision between both vehicles.

Best Regards, Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jim Wong See Pah [mailto:jimwong@cdge.com.sg]

Sent: Wednesday, 12 April, 2017 9:18 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: Your Ref: CC16070469/SHB 3883T/ AG (J) *Our Ref: CC3/EQI16013042/H1pa3 [ACCIDENT INVOLVING PA 5439R(EQ)

& SHB 3883T ON 12/07/2016]

Dear Ms Chew,

We refer your rejective mail as below.

Apparently, your client reported unaware of accident and not no contact of vehicles. Furthermore, your client's sketch plan indicated the contact point scenario that happened at merging lane and damaging taxi was being surveyed by your appointed surveyor.

In view of conflicting version report, we propose 50/50 to resolve our property damage claim amicably.

Please respond favourably.

Best Regards Jim Wong Claims Department / ComfortDelgro Engineering Pte Ltd Off: 62148374 / Fax: 62141843

From: "Hsiao Tong (LKKAuto)" <<u>chewht@lkkauto.com</u>>
To: Jim Wong See Pah <<u>liimwong@cdoe.com.sg</u>>

Date: 11/04/2017 05:35 PM

Subject: Your Ref: CC16070469/SHB 3883T/ AG (J) *Our Ref: CC3/EQI16013042/H1pa3 [ACCIDENT INVOLVING PA 5439R(EQ) & SHB 3883T ON

12/07/2016]

Your Ref: CC16070469/SHB 3883T/ AG (J)

Our Ref: CC3/EQI16013042/H1pa3

Without Prejudice

Dear Sirs.

ACCIDENT INVOLVING PA 5439R(EQ) & SHB 3883T ON 12/07/2016

We refer to the above matter.

Attached here with a copy of our insured's accident report for your easy reference.

Our insured driver adamant that there was no collision/ contact between both vehicles.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Bik 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inter-	nationale Des Experts En Autom	obile				
EQ INSURANCE COMPANY LTD			Ref : CC3/EQI16013042/K1pa3q2					
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 28-03-2019 Code : EQI					
1.		Policy Particul	ars :- THIRD PARTY CLAI	M				
	Insured Veh.	PA 5439R	Veh. Inspected	SHB 3883T /				
	Policy No.	DMCFHQ15-000113	Coverage (\$)	0.00				
	Claim No.	DM16HO01485/JT	Excess (\$)	0.00				
	Assign From		Assign Date	12/07/2016				
2.		Vehicle P	articulars & Condition	*				
	Make & Model	MERCEDES BENZ (A)	c.c	2184				
	Engine No.	HIDDEN	Year of Reg.	2012				
	Chassis No.	WDB2110062A652363	Colour	WHITE				
	Odometer	381812	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	NIL				
	General	GOOD						
3.		Cor	nditions of Tyres					
		Size	Make	Balance				
	R/H Front Tyre	205/60 R16	WEST LAKE	4 mm				
	L/H Front Tyre	205/60 R16	WEST LAKE	4 mm				
	R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm				
	L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm				
4.	Description of Damages							
	THE VEHICLE SU	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.						
	DAMAGES SEE D	DAMAGES SEE DETAILS.						
5.	General Information							
	Accident Date	12/07/2016	Inspection Date	12/07/2016				
	Survey held at	COMFORTDELGRO ENGIN	NEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969						
5a.	Remarks							
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.	I COLUMN TO THE OWNER.	Estim	ate Days of Repair	CHE VIOLETTI				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Day	8				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3883T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
-1	BUMPER ASSY ,FRT	CRACKED	1,345.00	1,345.00
1	BUMPER BRACKET ,FRT/RH	NECESSARY	41.80	41.80
- 1	HEAD LAMP ASSY (RH)	SERVICEABLE	976.60	5
1	FENDER ,FRT/RH	DENTED	878.50	878.50
1	FENDER ,SPLASHSHIELD ,FRT/RH (FRONT)	TORN	133.00	133.00
1	WHEEL RIM	CUT	552.50	552.50
1	TYRE 205/60R16 YOKOHAMA RH	SERVICEABLE	310.00	13
	LESS 20% DISCOUNT		-847.48	-590.16
			3,389.92	2,360.64
	LABOUR			
	PANEL BEATING.		650.00	500.00
1	SPRAY PAINTING CHARGE.		500.00	400.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.	NOT NECESSARY	50.00	8.5
GR			1,250.00	930.00
	GRAND TOTAL		4,639.92	3,290.64
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,650.00

Report Ref No. CC3/EQI16013042/K1pa3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>

Sent: Friday, 29 March 2019 2:19 PM

To: 'eqiprs@eqinsurance.com.sg'

Subject: TP Direct Settlement - Accident Involving PA 5439R (OI) and SHB 3883T (TP) on

12/07/2016

Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

We refer to the above matter.

Please be informed that we have rejected TP claim. (see attached)

We enclose herewith our without prejudice report and relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933