

INS. CASE OWNER:

CC 4/LPC1601

4069, R1 2602

LKK:

IDAC:

Surveyor:

Rasm

DOI:

7/8/16

Date / Time:

18/7/16

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No.:

SJC 720B

Name of Insured:

YAP PAH HOLE

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

25/7/16

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Tay Hui Goh

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

15/16/16/UP10/01/056

Policy No.:

2/15/1600/09349

Make / Model:

MITSUBISHI

Place of Accident:

FALLING WAY SLIP RD TO PE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SMB 660P

SJC 720B

FRK 1114



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
7/8/16	Non-Reporting ltr (1st):	
7/8/16	Non-Reporting ltr (2nd):	
7/8/16	Non-Reporting ltr (Final):	
7/8/16	Notification ltr (if non-pickup):	
7/8/16	Call OI:	
7/8/16	After call ltr to OI:	
7/8/16	Documentation Check List: Handler Typist	
7/8/16	Notification ltr (if non-pickup)	
7/8/16	After call ltr to OI:	
7/8/16	Authorisation To Act:	
7/8/16	Release Voucher:	
7/8/16	Final Repair Bill:	
7/8/16	Car Rental Invoice:	
7/8/16	Towing Invoice:	
7/8/16	LTA / GIA:	
7/8/16	Medical Bill:	
7/8/16	PIR:	
7/8/16	Mandate/Reject Instruction:	
7/8/16	LOD:	
7/8/16	Payment Breakdown Form:	
7/8/16	Post-Repair Photos:	
7/8/16	Others:	
7/8/16	Confirm by:	
7/8/16	Repair Cost: L10	
7/8/16	SS \$580.00 (3 days) Reduction: 71 %	
7/8/16	FINAL SETTLEMENT	
7/8/16	Final Liability: %	
7/8/16	Repair Cost: (w/ass) SS \$588.50	
7/8/16	Loss of Rental (LOR): SS	
7/8/16	Loss of Use (LOU): SS 90.00 (\$30 x 3 days)	
7/8/16	Loss of Income (LOI): SS	
7/8/16	LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]	
7/8/16	GIA/LTA Search: SS 2.00	
7/8/16	Medical: SS	
7/8/16	Disbursement: SS	
7/8/16	Legal Cost: SS	
7/8/16	Total: SS 680.50 Global Sum SS: -	
7/8/16	FINAL PAYMENT	
7/8/16	Payee 1: SS 680.50 Name 1: DE XING MOTOR PTE LTD	
7/8/16	Payee 2: (Strike if N.A.) SS - Name 2: -	
7/8/16	Payee 3: (Strike if N.A.) SS - Name 3: -	

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC16014069/R1zb3	
100 BEACH ROAD #19-00 SHAW TOWERS SINGAPORE 189702			Date : 29-07-2016	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJC 7220B		Veh. Inspected	FBK 291U
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	29/07/2016
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/07/2016		Inspection Date	02/08/2016
Survey held at	DE XING MOTOR PTE LTD BLK 3006 UBI ROAD 1 #01-356 SINGAPORE 408700			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC16014069/R1zb3

Date: 03.08.2016

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

FBK291U


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02.08.2016 at the premises of M/s De Xing Motor Pte Ltd have the following to report:-

Workshop Estimate Amount	: S\$	1,568.00
Revised Estimate Amount	: S\$	393.00
"Check" Items Amount	: S\$	725.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser



德興摩哆私人有限公司 DE XING MOTOR PTE. LTD.

Blk 3006 Ubi Road 1 #01-356 Singapore 408700
Tel: 67468582 (4 Lines) Fax: 67439525
GST Reg. No.: M2-0061652-9
Co. Reg. No.: 198303312R



(☒) Third-Party () Own Damage () List Price () Cost Price

Bike N FBK291U Date of Ac 25-07-2016
Make/ YAMAHA MX135 Chassis N MH250C006EK20206
Year 2014 Requester KOK LEONG

Attn: Claims Dept.

The bike will be here

S/ NO	Parts Description	Quantity	Unit Price	Total	Remarks
1	REAR FENDER	1	\$95.00	\$95.00	113
2	REAR NO PLATE	1	\$18.00	\$18.00	
3	REAR SIDE FARING	2	\$85.00	\$170.00	
4	REAR TAIL LAMP ASSY	1	\$105.00	\$105.00	
5	REAR SWING ARM	1	\$295.00	\$295.00	
6	REAR WHEEL SHAFT	1	\$45.00	\$45.00	
7	REAR SWING ARM	1	\$350.00	\$350.00	
8	REAR SWING BOLT	2	\$55.00	\$110.00	
9	LABOUR	1	\$380.00	\$380.00	2.80
10					
11	Rear frame body	1	\$350	\$350	300
12					
13					
14					
15					
16					
17					
18					
19					
20					

on Monday to
Survey.

Thanks-

(L) ASUL

Hp 90010068

3 days

4/3

Resurvey after repair

\$1,918.00

email: rasul@kkauto.com

02/08/16 @ 1000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Sub Total \$1,568.00
ADD 7%GST \$109.76
Grand Total \$1,677.76

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE, SHOULD THERE BE ANY ADDITIONAL PARTS REQUIRED OR DAMAGED DURING OUR COURSE OF REPAIRS, WE WILL INFORM YOU ACCORDINGLY FOR NECESSARY ACTION. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

APPROVING OFFICER'S SIGNATURE & COMPANY'S STAMP



P- 113
10%
101.70

L- 580.00

T- 681.70

20%

545.00

45-550

3 days

Ashley Chong (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Thursday, 28 July, 2016 3:37 PM
To: assignments@lkkauto.com
Cc: GERALD POH WEE BIN; LIONEL CHUA KOK KEONG
Subject: Our ref: 15/16/16/VP00/019056 Accident involving SJC 7220B & FBK 291U
along PIE towards Ubi on 25/7/16
Attachments: 28072016153459.pdf

Dear Catherine,

Kindly refer to our attachment.

Please proceed to appoint Marcus Chua to conduct a survey of the vehicle no: FBK 291U on without prejudice.

We look forward to receiving your report soon.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
100 Beach Road, #19-00 Shaw Tower, Singapore 189702
Tel: (65) 6250 7388 Ext.252 | Fax: (65) 6296 2706

28/7/2016 @ 3:45pm
wei wei
vehicle not in

Shu Pei (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 3 August, 2016 5:02 PM
To: Shu Pei (LKKAUTO)
Cc: LIONEL CHUA KOK KEONG; ERIC WOO JUN KIAT
Subject: RE: Our ref: 15/16/16/VP00/019056 Accident involving SJC 7220B & FBK 291U along PIE towards Ubi on 25/7/16 ***LKK REF:CC4/LPC16014069/R1zb3
Attachments: 03082016165958.pdf

Dear Shu Pei,

We attached a copy of our insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
100 Beach Road, #19-00 Shaw Tower, Singapore 189702
Tel: (65) 6250 7388 Ext.240 | Fax: (65) 6296 2706

From: Shu Pei (LKKAUTO) [mailto:shupel@lkkauto.com]
Sent: Wednesday, 3 August, 2016 4:44 PM
To: ERIC WOO JUN KIAT
Cc: GERALD POH WEE BIN; LIONEL CHUA KOK KEONG; Admin A; Zayyer (LKKAUTO); Hsiao Tong (LKKAUTO); Vivian Lau (LKKAUTO)
Subject: RE: Our ref: 15/16/16/VP00/019056 Accident involving SJC 7220B & FBK 291U along PIE towards Ubi on 25/7/16 ***LKK REF:CC4/LPC16014069/R1zb3

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle FBK 291U at M/s De Xing Motor Pte Ltd.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Zayyer and he can be contacted at DID: 6841 2409.

Thank you.

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 28 July, 2016 3:47 PM
To: 'ERIC WOO JUN KIAT' <ericwoo@lonpac.com>; Admin A <admin-a@lkkauto.com>
Cc: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; 'LIONEL CHUA KOK KEONG' <lionelchua@lonpac.com>;
assignments <assignments@lkkauto.com>
Subject: RE: Our ref: 15/16/16/VP00/019056 Accident involving SJC 7220B & FBK 291U along PIE towards Ubi on 25/7/16

Dear Eric,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Ashley Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]
Sent: Thursday, 28 July, 2016 3:37 PM
To: assignments@lkkauto.com
Cc: GERALD POH WEE BIN; LIONEL CHUA KOK KEONG
Subject: Our ref: 15/16/16/VP00/019056 Accident involving SJC 7220B & FBK 291U along PIE towards Ubi on 25/7/16

Dear Catherine,

Kindly refer to our attachment.

Please proceed to appoint Marcus Chua to conduct a survey of the vehicle no: FBK 291U on without prejudice.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

100 Beach Road, #19-00 Shaw Tower, Singapore 189702

Tel: (65) 6250 7388 Ext.252 | Fax: (65) 6296 2706



Vic
德興摩哆私人有限公司
DE XING MOTOR PTE. LTD.

Blk 3006 Ubi Road 1 #01-356 Singapore 408700
Tel : (65) 67468582 (4 Lines) Fax : (65) 67439525
Email : dxmotor@singnet.com.sg
Website : www.dxmotor.com
Co. Reg. No.: 198303312R



DATE: 10/08/16

SATISFACTORY & DISCHARGE VOUCHER

I/ WE, HEREBY DECLARE THAT THE REPAIRS TO MY/OUR
MOTORCYCLE VEHICLE REGISTERED NUMBER: FBK 2914
HAVE BEEN COMPLETED TO MY/ OUR SATISFACTION AND I/ WE
AGREE THAT THE PAYMENT OF THE AMOUNT PAID TO **DE XING**
MOTOR PTE LTD, BLK 3006 UBI ROAD 1 #01-356 SINGAPORE
408700 FOR SUCH REPAIRS ARE IN FULL DISCHARGE OF OUR
CLAIM POLICY NUMBER: _____ IN
RESPECT OF THE DAMAGES CAUSED IN ACCIDENT WHICH
OCCURRED ON THE 25/07 / 2016 .



SIGNATURE OF INSURED

NAME:

NRIC NO:

Gagan arshad 10/8/16
S1526228N



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC16014069/R1hb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 05-11-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJC 7220B	Veh. Inspected	FBK 291U	
Policy No.	Z/15/VP00/095119	Coverage (\$)	0.00	
Claim No.	15/16/16/VP00/019056	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	28/07/2016	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA JUPITER MX	c.c	134	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MH250C006EK20206	Colour	BLACK	
Odometer	72685	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	90/80-17	PIRELLI	3 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	110/70-17	PIRELLI	3 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/07/2016	Inspection Date	02/08/2016	
Survey held at	DE XING MOTOR PTE LTD BLK 3006 UBI ROAD 1 #01-356 SINGAPORE 408700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 291U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER	CRACKED	95.00	95.00
1	REAR NO PLATE	BENT	18.00	18.00
2	REAR SIDE FARING @\$85.00	SERVICEABLE	170.00	-
1	REAR TAIL LAMP ASSY	SERVICEABLE	105.00	-
1	REAR SWING ARM	SERVICEABLE	295.00	-
1	REAR WHEEL SHAFT	SERVICEABLE	45.00	-
1	REAR SWING ARM	SERVICEABLE	350.00	-
2	REAR SWING BOLT @\$55.00	NOT NECESSARY	110.00	-
	LESS 10% DISCOUNT		-	-11.30
			1,188.00	101.70
	LABOUR			
	LABOUR.		380.00	280.00
	REAR FRAME BODY .		350.00	300.00
			730.00	580.00
	GRAND TOTAL		1,918.00	681.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			550.00

Report Ref No. CC4/LPC16014069/R1hb3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.