

Surveyor:

ASSIGNMENT

From: _____ Date: 16/09/2016

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKI 5371Z

at Workshop m/s SK Automobile

of 8 Kaki Bukit Ave 4 # 08-46

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: ~ 52K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Wp

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKES377Z Yr Regn: 2012, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Almera c.c 1498

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 119058 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MNTBBAN1720000024

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 16/09/16

Survey held at SK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AXA.

CLS \$5700/-

MV: 52000.00
LTA: 39419.00 (LTA)
NV:

(Net \$11682.39 / 67.22)

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/AXA16017401/Ayb3	
8 SHENTON WAY #27-01 SINGAPORE 068811			Date : 16-09-2016	
			Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 5541L		Veh. Inspected	SKE 5377Z
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	16/09/2016
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/09/2016		Inspection Date	16/09/2016
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: AXA	DATE	: 14-Sep-16
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	: <i>Benon</i>	VEHICLE NO	: <i>SKZ5377Z</i>
ADDRESS	:	MODEL	: NISSAN ALMERA
TEL. NO.	:	CHASSIS NO	: <i>MNTBBA11Z0000024</i>
OWNER'S INSURANCE :			
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>		DATE	:
		TIME	:
THIRD PARTY REQUESTOR / CONTACT : XIONG 8121 0478			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Dented</i>	1	\$ 589.00	\$ 589.00
2	BOOT LID TOP LOCK <i>Ryid</i>	1	\$ 147.90	\$ 147.90
3	BOOT LID OUTER MOULDING <i>new</i>	1	\$ 371.00	\$ 371.00
4	REAR BUMPER <i>Dislodged</i>	1	\$ 384.00	\$ 384.00
5	REAR BUMPER BRACKET <i>Dented</i>	2	\$ <i>91.7</i> 124.60	\$ <i>249.20</i> 183.40
6	TAIL LAMP PANEL <i>Dented</i>	2	\$ <i>127.10</i> 249.20	\$ <i>498.40</i> 394.20
7	TAIL LAMP <i>Cracked</i>	2	\$ 180.00	\$ 360.00
8	REAR FENDER LH <i>Ryid</i>	1	\$ 453.40	\$ 453.40
9	REAR DOOR INNER LOCK LH <i>new</i>	1	\$ 389.50	\$ 389.50
10	REAR END PANEL <i>Dislodged</i>	1	\$ 650.60	\$ 650.60
11	REAR END TOWING HOOK PANEL <i>new</i>	1	\$ 211.00	\$ 211.00
12	REAR FLOOR PANEL <i>Buckled</i>	1	\$ 1,497.90	\$ <i>1,497.90</i> 694
13	REAR CHASSIS EXTENSION MEMBER LH <i>Ryid</i>	1	\$ 665.00	\$ 665.00
14	REAR EXHAUST PIPE <i>Beats Ryid</i>	1	\$ 793.40	\$ 793.40
15	REAR EXHAUST CENTER PIPE <i>new</i>	1	\$ 845.00	\$ 845.00

3383.10
2368.17

TOTAL PRICE	\$ 8,105.30
LESS 30%	\$ 2,431.59
SUB TOTAL PRICE	\$ 5,673.71

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID LOGO <i>New</i>	1	\$ 53.20	\$ 53.20
2	BOOT LID INNER TRIM <i>Not new</i>	1	\$ 332.00	\$ 332.00
3	BOOT LID EMBLEM 'ALMERA' <i>New</i>	1	\$ 75.10	\$ 75.10
4	BOOT LID LOWER LOCK <i>Not new</i>	1	\$ 50.60	\$ 50.60
5	BOOT LID WEATHER STRIP <i>Not</i>	1	\$ 166.30	\$ 166.30
6	BOOT LID STOPPER <i>Not</i>	2	\$ 12.40	\$ 24.80
7	REAR BUMPER SIDE RETAINER <i>Not</i>	2	\$ 43.00	\$ 86.00
8	REAR BUMPER SIDE RETAINER (CONNER) <i>Not</i>	2	\$ 43.00	\$ 86.00
9	REAR BUMPER SPONGE <i>Not</i>	1	\$ 184.50	\$ 184.50
10	REAR FENDER INNER COWLING <i>Not</i>	2	\$ 182.90	\$ 365.80
11	REAR FENDER INNER TRIM <i>LH torn</i>	2	\$ 398.60	\$ 797.20
12	REAR FENDER AIR VENT <i>Not</i>	1	\$ 94.90	\$ 94.90
13	REAR WINDSCREEN MOULDING <i>Not</i>	1	\$ 198.80	\$ 198.80
14	REAR DOOR WEATHERSTRIP LH <i>Not</i>	1	\$ 145.00	\$ 145.00
15	REAR DOOR INNER TRIM <i>Not</i>	1	\$ 651.00	\$ 651.00
16	REAR END PANEL TOP GARNISH <i>Not</i>	1	\$ 144.10	\$ 144.10
17	REAR FLOOR PANEL BOARD <i>torn</i>	1	\$ 543.00	\$ 543.00
18	REAR SPARE TYRE BOLT <i>Not</i>	1	\$ 42.30	\$ 42.30
19	REAR EXHAUST INSULATOR <i>Not New</i>	1	\$ 235.20	\$ 235.20
20	REAR EXHAUST MOUNTING <i>Not</i>	2	\$ 34.70	\$ 69.40

15862

1477.58

TOTAL PRICE \$ 4,345.20
 LESS 10% \$ 434.52
 SUB TOTAL PRICE \$ 3,910.68

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Noted</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP <i>New</i>	10	\$ 6.50	\$ 65.00
4	BOOT LID SEALANT <i>Not</i>	1	\$ 80.00	\$ 80.00
6	BOOT LID INSULATOR CLIP <i>Not</i>	10	\$ 6.50	\$ 65.00
7	BOOT LID OUTER MOULDING <i>Not</i>	6	\$ 6.50	\$ 39.00
8	TAIL LAMP CLIP <i>Not</i>	4	\$ 8.00	\$ 32.00
9	TAIL LAMP PANEL SEALANT <i>Not</i>	2	\$ 80.00	\$ 160.00
10	REAR FENDER SEALANT LH <i>Not</i>	1	\$ 80.00	\$ 80.00
11	REAR FENDER COWLING CLIP <i>Not</i>	16	\$ 6.50	\$ 104.00
12	REAR FENDER INNER TRIM CLIPS <i>New</i>	18	\$ 6.50	\$ 117.00
13	REAR WINDSCREEN MOULDING SEALANT <i>Not</i>	1	\$ 80.00	\$ 80.00

14	REAR WINDSCREEN MOULDING INNER SEAL <i>me</i>	1	\$ 60.00	\$ 60.00	x
15	REAR END PANEL TOP GARNISH CLIPS <i>me</i>	4	\$ 6.50	\$ 26.00	10
16	REAR END PANEL SEALANT <i>me</i>	1	\$ 150.00	\$ 150.00	60
17	REAR FLOOR PANEL INSULATION SEAL <i>me</i>	1	\$ 250.00	\$ 250.00	50
19	REVERSE SENSOR <i>me</i>	1	\$ 220.00	\$ 220.00	-
20	REAR EXHAUST CHROME PIPE <i>bet</i>	1	\$ 180.00	\$ 180.00	100

582

TOTAL \$ 1,758.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	1200	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1200	
3	TUFF COAT	\$ 300.00	100	
4	WIRING CHECK	\$ 120.00	30	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 300.00	80	
6	REMOVE/REFIX REAR WINDSCREEN	\$ 120.00	x	
7	REMOVE/REFIX PETROL TANK	\$ 150.00	80	
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	40	
9	REAR CHASSIS ALIGNMENT	\$ 350.00	x	
10	TRANSFER BOOTLID MECHANISM	\$ 80.00	x	
11	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x	
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	100	
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	x	

TOTAL \$6,040.00

2830

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,342.39
TOTAL LABOUR COST : \$ 6,040.00
TOTAL REPAIR COST : \$ 17,382.39

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adnan Lij
16/09/16 ✓

09 Days

total 7207.75

4/5 5.7K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before and after painting
- To declare cost of repair and parts including
- Parts price and labour cost
- Third party liability and vehicle policies held
- No illegal modifications is allowed
- Supplementary items must be resurveyed and
is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO : AXA DATE : 14-Sep-16
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM

ESTIMATE REPORT :

OWNER'S PARTICULAR

NAME :

ADDRESS :

TEL NO. :

OWNER'S INSURANCE :

POLICY NO. :

ACCIDENT DETAILS

DATE :

TIME :

THIRD PARTY REQUESTOR / CONTACT : XIONG 8121 0478

VEHICLE DETAILS

VEHICLE NO : ^{SRE} ~~8KZ~~ 5377Z

MODEL : NISSAN ALMERA

CHASSIS NO : MNTBBA1720000224

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Dented</i>	1	\$ 589.00	\$ 589.00
2	BOOT LID TOP LOCK <i>Ryid</i>	1	\$ 147.90	\$ 147.90
3	BOOT LID OUTER MOULDING <i>new</i>	1	\$ 371.00	\$ 371.00
4	REAR BUMPER <i>Distorted</i>	1	\$ 384.00	\$ 384.00
5	REAR BUMPER BRACKET <i>Dented</i>	2	\$ 124.60	\$ 249.20
6	TAIL LAMP PANEL <i>Dented</i>	2	\$ 249.20	\$ 498.40
7	TAIL LAMP <i>Cracked</i>	2	\$ 180.00	\$ 360.00
8	REAR FENDER LH <i>Ryid</i>	1	\$ 453.40	\$ 453.40
9	REAR DOOR INNER LOCK LH <i>new</i>	1	\$ 389.50	\$ 389.50
10	REAR END PANEL <i>Distorted</i>	1	\$ 650.60	\$ 650.60
11	REAR END TOWING HOOK PANEL <i>new</i>	1	\$ 211.00	\$ 211.00
12	REAR FLOOR PANEL <i>Buckled</i>	1	\$ 1,497.90	\$ 1,497.90
13	REAR CHASSIS EXTENSION MEMBER LH <i>Ryid</i>	1	\$ 665.00	\$ 665.00
14	REAR EXHAUST PIPE <i>Best</i>	1	\$ 793.40	\$ 793.40
15	REAR EXHAUST CENTER PIPE ?	1	\$ 845.00	\$ 845.00

TOTAL PRICE \$ 8,105.30
LESS 30% \$ 2,431.59
SUB TOTAL PRICE \$ 5,673.71

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID LOGO <i>New</i>	1	\$ 53.20	\$ 53.20
2	BOOT LID INNER TRIM <i>New</i>	1	\$ 332.00	\$ 332.00
3	BOOT LID EMBLEM 'ALMERA' <i>New</i>	1	\$ 75.10	\$ 75.10
4	BOOT LID LOWER LOCK <i>New</i>	1	\$ 50.60	\$ 50.60
5	BOOT LID WEATHER STRIP <i>Kit</i>	1	\$ 166.30	\$ 166.30
6	BOOT LID STOPPER <i>New</i>	2	\$ 12.40	\$ 24.80
7	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 43.00	\$ 86.00
8	REAR BUMPER SIDE RETAINER (CONNER) <i>New</i>	2	\$ 43.00	\$ 86.00
9	REAR BUMPER SPONGE <i>cut d</i>	1	\$ 184.50	\$ 184.50
10	REAR FENDER INNER COWLING <i>New</i>	2	\$ 182.90	\$ 365.80
11	REAR FENDER INNER TRIM <i>LH torn</i>	2	\$ 398.60	\$ 797.20
12	REAR FENDER AIR VENT <i>New</i>	1	\$ 94.90	\$ 94.90
13	REAR WINDSCREEN MOULDING <i>New</i>	1	\$ 198.80	\$ 198.80
14	REAR DOOR WEATHERSTRIP LH <i>New</i>	1	\$ 145.00	\$ 145.00
15	REAR DOOR INNER TRIM <i>New</i>	1	\$ 651.00	\$ 651.00
16	REAR END PANEL TOP GARNISH <i>Replaced</i>	1	\$ 144.10	\$ 144.10
17	REAR FLOOR PANEL BOARD <i>torn</i>	1	\$ 543.00	\$ 543.00
18	REAR SPARE TYRE BOLT <i>Best</i>	1	\$ 42.30	\$ 42.30
19	REAR EXHAUST INSULATOR	1	\$ 235.20	\$ 235.20
20	REAR EXHAUST MOUNTING <i>New</i>	2	\$ 34.70	\$ 69.40

TOTAL PRICE \$ 4,345.20

LESS 10% \$ 434.52

SUB TOTAL PRICE \$ 3,910.68

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Replaced</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP <i>New</i>	10	\$ 6.50	\$ 65.00
4	BOOT LID SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00
6	BOOT LID INSULATOR CLIP <i>New</i>	10	\$ 6.50	\$ 65.00
7	BOOT LID OUTER MOULDING <i>New</i>	6	\$ 6.50	\$ 39.00
8	TAIL LAMP CLIP <i>New</i>	4	\$ 8.00	\$ 32.00
9	TAIL LAMP PANEL SEALANT <i>New</i>	2	\$ 80.00	\$ 160.00
10	REAR FENDER SEALANT LH <i>New</i>	1	\$ 80.00	\$ 80.00
11	REAR FENDER COWLING CLIP <i>New</i>	16	\$ 6.50	\$ 104.00
12	REAR FENDER INNER TRIM CLIPS <i>New</i>	18	\$ 6.50	\$ 117.00
13	REAR WINDSCREEN MOULDING SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00

14	REAR WINDSCREEN MOULDING INNER SEAL <i>m</i>	1	\$ 60.00	\$ 60.00	x
15	REAR END PANEL TOP GARNISH CLIPS <i>m</i>	4	\$ 6.50	\$ 26.00	10
16	REAR END PANEL SEALANT <i>m</i>	1	\$ 150.00	\$ 150.00	60
17	REAR FLOOR PANEL INSULATION SEAL <i>m</i>	1	\$ 250.00	\$ 250.00	50
19	REVERSE SENSOR <i>Bcd</i>	1	\$ 220.00	\$ 220.00	-
20	REAR EXHAUST CHROME PIPE <i>bet</i>	1	\$ 180.00	\$ 180.00	100

TOTAL \$ 1,758.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	1200	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1200	
3	TUFF COAT	\$ 300.00	100	
4	WIRING CHECK	\$ 120.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 300.00	80	
6	REMOVE/REFIX REAR WINDSCREEN	\$ 120.00	x	
7	REMOVE/REFIX PETROL TANK	\$ 150.00	80	
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	40	
9	REAR CHASSIS ALIGNMENT	\$ 350.00	x	
10	TRANFER BOOTLID MECHANISM	\$ 80.00	x	
11	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x	
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	100	
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	x	

TOTAL \$6,040.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,342.39
TOTAL LABOUR COST : \$ 6,040.00
TOTAL REPAIR COST : \$ 17,382.39

851376
805.18
9716.44

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adnan Lij
16/09/16 ↓

09 ays

View Sent Message

This mail is associated with :

*SKE5377Z (C0399830)
[SHC5541L]

TP

CHUA LYE CHOON

Sep 13 2016 10:00PM

[TRANS-CAB SERVICES PTE LTD]

Sk Automobile Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 11/05/2018 08:19 AM.
To AXA_SG; sawtheng.khor@axa.com.sg
CC sur@lkkauto.com; assignments@lkkauto.com; bevanlim@lkkauto.com; vicalpeh@lkkauto.com; admin-a@lkkauto.com
Subject Re: C0399830 STATUS OF CLAIM

Dear Sir/Madam,

We refer to your email below.

We are preparing our report for mandate request.

We will revert with our report for mandate soonest.

thank you.

BEVAN LIM
LKK AUTO CONSULTANTS PTE LTD

<-- Original Message -->

From: AXA_SG
To: LKK_HQ; AXA_SG
CC: sur@lkkauto.com; assignments@lkkauto.com
Sent On: 10/05/2018 03:09 PM
Subject: Re: C0399830 STATUS OF CLAIM

hi,

please update status of the claim.

Regards'

<-- Original Message -->

From: AXA_SG
To: LKK_HQ
CC: AXA_SG; sur@lkkauto.com; assignments@lkkauto.com
Sent On: 25/09/2017 05:40 PM
Subject: C0399830 STATUS OF CLAIM



Dear LKK

Please advise on the status of this matter.

Regards

Saw Theng

LKK INSURANCE PTE LTD
4 Maxwell Way, #04-01 MAX Tower
Singapore 069112
Incorporated in Singapore
☎ +65 6346 8888
☎ +65 6328 2527
✉ www.lkk.com.sg
GST Reg No.: 2000010128
Co. Reg No.: 2009010128

DOCUMENTS SUMMARY

There are no documents.

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 7696H

Vehicle Details

Vehicle No.: SKE5377Z

Vehicle to be Exported: Yes

Intended De-registration Date: 15 Sep 2016

Vehicle Make: NISSAN

Vehicle Model: ALMERA 1.5 4AT ABS AIRBAG 2WD 4DR CMFT

Primary Colour: Silver

*Manufacturing Year: 2012

Engine No.: HR15912372B

Chassis No.: MNTBBAN17Z0000024

Maximum Power Output: 73.0 kW (97 bhp)

Open Market Value: \$14,244.00

Original Registration Date: 12 Mar 2012

First Registration Date: 12 Mar 2012

Transfer Count: 0

Actual ARF Paid: \$14,244.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 11 Mar 2022

PARF Rebate Amount: \$10,683.00

Intended COE Rebate Details

COE Expiry Date: 11 Mar 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$52,392.00

COE Rebate Amount: \$28,738.00

Total Rebate Amount: \$39,419.00

The information contained herein is correct as at 15 Sep 2016

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 8.0 SP3 and above, 1024 X 768 resolution

Copyright © 2016 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

DOA: 13/9/16

left 66 months.

≈ \$840 / yr = \$70 / month.

$$\begin{array}{r}
 70 \times 66 = 46200 \\
 + \\
 7122 \\
 \hline
 \approx 53322.0
 \end{array}$$

7122



NEW Adidas Neo Slip On
Over 50% Discount
Ship direct from U.S.A

51% OFF

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

14 Sep 2011 Porsche Panamera 3.6A PDK @ \$118,800!



High Offer/Trade-in Mid Year
Sale! Ends 15 July! A Stuttgart
Auto (Agent Unit)
Cars & Yachts [StarAd](#)



Browse by Category

Sort by Date Posted 20 results/page

1 vehicles

Nissan Almera

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Nissan Almera		Any	Any	2012	Any	Any	Any	Available
	Nissan Almera 1.5A		\$29,800	\$8,460 /yr	25-Feb-2012	1,498 cc	120,643 km	Sedan	Available
New Arrival! Fuel Efficient Sedan! Selling Cheap! Excellent Condition! Very Well Maintained! Low Mileage Unit! Call For A Viewing Appointment Today!									
Mayfair Motoring									
Posted: 17-Jun-2019 Tags: 2012 Nissan Almera, 2012 nissan almera, Nissan Almera, nissan almera, Nissan, Almera, almera, Used Nissan									

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
--	------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view **Expired ads**

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Nissan, Nissan Singapore, used Nissan Singapore, used Nissan, used vehicles Singapore or even buy used Nissan Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare

Print Sent Message

This mail is associated with :

***SKE5377Z (C0399830)**
[SHC5541L]

TP
CHUA LYE CHOON
Sep 13 2016 10:00PM
[TRANS-CAB SERVICES PTE LTD]
Sk Automobile Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 22/06/2019 12:13 PM.
To sashe.goms@axa.com.sg
CC AXA_SG; chewht@lkkauto.com; admin-a@lkkauto.com
Subject <Seek Mandate> C0399830

Dear Sirs/Mdm,

We refer to the above matter.

Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue.

We seek your mandate at \$7,099.00(all-in).

TP-Mandate IA had been uploaded in Merimen.

Kindly let us have your approval/instruction.

Hsiao Tong



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVENUE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 22/06/2019

Survey Details:

Date of loss	13.09.2016
Date of appointment	15.09.2016
Date of survey	16.09.2016
Location of survey	SK AUTOMOBILE PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKE5377Z
Make and Model	Nissan Almera
Date of registration	12.02.2012
Excess	
Market Value/ Book Value	\$ 52,000.00 (est)
Part/COE Rebate	\$ 39,419.00 (est)
Nett Value/ ERV	\$ 12,581.00 (est)

Repair details:

Initial Estimate	\$ 17,382.39
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 4,377.75
Check items (estimate)	NIL
Labour	\$ 2,830.00
Supplementary	NIL
Total	\$ 7,207.75
Lump Sum(if applicable)	\$ 5,700.00

Number of days for repair	<u>9</u>
---------------------------	----------



Auto
Consultants
Pte Ltd.

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 6,099.00	
Loss of use)	NIL	
Loss of rental	\$ 1,000.00	(10days x \$100.00)
Loss of income	NIL	
LTA/GIA search fees	NIL	
Others (Audatex Fee)	NIL	
Proposed Total	\$ 7,099.00	

Print Received Message

This mail is associated with :

*SKE5377Z (C0399830)
[SHC5541L]
TP
CHUA LYE CHOON
Sep 13 2016 10:00PM
[TRANS-CAB SERVICES PTE LTD]
Sk Automobile Pte Ltd

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 24/06/2019 09:18 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6900.00) - SKE5377Z - Claim Handler: Vale Oh

Approved:6900.00:Please offer up to \$6,900/-(all-in). Thank you.

Hsiao Tong (LKKAUTO)

From: SK Admin <admin@skauto.com.sg>
Sent: Wednesday, 26 June 2019 12:01 PM
To: Hsiao Tong (LKKAUTO)
Cc: simon koh; Julie Johari; Tyson Koh; KY Leong; Admin A
Subject: Re: Accident involving SKE5377Z & SHC5541L On 13/09/2016 *LKK REF: CC4/AXA16017401/Apb3

Dear Hsiao Tong,

Thanks for your reply.

We confirmed accept your offer @ S\$6,900.00(all in)

Kindly forward us your Discharge Voucher

Regards,
Huey Lee
SK Automobile Pte Ltd

On Wed, Jun 26, 2019 at 8:58 AM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer at a global sum of \$6,900.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: SK Admin <admin@skauto.com.sg>

Sent: Saturday, 22 June 2019 10:45 AM

To: pohkim@lkkauto.com; Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: simon koh <simon@skauto.com.sg>; Julie Johari <julie@skauto.com.sg>; Tyson Koh

<tysonkoh@skauto.com.sg>; KY Leong <kyleong@skauto.com.sg>

Subject: Re: Accident involving SKE5377Z & SHC5541L On 13/09/2016

Dear Hsiao Thing,

Pls see attached .

Thank you

Regards,

Huey Lee

SK Automobile Pte Ltd

On Wed, Oct 24, 2018 at 6:11 PM SK Admin <admin@skauto.com.sg> wrote:

Dear Poh Kim,

Kindly assist us to update the claim status.

Pls check & revert to us soon.

Thanks for your kind attention.

Regards,

Huey Lee

SK Automobile Pte Ltd

----- Forwarded message -----

From: **SK Admin** <admin@skauto.com.sg>

Date: Wed, Oct 24, 2018 at 6:08 PM

Subject: Re: Accident involving SKE5377Z & SHC5541L On 13/09/2016

To: "Bevan Lim (LKK Auto)" <bevanlim@lkkauto.com>, Admin A <admin-a@lkkauto.com>

Cc: simon koh <simon@skauto.com.sg>, Julie Johari <julie@skauto.com.sg>, KY Leong <kyleong@skauto.com.sg>

Dear Bevan,

We would like to check with you the claim status.

Kindly assist to update us the offer.

Thank you

Regards,

Huey Lee

SK Automobile Pte Ltd

On Mon, Apr 30, 2018 at 4:35 PM, SK Admin <admin@skauto.com.sg> wrote:

Dear Bevan,

Enclosed the final bill and relevant documents for your perusal.
Kindly refer to attachment and revert back to us the soonest.

Breakdown as below:

Cost of repair : S\$ 6,099.00 (incl' GST 7%)

Loss of rental : S\$ 1,400.00 (10 days @ S\$140.00)

Total : S\$ 7,499.00

If acceptable, kindly forward us your discharge voucher for us to enable our client to complete and sign.

We appreciate your early reply .

Thanks

--

Regards,

Huey Lee

SK Automobile Pte Ltd

Tel: 6789 5155 Fax: 6783 5155

SK Automobile Pte Ltd

23 Kaki Bukit Ave 4 #03-01
Vicom Inspection Centre (South Wing) S(415933)
Tel: +65 6789 5155 Fax: +65 6783 5155
Co. Reg No.201500047H GST Reg No. 201500047H

Your Ref: SHC 5541 L

To: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Thru: LKK Auto Consultants Pte Ltd

Attn: Motor Claims Dept

Dear Sir/Mdm,

RE: THIRD PARTY CLAIM FOR VEHICLE SKE5377Z & SHC5541L on 13/09/2016

We refer to the above matter.

Attached copies of the following for your perusal:

- 1) Tax Invoice No. IV18-80134 (S\$6,099.00)
- 2) Loss of Rental days 10 @ S\$140.00 (S\$1,400.00) Invoice & Rental Agreement
- 3) Authorization To Act

Please look into the above claim and let us have your payment of S\$7,499.00 soonest.

Thank You.

Yours faithfully,



Huey Lee

E-mail: admin@skauto.com.sg

From: Jas Khine (LKKAUTO)
Sent: Tuesday, 24 January, 2017 3:22 PM
To: claims@transcab.com.sg
Cc: CS A Team; 'carrisalee@ava-ins.com'; 'icewong@ava-ins.com'; 'ireneng@ava-ins.com'; 'foonghon@ava-ins.com'
Subject: ACCIDENT INVOLVING SHC 5541L & SKE 5377Z ALONG/AT JURONG WEST ST 92 T-X JURONG WEST ST 91 ON 13/09/2016

24 January 2016

Transcab Taxi
Singapore

Dear Sir/Mdm,

OUR REF : CC4/AXA16017401/Ayb3
YOUR REF : SHC 5541L

ACCIDENT INVOLVING SHC 5541L & SKE 5377Z ALONG/AT JURONG WEST ST 92 T-X JURONG WEST ST 91 ON 13/09/2016

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **SK Automobile Pte Ltd** acting on behalf of the owner **SKE 5377Z** against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties (front-to-rear collision) where you/your driver had hit third-party vehicle from the rear, we are of the opinion that we cannot be absolved from liability.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

There is an excess of S\$ 5,000.00 on Third Party claims under your policy. Please make a cheque payment of S\$ 5,000.00 payable to "AXA Insurance Pte Ltd" with your vehicle registration number and the date of accident indicated on the back of your cheque and mail to AXA Insurance Pte Ltd.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by AXA for the above subject matter, AXA expressly reserves all their rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter/email. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to jaskhine@lkkauto.com within 10 days from the date of this letter/email **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA's Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2928 or email us at jaskhine@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Thank you.

"Wishes you a Merry Christmas & Happy New Year 2017"

Best Regards,

Jas Khine | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This is a computer generated letter and no signature is required.

Cc Motor Claims Department
AXA Insurance Pte Ltd


AUTHORISATION TO ACT

I/We, Chua Lye Choon (the third party claimant) of Blk 852 Jurong West St 91
02-315 S (G40852) (address), owner of SKE 53772 (vehicle no.) hereby
authorize SE Automobile Pte Ltd ("the workshop") to act for me with respect
to my claim for repair costs and/or rental loss of use ("claim") for my vehicle no.
SKE 53772 that was damaged pursuant to the accident which occurred on 13/09/16 (date)
along Junction Jurong West St 91 & 92 (location) involving
vehicle no/s SHC 5541 L ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they
deem fit and the workshop is further authorized to received payment further to settlement of my
claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability basis insofar as the driver / owner / insurers
of the other vehicle/s is concerned.

Dated this 20 (day) of SEP (month) 20 16 (year)



Signed by "the third party claimant"

(with company stamp if applicable)



Signed by "the workshop"

(with company stamp)



Provided always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect my further claim for general and special damages for my personal injuries sustained in the same accident.

AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SHC 5541L (Insd veh)	Model: Nissan Almera (1498cc)
	SKE 5377Z (TP veh)	
Date of Accident/ Time:	13/09/2018	

Repair Estimate	: \$	18,599.16	
Final Repair Cost	: \$		
Loss of Use	: \$		days at \$ per day
Rental (if any)	: \$		days at \$ per day
LTB / GIA Search Fee	: \$		
Others:	: \$		
	: \$		
Final Settlement Sum (Global Sum)	: \$	6,900.00	

Payee Name : SK AUTOMOBILE PTE LTD

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability 100 (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks:		

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp
Name of Representative: Hui Lee
Date: 26/06/19

Signature of Witness / Workshop stamp (if applicable)
Name of Witness: KOH Tyson
Date:

Signature of AXA's surveyor/representative
Name of AXA's surveyor /Representative:
Date:

SK AUTOMOBILE PTE LTD

23 Kaki Bukit Ave 4 #03-01
Vicom Inspection Centre (South Wing) S415933
Phone +65 6789-5155 Fax +65 6783-5155
CO Reg No. 201500047H GST Reg No. 201500047H

TAX INVOICE

DATE: 30-Apr-18
INVOICE # IV18-80134
VEH REG NO: SKE 5377 Z

Bill To:
AXA INSURANCE SINGAPORE PTE LTD

DESCRIPTION	AMOUNT
Being cost of repair inclusive of labour charges, parts and accessories for the abovementioned vehicle.	\$ 5,700.00
Sub.Total	\$ 5,700.00
7% GST	\$ 399.00
Total	\$ 6,099.00

Make all cheques payable to "SK AUTOMOBILE PTE LTD"

THANK YOU FOR YOUR BUSINESS!



CARS FOR RENT (2016) PTE LTD

5 TANAH MERAH KECHIL ROAD
#17-05 SINGAPORE 466665
TEL: 6789 5155 FAX: 6783 5155

INVOICE**Invoice To:****CHUA LYE CHOON**

BLK 852 JURONG WEST ST 81
#02-315 SINGAPORE 640852

DATE	INVOICE #
26/09/2016	VII50052

VEH REG NO	TERMS
SKE5377Z	DUE ON RECPT

	DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
	CAR RENTAL FROM 14/09/16 TO 24/09/16	10	\$140.00	\$1,400.00
			TOTAL	\$1,400.00



CARS FOR RENT (2016) PTE LTD



5 Tanah Merah Kechil Road #17-05 S 46885
Tel: 6780 5155 Fax: 67835155

No: 1443

ROC No: 201609732N

VEHICLE RENTAL AGREEMENT

SK53772 SK4/0P/L


HIRER'S PARTICULAR Name: (as in VC) <u>Chua Lye Choon</u> NRIC/PASSPORT No: <u>S6847696H</u> Address (Res): <u>Blk 852 Serangoon West St 8/ #02-315</u> <u>S(640852)</u> Name & Address of Employer: _____ Occupation: _____ Driving Exp: <u>24/12/2015</u> Driving Licence No: _____ D/L Type: Local / International Issue Date: _____ Date of Birth: <u>27/12/1968</u> Tel: (C) _____ (F) _____ HP/PG <u>9003 5903</u>		Vehicle No: <u>SJB3753L</u> Replace Veh No: _____ Mileage Out: _____ Mileage In: _____ Make & Model: <u>TOYOTA AXIO</u> Auto / Manual Group: _____ OUT : Date <u>14/09/16</u> Time: <u>15:10 hrs</u> HIRE/PERIOD EXPIRY: _____ COLLISION DAMAGE WAIVER Excess <u>3000/-</u> YES / NO PERSONAL ACCIDENT INSURANCE YES / NO																																														
ADDITIONAL DRIVER'S PARTICULARS Name: (as in VC) _____ NRIC/PASSPORT No: _____ Address (Res): _____ Driving Licence No: _____ D/L Type: Local / International Issue Date: _____ Date of Birth: _____ Occupation: _____ Driving Exp: _____		CHARGES <table border="1"> <tr> <td>Daily</td> <td>10 @</td> <td>140.00 per day</td> <td>1400</td> <td>00</td> </tr> <tr> <td>Weekly</td> <td>@</td> <td>per week</td> <td></td> <td></td> </tr> <tr> <td>Monthly</td> <td>@</td> <td>per month</td> <td></td> <td></td> </tr> <tr> <td>Hours</td> <td>@</td> <td>per hour</td> <td></td> <td></td> </tr> <tr> <td>Others</td> <td>@</td> <td></td> <td></td> <td></td> </tr> <tr> <td>CDW</td> <td>@</td> <td>per day/month</td> <td></td> <td></td> </tr> <tr> <td>PAI</td> <td>@</td> <td>per day/month</td> <td></td> <td></td> </tr> <tr> <td>Delivery Service</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="3">SUB-TOTAL \$</td> <td>1400</td> <td>00</td> </tr> </table>		Daily	10 @	140.00 per day	1400	00	Weekly	@	per week			Monthly	@	per month			Hours	@	per hour			Others	@				CDW	@	per day/month			PAI	@	per day/month			Delivery Service					SUB-TOTAL \$			1400	00
Daily	10 @	140.00 per day	1400	00																																												
Weekly	@	per week																																														
Monthly	@	per month																																														
Hours	@	per hour																																														
Others	@																																															
CDW	@	per day/month																																														
PAI	@	per day/month																																														
Delivery Service																																																
SUB-TOTAL \$			1400	00																																												
VEHICLE CHECK LIST D - DENTS S - SCRATCHES A - ACCIDENTS RIGHT FRONT TOP LEFT 		PETROL LEVEL <table border="1"> <tr> <td>Out</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td>3/4</td> <td>F</td> </tr> <tr> <td>In</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td>3/4</td> <td>F</td> </tr> </table> EXTENSION Collection Service _____ Misc. _____ TOTAL CHARGES \$ _____		Out	E	1/4	1/2	3/4	F	In	E	1/4	1/2	3/4	F																																	
Out	E	1/4	1/2	3/4	F																																											
In	E	1/4	1/2	3/4	F																																											
ACCESSORIES CHECK <input type="checkbox"/> Ashtray <input type="checkbox"/> Cig Lighter <input type="checkbox"/> S/Tyre <input type="checkbox"/> STD Tools <input type="checkbox"/> Jack <input type="checkbox"/> Hub Caps <input type="checkbox"/> Radio / Cass <input type="checkbox"/> CD <input type="checkbox"/> Cartridges		Rented out by: _____ Hirer's Signature  Addition Driver's Signature _____																																														

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/ credit card for payment, I agree that all amount payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given CARS FOR RENT (2016) PTE LTD in connection with this agreement is true.

* IMPORTANT

- ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND FOR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY CARS FOR RENT (2016) PTE LTD

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO CARS FOR RENT (2016) PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
24/9/16	10:30am				

...CLAIM SUBFOLDER...(Pending for Survey Report)

Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Sep 2016		15 Sep 2016 15:57 Edit Adj Rpt	\$55,700.00 Edit Estimates	\$55,700.00 View Rpt		Pending for Survey Report Cancel Case





























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TRANS-CAB SERVICES PTE LTD, ID: -								
Main Claimant:	CHUA LYE CHOON, ID: S6847696H								
Vehicle Reg. No.:	SKE5377Z	Date of Loss:	13/09/2016 22:00 - :59 [54 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0399830	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	SHC5541L	Policy No. (Claimant):	10473254						
		Excess:	\$45,000.00						
Repairer:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by SASHE Go Mui Sang]								
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/09/2016]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (24/06/2019): Alert - Adj Mandate Approved (\$6900.00) - SKE5377Z - Claim Handler: Vale Oh AXA_SG (27/03/2019): REMINDER ON ADVISING STATUS-VO AXA_SG (29/01/2019): FILE REVIEW - PLS ADVISE STATUS-VO AXA_SG (10/05/2018): Re: C0399830 STATUS OF CLAIM AXA_SG (25/09/2017): C0399830 STATUS OF CLAIM AXA_SG (11/01/2017): TP settlement - C0399830/P1680520 AXA_SG (14/12/2016): RE: Direct Settlement - Accident Involving SHC5541L (OI: AXA - C0399830) and SK... AXA_SG (15/09/2016): WP / New TP Assignment - C0399830/P1680520 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKE5377Z (C0399830)
[SHC5541L]
TP
CHUA LYE CHOON
Sep 13 2016 10:00PM
[TRANS-CAB SERVICES PTE LTD]
SK Automobile Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	AXA Insurance Pte Ltd (HQ)													Thumbnail			Print		
1	14/12/16 22:21	Accident Statement From: SC - Reg. No: SHC5541L, Claimant: TRANS-CAB SERVICES PTE LTD																Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	16/12/16 10:42	Adjuster Immediate Advice																Load HTM		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
2	08/12/17 11:38	Chassis Number																Load JPG <input checked="" type="checkbox"/>		
3	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
4	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
5	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
6	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
7	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
8	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
9	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
10	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
11	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
12	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
13	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
14	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
15	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
16	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
17	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
18	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
19	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
20	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
21	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
22	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
23	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
24	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
25	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
26	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
27	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
28	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
29	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
30	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
31	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		
32	08/12/17 11:38	General View																Load JPG <input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
34	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
35	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
36	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
37	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
38	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
39	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
40	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
41	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
42	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
43	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
44	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
45	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
46	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
47	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
48	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
49	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
50	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
51	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
52	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
53	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
54	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
55	08/12/17 11:38	General View		<input checked="" type="checkbox"/>
56	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
57	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
58	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
59	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
60	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
61	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
62	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
63	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
64	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
65	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
66	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
67	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
68	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
69	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
70	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
71	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
72	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
73	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
74	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
75	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
76	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
77	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
78	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
79	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
80	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>
81	08/12/17 11:38	Reinspection Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
82	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	08/12/17 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	15/09/16 12:06	EMAIL_ABS	 Load PDF	
2	15/09/16 12:06	CO-CLAIMANT_ABS	 Load PDF	
3	15/09/16 12:06	SKE53772 TP GIA REPORT_ABS	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/12/16 11:41	TP ESTIMATE- MARKED	 Load PDF	
2	05/06/18 13:52	RENTAL RECEIPT	 Load PDF	
3	05/06/18 13:52	LETTER TO OI	 Load PDF	
4	22/06/19 12:08	PARF_COE REBATE	 Load PDF	
5	22/06/19 12:08	LKK Survey Photos	 Load PDF	
6	22/06/19 12:08	LKK Resurvey Photos	 Load PDF	
7	10/07/19 09:22	WORKSHOP INVOICE	 Load PDF	
8	10/07/19 09:22	AUTHORISATION TO ACT FORM	 Load PDF	
9	10/07/19 09:22	PAYMENT BREAKDOWN_EXPRESS SETTLEMENT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer. <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16017401/APB3Q2

Date: 10/07/2019

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No: P1680520

Claimant Vehicle No : SKE5377Z

Insured Vehicle No : SHC5541L

Date of Loss: 13/08/2016

Nature of Claim: TP

Claim No: C0399830

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKE5377Z

Make & Model: NISSAN ALMERA, 1.5 (A)

Reg. Date: 01/03/2012 (Man. Year: 2012)

Colour: Silver

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: HIDDEN

Chassis No: MNTBBAN1720000024

Odometer: 119058 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,342.39	4,377.75	6,964.64	61.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,040.00	2,830.00	3,210.00	53.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,382.39	7,207.75	10,174.64	58.53
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	17,382.39	5,700.00	11,682.39	67.21
+ GST 7.00/7.00% (S\$)	1,216.77	399.00	817.77	67.21
Nett Amount (S\$)	18,599.16	6,099.00	12,500.16	67.21
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
Nett Liability (S\$)		7,099.00		
Global Sum Settlement (S\$)		6,900.00		

INSPECTION

Date of Assignment: 15/09/2016

Date Inspected: 16/09/2016 Inspected At:

Sk Automobile Pte Ltd
8 Kaki Bukit Ave 4, #08-46 Premier @ Kaki

Bukit
Singapore 415875

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2018)
Parts: 143	NISSAN ALMERA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKE5377Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID (CONSISTENT)	Dented	589.00 FL	*589.00 FL
2	1		*BOOT LID TOP LOCK (CONSISTENT)	Damaged	147.90 FL	*147.90 FL
3	1		*BOOT LID OUTER MOULDING (CONSISTENT)	Not Necessary	371.00 FL	*- FL
4	1		*REAR BUMPER (CONSISTENT)	Distorted	384.00 FL	*384.00 FL
5	2		*REAR BUMPER BRACKET (CONSISTENT)	Dented	249.20 FL	*183.40 FL
6	2		*TAIL LAMP PANEL (CONSISTENT)	Dented	498.40 FL	*374.20 FL
7	2		*TAIL LAMP (CONSISTENT)	Cracked	360.00 FL	*360.00 FL
8	1		*REAR FENDER LH (CONSISTENT)	Repair	453.40 FL	*- FL
9	1		*REAR DOOR INNER LOCK LH (CONSISTENT)	Not Necessary	389.50 FL	*- FL
10	1		*REAR END PANEL (CONSISTENT)	Distorted	650.60 FL	*650.60 FL
11	1		*REAR END TOWING HOOK PANEL (CONSISTENT)	Not Necessary	211.00 FL	*- FL
12	1		*REAR FLOOR PANEL (CONSISTENT)	Buckled	1,497.90 FL	*694.00 FL
13	1		*REAR CHASSIS EXTENSION MEMBER LH (CONSISTENT)	Repair	665.00 FL	*- FL
14	1		*REAR EXHAUST PIPE (CONSISTENT)	Repair	793.40 FL	*- FL
15	1		*REAR EXHAUST CENTER PIPE (CONSISTENT)	Not Necessary	845.00 FL	*- FL
16	1		*BOOT LID LOGO (CONSISTENT)	Necessary	53.20 FN	*53.20 FN
17	1		*BOOT LID INNER TRIM (CONSISTENT)	Not Necessary	332.00 FN	*- FN
18	1		*BOOT LID EMBLEM ALMERA(CONSISTENT)	Necessary	75.10 FN	*75.10 FN
19	1		*BOOT LID LOWER LOCK (CONSISTENT)	Not Necessary	50.60 FN	*- FN
20	1		*BOOT LID WEATHER STRIP (CONSISTENT)	Cut	166.30 FN	*166.30 FN
21	2		*BOOT LID STOPPER (CONSISTENT)	Necessary	24.80 FN	*24.80 FN
22	2		*REAR BUMPER SIDE RETAINER (CONSISTENT)	Necessary	86.00 FN	*86.00 FN
23	2		*REAR BUMPER SIDE RETAINER (CONNER) (CONSISTENT)	Not Necessary	86.00 FN	*- FN
24	1		*REAR BUMPER SPONGE (CONSISTENT)	Cracked	184.50 FN	*133.80 FN
25	2		*REAR FENDER INNER COWLING (CONSISTENT)	Not Necessary	365.80 FN	*- FN
26	1		*REAR FENDER INNER TRIM (CONSISTENT)	N/S Torn	797.20 FN	*365.20 FN
27	1		*REAR FENDER AIR VENT (CONSISTENT)	Not Necessary	94.90 FN	*- FN
28	1		*REAR WINDSCREEN MOULDING (CONSISTENT)	Not Necessary	198.80 FN	*- FN
29	1		*REAR DOOR WEATHERSTRIP LH (CONSISTENT)	Not Necessary	145.00 FN	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
30	1		*REAR DOOR INNER TRIM (CONSISTENT)	Not Necessary	651.00 FN	*- FN
31	1		*REAR END PANEL TOP GARNISH (CONSISTENT)	Deformed	144.10 FN	*144.10 FN
32	1		*REAR FLOOR PANEL BOARD (CONSISTENT)	Torn	543.00 FN	*495.40 FN
33	1		*REAR SPARE TYRE BOLT (CONSISTENT)	Bent	42.30 FN	*42.30 FN
34	1		*REAR EXHAUST INSULATOR (CONSISTENT)	Not Necessary	235.20 FN	*- FN
35	2		*REAR EXHAUST MOUNTING (CONSISTENT)	Not Necessary	69.40 FN	*- FN
36	1		*REAR NUMBER PLATE (CONSISTENT)	Dented	50.00 FS	*50.00 FS
37	10		*REAR BUMPER CLIP (CONSISTENT)	Necessary	65.00 FS	*30.00 FS
38	1		*BOOT LID SEALANT (CONSISTENT)	Not Necessary	80.00 FS	*- FS
39	10		*BOOT LID INSULATOR CLIP (CONSISTENT)	Not Necessary	65.00 FS	*- FS
40	6		*BOOT LID OUTER MOULDING (CONSISTENT)	Not Necessary	39.00 FS	*- FS
41	4		*TAIL LAMP CLIP (CONSISTENT)	Necessary	32.00 FS	*32.00 FS
42	2		*TAIL LAMP PANEL SEALANT (CONSISTENT)	Not Necessary	160.00 FS	*- FS
43	1		*REAR FENDER SEALANT LH (CONSISTENT)	Not Necessary	80.00 FS	*- FS
44	16		*REAR FENDER COWLING CLIP (CONSISTENT)	Not Necessary	104.00 FS	*- FS
45	1		*REAR FENDER INNER TRIM CLIPS (CONSISTENT) (18 PCS)	Necessary	117.00 FS	*30.00 FS
46	1		*REAR WINDSCREEN MOULDING SEALANT (CONSISTENT)	Not Necessary	80.00 FS	*- FS
47	1		*REAR WINDSCREEN MOULDING INNER SEAL (CONSISTENT)	Not Necessary	60.00 FS	*- FS
48	4		*REAR END PANEL TOP GARNISH CLIPS (CONSISTENT)	Necessary	26.00 FS	*10.00 FS
49	1		*REAR END PANEL SEALANT (CONSISTENT)	Necessary	150.00 FS	*60.00 FS
50	1		*REAR FLOOR PANEL INSULATION SEAL (CONSISTENT)	Necessary	250.00 FS	*50.00 FS
51	1		*REVERSE SENSOR (CONSISTENT)	Damaged	220.00 FS	*220.00 FS
52	1		*REAR EXHAUST CHROME PIPE (CONSISTENT)	Bent	180.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	14,208.50	5,551.30
- List Item Discount on L Items 30.00/30.00% (S\$)	2,431.59	1,014.93
- Nett Item Discount on N Items 10.00/10.00% (S\$)	434.52	158.62

Total Parts (S\$)	11,342.39	4,377.75
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,200.00	1,200.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,200.00
3	TUFF COAT	New	300.00	100.00
4	WIRING CHECK	New	120.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	300.00	80.00
6	REMOVE/REFIX REAR WINDSCREEN	New	120.00	0.00
7	REMOVE/REFIX PETROL TANK	New	150.00	80.00
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	40.00
9	REAR CHASSIS ALIGNMENT	New	350.00	0.00
10	TRANFER BOOTLID MECHANISM	New	80.00	0.00
11	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
12	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	100.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	280.00	0.00
Gross Labour Cost (S\$)			6,040.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >