

SERVICE ESTIMATE

84168 - C00001 SL: SERVICE SALES - PC

Mr Lim Yung Feng
Blk 789 Choa Chu Kang North 6
#12-226

Singapore 680789

Closed by : Keion Toh
Svc Consultant :
Remarks : Mr Lim Yung Feng

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 6
Inv.date. : 19/09/2016
WIP No. . : 13445
Veh.In/Out:
*Tel.No. . : Mobile: 81020883
Reg.No. . : SKE1101D
Reg.date. : 11/12/2014
Mileage . : 0
Chassis No: JN1BCAV37Z0450004

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount
-------	-------------	----------	-------	-------	-----	--------

LAMP ASSY-LH

1.0 EA 3851.50 2675.76 3,851.50

CLIP

1.0 EA 50.40 40.32 ✓ 50.40

CLIP

1.0 EA 50.40 40.32 ✓ 50.40

CONDENSER

1.0 EA 1224.20 1,224.20 ? x sue

AIR GUIDE

1.0 EA 33.60 26.78 ✓ 33.60

SEAL-CONDENSER,

1.0 EA 49.30 39.44 ✓ 49.30

AIR GUIDE

1.0 EA 67.20 53.78 ✓ 67.20

TOP PANEL

1.0 EA 678.40 471.28 ✓ 678.40

SUPPORT-RADIATO

1.0 EA 50.40 40.32 ✓ 50.40

SUPPORT-RADIATO

1.0 EA 50.40 40.32 ✓ 50.40

RET-FR BUMPER

1.0 EA 93.90 75.12 ✓ 93.90

BRACE ASSY-R/CO

1.0 EA 110.40 88.32 ✓ 110.40

BODY PANEL SEALANT X

1.0 EA 755.50 358.24 X 755.50

ADHESIVE SEALER FL2

1.0 EA 359.50 359.50

D WELDING PRIMER

1.0 EA 127.50 127.50

FIN-FR FASCIA

1.0 EA 77.10 X 77.10 ?

FINISHER-FR,LH

1.0 EA 77.10 X 77.10 ?

SERVICE ESTIMATE

84168 - C00001 SL: SERVICE SALES - PC
 Mr Lim Yung Feng
 Blk 789 Choa Chu Kang North 6
 #12-226

Singapore 680789

Closed by : Keion Toh
 Svc Consultant :
 Remarks : Mr Lim Yung Feng

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 7
 Inv.date. : 19/09/2016
 WIP No. . : 13445
 Veh.In/Out:
 *Tel.No. . : Mobile: 81020883
 Reg.No. . : SKE1101D
 Reg.date. : 11/12/2014
 Mileage . : 0
 Chassis No: JN1BCAV37Z0450004

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount
	BRKT LICENS PLA	1.0 EA	117.50			117.50
	MEMBER RH	1.0 EA	732.40			732.40
	MEMBER LH	1.0 EA	732.40			732.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Rasul
90010068
14 days
20/02/16 @ 1445
email: rasul@lkkauto.com
EXCESS: 1000
Rebate

Labour Total 28,540.00
Parts Total 31,655.60
Package Total 0.00

Gross Total. 60,195.60
 Net..... 60,195.60
 GST @ 7.0% 4,213.69
 Total..... 64,409.30
 Paid..... 0.00
 Please Pay.. 64,409.30

60235.04

SERVICE ESTIMATE

O - M00002
 MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

SL: MSIG INSURANCE (SINGAPORE) PTE LTD

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 6
 Inv.date : 03/04/2017
 WIP No. : 13445
 Veh.In/Out: 08/09/2016 16/11/2016
 *Tel.No. : 62209644
 Reg.No. : SKE1101D
 Reg.date : 11/12/2014
 Mileage : 45,308
 Chassis No: JN1BCAV37Z0450004

Closed by : Cresendo Llorca
 Svc Consultant : ACC
 Remarks : Mr Lim Yung Feng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BRACE ASSY-R/CO	1.0 EA	110.40✓			110.40	S
	BODY PANEL SEALANT X	1.0 EA	1010.60✓			1,010.60	S
	ADHESIVE SEALER FL2	1.0 EA	447.80✓			447.80	S
	BRKT LICENS PLA	1.0 EA	117.50✓			117.50	S
	SEAL-CONDENSER,	1.0 EA	49.30✓			49.30	S
	AIR GUIDE	1.0 EA	33.60✓			33.60	S
	HARNESS-SUB,FRO	1.0 EA	130.10			130.10	S
	HARNESS ENGINE	1.0 EA	2966.20			2,966.20	S
	I654714GAOA/STAY ASS	1.0 EA	140.40			140.40	S
	COND & LIQUID	1.0 EA	1224.20			1,224.20	S
	HORN ASSY	1.0 EA	97.40			97.40	S
	HORN ASSY	1.0 EA	91.30			91.30	S
	BRACKET-ADDON F	1.0 EA	84.00			84.00	S
	CONN ASSY-FR SI	1.0 EA	56.00			56.00	S
	PIPE-COOLER	1.0 EA	98.60			98.60	S
	LABEL	1.0 EA	5.80			5.80	S
	AIR DUCT	1.0 EA	72.80			72.80	S

SERVICE ESTIMATE

0 - M00002 SL: MSIG INSURANCE (SINGAPORE) PTE LTD
 MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

GST Reg.No:M28920628X
 0 Page 7
 Inv.No. . : B&P
 Inv.date. : 03/04/2017
 WIP No. . : 13445
 Veh.In/Out: 08/09/2016 16/11/2016
 *Tel.No. . : 62209644
 Reg.No. . : SKE1101D
 Reg.date. : 11/12/2014
 Mileage . : 45,308
 Chassis No: JN1BCAV37Z0450004

Closed by : Cresendo Llorca
 Svc Consultant : ACC
 Remarks : Mr Lim Yung Feng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	COOLANT BLUE 4LT 50%	1.0 EA	91.70			91.70	S
	D WELDING PRIMER	1.0 EA	65.60			65.60	S
	BRACKET-FENDER,	1.0 EA	77.10			77.10	S
	BRACKET	1.0 EA	77.10			77.10	S
	WASHER-LOCK	1.0 EA	1.60			1.60	S
	LAMP ASSY-LH	1.0 EA	3344.70			3,344.70	S
	CLIP	1.0 EA	50.40			50.40	S
	FACE-FR BUMPER	1.0 EA	600.10			600.10	S
	BRKT-BPR SIDE,R	1.0 EA	14.00			14.00	S
	BRKT-HOOD SUPT	1.0 EA	16.80			16.80	S
	BRKT-HOOD SUPT	1.0 EA	16.80			16.80	S
	STAY-HOOD LOCK	1.0 EA	29.20			29.20	S
	CONT ASSY-HOOD	1.0 EA	1092.00			1,092.00	S
	BRACKET	1.0 EA	8.40			8.40	S

Labour Total 18,280.00
 Parts Total 32,232.30
 Package Total 0.00

Gross Total. 50,512.30
 Less..... 1,000.00
 Net..... 49,512.30
 GST @ 7.0% 3,465.86
 Total..... 52,978.16
 Paid..... 0.00
 Please Pay.. 52,978.16

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - M00002
MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581

SL: MSIG INSURANCE (SINGAPORE) PTE LTD

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1
Inv.date : 16/11/2017
WIP No. : 13445
Veh.In/Out: 08/09/2016 16/11/2016
*Tel.No. : 62209644
Reg.No. : SKE1101D
Reg.date : 11/12/2014
Mileage : 59,006
Chassis No: JN1BCAV37Z0450004

Closed by : Richmond Ho
Svc Consultant : ACC
Remarks : Mr Lim Yung Feng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE BONNET, FRT BUMPER, REINFORCEMENT, RADIATOR GRILLE, HEADLAMPS, RADIATOR, CONDENSOR, FAN MOTOR, SUPPORT PANEL, BOTH FENDERS, BOTH CHASSIS HEAD AND REPAIR FRT BOTH DOOR	0	9000.00	0		9,000.00	S
800	TO SPRAY PAINT ON FRONT BUMPER, BONNET, FRONT LH FENDER, FRONT RH FENDER, FRT LH CHASSIS, FRT RH CHASSIS, FRONT LH DOOR, FRONT RH DOOR AND ETC	0	6400.00	0		6,400.00	S
802	TO TOP UP A/C GAS	0	500.00	0		500.00	S
287	TO REPLACE BONNET DEPLOYED ACTUATOR	0	1560.00	0		1,560.00	S
287	TO CHECK WIRING INCLUSIVE OF RESETTING ALL ELECTRICAL MODULE	0	390.00	0		390.00	S

SERVICE ESTIMATE

0 - M00002 SL: MSIG INSURANCE (SINGAPORE) PTE LTD
 MSIG INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 16 RAFFLES QUAY #24-01 0 Page 2
 HONG LEONG BUILDING
 SINGAPORE 048581

Inv.No. : B&P
 Inv.date. : 16/11/2017
 WIP No. : 13445
 Veh.In/Out: 08/09/2016 16/11/2016
 *Tel.No. : 62209644
 Reg.No. : SKE1101D
 Reg.date. : 11/12/2014
 Mileage : 59,006
 Chassis No: JN1BCAV37Z0450004

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Lim Yung Feng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
287	TO FOCUS ON HEADLAMP	0	130.00	0		130.00	S
0036	NUMBER PLATE AND FRAME (1PC)	0	50.00	0		50.00	S
R16	Towing due to accident	0	250.00	0		250.00	S
EXC	Excess cost	0	1000.00	0		-1,000.00	S
	CLIP	1.0 EA	50.40	20		40.32	S ✓
	STIFFENER	1.0 EA	56.00	20		44.80	S ✓
	CLIP	1.0 EA	50.40	20		40.32	S ✓
	STIFFENER	1.0 EA	56.00	20		44.80	S ✓
	SPACER	2.0 EA	7.50	20		12.00	S ✓
	ENERGY ABSORBER	1.0 EA	168.60	20		134.88	S ✓
	BRACKET ASSY-AP	1.0 EA	84.00	20		67.20	S ✓
	BRACKET ASSY-AP	1.0 EA	84.00	20		67.20	S ✓
	REINFORCE-BUMPE	1.0 EA	481.40	20		385.12	S ✓
	STAY-BUMPER RH	1.0 EA	115.50	20		92.40	S ✓
	STAY-BUMPER LH	1.0 EA	115.50	20		92.40	S ✓
	SEAL ASSY-HOOD,	1.0 EA	112.00	20		89.60	S ✓
	BRKT-FR BUMPER	1.0 EA	19.60	20		15.68	S ✓

SERVICE ESTIMATE

0 - M00002 SL: MSIG INSURANCE (SINGAPORE) PTE LTD
 MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

GST Reg.No:M28920628X
 0 Page 3
 Inv.No. . : B&P
 Inv.date. : 16/11/2017
 WIP No. . : 13445
 Veh.In/Out: 08/09/2016 16/11/2016
 *Tel.No. . : 62209644
 Reg.No. . : SKE1101D
 Reg.date. : 11/12/2014
 Mileage . : 59,006
 Chassis No: JN1BCAV37Z0450004

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Lim Yung Feng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BRKT-FR BUMPER	1.0 EA	19.60	20		15.68	S ✓
	COVER-BUMPER	1.0 EA	19.90	20		15.92	S ✓
	BRKT-BPR SIDE,L	1.0 EA	14.00	20		11.20	S ✓
	FENDER-FRONT LH	1.0 EA	813.80	20		651.04	S ✓
	FENDER-FRONT RH	1.0 EA	706.70	20		565.36	S ✓
	FRT RH FENDER BRACKE	1.0 EA	43.50	20		34.80	S ✓
	FRT LH FENDER BRACKE	1.0 EA	43.50	20		34.80	S ✓
	FENDER SEAL LH	1.0 EA	11.20	20		8.96	S ✓
	FENDER SEAL RH	1.0 EA	11.20	20		8.96	S ✓
	HOOD	1.0 EA	1189.50	20		951.60	S ✓
	HINGE HOOD LH	1.0 EA	324.80	20		259.84	S ✓
	HOOD HINGE RH	1.0 EA	324.80	20		259.84	S ✓
	STAY ASSY-HOOD	1.0 EA	140.40	20		112.32	S ✓
	BONNET INSULATOR CLI	10.0 EA	1.10	20		8.80	S ✓
	RUB-SEAL HOOD F	1.0 EA	28.00	20		22.40	S ✓
	LOCK ASSY-HOOD	1.0 EA	93.20	20		74.56	S ✓
	LOCK ASSY-HOOD	1.0 EA	93.20	20		74.56	S ✓

QUOTATION ESTIMATE

0 - M00002
 MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

Inv.No. . : B&P
 Inv.date. : 16/11/2017
 WIP No. . : 13445
 Veh.In/Out: 08/09/2016 16/11/2016
 *Tel.No. . : 62209644
 Reg.No. . : SKE1101D
 Reg.date. : 11/12/2014
 Mileage . : 59,006
 Chassis No: JN1BCAV37Z0450004

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Lim Yung Feng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	STRIKER-HOOD	2.0 EA	16.80	20		26.88	S
	SECONDARY-HOOD	1.0 EA	65.20	20		52.16	S
	COVER HOOD LOCK	2.0 EA	14.00	20		22.40	S
	CABLE ASSY-HOOD	1.0 EA	59.60	20		47.68	S
	EMBLEM-RADIATOR	1.0 EA	59.00	20		47.20	S
	EMBLEM	2.0 EA	47.90	20		76.64	S
	BRACKET-EMBLEM	1.0 EA	28.00	20		22.40	S
	GRILLE-RADIATOR	1.0 EA	522.00	20		417.60	S
	COOLER ASSY-INT	1.0 EA	2013.80	20		1,611.04	S
	AIR DUCT	1.0 EA	302.40	20		241.92	S
	CLIP	10.0 EA	2.60	20		20.80	S
	BUMPER CLIP FX50	10.0 EA	1.30	20		10.40	S
	OTL COOLER ASSY	1.0 EA	588.40	20		470.72	S
	RADIATOR ASSY	1.0 EA	888.10	20		710.48	S
	LABEL CAUTION	1.0 EA	2.40	20		1.92	S
	MOTOR FAN ASSY-	1.0 EA	697.60	20		558.08	S
	E SEN-SIDE AIRBAG	1.0 EA	1618.40	20		1,294.72	S

SERVICE ESTIMATE

0 - M00002 SL: MSIG INSURANCE (SINGAPORE) PTE LTD
 MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

GST Reg.No: M28920628X
 0 Page 6
 Inv.No. : B&P
 Inv.date. : 16/11/2017
 WIP No. : 13445
 Veh.In/Out: 08/09/2016 16/11/2016
 *Tel.No. : 62209644
 Reg.No. : SKR1101D
 Reg.date. : 11/12/2014
 Mileage : 59,006
 Chassis No: JN1BCAV37Z0450004

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Lim Yung Feng

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	LAMP ASSY-LH	1.0	EA	3344.70	20		2,675.76 S	✓
	FACE-FR BUMPER	1.0	EA	600.10	20		480.08 S	✓
	ADHESIVE SEALER FL2	1.0	EA	447.80	20		358.24 S	✓
	STAY ASSY-HOOD	1.0	EA	140.40	20		112.32 S	✓
	BRKT LICENS PLA	1.0	EA	117.50	20		94.00 S	✓

Labour Total 18,280.00
 Parts Total 19,688.48
 Package Total 0.00

Gross Total. 37,968.48
 Less..... 1,000.00
 Net..... 36,968.48
 GST @ 7.0% 2,587.79
 Total..... 39,556.27
 Paid..... 0.00
 Please Pay.. 39,556.27

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - M00002 SL: MSIG INSURANCE (SINGAPORE) PTE LTD
 MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

GST Reg.No: M28920628X
 0 Page 5
 Inv.No. : B&P
 Inv.date. : 16/11/2017
 WIP No. : 13445
 Veh.In/Out: 08/09/2016 16/11/2016
 *Tel.No. : 62209644
 Reg.No. : SKE1101D
 Reg.date. : 11/12/2014
 Mileage : 59,006
 Chassis No: JN1BCAV37Z0450004

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Lim Yung Feng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	SENSOR ASSY	1.0 EA	224.00	20		179.20	S
	COVER	2.0 EA	46.30	20		74.08	S
	SENSOR-AIR BAG	3.0 EA	380.80	20		913.92	S
	ACTUATOR ASSY-H	1.0 EA	812.00	20		649.60	S
	ACTUATOR ASSY-H	1.0 EA	812.00	20		649.60	S
	LAMP ASSY-RH	1.0 EA	3344.70	20		2,675.76	S
	CLIP	1.0 EA	50.40	20		40.32	S
	CLIP	1.0 EA	50.40	20		40.32	S
	AIR GUIDE	1.0 EA	33.60	20		26.88	S
	SEAL-CONDENSER,	1.0 EA	49.30	20		39.44	S
	AIR GUIDE	1.0 EA	67.20	20		53.76	S
	TOP PANEL	1.0 EA	589.10	20		471.28	S
	SUPPORT-RADIATO	1.0 EA	50.40	20		40.32	S
	SUPPOPT-RADIATO	1.0 EA	50.40	20		40.32	S
	RET-FR BUMPER	1.0 EA	93.90	20		75.12	S
	BRACE ASSY-R/CO	1.0 EA	110.40	20		88.32	S
	SEAL-CONDENSER,	1.0 EA	49.30	20		39.44	S (Neg)

ATTN: RASUL
FINALIZED AMOUNT
DOA: 08 SEP 2016

keep record



SERVICE ESTIMATE

0 - MOD002
MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581

SE: MSIG INSURANCE (SINGAPORE) PTE LTD
GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 03/04/2017
WIP No. . : 13445
Veh.In/Out: 08/09/2016 16/11/2016
*Tel.No. . : 62209644
Reg.No. . : SKE1101D
Reg.date . : 11/12/2014
Mileage . : 45,308
Chassis No: JN1BCAV37Z0450004

Closed by : Cresendo Llurca
Svc Consultant : ACC
Remarks : Mr Lim Yung Feng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE BONNET, FRT BUMPER, REINFORCEMENT, RADIATOR GRILLE, HEADLAMPS, RADIATOR, CONDENSOR, FAN MOTOR, SUPPORT PANEL, BOTH FENDERS, BOTH CHASSIS HEAD AND REPAIR FRT BOTH DOOR	0	9000.00	0		9,000.00	S ✓
800	TO SPRAY PAINT ON FRONT BUMPER, BONNET, FRONT LH FENDER, FRONT RH FENDER, FRT LH CHASSIS, FRT RH CHASSIS, FRONT LH DOOR, FRONT RH DOOR AND ETC	0	6400.00	0		6,400.00	S ✓
802	TO TOP UP A/C GAS	0	500.00	0		500.00	S ✓
287	TO REPLACE BONNET DEPLOYED ACTUATOR	0	1560.00	0		1,560.00	S ✓
287	TO CHECK WIRING INCLUSIVE OF RESETTING ALL ELECTRICAL MODULE	0	390.00	0		390.00	S

Keep

SERVICE ESTIMATE

0 - M00002 SL: MSIG INSURANCE (SINGAPORE) PTE LTD
 MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

Inv.No. : B&P 0 Page 2
 Inv.date : 03/04/2017
 WIP No. : 13445
 Veh.In/Out: 08/09/2016 16/11/2016
 *Tel.No. : 62209644
 Reg.No. : SKE1101D
 Reg.date : 11/12/2014
 Mileage : 45,308
 Chassis No: JN1BCAV37Z0450004

Closed by : Cresendo Llurca
 Svc Consultant : ACC
 Remarks : Mr Lim Yung Feng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
287	TO FOCUS ON HEADLAMP	0	130.00	0		130.00	S ✓
0036	NUMBER PLATE AND FRAME (1PC)	0	50.00	0		50.00	S ✓
R16	Towing due to accident	0	250.00	0		250.00	S ✓
EXC	Excess cost	0	1000.00	0		-1,000.00	S
	CLIP	1.0 EA	50.40	✓		50.40	S
	STIFFENER	1.0 EA	56.00	✓		56.00	S
	CLIP	1.0 EA	50.40	✓		50.40	S
	STIFFENER	1.0 EA	56.00	✓		56.00	S
	SPACER	2.0 EA	7.50	✓		15.00	S
	ENERGY ABSORBER	1.0 EA	168.60	✓		168.60	S
	BRACKET-BUMPER	1.0 EA	70.00	✓		70.00	S
	BRACKET ASSY-AP	1.0 EA	84.00	✓		84.00	S
	BRACKET ASSY-AP	1.0 EA	84.00	✓		84.00	S
	REINFORCE-BUMPE	1.0 EA	481.40	✓		481.40	S
	STAY-BUMPER RH	1.0 EA	115.50	✓		115.50	S
	STAY-BUMPER LH	1.0 EA	115.50	✓		115.50	S
	SEAL ASSY-HOOD,	1.0 EA	112.00	✓		112.00	S

keep

SERVICE ESTIMATE

0 - M00002
 MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

SL: MSIG INSURANCE (SINGAPORE) PTE LTD

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 3
 Inv.date. : 03/04/2017
 WIP No. . : 13445
 Veh.In/Out: 08/09/2016 16/11/2016
 *Tel.No. . : 62209644
 Reg.No. . : SKE1101D
 Reg.date. : 11/12/2014
 Mileage . : 45,308
 Chassis No: JN1BCAV37Z0450004

Closed by : Cresendo Llorca
 Svc Consultant : ACC
 Remarks : Mr Lim Yung Feng

Op.No	Description	Mech Qty	Price Disc%	Pkg Amount G
	BRKT-FR BUMPER	1.0 EA	19.60 ✓	19.60 S
	BRKT-FR BUMPER	1.0 EA	19.60 ✓	19.60 S
	COVER-BUMPER	1.0 EA	19.90 ✓	19.90 S
	BRKT-BPR SIDE,L	1.0 EA	14.00 ✓	14.00 S
	FENDER-FRONT LH	1.0 EA	813.80 ✓	813.80 S
	FENDER-FRONT RH	1.0 EA	706.70 ✓	706.70 S
	FRT RH FENDER BRACKE	1.0 EA	43.50 ✓	43.50 S
	FRT LH FENDER BRACKE	1.0 EA	43.50 ✓	43.50 S
	FENDER SEAL LH	1.0 EA	11.20 ✓	11.20 S
	FENDER SEAL RH	1.0 EA	11.20 ✓	11.20 S
	HOOD	1.0 EA	1189.50 ✓	1,189.50 S
	HINGE HOOD LH	1.0 EA	324.80 ✓	324.80 S
	HOOD HINGE RH	1.0 EA	324.80 ✓	324.80 S
	STAY ASSY-HOOD	1.0 EA	140.40 ✓	140.40 S
	STAY ASSY-HOOD	1.0 EA	140.40 ✓	140.40 S
	BONNET INSULATOR CLI	10.0 EA	1.10 ✓	11.00 S
	RUB-SEAL HOOD F	1.0 EA	28.00 ✓	28.00 S

Keep

SERVICE ESTIMATE

0 - M00002 SL: MSIG INSURANCE (SINGAPORE) PTE LTD
 MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

GST Reg.No: M28920628X
 0 Page 4
 Inv.No. : B&P
 Inv.date : 03/04/2017
 WIP No. : 13445
 Veh.In/Out: 08/09/2016 16/11/2016
 *Tel.No. : 62209644
 Reg.No. : SKE1101D
 Reg.date : 11/12/2014
 Mileage : 45,308
 Chassis No: JN1BCAV37Z0450004

Closed by : Cresendo Llurca
 Svc Consultant : ACC
 Remarks : Mr Lim Yung Feng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	LOCK ASSY-HOOD	1.0 EA	93.20	✓		93.20	S
	LOCK ASSY-HOOD	1.0 EA	93.20	✓		93.20	S
	STRIKER-HOOD	2.0 EA	16.80	✓		33.60	S
	SECONDARY-HOOD	1.0 EA	65.20	✓		65.20	S
	COVER HOOD LOCK	2.0 EA	14.00	✓		28.00	S
	CABLE ASSY-HOOD	1.0 EA	59.60	✓		59.60	S
	EMBLEM-RADIATOR	1.0 EA	59.00	✓		59.00	S
	EMBLEM	2.0 EA	47.90	✓		95.80	S
	BRACKET-EMBLEM	1.0 EA	28.00	✓		28.00	S
	GRILLE-RADIATOR	1.0 EA	522.00	✓		522.00	S
	COOLER ASSY-INT	1.0 EA	2013.80	?		2,013.80	S ✓
	AIR DUCT	1.0 EA	302.40	?		302.40	S ✓
	CLIP	10.0 EA	2.60	✓		26.00	S
	BUMPER CLIP FX50	10.0 EA	1.30	✓		13.00	S ✓
	OIL COOLER ASSY	1.0 EA	588.40	?		588.40	S ✓
	RADIATOR ASSY	1.0 EA	888.10	?		888.10	S ✓
	LABEL CAUTION	1.0 EA	2.40	✓		2.40	S

Keep record

SERVICE ESTIMATE

O - M00002 SL: MSIG INSURANCE (SINGAPORE) PTE LTD
 MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING
 SINGAPORE 048581

GST Reg.No:M28920628X
 0 Page 5
 Inv.No. : B&P
 Inv.date. : 03/04/2017
 WIP No. : 13445
 Veh.In/Out: 08/09/2016 16/11/2016
 *Tel.No. : 62209644
 Reg.No. : SKE1101D
 Reg.date. : 11/12/2014
 Mileage : 45,308
 Chassis No: JN1BCAV37Z0450004

Closed by : Cresendo Llorca
 Svc Consultant : ACC
 Remarks : Mr Lim Yung Feng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	MOTOR FAN ASSY-	1.0 EA	697.60			697.60	S
	E SEN-SIDE AIRBAG	1.0 EA	1618.40	✓		1,618.40	S
	SENSOR ASSY	1.0 EA	224.00	✓		224.00	S
	COVER	2.0 EA	46.30	✓		92.60	S
	SENSOR-AIR BAG	3.0 EA	380.80	✓		1,142.40	S
	ACTUATOR ASSY-H	1.0 EA	812.00	✓		812.00	S
	ACTUATOR ASSY-H	1.0 EA	812.00	✓		812.00	S
	LAMP ASSY-RH	1.0 EA	3344.70	✓		3,344.70	S
	CLIP	1.0 EA	50.40	✓		50.40	S
	CLIP	1.0 EA	50.40	✓		50.40	S
	AIR GUIDE	1.0 EA	33.60	✓		33.60	S
	SEAL-CONDENSER,	1.0 EA	49.30	✓		49.30	S
	AIR GUIDE	1.0 EA	67.20	✓		67.20	S
	TOP PANEL	1.0 EA	589.10	✓		589.10	S
	SUPPORT-RADIATO	1.0 EA	50.40	✓		50.40	S
	SUPPOPT-RADIATO	1.0 EA	50.40	✓		50.40	S
	RET-FR BUMPER	1.0 EA	93.90	✓		93.90	S

keep record

SERVICE ESTIMATE

84168 - C00001 SL: SERVICE SALES - PC

Mr Lim Yung Feng

Blk 789 Choa Chu Kang North 6

#12-226

Singapore 680789

Closed by : Keion Toh

Svc Consultant :

Remarks : Mr Lim Yung Feng

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 19/09/2016

WIP No. . : 13445

Veh.In/Out:

*Tel.No. . : Mobile: 81020883

Reg.No. . : SKE1101D

Reg.date . : 11/12/2014

Mileage ... : 0

Chassis No: JN1BCAV37Z0450004

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount
-------	-------------	----------	-------	-------	-----	--------

802	TO REPLACE BONNET, FRT BUMPER, REINFORCEMENT, RADIATOR GRILLE, HEADLAMPS, RADIATOR, CONDENSOR, FAN MOTOR, SUPPORT PANEL, BOTH FENDERS, BOTH CHASSIS HEAD AND REPAIR FRT BOTH DOOR	0	14400.00	0	14,400.00	9000
800	TO SPRAY PAINT ON FRONT BUMPER, BONNET, FRONT LH FENDER, FRONT RH FENDER, FRT LH CHASSIS, FRT RH CHASSIS, FRONT LH DOOR, FRONT RH DOOR AND ETC	0	7200.00	0	7,200.00	6400
802	TO TOP UP A/C GAS	0	500.00	0	500.00	✓
287	TO REPLACE BONNET DEPLOYED ACTUATOR	0	3120.00	0	3,120.00	1560
287	TO CHECK WIRING INCLUSIVE OF RESETTING ALL ELECTRICAL MODULE	0	390.00	0	390.00	✓

SERVICE ESTIMATE

84168 - C00001 SL: SERVICE SALES - PC

Mr Lim Yung Feng
Blk 789 Choa Chu Kang North 6
#12-226

Singapore 680789

Closed by : Keion Toh
Svc Consultant :
Remarks : Mr Lim Yung Feng

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 19/09/2016
WIP No. . : 13445
Veh.In/Out:
*Tel.No. . : Mobile: 81020883
Reg.No. . : SKE1101D
Reg.date. : 11/12/2014
Mileage . : 0
Chassis No: JN1BCAV37Z0450004

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount
287	TO FOCUS ON HEADLAMP	0	130.00	0		130.00 ✓
802	TO PREPARE TOOLS FOR CELLETTE BENCH	0	1500.00	0		1,500.00 ? photo
802	TO CONDUCT CAROLINER CHASSIS ALIGNMENT	0	1000.00	0		1,000.00 ? photo
0036	NUMBER PLATE AND FRAME (1PC)	0	50.00	0		50.00 ✓
R16	Towing due to accident	0	250.00	0		250.00 ✓
	1 FACE-FR BUMPER	1.0 EA	789.70			789.70 ✓
	2 CLIP	1.0 EA	50.40			50.40 ✓
	3 STIFFENER	1.0 EA	56.00			56.00 ✓
	4 CLIP	1.0 EA	50.40			50.40 ✓
	5 STIFFENER	1.0 EA	56.00			56.00 ✓
	6 SPACER	2.0 EA	7.50			15.00 ✓
	7 ENERGY ABSORBER	1.0 EA	168.60			168.60 ✓
	8 BRACKET-BUMPER	1.0 EA	70.00			70.00 ✓
	9 BRACKET ASSY-AP	1.0 EA	84.00			84.00 ✓
	10 BRACKET ASSY-AP	1.0 EA	84.00			84.00 ✓

SERVICE ESTIMATE

84168 - C00001 SL: SERVICE SALES - PC

Mr Lim Yung Feng

Blk 789 Choa Chu Kang North 6

#12-226

Singapore 680789

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 3

Inv.date. : 19/09/2016

WIP No. . : 13445

Veh.In/Out:

*Tel.No. . : Mobile: 81020883

Reg.No. . : SKE1101D

Reg.date. : 11/12/2014

Mileage . : 0

Chassis No: JN1BCAV37Z0450004

Closed by : Keion Toh

Svc Consultant :

Remarks : Mr Lim Yung Feng

Op.No	Description	Mech Qty	Price Disc% Pkg	Amount
11	REINFORCE-BUMPE	1.0 EA	481.40	481.40 <i>BT</i>
12	STAY-BUMPER RH	1.0 EA	115.50	115.50 <i>rec</i>
13	STAY-BUMPER LH	1.0 EA	115.50	115.50 <i>rec</i>
14	SEAL ASSY-HOOD,	1.0 EA	112.00	112.00 <i>rec</i>
15	BRKT-FR BUMPER	1.0 EA	19.60	19.60 <i>rec</i>
16	BRKT-FR BUMPER	1.0 EA	19.60	19.60 <i>rec</i>
17	COVER-BUMPER	1.0 EA	19.90	19.90 <i>rec</i>
18	BRKT-BPR SIDE,L	1.0 EA	14.00	14.00 <i>rec</i>
19	FENDER-FRONT LH	1.0 EA	813.80	813.80 <i>BT</i>
20	FENDER-FRONT RH	1.0 EA	813.80	813.80 <i>BT</i>
21	FRT RH FENDER BRACKE	1.0 EA	43.50	43.50 <i>rec</i>
22	FRT LH FENDER BRACKE	1.0 EA	43.50	43.50 <i>rec</i>
23	SEAL ASSY-HOOD,	1.0 EA	112.00	112.00 ?
24	SEAL ASSY-HOOD,	1.0 EA	112.00	112.00 ?
25	FENDER SEAL LH	1.0 EA	11.20	11.20 <i>rec</i>
26	FENDER SEAL RH	1.0 EA	11.20	11.20 <i>rec</i>
27	HOOD	1.0 EA	1369.70	1,369.70 <i>BT</i>

SERVICE ESTIMATE

84168 - C00001 SL: SERVICE SALES - PC

Mr Lim Yung Feng

Blk 789 Choa Chu Kang North 6
#12-226

Singapore 680789

Closed by : Keion Toh

Svc Consultant :

Remarks : Mr Lim Yung Feng

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 4

Inv.date. : 19/09/2016

WIP No. . : 13445

Veh.In/Out:

*Tel.No. . : Mobile: 81020883

Reg.No. . : SKE1101D

Reg.date. : 11/12/2014

Mileage . : 0

Chassis No: JN1BCAV37Z0450004

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount
28	HINGE HOOD LH	1.0 EA	324.80			324.80 <i>PA</i>
29	HOOD HINGE RH	1.0 EA	324.80			324.80 <i>PA</i>
30	STAY ASSY-HOOD	1.0 EA	140.40			140.40 <i>PA</i>
31	STAY ASSY-HOOD	1.0 EA	140.40			140.40 <i>PA</i>
32	INSULATOR-HOOD	1.0 EA	187.50			187.50 <i>X</i>
33	BONNET INSULATOR CLI	10.0 EA	1.10			11.00 <i>see</i>
34	RUB-SEAL HOOD F	1.0 EA	28.00			28.00 <i>see</i>
35	LOCK ASSY-HOOD	1.0 EA	93.20			93.20 <i>PA</i>
36	LOCK ASSY-HOOD	1.0 EA	93.20			93.20 <i>PA</i>
37	STRIKER-HOOD	2.0 EA	16.80			33.60 <i>PA</i>
38	SECONDARY-HOOD	1.0 EA	65.20			65.20 <i>PA</i>
39	COVER HOOD LOCK	2.0 EA	14.00			28.00 <i>CPA</i>
40	CABLE ASSY-HOOD	1.0 EA	59.60			59.60 <i>cut</i>
41	EMBLEM-RADIATOR	1.0 EA	59.00			59.00 <i>ms</i>
42	EMBLEM	2.0 EA	47.90			95.80 <i>ms</i>
43	BRACKET-EMBLEM	1.0 EA	28.00			28.00 <i>aa</i>
44	GRILLE-RADIATOR	1.0 EA	601.10			601.10 <i>pro</i>

SERVICE ESTIMATE

84168 - C00001 SL: SERVICE SALES - PC

Mr Lim Yung Feng

Blk 789 Choa Chu Kang North 6
#12-226

Singapore 680789

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 5

Inv.date. : 19/09/2016

WIP No. : 13445

Veh.In/Out:

*Tel.No. : Mobile: 81020883

Reg.No. : SKE1101D

Reg.date. : 11/12/2014

Mileage : 0

Chassis No: JN1BCAV37Z0450004

Closed by : Keion Toh

Svc Consultant :

Remarks : Mr Lim Yung Feng

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount
45	COOLER ASSY-INT	1.0 EA	2013.80			2,013.80 ?
46	AIR DUCT	1.0 EA	302.40			302.40 ?
47	CLIP	10.0 EA	2.60			26.00 neu -
48	BUMPER CLIP FX50	10.0 EA	1.30			13.00 neu -
49	OIL COOLER ASSY	1.0 EA	588.40			588.40 ?
50	RADIATOR ASSY	1.0 EA	888.10			888.10 ?
51	LABEL CAUTION	1.0 EA	2.40			2.40 neu -
52	MOTOR FAN ASSY-	1.0 EA	697.60			697.60 ?
53	*E* SEN-SIDE AIRBAG	1.0 EA	1618.40			1,618.40 neu -
54	SENSOR ASSY	1.0 EA	224.00			224.00 neu -
55	COVER	2.0 EA	46.30			92.60 neu -
56	SENSOR-AIR BAG	3.0 EA	380.80			1,142.40 neu -
57	CONT ASSY-HOOD	1.0 EA	1092.00			1,092.00 ?
58	ACTUATOR ASSY-H	1.0 EA	812.00			812.00 neu -
59	ACTUATOR ASSY-H	1.0 EA	812.00			812.00 neu -
60	LAMP ASSY-RH	1.0 EA	3851.50			3,851.50 neu -
61	SENSOR ASSY	1.0 EA	224.00			224.00 neu -