

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lynn Khong

Date: 29 Sep 2016

Preliminary Advice

Insured Vehicle No	: YL2616B		
TP Vehicle No	: SMB108J	Accident Date	: 26/09/2016
Make	: MERCEDES-BENZ B160	Assignment Date	: 28/09/2016
Date of Inspection	: 28/09/2016	Est. Duration of Repair	: 1/2 /Days
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesO/S... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,603.91
Revised Amount	:S\$	1,438.91
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,438.91

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :We have not authorized repairs.