Mei Kwan (LKKAuto)

From: Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>

Sent: Wednesday, 5 October, 2016 3:16 PM

To: Mei Kwan (LKKAuto)

Cc: Asher Sng (LKKAuto); Thin Thin (LKKAuto); Admin A

Subject: RE: Direct Settlement - Accident Involving GBC7529G (OI : EQI -

DM16HO02090/WY) AND GZ4652Y (TP: LKK REF - CC6/EQI16018702/Kua3) on

30.09.2016

Attachments: EQIC-MARS00001171-GBC7529G-GIA.PDF

Follow Up Flag: Follow up Flag Status: Flagged

Categories: HMK

Dear Mei Kwan,

Refer to your email below, please find OI's report attached.

Liability unclear, please proceed on WP.

Warmest Regards, Tan Wei Yin

Claims Executive

EQ Insurance Company Limited

5 Maxwell Road, #17-00 Tower Block, MND Complex Singapore 069110

6223 9433 (Tel) 6496 9034 (DID)

6223 4190 (Fax)

Website: www.eqinsurance.com.sg

Disclaimer: Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Wednesday, October 5, 2016 1:17 PM

To: Tan Wei Yin

Cc: Asher Sng (LKKAuto); Thin Thin (LKKAuto); Admin A

Subject: Direct Settlement - Accident Involving GBC7529G (OI: EQI - TBA) AND GZ4652Y (TP: LKK REF -

CC6/EQI16018702/Kua3) on 30.09.2016

WITHOUT PREJUDICE

Dear Wei Yin,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle GZ 4652Y at M/s Cheng Hoe Motor Pte Ltd (Yishun).

Enclosed for your perusal is:

- Estimated cost of repair
- TP GIA report
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: <u>MeiKwan@lkkauto.com</u> | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)