

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vale Oh

Date: 06 Oct 2016

Preliminary Advice

Insured Vehicle No : SGM7344K

TP Vehicle No : WNH4497

Make : PRONTON WAJA

Date of Inspection : 05/10/2016

Inspection At : AUTOEXCEL ENGINEERING PTE LTD

Accident Date : 28/09/2016

Assignment Date : 04/10/2016

Est. Duration of Repair : 7 /Days

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesN/S Front... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:RM	31,740.69
Revised Amount	:RM	13,073.18
Check Items (Estimated)	:RM	8,948.02
Total	:RM	22,021.20

Lump Sum Repair :RM

Total Loss Consideration

New for Old Value	:RM
Pre-Accident Value	:RM
COE / PARF Rebate	:RM
Salvage Value	:RM
Margin for Repair	:RM

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :We have not authorized repairs.