



Kaki Bukit Autohub,
2 Kaki Bukit Ave 2, #01-18
Singapore 417921
Tel No. : +65 6842 0051 / 6744 0510 Fax No. : +65 6741 0510
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

Our Ref: **SFY 1080 J**
Your ref: **SKX 3763 E**

18 October 2016

AIG ASIA PACIFIC INSURANCE PTE. LTD.

BY EMAIL BernardJiQian.Ler@aig.com ONLY

NO: 78 SHENTON WAY
#07-16 CHARTIS BUILDING
SINGAPORE 079120
Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : TANG SOO LAN JOCELYN
VEHICLE NUMBER : SFY 1080 J
YOUR INSURED VEHICLE NUMBER : SKX 3763 E
ACCIDENT ON 12 Oct 2016 ALONG TURF CLUB ROAD CARPARK DRIVEWAY
AT ABOUT 18:40 HOURS

We refer to your email dated 18 Oct 2016 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **ADRIAN LING** of **LKK AUTO CONSULTANTS PTE LTD** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-18
Singapore 417921
6842 0051 / 6744 0510 (Melody)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



N-51 AUTOMOTIVE PTE LTD

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection: