



(New) SLV82E
Our Reference: **SKM4327H/7016018**
Your Reference: **SHD4364H**

By Email / Mail

09/12/2019

INDIA INTERNATIONAL INSURANCE PTE LTD C/O LKK AUTO CONSULTANTS
Attn: Third Party Claim Department -

ACCIDENT INVOLVING SKM4327H & SHD4364H ON 19 OCT 2016.

Dear Officer,

We wish to inform you that the repairs to our client vehicle have been completed.

We hereby submit the claims as follows:

Details	Remarks	Amount (SGD)
Cost of Repairs		\$24,976.37
Loss Of Rental	\$139.10 x 5 days	\$695.50
Others		
TOTAL		\$25,671.87

Kindly let us have your offer to Christine.yow@wearnes.com

Your soonest reply is much appreciated. Thank you.



Yours faithfully
Christine Yow
D (65) 6430 4899
Wearnes Automotive Pte Ltd
Bodyshop and Paint Division
249 Alexandra Road
Singapore 159935

This is a computer generated printout, no signature is required.


AUTHORIZATION TO ACT

I, TAY LIN YUAN IVY ("the third party Claimant")
of 302A PUNGGOL PHASE #13-241 S 821 302 (address),
owner of SKM 4327H (vehicle no.)
hereby authorize WEARNES AUTOMOTIVE PTE LTD ("The workshop")
to act for me with respect to my claim for repair costs and / or rental and / or loss of use
("claim") for my Vehicle No. SKM 4327H that was damaged
pursuant to the accident which occurred on 19 / 10 / 2016 (date) along
6 SERANGOON NORTH AVE 5 CARPARIC (location)
involving Vehicle No/s SHD 43644 ("The accident").

I further authorize the workshop to sign the discharge voucher on my behalf to settle my
above mentioned claim in a manner that they deem fit and the workshop is further
authorized to receive payment further to settlement of my claim with payment cheque/s
being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability basis insofar as the driver / owner /
insurers of the other vehicle/s is concerned.

Date this 26 day of Oct (month) 20 16 (year)



Signed by "the third party claimant"



Signed by "the workshop"

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT16100872
Claimant Ref : SKM 4327H/7011112

We/I, Wearnes Automotive Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ \$24,976.37 (repair cost), S\$ 695.50 (loss of use/rental), S\$ — (search fee), vehicle no. SKM 4327H that was damaged pursuant to the accident which occurred on 19/10/2016 (date) at 6 Serangoon North Ave 5 Carpark (location) involving vehicle no. SHD 4364H (insured vehicle). This is pursuant to the inspection conducted on 28/10/2016 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Tay Lin Yuan Ivy ("the third party claimant") of vehicle no. SKM 4327H to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKM 4327H (vehicle no.) as a result of the accident.


We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.


This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 25,671.87 to Wearnes Automotive Pte Ltd.

Dated this 15 day of July 2021

CLAIMANT:

Signature: 
Name: Wearnes Automotive Pte Ltd
NRIC: 199501400R
Address: 249 Alexandra Road, S159935
Nationality: _____
Occupation: _____

Signature:  MH
Signed by appointed Surveyor
Name: LKK Auto Consultants Pte Ltd
NRIC: 199607198R
Address: 51 Ubi Avenue 1
#01-25 Paya Ubi Ind. Park S(408933)
Nationality: _____
Occupation: _____

CERTIFIED TRUE COPY



SERVICE TAX INVOICE

0 - I00012 SL: INDIA INTERNATIONAL INSURANCE
INDIA INTERNATIONAL INSURANCE
64 CECIL ST
#04-05 IOB BUILDING
SINGAPORE 049711

GST Reg.No:M28920628X

Inv.No. . : B&P 7016018 Page 1

Inv.date. : 24/05/2019

WIP No. . : 10069

Veh.In/Out:

*Tel.No. : : New / old
Reg.No. . : SLV82E / SKM432TH

Reg.date . : 28/02/2014

Mileage .. : 71,063

Chassis No: SAJAC05M9EPU17026

Closed by : Richmond Ho
Svc Consultant :
Remarks : Ms Tay Lin Yuan, Ivy

Parts/Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
280	TO REPLACE FRT RH FENDER AND REPAIR ON FRT BUMPER	0		1700.00	0		1,700.00	S
280	TO SPRAY PAINT ON FRONT BUMPER, FRT RH FENDER, FENDER INNER PANEL	0		1500.00	0		1,500.00	S
280	TO REPLACE FRT RH AFFECTED UNDERCARRIAGE	0		3888.00	0		3,888.00	S
280	TO CHECK WIRING INLCUDE OF RESETTNG OF ALL ELECTRICAL MODULES	0		486.00	0		486.00	S
280	TOWING CHARGES	0		250.00	0		250.00	S
280	COMPUTERISED WHEEL ALIGNMENT	0		280.00	0		280.00	S
C2Z16958	FENDER PANEL FRT RH	1.0	EA	1551.10			1,551.10	S
C2Z27959LM	FINISHER-VEN	1.0	EA	310.30			310.30	S
XR87606	WHEELARCH PLASTIC NU	10.0	EA	3.70			37.00	S
C2Z27763	SHOCK ABSORBER FRT R	1.0	EA	823.40			823.40	S
C2Z15891	ABSORBER SPRING INSU	2.0	EA	78.40			156.80	S

CERTIFIED TRUE COPY



SERVICE TAX INVOICE

0 - I00012 SL: INDIA INTERNATIONAL INSURANCE
INDIA INTERNATIONAL INSURANCE
64 CECIL ST
#04-05 IOB BUILDING
SINGAPORE 049711

GST Reg.No:M28920628X

Inv.No. : B&P 7016018 Page 2
Inv.date. : 24/05/2019
WIP No. : 10069

Veh.In/Out:

*Tel.No. : *New*
Reg.No. : SLV82E/*SKM43274*

Reg.date. : 28/02/2014

Mileage : 71,063

Chassis No: SAJAC05M9EPU17026

Closed by : Richmond Ho
Svc Consultant :
Remarks : Ms Tay Lin Yuan, Ivy

Parts/Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
C2P25453	VERTICAL LINK RH XF	1.0	EA	587.30			587.30	S
C2D49191	HUB & BEARING FRONT	1.0	EA	518.50			518.50	S
C2P24861	LATERAL LOWER ARM RH	1.0	EA	1799.90			1,799.90	S
C2Z29115	WISHBONE ARM FRT RH	1.0	EA	1293.20			1,293.20	S
C2Z3523	STABILIZER BAR FRT X	1.0	EA	881.70			881.70	S
C2D24220	STABILIZER LINK FRT	1.0	EA	107.60			107.60	S
C2C35589	STABILIZER BUSH FRT	2.0	EA	27.60			55.20	S
C2P18511	ALLOY RIM 18 VELA FR	1.0	EA	1681.70			1,681.70	S
C2Z2215	STEERING RACK XF	1.0	EA	5348.70			5,348.70	S
C2P10363	STEERING OIL 1L XF S	2.0	EA	43.00			86.00	S

Gross Total. 23,342.40

Labour Total 8,104.00
Parts Total 15,238.40
Package Total 0.00

Net..... 23,342.40
GST @ 7.0% 1,633.97
Total..... 24,976.37
Paid..... 0.00
Please Pay.. 24,976.37

GST: S=StdRated; O=OutOfScope; Z=ZeroRated
Enquiries must be lodged within 14 days from the invoice date
This is a computer generated invoice. No signature is required.

**Wearnes Automotive Pte. Ltd.**

Co Reg No 199501400R / GST Reg No M28920628X
28 Leng Kee Road, Singapore 159105
Telephone: +65 6876 5063
www.wearnesleasing.com

Tax Invoice**FIRST CAPITAL INSURANCE LTD**

36 ROBINSON ROAD
#16-01, CITY HOUSE
Singapore 068877

Inv No. : R1700848
Inv Date : 27 Jun 2017
Ref :
Terms : 90 Days

Rental Information

Agreement No. : RA16/01083
Billing Period : 28/10/2016 09:00 - 02/11/2016 09:00
Driver Name : Went Peter Andrew Clive

Car Information

Registration No. : SKC7434P
Make : VOLVO
Model : S80 2.0T AT ABS D/AB
2WD 4DR TURBO

#	Description	Qty	UOM	Unit Price	Amt
1	Being Rental Payment for the Period Stated Above	5.00	Days	130.00	650.00

Remarks:

SKM4327H_India_Kelon

Payment method:

Interbank Giro: deduction will take place between 9th to 13th of the month.
Credit Card payments: deduction will take place between 5th to 10th of the month.

Cheque payments: all cheques should be crossed and made payable to "Wearnes Automotive Pte Ltd".

Bank Transfers:

Oversea-Chinese Banking Corporation Limited
Bank Code: 7339
Branch Code: 501
Bank Account Name: Wearnes Automotive Pte Ltd
Bank Account: 296727-001
SWIFT CODE: OCBGSGSG

Subtotal : S\$ 650.00
GST 7.0% : S\$ 45.50
Total : S\$ 695.50

Please note that late payment interest will be imposed at a rate of 2% per month commencing from the date the payment is due, compounded daily, plus an administrative fee of \$50 each time.

This is a computer generated document. No signature is required.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	21 Oct 2016 14:02	Clim Veh Model Changed	(202979) JAGUAR XF 2.0 GTDI Luxury (A).	[A] Lau Shu Pei
2	21 Oct 2016 14:02	Clim Created	Reg No: SKM4327H. Acct Date: 2016/10/19. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: Liberty Insurance Pte Ltd (HQ). Workshop: Wearnes Automotive Pte Ltd (Leng Ke e)	[A] Lau Shu Pei
3	21 Oct 2016 14:02	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	21 Oct 2016 14:02	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2016/11/01	[A] Lau Shu Pei
5	21 Oct 2016 14:02	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	21 Oct 2016 14:02	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	21 Oct 2016 14:02	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] Lau Shu Pei
8	25 Oct 2016 13:39	Adj Mandate Request	Cur.Reg:0.00:LIABILITY: 100% REMARK : OI REVERSED HIS VEHICLE AND ACCIDENTLY HIT ONTO TP VEH...BOLA NIL	[A] Jasmine Khine Phoo Wai
9	25 Oct 2016 16:24	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2016/11/01. Mandate Remarks: agree to do direct settlement	[I] Sundari Nagarajan
10	25 Oct 2016 16:24	Adj Mandate Set	Approved:0.00:agree to do direct settlement	[I] Sundari Nagarajan
11	31 Oct 2016 10:39	Adj Adjuster Assigned	MOHD RASUL -> MOHD TAUFIKH	[A] Lau Shu Pei
12	31 Oct 2016 10:41	Adj Rpt Initiated		[A] Lau Shu Pei
13	31 Oct 2016 10:41	Clim Details Notified		[A] Lau Shu Pei
14	16 Nov 2018 13:12	Adj Mandate Request	Cur.Reg:25980.56:PODS Liability: 100% Quantum: (a)COR w/GST: \$25,285.06 + (b) LOR w/GST (5 days x \$139.10): \$695.50 + (c)LTA/GIA search fee: NIL = Total: \$25,980.56 Vehicle Model: Jaguar XF-2.0 (1999 cc) 5 recommendation repair days. F	[A] OLIVIA LAU WAN YEE
15	23 Nov 2018 09:27	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2016/11/01. Mandate Remarks: We could not see any damage to the fender brackets (items 3&6) and the bumper bracket (item 5). Please provide us the photos	[I] Sundari Nagarajan
16	23 Nov 2018 09:27	Adj Mandate Set	Approved:0.00:We could not see any damage to the fender brackets (items 3&6) and the bumper bracket (item 5). Please provide us the photos	[I] Sundari Nagarajan
17	20 Dec 2018 14:08	Adj Mandate Request	Cur.Reg:25980.56:Kindly refer to our email dated 03/12/2018. PODS Liability: 100% Quantum: (a)COR w/GST: \$25,285.06 + (b) LOR w/GST (5 days x \$139.10): \$695.50 = Total: \$25,980.56 Vehicle Model: Jaguar XF-2.0 (1999 cc) 5 recommendation repair days.	[A] CHEW HSIAO TONG
18	21 Dec 2018 10:06	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2016/11/01. Mandate Remarks: The shock absorber, absorber insulator, verticle link, hub, lateral lower arm, wishbone, stabilizer bar and link, bush, and steering oil could also be affected. We could not see any damage to	[I] Lalitha Krishnan
19	21 Dec 2018 10:06	Adj Mandate Set	Maintained:The shock absorber, absorber insulator, verticle link, hub, lateral lower arm, wishbone, stabilizer bar and link, bush, and steering oil could also be affected. We could not see any damage to the fender brackets (items 3&6) and the bumper	[I] Lalitha Krishnan
20	06 Mar 2019 17:11	Adj Mandate Request	Cur.Reg:25725.37:PODS Liability: 100% Quantum: (a)COR w/GST: \$25,029.87 + (b) LOR w/GST (5 days x \$139.10): \$695.50 + (c)LTA/GIA search fee: NIL = Total: \$25,725.37 Vehicle Model: Jaguar XF-2.0 (1999 cc) 5 recommendation repair days	[A] OLIVIA LAU WAN YEE
21	12 Mar 2019 09:44	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2016/11/01. Mandate Remarks: We could not see any damage to the fender brackets (items 3&6) and the bumper bracket (item 5). Kindly furnish more photographs for us to view damages	[I] Sundari Nagarajan
22	12 Mar 2019 09:44	Adj Mandate Set	Approved:0.00:We could not see any damage to the fender brackets (items 3&6) and the bumper bracket (item 5). Kindly furnish more photographs for us to view damages	[I] Sundari Nagarajan
23	15 Mar 2019 10:56	Adj Mandate Request	Cur.Reg:25725.37:We have further negotiated with TP workshop. It has agreed to remove the fender brackets (items 3&6) and the bumper bracket (item 5). Cur.Reg:25725.37:PODS Liability: 100% Quantum: (a)COR w/GST: \$25,029.87 + (b) LOR w/GST (5 days x \$	[A] OLIVIA LAU WAN YEE
24	19 Mar 2019 15:54	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2016/11/01. Mandate Remarks: We could not see any damage to the fender brackets (items 3&6) and the bumper bracket (item 5). Kindly furnish more photographs for us to view damages	[I] Mekavathanan Sarangapani
25	19 Mar 2019 15:54	Adj Mandate Set	Approved:25725.37:We could not see any damage to the fender brackets (items 3&6) and the bumper bracket (item 5). Kindly furnish more photographs for us to view damages	[I] Mekavathanan Sarangapani
26	13 Dec 2019 10:16	Clim Registration Modified	Rep:200075->201546.	[A] Lau Shu Pei

Date From

Date To

Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1291366	31 Oct 2016 10:41:41	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKM4327H		10.70