

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBC8192L160617

Estimate**Customer**

Name: AXA Insurance Singapore Pte Ltd

Address: Motor Claims Department

8 Shenton Way #27-01

AXA Tower

Singapore 068811

Date: 20-10-16

Vehicle No: GBC8192L

Model/Make: Toyota Hiace Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Lh Side Mirror "Corporate" Advertisement Sticker Labor & Replacing Parts Etc To putty & spray painting & including touch up paint on accident affected areas	\$ 1,165.00 \$ 1,200.00 \$ 400.00 \$ 1,400.00	 600 500

Total Parts & Labour of estimate for damaged vehicle

\$ 4,165.00

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

\$ -

SDLS: _____



M/s Liu's Brother Auto Engrg Wks

not allowed
LH
TOTAL \$1100
3 day.
28/10/16
P/P.