

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TINAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TINAH
CONTACT NO : 4694091
REFERENCE : INS/IC/SC/0511/2016
DATE : 13-SEP-2016

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : LIM BEE YAN
ADDRESS : BLK 2E HONG SAN WALK
#02-04 PALM GARDEN
S(6E9051)
TELEPHONE NO : 96464603

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : PA32728 DIRECT SETTLEMENT
VEHICLE NO : SKQ961G
MODEL CODE : B0TARCEB17EWA----A
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)
ENGINE NO : HR169493029
CHASSIS NO : HNTBBAB17Z0020501
MILEAGE : 1 KM
DATE IN : 13/09/2016
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : STEVEN CHUI FOOK SENG
ACCIDENT DATE : 13/09/2016

mony contact
93850520

sway at
woodlands Waterfront park
car park

7.11.16
10/11/16

Adeline
19/9/16
1900h
27/9/16
245h

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH M/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO 5KQ961G

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	TO RENEW LHR DOOR, LHF DOOR. TO KNOCK OUT LHR FENDER	1800.00	390 1170.
2	ZZ/002	TO SPRAY LHF DOOR, LHR DOOR, LHR FENDER	1400.00	250 750.
3	ZZ/003	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL	200.00	X
4	ZZ/004	PERFORM RUST PROOF TREATMENT FOR AFFECTED BODY PARTS	240.00	120
5	ZZ/005	TO TRANSFER LHR DOOR PARTS	60.00	120 ✓
TOTAL LABOUR CHARGES			3700.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKQ961G

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 TAPE-FR DOOR SA	80817-3SB0A			15.50 <i>neu</i> ✓
2 TAPE-FR DOOR, LH	80819-3SB0A			11.90 <i>neu</i> ✓
3 DOOR A FR LHT	H010A-3SBMA			502.30 <i>bt</i> ✓
4 SUNDRIES	KPH			100.00 ?
5 TAPE-RR DOOR, LH	82819-3SB0A			15.50 <i>neu</i> ✓
6 TAPE-RR DOOR, LH	82813-3SB0A	12.10	<i>neu</i> ✓	
7 TAPE-RR DOOR, LH	82817-3SB0A			11.60 <i>neu</i> ✓
8 DOOR A RR	H210A-3SBMA			533.30 <i>bt</i> ✓
SUB TOTAL		12.10	0.00	1190.10
LESS DISCOUNT (NETT-20.00%, LIST-10.00%, S/NETT-.00%)		2.42	0.00	0.00
GRAND TOTAL		9.68	0.00	1190.10
OVERALL TOTAL		1199.78		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE, LTD.

DUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGS NO SK09610

TOTAL LABOUR CHARGES	3700.00
TOTAL SPARE PARTS CHARGES	1199.78
GRAND TOTAL	4899.78 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.