

Surveyor:

MA CF

DOI:

ASSIGNMENT

15/11/2018

Date / Time:

14-11-16

Registered in Merimen:

11-11-16

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHB 7835 G

Name of Insured:

Trans Cab Services plc

Insured Tel No.:

HP:

Excess Sec II : \$5

5,000.00

D.O.A.:

10-11-16

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Hinh Lim Yonk (Wang Jin Long)

Driver Tel No.:

9066 3057

(V/L: YES / NO)

Claim No.:

00407770

Policy No.:

P1680520

Make / Model:

C-EPICA

Place of Accident:

Monal Avenida Hospital

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJG1772T



INSRS:

WSP:

Tel:

Liability:

RMKS:

Em-1



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

20/11/16

VAC

SJG1772T - 100/1114006571/04 : DOA - 05/04/14

SHB 7835 G - 003/11115014338/Kj0202 : DOA - 20/08/15

23/11/14

File review, QD reported that the rear ended TP. Email to workshop.

Trans-Cab.

13-06-17 REAR ENDED TP. WE ARE AT FAULT PLEASE SPEED UP SETTLEMENT.

after repair photo

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS 6,700.00

(7 days)

Reduction:

64

%

Email

Call

FINAL SETTLEMENT

Date/Time:

25/3/2019

Confirm with:

H/A/02

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS 7,169.00

Loss of Rental (LOR):

SS 749.00

(7 days)

X9100.00 + 17% GST

Loss of Use (LOU):

SS

-

(\$

x

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

-

Medical:

SS

192.60

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS 8,110.60

Global Sum SS:

8,100.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 8,100.00

Name 1:

EM-1 Auto Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1	993.00 ✓	30.00 ✓	800.00 ✓
2	62.00 ✓	220.00 ✓	900.00 ✓
3	48.20 ✓	350.00 ✓	30.00 ✓
4	46.00 ✓	500.00 ✓	60.00 ✓
5	46.20 ✓		60.00 ✓
6	315.00 ✓		60.00 ✓
7	40.00 ✓		80.00 ✓
8	30.00 ✓		80.00 X
9	30.00 ✓		
10	252.60 ✓		
11			
12	119.70 ✓		
13	794.90 ✓		
14	40.00 ✓		
15	30.00 ✓		
16	835.60 ✓		
17	84.00 ✓		
18	72.00 ✓		
19	40.00 ✓		
20	396.50 ✓		
21	138.40 ✓		
22	226.20 ✓		
23			
24	423.50 ✓		
25	192.50 ✓		
26	30.00 ✓		
27	172.20 ✓		
28			
29			
30	989.50 T		
31			
32	46.60 T		

Total List Price	\$	6,494.60
Discount		20%
List Price (after Discount)	\$	5,195.68
Total Nett Price	\$	-
Discount		10%
Nett Price (after Discount)	\$	-
Total Special Nett	\$	1,100.00
Total Labour	\$	2,070.00
Grand Total	\$	8,365.68
Discount 20%		20%
Lump Sum Repair Cost	\$	6,692.54

\$ 6,700.00

Columns	
A	Serial No.
B	List Price
C	Nett Price
D	Special Nett
E	Labour

File No ✓
4815

VEHICLE NO.
SJG 1772T

DOA :
10.11.2016

MODEL
MAZDA 3

RENTAL :
7 DAYS

\$ 6,494.60
 X 80%

 \$ 5,195.68
 + \$ 1,100.00
 + \$ 2,070.00

 \$ 8,365.68
 X 80%

 \$ 6,692.54

Mr chia mention change old exhaust pipe

= L/S: \$ 6,700.00 // with 7 working days

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SJG 1772T

Vehicle Model : MAZDA 3

Accident Date : 10.11.2016

Original Reg Date : 24.06.2008

Date : 11.11.2016

Chassis : JM6BK106280412956

TP Ins. AXA

ESTIMATE

1	1 pc	Boot Lid		993.00	✓
2	1 pc	Boot Lid Badge		62.00	✓
3	1 pc	Boot Lid Emblem MAZDA		48.20	✓
4	1 pc	Boot Lid Emblem 3		46.00	✓
5	1 pc	Boot Lid Emblem (SP)		46.20	✓
6	2 pcs	Boot Lid Lamps	315.00	630.00	✓
7	2 pcs	Boot Lid Lamps Inner Sealer	30.00	60.00	40 ✓
8	2 set	Boot Lid Lamps Clips	25.00	50.00	30 ✓
9	1 set	Boot Lid Insulator Clips		40.00	30 ✓
10	1 pc	Boot Lid Inner Lock		252.60	✓
11	1 pc	Boot Lid Lock Catch		75.20	✓
12	1 pc	Boot Lid Weatherstrip		119.70	✓
13	2 pcs	Taillamps	794.90	1,589.80	✓
14	2 pcs	Taillamps Inner Sealer	30.00	60.00	40 ✓
15	2 set	Taillamps Clips	25.00	50.00	30 ✓
16	1 pc	Rear Bumper		835.60	✓
17	2 pcs	Rear Bumper Side Retainers	42.00	84.00	✓
18	2 pcs	Rear Bumper Attachment Retainers	36.00	72.00	✓
19	1 set	Rear Bumper Clips		50.00	40 ✓
20	1 pc	Rear Bumper Reinforcement		396.50	✓ DD
21	2 pcs	Rear Bumper Reflectors	69.20	138.40	✓ CRA
22	2 pcs	Rear Bumper Number Plate Lamps		226.20	✓
23	2 pcs	Rear Air Vents	56.10	112.20	✓ NN
24	1 pc	End Panel		423.50	✓ BUC
25	1 pc	End Panel Top Trim		192.50	✓ CRA
26	1 set	End Panel Top Trim Clips		30.00	✓
27	1 pc	Spare Tyre Panel Top Tray Board		172.20	✓
28	2 pcs	Rear Fenders Inner Trim	269.30	538.60	✓ NN
29	2 set	Rear Fenders Inner Trim Clips	30.00	60.00	✓
30	1 pc	Rear Exhaust Silencer		989.50	✓ BTZ
31	2 pcs	Rear Exhaust Mountings	42.20	84.40	✓ NN
32	1 pc	Rear Exhaust Gasket		46.60	✓ NECZ

8,574.90

Less 20% 1,714.98

6,859.92

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No. : SJG 1772T

B/F

6,859.92

Special Nett

1	1 pc	Rear Number Plate	30	50.00	30
2	1 set	Reverse Sensor	200	250.00	220
3	1 pc	Reverse Camera	350	450.00	350
4	1 set	Rear Bumper Lower Side Spoiler	400	850.00	PCRA
5	1 set	Body Panel Joint Sealant	—	120.00	80

Labour charge

Panel Beating	800	1,200.00	800
Spray painting	900	1,200.00	900
Check Wiring	30	50.00	30
Anti rust	60	100.00	60
Remove and install carpet and seat.	60	120.00	60
Remove and install reverse sensor	60	90.00	60
Remove and install reverse camera	80	150.00	80
Remove and install rear exhaust silencer	80	120.00	80

List price - \$6,494.60

- 20%

\$5,195.68

+ S/N \$1,100.00

+ Labour \$2,070.00

\$8,365.68

X 80%

\$6,692.54

= L/S 6,700.00 with 7 days

Not Authorised
H/S Reason
6-7 wdays
After paint plate.
LKK Auto (MA)
15/11/2012

\$ 18,469.84

6 days

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SJG 1772T

Vehicle Model : MAZDA 3

Accident Date : 10.11.2016

Original Reg Date : 24.06.2008

Date : 11.11.2016

Chassis : JM6BK106280412956

TP Ins. AXA

ESTIMATE

1	1 pc	Boot Lid	✓		hse	993.00	✓
2	1 pc	Boot Lid Badge	✓		hse	62.00	✓
3	1 pc	Boot Lid Emblem MAZDA	✓		hse	48.20	✓
4	1 pc	Boot Lid Emblem 3	✓		hse	46.00	✓
5	1 pc	Boot Lid Emblem (SP)	✓		hse	46.20	✓
6	2 pcs	Boot Lid Lamps	✓	315.00	hse	630.00	✓
7	2 pcs	Boot Lid Lamps Inner Sealer	✓	30.00	hse	60.00	40 ✓
8	2 set	Boot Lid Lamps Clips	✓	25.00	hse	50.00	30 ✓
9	1 set	Boot Lid Insulator Clips	✓		hse	40.00	30 ✓
10	1 pc	Boot Lid Inner Lock	✓		hse	252.60	✓
11	1 pc	Boot Lid Lock Catch	X		R	75.20	
12	1 pc	Boot Lid Weatherstrip	✓		dig	119.70	✓
13	2 pcs	Taillamps	✓	794.90	hse	1,589.80	✓
14	2 pcs	Taillamps Inner Sealer	✓	30.00	hse	60.00	40 ✓
15	2 set	Taillamps Clips	✓	25.00	hse	50.00	30 ✓
16	1 pc	Rear Bumper	✓		hse	835.60	✓
17	2 pcs	Rear Bumper Side Retainers	✓	42.00	dig	84.00	✓
18	2 pcs	Rear Bumper Attachment Retainers	✓	36.00	dig	72.00	✓
19	1 set	Rear Bumper Clips	✓			50.00	40 ✓
20	1 pc	Rear Bumper Reinforcement	✓			396.50	DD
21	2 pcs	Rear Bumper Reflectors	✓	69.20		138.40	CRA
22	2 pcs	Rear Bumper Number Plate Lamps	✓		hse	226.20	✓
23	2 pcs	Rear Air Vents	X	56.10		112.20	NN
24	1 pc	End Panel	✓			423.50	BUC
25	1 pc	End Panel Top Trim	✓			192.50	CRA
26	1 set	End Panel Top Trim Clips	✓		hse	30.00	✓
27	1 pc	Spare Tyre Panel Top Tray Board	✓		dig	172.20	✓
28	2 pcs	Rear Fenders Inner Trim	X	269.30		538.60	NN
29	2 set	Rear Fenders Inner Trim Clips	X	30.00		60.00	NN
30	1 pc	Rear Exhaust Silencer	✓			989.50	BTZ
31	2 pcs	Rear Exhaust Mountings	X	42.20		84.40	NN
32	1 pc	Rear Exhaust Gasket	✓			46.60	NECZ
						8,574.90	
					Less 20%	1,714.98	
						6,859.92	

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: emlautopte ltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No. : SJG 1772T

B/F

6,859.92

Special Nett

1	1 pc	Rear Number Plate	✓	30	50.00	30
2	1 set	Reverse Sensor	✓	220	250.00	220
3	1 pc	Reverse Camera	✓	350	450.00	350
4	1 set	Rear Bumper Lower Side Spoiler	✓	200	850.00	PCRA
5	1 set	Body Panel Joint Sealant	✗	—	120.00	80

Labour charge

Panel Beating	800	1,200.00	800
Spray painting	900	1,200.00	900
Check Wiring	30	50.00	30
Anti rust	60	100.00	60
Remove and install carpet and seat.	60	120.00	60
Remove and install reverse sensor	60	90.00	60
Remove and install reverse camera	80	150.00	80
Remove and install rear exhaust silencer	80	120.00	80

\$ 18,469.84

✓ Lot Authorized
H/S Repare
6-7 wdays
After panel photo.
LKK Auto (MHA)
15/11/2012

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8690A

D.O.A - 10/11/2016
Bal - 1yr 7.4mths

Vehicle Details

Vehicle No.: SJG1772T

Vehicle to be Exported: Yes

Intended De-registration Date: 12 Nov 2016

Vehicle Make: MAZDA

Vehicle Model: MAZDA3SP LUX

Primary Colour: Silver

Manufacturing Year: 2008

Engine No.: Z6689912

Chassis No.: JM6BK106280412956

Maximum Power Output: 79.0 kW (105 bhp)

Open Market Value: \$16,135.00

Original Registration Date: 24 Jun 2008 ✓

First Registration Date: 24 Jun 2008

Transfer Count: 1

Actual ARF Paid: \$16,135.00

81067

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 23 Jun 2018 ✓

PARF Rebate Amount: \$8,874.00

Intended COE Rebate Details

COE Expiry Date: 23 Jun 2018 ✓

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$14,590.00

COE Rebate Amount: \$2,354.00

Total Rebate Amount: \$11,228.00 ✓

The information contained herein is correct as at 11 Nov 2016

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 8.0, COE and 4th Nov 1074 V 7.68 resolution



Username / Email Add
password

Sign Up New Account
Forgot Password

Mazda 3 Price Range: 2008 Transmission: Vehicle Type

Advanced Search

Home » Used Cars » Happy Motor » Mazda 3 1.6A SP Luxury

Tools & Tips

[Car Buying](#)

[Car Selling](#)

[Car Aftermarket](#)

[Car Ownership](#)

[On The Move](#)

[Lifestyle](#)



Mazda 3 1.6A SP Luxury

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

[Add to Compare](#) [Add to Shortlist](#) [Add a Note](#) [Report Error](#) [More Actions](#) [Share](#)

Car Details

Price	\$27,800
Reg Date	06-Jul-2008
Mileage	98,232 km
Transmission	Auto
Engine Cap	1,598 cc
Road Tax	\$742 /yr
Power	79.0 kW (105 bhp) View specs of the Mazda 3 Sedan (2004-2009)
Features	16 Valves, DOHC, VVT Engine, 4 Speed Tiptronic Gearbox Auto Transmission, Multi Function Steering Audio Controls, Immobilizer, ABS, Dual SRS Airbags.
Accessories	Leather Seats, Sports Rims, Retractable Side Mirrors, Built In Audio System With Steering Audio Controls, Knockdown Rear Seats, Reverse Sensors.
Description	1 Owner Only, High OHV \$16,283, Well Maintained Clean Interior Leather, Excellent Engine And Smooth Transmission, View To Believe! Hurry! Trade In Welcome, Car Available In Showroom For Viewing Now, Contact For More Details.
CDE	\$14,101
OHV	\$16,283
Depreciation	N.A. Use the Depreciation Calculator to get estimated figure
No. of Owners	1
Type of Veh	Mid-Sized Sedan
Category	PARF Car
Availability	Available
Like	82%

Posted on: 03-Nov-2016 | Last Updated on: 11-Nov-2016

Tags: Mazda 3, 2008 Mazda 3, Mazda, Mazda 3, Used Mazda

Upfront Payment

» more Financial info

Transfer Fee	\$11	
Down Payment	\$8,340 (change)	Maximum 70% Loan
1st Instalment	\$1,073	
Total Upfront Payment	\$9,424 (excluding insurance)	

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.

Items for Mazda Mazda 3

» View All



10M Team 5192 17" Rim
From \$130



Real Bumper
\$100

Compare [1]



Seller Information

Company	Happy Motor » dealer's pricelist » 40 vehs sold 16 vehs available	
Address	61 Ubi Avenue 2 #04-14 Search cars nearby this location	
Location	Automobile Megamart	
Office No	68442228	
Contact Person(s)	Desmond Sham	90216517 84228768

Useful Services



Make sure of this car condition with STA Evaluation.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SJG 1772T
Vehicle Model : MAZDA 3
Accident Date : 10.11.2016
Original Reg Date : 24.06.2008

Date : 11.11.2016
Chassis : JM6BK106280412956
TP Ins. : AXA

ESTIMATE

1	1 pc	Boot Lid		993.00	✓
2	1 pc	Boot Lid Badge		62.00	✓
3	1 pc	Boot Lid Emblem MAZDA		48.20	✓
4	1 pc	Boot Lid Emblem 3		46.00	✓
5	1 pc	Boot Lid Emblem (SP)		46.20	✓
6	2 pcs	Boot Lid Lamps	✓ 315.00	630.00	
7	2 pcs	Boot Lid Lamps Inner Sealer	✓ 30.00	60.00	40 ✓ ?
8	2 set	Boot Lid Lamps Clips	25.00	50.00	30 ✓
9	1 set	Boot Lid Insulator Clips		40.00	30 ✓
10	1 pc	Boot Lid Inner Lock		252.60	✓
11	1 pc	Boot Lid Lock Catch		75.20	
12	1 pc	Boot Lid Weatherstrip		119.70	✓
13	2 pcs	Taillamps	✓ 794.90	1,589.80	
14	2 pcs	Taillamps Inner Sealer	30.00	60.00	40 ✓
15	2 set	Taillamps Clips	25.00	50.00	20 ✓
16	1 pc	Rear Bumper		835.60	✓
17	2 pcs	Rear Bumper Side Retainers	42.00	84.00	
18	2 pcs	Rear Bumper Attachment Retainers	36.00	72.00	
19	1 set	Rear Bumper Clips		50.00	40 ✓
20	1 pc	Rear Bumper Reinforcement		396.50	?
21	2 pcs	Rear Bumper Reflectors	69.20	138.40	?
22	2 pcs	Rear Bumper Number Plate Lamps		226.20	
23	2 pcs	Rear Air Vents	56.10	112.20	X
24	1 pc	End Panel		423.50	?
25	1 pc	End Panel Top Trim		192.50	?
26	1 set	End Panel Top Trim Clips		30.00	
27	1 pc	Spare Tyre Panel Top Tray Board		172.20	
28	2 pcs	Rear Fenders Inner Trim	269.30	538.60	
29	2 set	Rear Fenders Inner Trim Clips	30.00	60.00	
30	1 pc	Rear Exhaust Silencer		989.50	?
31	2 pcs	Rear Exhaust Mountings	42.20	84.40	X
32	1 pc	Rear Exhaust Gasket		46.60	?

8,574.90

Less 20% 1,714.98

6,859.92

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No. : SJG 1772T

B/F

6,859.92

Special Nett

1	1 pc	Rear Number Plate		50.00	30
2	1 set	Reverse Sensor		250.00	220
3	1 pc	Reverse Camera		450.00	350
4	1 set	Rear Bumper Lower Side Spoiler		850.00	?
5	1 set	Body Panel Joint Sealant		120.00	80

Labour charge

Panel Beating		1,200.00	800
Spray painting		1,200.00	900
Check Wiring		50.00	30
Anti rust		100.00	60
Remove and install carpet and seat.		120.00	60
Remove and install reverse sensor		90.00	60
Remove and install reverse camera		150.00	80
Remove and install rear exhaust silencer		120.00	80

S 18,469.84

Not Authorized
H/S Reason
6-7 wdays
After paint photo.
LKK Auth (MA)
15/11/2012

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vale Oh

Date: 16 Nov 2016

Preliminary Advice

Insured Vehicle No	: SHB7835G	Accident Date	: 10/11/2016
TP Vehicle No	: SJG1772T	Assignment Date	: 14/11/2016
Make	: MAZDA MAZDA5	Est. Duration of Repair	: 6-7 days
Date of Inspection	: 15/11/2016		
Inspection At	: Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68 Singapore 575643		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,469.84
Revised Amount	:S\$	6,116.08
Check Items (Estimated)	:S\$	2,329.60
Total	:S\$	8,445.68

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

Poh Kin (LKKAUTO)

From: Chia Sin Muk <em1autopteltd@gmail.com>
Sent: Monday, 25 March 2019 4:28 PM
To: Poh Kin (LKKAUTO)
Cc: Admin A
Subject: Re: RTA involving vehicle nos. SHB 7835G and SJG 1772T on 10.11.2016 - TP AXA

WITHOUT PREJUDICE

Dear Poh Kin,

Agree on your offer \$ 8,100

Kindly arrange DV to us.

Thanks & Best Regards,

Nicole, on behalf of,

Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

On Mon, 25 Mar 2019 at 08:44, Poh Kin (LKKAUTO) <pohkin@lkkauto.com> wrote:

"Without Prejudice"

"Save As To Costs"

Our Ref: CC4/AXA16021636/M1fa3

Your Ref: SJG 1772T

Dear Sir/Madam,

We refer to the above matter.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Monday, 25 March 2019 8:45 AM
To: 'Chia Sin Muk'
Cc: Admin A
Subject: RE: RTA involving vehicle nos. SHB 7835G and SJG 1772T on 10.11.2016 - TP AXA

Importance: High

"Without Prejudice"

"Save As To Costs"

Our Ref: CC4/AXA16021636/M1fa3
Your Ref: SJG 1772T

Dear Sir/Madam,

We refer to the above matter.

towards an amicable settlement and without admission of liability to our Insured's part, we have instruction from our principal to offer at global sum of **\$ 8,100.00(all in)**:

Kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Chia Sin Muk [mailto:em1autopteltd@gmail.com]
Sent: Tuesday, 19 February 2019 5:17 PM

Print Received Message

This mail is associated with :

***SJG1772T (C0407770)**

[SHB7835G]

TP

WEE YEW YEE

Nov 10 2016 3:00PM

[TRANS-CAB SERVICES PTE LTD]

Em-1 Auto Pte Ltd

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 22/03/2019 13:48 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8110.60) - SJG1772T - Claim Handler: Chan Kian Chuan

Approved:8110.60.

Print Sent Message

This mail is associated with :

***SJG1772T (C0407770)**
[SHB7835G]

TP
WEE YEW YEE
Nov 10 2016 3:00PM
[TRANS-CAB SERVICES PTE LTD]
Em-1 Auto Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 15/03/2019 17:49 PM.
To AXA_SG
CC pohkin@lkkauto.com; admin-a@lkkauto.com
Subject <Seek Mandate> C0407770

Our Ref: CC4/AXA16021636/M1fb3
Your Ref: C0407770

Dear Sir/Madam,

Liability: Insured driver collided into the rear of third party vehicle. Liability is down against our insured.

Send letter to OI via E-mail to notify TP claim and excess amount on 23rd January 2017.

Immediate Advice (with mandate) have been uploaded in Merimen. We hereby seek your approval to offer Third Party repairer M/s "EM-1 Auto Pte Ltd" is as follows: -

1) COR(w/gst): \$7,169.00 + 2) Loss of Rental (7daysx\$100.00)+7% gst: \$749.00 +3) Medical fee: 192.60
=Total: **\$8,110.60.**

**07days recommendation for repair.

**All the relevant documents had been uploaded in Merimen.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 15/03/2019

Survey Details:

Date of loss	10-Nov-16
Date of appointment	14-Nov-16
Date of survey	15-Nov-16
Location of survey	EM-1 AUTO PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SJG 1772T
Make and Model	MAZDA 3 - 1598CC
Date of registration	24/6/2008
Excess	
Market Value	\$25,000
Part Rebate	\$11,228
Nett Loss	\$13,772

Repair details:

Initial Estimate	\$ 18,469.84
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 6,295.68	list price -20%
Check items (estimate)	\$ -	
Labour	\$ 2,070.00	
Total (I/B/I)	\$ 8,365.68	
Lump Sum(if applicable)	\$ 6,700.00	after -20%

Number of days for repair	7
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs.

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 7,169.00	(\$6,700.00 + 7%gst)
Loss of use	\$ -	
Loss of rental	\$ 749.00	(\$100.00 x 7 days)+7%gst
Loss of income	\$ -	
LTA search fees	\$ -	
Medical fee	\$ 192.60	
Proposed Total	\$ 8,110.60	

Poh Kin (LKKAUTO)

Subject: FW: LOD - SJG 1772T DOA 10.11.2016 - TP AXA
Attachments: 1772a-12092018105625.pdf

----- Forwarded message -----

From: **Chia Sin Muk** <em1autopteltd@gmail.com>
Date: Mon, 21 Jan 2019 at 10:33
Subject: Fwd: LOD - SJG 1772T DOA 10.11.2016 - TP AXA
To: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>

WITHOUT PREJUDICE

Dear Sir/Madam,

Please find the attached LOD.

COR \$ 7,169.00
Med \$ 192.60
LOR \$ 786.45
Total : \$ 8,148.05

Kindly arrange for settlement.

Thanks & Best Regards,

Nicole, on behalf of,

Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

Zayyer (LKKAuto)

From: Zayyer (LKKAuto)
Sent: Monday, 23 January, 2017 4:58 PM
To: 'claims@transcab.com.sg'
Cc: 'carrisalee@ava-ins.com'; 'icewong@ava-ins.com'; 'ireneng@ava-ins.com'; 'foonghon@ava-ins.com'
Subject: RE: ACCIDENT INVOLVING SHB 7835G & SJG 1772T ALONG / AT MOUNT ALVERNIA HOSPITAL EXIT TOWARDS LORNIE ROAD on 10/11/2016

Resend.

23 January 2017

Transcab Taxi
Singapore

Dear Sir/Mdm,

YOUR REF : SHB 7835G
OUR REF : CC4/AXA16021636/M1za3

ACCIDENT INVOLVING SHB 7835G & SJG 1772T ALONG / AT MOUNT ALVERNIA HOSPITAL EXIT TOWARDS LORNIE ROAD on 10/11/2016

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s **EM-1 AUTO PTE LTD** acting on behalf of the owner of **SJG 1772T** against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties, we are of the opinion that we cannot be absolved from liability.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We also wish to advise that there is an excess of **S\$5000.00** attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim. The applicability of the excess is as follows:

- (1) Any settlement equal to or above the excess, you shall be liable to make the payment of **S\$5000.00**; or
- (2) Any settlement below the excess, you shall be liable for the amount settled.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Singapore Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by AXA for the above subject matter, AXA expressly reserves all their rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to zayyer@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to est@axa.com.sg or deliver it by hand to AXA's Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorized driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at **6841 2409** or email us at zayyer@lkkauto.com Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Zayyer
LKK auto Consultants Pte Ltd

Cc Motor Claims Department
AXA Insurance Singapore Pte Ltd

LETTER OF AUTHORISATION

ACCIDENT INVOLVING (my vehicle) SJ61772T and SHB7835G,
ON 10/11/16 ALONG Mt. Alvernia Hospital exit to Lorne Rd

I, Wee Yew Yee, NRIC No. / Company Reg. No.
S7618690A of (address) _____

Postal Code _____, the registered owner (or authorised agent) of motor vehicle registration number
SJ61772T hereby authorise your workshop EM-1 Auto Pte Ltd (Company/GST REG.No. : 201316380R)

Blk 8 #01-68 Sector C Sin Ming Industrial Estate Singapore 575643 to :-

1. Begin or commence repairs to my/our motor vehicle;
2. Start or initiate third party claims for damages incurred by me against third party(ies) responsible for the accident.
3. To instruct EM-1 Auto Pte Ltd on my/our behalf to negotiate a settlement with the third party and/ or his insurers as you deem fit.
4. To appoint vehicle surveyor on my/our behalf to determine reasonable costs of repair and period of repair.
5. To act on my/our behalf for any documents mailed to EM-1 Auto Pte Ltd by the third party and/or his insurers for the claim of my vehicle, if I am not contactable.

I am prepared to attend at my/our solicitors' office or to attend Court in connection with my/our claim, if necessary, I shall give my full co-operation and support for the claim for cost of repair and loss of use and shall keep you informed of any correspondences and/or summons that I may receive due to this action before agreeing to pay up or receive any monies due to this claim.


I authorise you to claim for the period of loss of use as specified by the motor surveyor or such shorter period due to accelerated work. I further authorise you to accelerate the repair period with overtime work and additional resource, I will pay you a reasonable amount to reflect the additional period of time to shorten.

I agree to keep you informed of any document(s), including cheques, mailed to me by third party and/or his insurers before taking any action. I also will not bank in any cheques issued by third party insurance and/or his insurers without the approval of EM-1 Auto Pte Ltd, and should I get approval from EM-1 Auto Pte Ltd to bank in the said cheques, I agree to pay EM-1 Auto Pte Ltd the full settlement amount as stated on the cheques within 5 working days.

Should my/our claim be partly successful or unsuccessful or cannot be proceeded with and/or if any judgement or settlement is not honoured or satisfied by third party, I/We:

1. Agree to pay you the sum of monies (as agreed) or as certified by the surveyor appointed, being the costs of repairs, survey fees and/or any other expenses reasonably incurred by you on my/our behalf. You may use the recovered amount from my claim for loss of us to partially offset the difference.
2. Agree to pay you such increased cost for additional resources and overtime work to shorten the period of repair.
3. Will pay for any shortfall that may result in the settlement amount.

In the event that EM-1 Auto Pte Ltd or the Repairer is compelled to enforce this undertaking, I/We agree that I/we shall pay on a full indemnity basis, the legal costs incurred by EM-1 Auto Pte Ltd or the Repairer.

Signature: 

Company Stamp:
(if applicable)

Name: Wee Yew Yee

NRIC No: S7618690A

Contact No: 96455551

Date: 10/11/16



Provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude me from making a further claim for general and special damages for my personal injuries sustained in the same accident.

AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	348 78382 (insd veh)	Model: Mazda 3
	348 17221 (TP veh)	
Date of Accident/ Time:	10/11/2016	

Repair Estimate	: \$	11,503.92	
Final Repair Cost	: \$	7,189.00	(\$6,700.00 + 7%gst)
Loss of Use	: \$	Nil	days at \$ per day
Rental (if any)	: \$	749.00 (w/gst)	7 days at \$ 100.00 per day
LTA / GIA Search Fee	: \$	Nil	
Others:	: \$	192.00	
	: \$	Nil	
Final Settlement Sum	: \$	8,130.00	

Payee Name: EM-1 Auto Pte Ltd

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop:	Agreed Liability: 100 (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (**): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks:	

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

 Signature of workshop representative / Workshop stamp Name of Representative: Chia Sin Hark Date: 7/5/19	 Signature of Witness / Workshop stamp (if applicable) Name of Witness: Chang Mee Choo Date: 7/5/19
 Signature of AXA's surveyor/representative Name of AXA's surveyor / Representative: MUF Date: 7/5/19	

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

TAX INVOICE

M/S WEE YEW YEE

Invoice No : 19/00134/4815TP

Date : 29-Mar-2019

AXA Insurance Singapore Pte Ltd

Motor Claim Department

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Date of Accident : 10-Nov-2016

Our Client's Vehicle Number : SJG 1772T

Vehicle Make / Model : MAZDA 3

Your Insurer : SHB 7835G

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Lump Sum Repair Cost (Recommended by LKK Mr Ma)	6,700.00	469.00	7,169.00 SR

SGD (Seven Thousand One Hundred Sixty-Nine only)

GRAND TOTAL

7,169.00

Subject to 7% GST

469.00



Authorised Signature and Company Stamp



友立旅遊服務私人有限公司
UNIQUE TOURIST SERVICE (PTE) LTD

1, Rochor Centre, # 02-574,
Singapore 0718.
Tel: 2927656
Fax: (65) 2939720
STPB LIC TA076

GST Reg. No.: M2-0019671-6

Mr Wee Yew Yen
Blk 403C Fernvale Lane
12-163
Singapore 793403

20, Sin Ming Lane,
#08-51, Midview City
Singapore 573968
Tel: 6292 7656

TAX INVOICE

NO. WP21102

Singapore, 19.11.2016 19

DATE	PARTICULARS	Ⓔ	₹	cts
	Rental of one unit Toyota Corolla Altis 1.6 Auto Registration no. SJG 4847 S self driven as from 11.11.2016 to 18.11.2016.			
	7 days at \$105.00 per day		\$	735.00
			\$	735.00
	Add GST at 7%		\$	51.45
	Amount Due		\$	786.45
	(SIN DOLLARS: SEVEN HUNDRED EIGHTY SIX AND FORTY FIVE CENTS ONLY)			
	Standard Rated Supplies: \$	735.00		
	Total Amount of GST: \$	51.45		


AUTHORISED SIGNATURE



UNIQUE TOURIST SERVICE (PTE) LTD.

APT. BLK 1, ROCHOR ROAD, #02-574, ROCHOR CENTRE, SINGAPORE 180001

TEL: 6292 7656 FAX: 6293 9720 EMAIL: unigtour@singnet.com.sg

COMPANY REG NO: 197401067R

GST REG NO: M2-0019671-6

THIS IS NOT A TAX INVOICE

20, Sin Ming Lane,
#08-51, Midview City

Singapore 573968

6292 7656

CAR RENTAL AGREEMENT

RA No. 20595

VEHICLE NO. SJG 4847S MAKE/MODEL TOYOTA COROLLA DUTIS

NAME OF HIRER Woe Yew Yee
ADDRESS BLK 403C Fernvale Lane, #12-163
SINGAPORE 793463
OFFICE TEL _____ RES TEL _____ HP 96455551
NAMED DRIVER _____
OCCUPATION _____ NATIONALITY SINGAPORE
PASSPORT / NRIC S7618690A DATE OF BIRTH 3/7/1976
DRIVING LIC NO. S7618690A
PLACE OF ISSUE Singapore DATE PASS/EXPIRY 15/7/96

ADDITIONAL NAMED DRIVER
ADDRESS _____
SINGAPORE _____
OFFICE TEL _____ RES TEL _____ HP _____
OCCUPATION _____ NATIONALITY _____
PASSPORT / NRIC _____ DATE OF BIRTH _____
DRIVING LIC NO. _____
PLACE OF ISSUE _____ DATE PASS/EXPIRY _____

BY INITIATING MARK "X" HIRER AGREE TO PAY THE FOLLOWINGS
A. COLLISION DAMAGE WAIVER (CDW) AT \$ _____ PER DAY / WEEK / MONTH "X"
B. SURCHARGE OF \$ _____ FOR USE IN MALAYSIA FROM
TO "X" "X"
* THE HIRER IS RESPONSIBLE FOR ANY DAMAGES UP TO THE EXTENT OF TOTAL LOSS OF
CAR, LOSS OF INCOME AND COST OF RECOVERY OF VEHICLE IF THE CAR IS DRIVEN INTO
MALAYSIA WITHOUT PRIOR CONSENT FROM THE COMPANY.

COMPULSORY EXCESS, DOLLAR \$ 1200 =

NOTE: HIRER IS LIABLE FOR ALL PARKING & TRAFFIC VIOLATIONS.
YOUR ATTENTION IS DRAWN TO TERMS & CONDITIONS
PRINTED OVERLEAF.

FOR SINGAPORE DRIVE ONLY

DATE: _____ SIGNATURE OF HIRER [Signature]

DATE OUT 11/11/16 TIME OUT 12:05
PETROL OUT E 1/4 1/2 3/4 (P)
DATE IN 18/11/16 TIME IN 13:00
PETROL IN E 1/4 1/2 3/4 F
RENTAL RATES: \$ C
MONTHLY @ \$ _____
WEEKLY @ \$ _____
DAILY 7 @ \$105 = 735.00
C.D.W. FEE _____
PETROL CONSUMPTION _____
DELIVERY CHARGE _____
COLLECTION CHARGE _____
SUB-TOTAL _____
GST 7.1 51.45
RENTAL DEPOSIT _____
TOTAL 786.45

DEPOSIT REFUND

PAYMENT BY: BILL TO / CREDIT CARD / CASH

ATTENDED BY: [Signature]
OF UNIQUE TOURIST SERVICE (PTE) LTD

DECLARATION

I HEREBY DECLARE THAT NO MOTOR
ACCIDENT HAD OCCURED DURING MY HIRE
OF YOUR MOTOR VEHICLE AS STATED IN
THE ABOVE MENTIONED SCHEDULE * OR TO
ANY SUBSTITUTED VEHICLE AS STATED
IN THE MEMORANDUM DATED.

REPLACEMENT VEHICLE NO:

1. _____ ON _____ TIME _____
2. _____ ON _____ TIME _____
3. _____ ON _____ TIME _____

DATE: _____ SIGNATURE OF HIRER [Signature]



a clinic for women

Mount Alvernia Medical Centre Bldg D #08-58 820 Thomson Road Singapore 574623
Tel: 65-6463 3366 Website: www.aclinicforwomen.com.sg

OFFICIAL RECEIPT

KANG MUTIAN

Patient Reg No : 12764

GST Reg No : 20-0210156-G

Receipt Date : 10/11/2016

Receipt No : 47235

NRIC/PP No : SH8373729

ULTRASOUND OBS VIABILITY

\$90.00

REVIEW CONSULTATION SHORT

\$90.00

Payment : **\$192.60 Visa**

SubTotal : \$180.00

GST Amount : \$12.60

Total Fee : \$192.60

Signature :

citibank

A CLINIC FOR WOMEN P L
820 THONGCH ROAD
#08-58 MOUNT ALVERNIA MEDICAL CENTRE BLK
SINGAPORE 574621

DATE/TIME: 10/11/16 16:25:51
MID: 000888100060627
TID: 36243336 INV: 005028
BATCH: 000497 TRACE: 009603
ORDER: 005028-000497009603
APR/AUTH CODE: 004424

SALE

VISA ***** 5366
ENT: CHIJ REF: 000011009603
CARD LABEL: VISA TSI: FB00
TVR: 0080008000 AID: A0000000031010
APP CRYPT: 30484DF21E84C585

BASE : S\$ 192.60

TOTAL : S\$ 192.60

I AGREE TO PAY THE ABOVE TOTAL AMOUNT
ACCORDING TO THE CARD ISSUER AGREEMENT
**** CUSTOMER COPY ****

To Whom It May Concern:

Accident Involving SJG1772 T on
10-11-2016 along MT Alvernia hospital car park exit to Lorne. Road

I, KANG MUTIAN, NRIC: S8373729H,
hereby confirmed that I was the *driver / passenger of SJG1772 T (vehicle no.)
when involved in the above accident.

I was injured due to the above accident, and seek medical treatment at
Co. Clinic for women, and incurred
a total of S\$ 192.60 for my medical expenses. I hereby confirmed that I am
only seeking reimbursement on the above medical expenses and do not have any further
claims with regards to my injury for the above accident.



Signature of *Driver / Passenger

*Delete where appropriate



[Handwritten signature]

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Nov 2016		14 Nov 2016 10:51 Edit Adj Rpt	S\$6,700.00 Edit Estimates	S\$6,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K									
Main Claimant: WEE YEW YEE , ID: S7618690A									
Vehicle Reg. No.: SJG1772T		Date of Loss: 10/11/2016 15:00 - :59 [100 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / C0407770		Policy/Cover Note No.: P1680520 (Third Party Only)							
Vehicle Reg. No. (Insured): SHB7835G		Policy No. (Claimant): Z16VP05010383							
		Excess: S\$5,000.00							
Repairer: Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298									
Handling Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Chan Kian Chuan - 6880 4269]									
Claimant's Insurer: Longpac Insurance Bhd (HQ) - Tel: +65 62507388									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 23/11/2016]									
Driver/Custodian (Insured): HING GIM YONG (WANG JINRONG) (41 / Male) , NRIC: S7520527I, Tel: +6590663057 Email:									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AXA_SG (22/03/2019): Alert - Adj Mandate Approved (S\$8110.60) - SJG1772T - Claim Handler: Chan Kian C... - AXA_SG (14/11/2016): New TP Assignment - C0407770/P1680520									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJG1772T (C0407770)
[SHB7835G]
TP
WEE YEW YEE
Nov 10 2016 3:00PM
[TRANS-CAB SERVICES PTE LTD]
Em-1 Auto Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1 Edit	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/11/16 17:12	Adjuster Immediate Advice	1 Load HTM	

Documentation

1 per page

No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	11/11/16 17:10	EMAIL_ABS	1 Load PDF	
2	11/11/16 17:10	CO-CLAIMANT_ABS	1 Load PDF	
3	11/11/16 17:10	SHB7835G INSD GIA REPORT_ABS	1 Load PDF	
4	11/11/16 17:10	SJG1772T TP GIA REPORT_ABS	1 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/11/16 15:32	TP ESTIMATE - MARKED	1 Load PDF	
2	15/03/19 17:43	Immediate Advice (with mandate) dated 15.03.2019	1 Load PDF	
3	15/03/19 17:43	Letter to OI	1 Load PDF	
4	15/03/19 17:43	LKK Resurvey Photo- after repair	1 Load PDF	
5	15/03/19 17:43	LKK Resurvey Photo	1 Load PDF	
6	15/03/19 17:43	LKK Survey Photo	1 Load PDF	
7	15/03/19 17:43	Medical tax invoice	1 Load PDF	
8	15/03/19 17:43	PRAF and COE rebate form	1 Load PDF	
9	15/03/19 17:43	Rental Agreement and tax invoice	1 Load PDF	
10	15/03/19 17:43	TP Estimate marked- revise	1 Load PDF	
11	15/05/19 10:05	WORKSHOP INVOICE	1 Load PDF	
12	15/05/19 10:05	AUTHORISATION TO ACT FORM	1 Load PDF	
13	15/05/19 10:05	DS FORM	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHB7835G (Insd veh)	Model:	MAZDA 3 1.6 (A)
	SJG1772T (TP veh)		
Date of Accident:	10/11/2016		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	12,422.61
Final Repair Cost	:	\$	7,169.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	749.00 7 days
LTA / GIA Search Fee	:	\$	0.00
Others: Medical Fee	:	\$	192.60
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	8,100.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Em-1 Auto Pte Ltd	:	\$ 8,100.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

15 May
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16021636/M1FA3Q2
Date: 15/05/2019

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1680520
Claimant Vehicle No :	SJG1772T	Insured Vehicle No :	SHB7835G
Date of Loss:	10/11/2016	Nature of Claim:	TP
		Claim No:	C0407770

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG1772T		
Make & Model:	MAZDA 3, 1.6 (A)	Engine No:	Z6689912
Reg. Date:	24/06/2008 (Man. Year: 2008)	Chassis No:	JM6BK106280412956
Colour:	Silver	Odometer:	150223 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 8 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,579.92	6,295.68	2,284.24	26.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,030.00	2,070.00	960.00	31.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,609.92	8,365.68	3,244.24	27.94
Approved Total (Overridden) (S\$)		6,700.00		
(S\$)	11,609.92	6,700.00	4,909.92	42.29
+ GST 7.00/7.00% (S\$)	812.69	469.00	343.69	42.29
Nett Amount (S\$)	12,422.61	7,169.00	5,253.61	42.29
+ Medical Costs (S\$)		192.60		
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$)		749.00		
Nett Liability (S\$)		8,110.60		
Global Sum Settlement (S\$)		8,100.00		

INSPECTION

Date of Assignment:	14/11/2016
Date Inspected:	15/11/2016 Inspected At:

Em-1 Auto Pte Ltd (HQ)
Blk 8 Sin Ming Industrial Estate Sector C,
#01-68
Singapore 575643

Estimated Period of Repair: 7.0 days

Adjuster: MA CHIN FOOK

Manager: Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 May 2019)
Parts: 144	MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJG1772T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID (CONSISTENT)	Bent	993.00 FL	*993.00 FL
2	1		*BOOT LID BADGE (CONSISTENT)	Necessary	62.00 FL	*62.00 FL
3	1		*BOOT LID EMBLEM MAZDA (CONSISTENT)	Necessary	48.20 FL	*48.20 FL
4	1		*BOOT LID EMBLEM 3 (CONSISTENT)	Necessary	46.00 FL	*46.00 FL
5	1		*BOOT LID EMBLEM (SP) (CONSISTENT)	Necessary	46.20 FL	*46.20 FL
6	1		*BOOT LID LAMPS (CONSISTENT)	N/S Cracked / O/S Serviceable	630.00 FL	*315.00 FL
7	2		*BOOT LID LAMPS INNER SEALER (CONSISTENT)	Necessary	60.00 FL	*40.00 FL
8	2		*SET BOOT LID LAMPS CLIPS (CONSISTENT)	Necessary	50.00 FL	*30.00 FL
9	1		*SET BOOT LID INSULATOR CLIPS (CONSISTENT)	Necessary	40.00 FL	*30.00 FL
10	1		*BOOT LID INNER LOCK (CONSISTENT)	Bent	252.60 FL	*252.60 FL
11	1		*BOOT LID LOCK CATCH (CONSISTENT)	Repair	75.20 FL	*- FL
12	1		*BOOT LID WEATHERSTRIP (CONSISTENT)	Distorted	119.70 FL	*119.70 FL
13	1		*TAILLAMPS (CONSISTENT)	O/S Serviceable / N/S Cut	1,589.80 FL	*794.90 FL
14	2		*TAILLAMPS INNER SEALER (CONSISTENT)	Necessary	60.00 FL	*40.00 FL
15	2		*SET TAILLAMPS CLIPS (CONSISTENT)	Necessary	50.00 FL	*30.00 FL
16	1		*REAR BUMPER (CONSISTENT)	Necessary	835.60 FL	*835.60 FL
17	2		*REAR BUMPER SIDE RETAINERS (CONSISTENT)	Distorted	84.00 FL	*84.00 FL
18	2		*REAR BUMPER ATTACHMENT RETAINERS (CONSISTENT)	Distorted	72.00 FL	*72.00 FL
19	1		*SET REAR BUMPER CLIPS (CONSISTENT)	Necessary	50.00 FL	*40.00 FL
20	1		*REAR BUMPER REINFORCEMENT (CONSISTENT)	Dented	396.50 FL	*396.50 FL
21	2		*REAR BUMPER REFLECTORS (CONSISTENT)	Cracked	138.40 FL	*138.40 FL
22	2		*REAR BUMPER NUMBER PLATE LAMPS (CONSISTENT)	Missing	226.20 FL	*226.20 FL
23	2		*REAR AIR VENTS (CONSISTENT)	Not Necessary	112.20 FL	*- FL
24	1		*END PANEL (CONSISTENT)	Buckled	423.50 FL	*423.50 FL
25	1		*END PANEL TOP TRIM (CONSISTENT)	Cracked	192.50 FL	*192.50 FL
26	1		*SET END PANEL TOP TRIM CLIPS (CONSISTENT)	Necessary	30.00 FL	*30.00 FL
27	1		*SPARE TYRE PANEL TOP TRAY BOARD (CONSISTENT)	Distorted	172.20 FL	*172.20 FL
28	2		*REAR FENDERS INNER TRIM (CONSISTENT)	Not Necessary	538.60 FL	*- FL
29	2		*SET REAR FENDERS INNER TRIM CLIPS (CONSISTENT)	Not Necessary	60.00 FL	*- FL
30	1		*REAR EXHAUST SILENCER (CONSISTENT)	Bent	989.50 FL	*989.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
31	2		*REAR EXHAUST MOUNTINGS (CONSISTENT)	Not Necessary	84.40 FL	*- FL
32	1		*REAR EXHAUST GASKET (CONSISTENT)	Necessary	46.60 FL	*46.60 FL
33	1		*REAR NUMBER PLATE (CONSISTENT)	Necessary	50.00 FS	*30.00 FS
34	1		*SET REVERSE SENSOR (CONSISTENT)	Shorted	250.00 FS	*220.00 FS
35	1		*REVERSE CAMERA (CONSISTENT)	Shorted	450.00 FS	*350.00 FS
36	1		*SET REAR BUMPER LOWER SIDE SPOILER (CONSISTENT)	Cracked	850.00 FS	*500.00 FS
37	1		*SET BODY PANEL JOINT SEALANT (CONSISTENT)	Serviceable	120.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc						
Sub Total (S\$)					10,294.90	7,594.60
- List Item Discount on L Items 20.00/20.00% (S\$)					1,714.98	1,298.92
Total Parts (S\$)					8,579.92	6,295.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	900.00
3	CHECK WIRING	New	50.00	30.00
4	ANTI RUST	New	100.00	60.00
5	REMOVE AND INSTALL CARPET AND SEAT	New	120.00	60.00
6	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	60.00
7	REMOVE AND INSTALL REVERSE CAMERA	New	150.00	80.00
8	REMOVE AND INSTALL REAR EXHAUST SILENCER	New	120.00	80.00
Gross Labour Cost (S\$)			3,030.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >