



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Estimation No. : E16110058

Vehicle No : SJB9117J
Make & Model : MERCEDES BENZ,E200 ML
Year of : 2005
Manufacture

No	Description	Qty	U/P	Amt
Section: List Items				
		1.00	0.00	0.00 ?
1	Rear bumper	1.00	0.00	0.00 ✓
2	Rear bumper clip	1.00	0.00	0.00 X
3	Rear bumper side retainer RH	1.00	0.00	0.00 X
4	Rear bumper bracket RH	1.00	0.00	0.00 X
5	Rear bumper sponge	1.00	0.00	0.00 ✓
6	Rear bumper chrome moulding	1.00	0.00	0.00 X
7	Rear bumper protector	1.00	0.00	0.00 X
8	Taillamp RH	1.00	0.00	0.00 X
9	Taillamp clip RH	1.00	0.00	0.00 X
10	RH rear fender	1.00	0.00	0.00 X
11	RH rear fender cowling	1.00	0.00	0.00 X
12	RH rear fender cowling clips	1.00	0.00	0.00 X
13	RH rear door	1.00	0.00	0.00 ?
14	RH rear door lock	1.00	0.00	0.00 X
15	RH rear door weatherstrip	1.00	0.00	0.00 ✓
16	RH rear door protector	1.00	0.00	0.00 ✓
17	RH rear door outer chrome moulding	1.00	0.00	0.00 ✓
18	RH rear door outer handle	1.00	0.00	0.00 ?
19	RH rear door regulator	1.00	0.00	0.00 ?
20	RH rear door power motor	1.00	0.00	0.00 ✓
21	RH rear rim	1.00	0.00	0.00 ?
22	RH rear knuckle arm	1.00	0.00	0.00 ?
23	RH rear knuckle bearing	1.00	0.00	0.00 X
24	RH rear lower arm	1.00	0.00	0.00 X
25	RH rear shock absorber	1.00	0.00	0.00 X

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Estimation No. : E16110058

Vehicle No : SJB9117J
Make & Model : MERCEDES BENZ,E200 ML
Year of Manufacture : 2005

No	Description	Qty	U/P	Amt
			Amt	S\$ 0.00
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$ 0.00

Section: Special Nett Items

26	RH rear tyre	3u 1.00	380.00	380.00 X
27	RH rear door sticker	1/1 1.00	100.00	100.00 X
			Amt	S\$ 480.00
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$ 480.00

Section: Labour Items

28	To knock & straighten on accident area, to remove & refit damage parts.	1.00	1,000.00	1,000.00 700
29	To putty & respray on accident affected area.	1.00	1,000.00	1,000.00 900
30	To rust proof accident affected area.	1.00	100.00	100.00 50
31	To do wheel alignment.	1.00	120.00	120.00 80
32	To remove & refit undercarriage to assist work load.	1.00	250.00	250.00 120
33	To remove & refit door trim, door glass, window regulator, door lock to assist work load.	1.00	100.00	100.00 60
			Amt	S\$ 2,570.00
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$ 2,570.00

not fulfil
done
1/5 S
S day
18/11/16

List Items Subtotal	S\$ 0.00
Special Nett Items Subtotal	S\$ 480.00
Labour Items Subtotal	S\$ 2,570.00
Total	S\$ 3,050.00