



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI17000421/Gcd3e2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 26-12-2019



Code : GAI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLF 7485P
Policy No.	MTGRAB20160032	Coverage (\$)	0.00
Claim No.	CLMOMVC000000373	Excess (\$)	2,000.00
Assign From	STELLA GOH	Assign Date	09/01/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKB3FU403532560	Colour	WHITE
Odometer	37036	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S AND REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/12/2016	Inspection Date	09/01/2017
Survey held at	10 DEFU LANE 8		
Repairer	INDECO ENGINEERS PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$110,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	18 Working Days
--	------------------------