

To CATHERINE

KWAN YING MUN MOTOR SERVICE**BLK 3023A UBI ROAD 1 #01-57 S (408717)****REG NO: 34571600X****Tel: 67476845; Fax No: 67493302****Vehicle No: GBC6727H****Vehicle model: Nissan Cab star F24****Surveyor Name:****Contact No:****Claim officer: Jason Tee****Email: Jason.tea@sg.cntaiping.com****Contact: 63896171****Estimated spare part cost:**

- R/R Tail lamp assy *Chkd*
- Rear Bumper *3ent*

*247
222.3
SN: 320***\$ 247.00 ✓****\$ 780.00***300 (SN)***Total:****\$ 1027.00****Estimated labor cost:**

- wiring
- Labor for installing

*110***\$ 40.00***20***\$ 80.00 ✓****Total:****\$ 120.00****Grand Total: \$ 1147.00****Days of repair: 1 days***Adrian ask Hold this estimate**total: 632.30**45: 500**012g*