

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0419/2017/JT

Date

24-May-17

Service Advisor

Jeffery Tan

Pages

1

Regn No

SLC 3756 A

Model No

Audi A4 Sedan 1.4 TFSI S-tronic

Quantity	Description	Unit Price	Amount
Parts			
1	LED headlight - LHS / CRA	\$ 7,861.00	6288.80
		<u>\$ 7,861.00</u>	
LABORS			
1	To renew LHS LED headlight.	\$ 600.00	250
TOTAL		<u>\$ 8,461.00</u>	

For Premium Automobiles Pte Ltd

Authorised Signature



Guo Qiang

25/5/17

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.	PA/OD/0419/2017/JT
Date	20-Jul-17
Service Advisor	Jeffery Tan
Pages	1
Regn No	SLC 3756 A
Model No	Audi A4 Sedan 1.4 TFSI S-tronic

Quantity	Description	Unit Price	Amount
Parts			
1	Front wheel bearing - LHS / <i>KC</i>	\$ 822.00	\$ 657.20
2	Front ball joint - LHS	\$ 157.00	\$ 125.60
3	Front wishbone link - LHS	\$ 462.00	\$ 369.60
4	Front suspension guide - LHS	\$ 560.00	\$ 455.60
5	Front wheel hub - LHS	\$ 630.00	\$ 503.60
6	Front upper arm - Inner/Outer LHS	\$ 868.00	\$ 694.40
7	Tie Rod - LHS	\$ 163.00	\$ 130.00
8	Suspension bolts and nuts / <i>KC</i>	\$ 200.00	\$ 138.56
		\$ 3,862.00	\$ 3,074.56
Labours			
1	To dismantle front suspension assy. Inspect for damages and renew according to damages. (Special Nett)	\$ 2,400.00	\$ 2,400.00
	TOTAL	\$ 6,262.00	\$ 5,474.56

For Premium Automobiles Pte Ltd

Authorised Signature