Labour charges

To remove & refit seat cushion & carpet			\$450.00 200
To remove & refit front R/H door, glass, trim boa gear motor, lock & rubber	ard,		\$180.00 %
To remove & refit roof top cushion			\$450.00 200
Towing fee			\$100.00 50
To check wiring			\$100.00 30
Tuff kote	2820		\$150.0060
Panel beating			\$4,000.00 12/0
Spray painting			\$3,000.00
		Subtotal :-	\$8,430.00

tolal: 7292.3 Hs: 5.8K.

the Repairer of the following:

To resurvey beforelatter spray painting:
To display damaged part(s) during resurvey:
Parts prices are subject to confirmation:
Third party survey is on a "Without Prejudice" basis:
No illegal modification(s) is allowed:
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total:- \$23,791.00

Page 7

Signature: Date: