



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI17009465/Aea3s2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 01-06-2020	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJG 5949A	Veh. Inspected	SKS 5900P	
Policy No.	DMHCSN1706351700	Coverage (\$)	0.00	
Claim No.	SNM17D02860/C02	Excess (\$)	0.00	
Assign From		Assign Date	15/05/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA MOBILIO	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MRHDD4870FP000068	Colour	WHITE	
Odometer	54443	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	MICHELIN	6 mm	
L/H Front Tyre	195/60 R15	MICHELIN	6 mm	
R/H Rear Tyre	195/60 R15	MICHELIN	6 mm	
L/H Rear Tyre	195/60 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/05/2017	Inspection Date	15/05/2017	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	