mermen	Racul	ASSIGNM	ENT (Office)	10	
From (Pe	son): Juel Goh	of	(12	Date/	Time 26/8/2017 10-
Estimated			Bill to:		
	WS/TP RES/OD RE Vehicle No: SBS	s/eva/inv/mv/0 33040	CS	Insured:	(1BD 9668U
at Works	op m/s	oner Thansil		Tel:	08482245
of		21 Bulin Dine			
Policy No	DM C	SN3172741600	Claim No:	SV	m1783098602
Sum Insu	ed:		Excess:		
Make of ' (Client's R			-XI	D.O.A	28/5/2017
CA / RI Date/Tim	V / REP. / REV 24 H	RS (W) Person Contacted	Swamp	· la	D. Endorsement
Date/Tim	Action/Instruction		?		
	DBD4684-	Κ			
	@ [Wifelin con	D (a . 1 = 1	C1 A /1 . /	Drahi Fu	\$ 333.68, 1 da

Tech Invs (\$

Weekend (\$

TOTAL

Report Format:

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

	The street of the	Affiliated to Federation Inter-	nationale Des Experts En Auto	omobile		
CH	INA TAIPING INSI	JRANCE (S) PTE LTD	Ref : CS/CTI17010	218/R1qh3		
3 A SP	NSON ROAD #16 RINGLEAF TOWE	-00 RSINGAPORE 079909	Date: 26-05-2017 Code: CTI			
1.		Policy Particul	ars :- THIRD PARTY CLA	AIM .		
	Insured Veh.	GBD 9668U	Veh. Inspected	SBS 3394U		
	Policy No.	DMCVSN3072741600	Coverage (\$)	0.00		
	Claim No.	SNM17D03098C02	Excess (\$)	0.00		
	Assign From	MERIMEN (JOEL GOH)	Assign Date	26/05/2017		
		Vehicle Pa	articulars & Condition			
	Make & Model		c.c	0		
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	18:	Steering			
	Brakes		Modification			
	General					
		Con	ditions of Tyres			
_		Size	Make	Balance		
_	R/H Front Tyre			mm		
	L/H Front Tyre			mm		
_	R/H Rear Tyre			mm		
_	L/H Rear Tyre			mm		
		Descrip	otion of Damages			
	Cogue Na:	Gene	ral Information			
	Accident Date	23/05/2017	Inspection Date	29/05/2017		
	Survey held at	TOWER TRANSIT SINGAPO				
		21 BULIM DRIVE SINGAPORE 648170				
			Remarks	THE RESERVE OF THE REAL PROPERTY.		
	A)THE INSPECTION	N WAS CONDUCTED ON A"VE TO YOUR INSTRUCTIONS,	VITHOUT PREJUDICE" BAS	IS.		

...CLAIM SUBFOLDER...(New Assignment)

	tratified	Est Submitted	Adj. Assigne		t	Airy Submitted	In Alithies	Status	
Main	25 May 2017		26 May 201 10:49 Assign	7				New Assignment Cancel Case	
	Main	Refere	nce	CI	aim Detail:		Documents	Show All	
CLAIM SU	JBFOLDER DETA	ILS					10 11		
Insured:		M/S ACEWIN	SERVICES				[Created by	(Insurer]	
Main Claim				ORE PTE	LTD. Co.	Reg. No : 20141	04170		
Vehicle Reg	g. No.:	TOWER TRANSIT SINGAPORE PTE LTD, Co. Reg. No.: 201419417K SBS3394U Date of Loss: 23/05/2017 18:00					19.00 -50		
Claim Type	8	TP / SNM17	7D03098C02	9	The state of the s	r Note No.:	23/05/2017 18:00 - :59		
Vehicle Reg	. No. (Insured):	GBD9668U			Policy No.		DMCVSN3072741600		
The second of th					Excess:		D-16086301MFBP S\$0.00		
Repairer:		Tower Transi 81688950	t Singapore P	te Ltd (F	(Q) 21 Bulir	n Drive, Bulim Bi	us Depot, 648170	Jurong West - Tel:	
Handling In		China Taiping	g Insurance (Singapor	e) Pte. Ltd	(HO) - Tel: 53	89 6111 [Hand		
Claimant's	Insurer:	tital capital.	Illaurance Lto	(HQ) -	lel: 622223	11			
Adjuster:		LKK Auto Con	sultants Pte	Ltd (HQ)	- Tel: 6256	-3561 [Fina	Rpt due 06/0	6/20171	
Adj Asg. Re	marks:	PLEMSE SURVE	T THIRD PART	Y. CHECK	CONSISTEM	I'V OF THE DAM	CEC ON MITTIES	T PREJUDICE BASIS. ATE PROVIDED DURING	
ASSOCIAT	TED MAIL RECEI	VED							
	o mail for this cas						View Al	Compose Case Mail	
		55)							
	CTATED TACKE					View All Sea	rch Tasks Create		
ALL ASSO	CIATED TASKS								
ALL ASSO			p Subject			AICH WII 269	Create	New Task Comp	

Shiau Chan (LKKAuto)

From:

Sharifah Nusaybah Binte Syed Jamil Binshahab <sharifah@towertransit.sg>

Sent:

Friday, 7 September 2018 12:45 PM

To:

Shiau Chan (LKKAuto); SUR

Cc: Subject: Subramanian Kasi; Wu Tzu Ying RE: FINALISE OF SBS3394U (DOA: 23/05/2017)

Attachments:

after-repair pic 1 SBS3394U.jpg

WITHOUT PREJUDICE

Hi Shiau Chan,

We confirm COR @ \$333.68 before GST and 1 day.

Thank you.

Sharifah Nusaybah (Ms)

Senior Executive, Claims

Mobile +65 9848 2243 Office +65 6817 1747

Email sharifah@towertransit.sg



Tower Transit Singapore Pte Ltd

21 Bulim Drive, Bulim Bus Depot, Singapore 648170

Registration number 201419417K

www.towertransit.sg



Disclaimer; This email and any attached files may be coincidental, privileged and intended solely for the addressee. It may not be reviewed, acted upon, filed or communicated to or by any other person. If you have received this email by error, please delete it and notify the sender immediately. The views expressed in this email are not necessarily the views of Tower Transit.

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Sent: Thursday, 6 September, 2018 10:08 AM

To: Sharifah Nusaybah Binte Syed Jamil Binshahab <sharifah@towertransit.sg>

Cc: SUR <sur@lkkauto.com>

Subject: FINALISE OF SBS 3394U (DOA: 23/05/2017)

Dear Sharifah,

WITHOUT PREJUDISE

MTG717088855 - Tower Transit Singapore Ptv Ltd - HQ ENTRY DATE & TIME 25/05/2017 15:43

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Fax Number Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	25/05/2017 15:43
Date Of Accident	23/05/2017 18:10
Exact Location Of Accident	JURONG TOWN HALL ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SBS3394U
Insured/Policyholder	
Name Of Registered Owner	TOWER TRANSIT SINGAPORE PTE LTD
Co Reg No	201419417K
Email Address	SHARIFAH@TOWERTRANSIT.SG
Mobile Phone No	
Alternative Phone No	OFFICE-68171747
Vehicle Particulars	
Manufacturer	VOLVO
Model	B9TL-9.4 D (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D-16086301MFBP
Cover Note Number	
Driver	
Name of Driver	HU PEI TIONG
Passport No/FIN	F7389310X
Date Of Birth	06/06/1963
Occupation	OUTDOOR
Date Of Driving Pass	07/06/1993
Driving Experience	23 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	

NOEMAIL

Phone Number Email Address

Describe Circumstances	, .		Contract of the Contract of th
01 27/5/1	7 paul	1 travella	1 Mary
Juny 7	own Hay	4, gradati	uty tem vo.
46D 9168	U an	+ A my	There and h
the whit	Side 1	nu bus	
7 1	0	40	E /
760 CM	7 was	Majant 1	in not morning
as this	a ano	prija ne	re called in
That st	7	0	
11191 411			
eclaration			
rciarapon			
No effect force the state	ars are true in every res;	nect.	
w secure tria foregoing particul			
as declare the foregoing particular			
Cynoloe & Schillar's (Date &	Sec.	Street in each the code	
	Sec.	driver is not the policyholder) / I	Date Witnessed by Reporting Centre Personnel

ESTIMATED ACCIDENT REPAIR COST



REPORTED	1810HRS	BUS REGISTRATION NUMBER	5BS3394U
ACCIDENT DATE	23-May-17	BUS TYPE (SD/DD)	DD
BUS CAPTAIN NAME	HU PEI TIONG	BUS ROUTE NUMBER	
MPLOYEE NUMBER		BUS ADVERTS (Y/N)	N

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

Part No.	Part or Item Description	Quantity	Total Cost
77200210	O/S BEZEL LIGHTS COVER	1	CP4 / \$163.68
		1	
			100
		7% GST	\$11.46
		FINAL TOTAL COST	\$175.14

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
TO REPLACE THE DAMAGED PARTS (INCLUDING SPRAY PAINTING)		170 \$200.00
	7% GST	\$14.00
	FINAL TOTAL COST	\$214.00

/ muse

363.68

ESTIMATED ACCIDENT REPAIR COST



SECTION 3: REPAIR DONE BY CONTRACTOR AFTER ASSESSMENT (CONTRACTOR COST)
---	------------------

TOTAL REPAIR COST BASED ON CONTRACTOR'S QUOTE

SECTION 4: ADMINISTRATIVE (OVERHEADS)

TOTAL OVERHEADS COST (10% OF PARTS & LABOUR)

SECTION 5: REPAIRS TO BUS ADVERTISMENT VINYLS/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST

SECTION 6: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST

SECTION 7: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date In For Repairs	29/5/2017
		Date Out From Repairs	30/5/2017
BUS TYPE (SD / DD)	DD	Number of Days Under Repair	1
	LOSS OF USE COST		\$400.00

SECTION 8: ENGINEERING RECOVERY OF ACCIDENT BUS (ENGINEERING RECOVERY COST)

ENGINEERING RECOVERY COST

SUM	MARY
SECTION NO.	COST
1	\$175.14
2	\$214.00
3	2
4	
5	**
6	**
7	\$400.00
8	5.
ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5+6+7+8)	\$789.14

LKK Auto Consultanta hence notify the Repairer of the following:

- . To resurvey before/after apray painting
- To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

140 grovools

I alays

P/1

29/05/10/14/40

Remy 64, wit

Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

service and a maked well-profes	OLDER TRA	-			7		I a management			
isanesse	Notified 25 May 2017	Est Submitted	Adj Assigned 26 May 2017	Adj Rpt \$\$333.68		Submitted 333.68	Ins Auth'ed	Pe	nding fo	Survey
Main			10:49 Edit Adj Rpt	Edit Estimate	s V	lew Rpt		1100	Report Cancel Case	
-	Main	∏ R	eference	Claim	Details		Docume	nts	٦.	Show All
	BFOLDER DE					[Created b	by insurer]			
Insured: Main Claimant:		VIN SERVICES, RANSIT SINGAP	ORE PTE LTD, Co	o. Reg. No.: 2014	19417K					
Vehicle Reg No.:	SBS339	SBS3394U					18:00 - :59 and 21 Days	From LTA	Reg Date	(Man Yr)]
Claim Type:	TP / SNN	TP / SNM17D03098C02			y/Cover No.:	DMCVSN3072741600				
Vehicle Reg No. (Insured):		GBD9668U			y No. mant):	D-16086301MFBP				
Repairer:	Towar Tra					S\$0.00 ppt, 648170 Jurong West - Tel: 81688950				
Handling Insurer:			Singapore) Pte. L				men Williams and a		30:	
Claimant's Insurer:	MS First C	apital Insuranc	e Ltd (HQ) - Tel: 6	2222311						
Adjuster:	THE RESERVE AND ADDRESS OF THE PARTY.		Ltd (HQ) - Tei: 62	THE RESERVE OF THE RESERVE AND ADDRESS OF THE PARTY OF TH	Principal of a bid of both	contact principles and infrared principles (by a discount)	art free has not also believe the first free and the same	THE RESERVE AND PARTY AND PARTY.	and the second second second second	Name and Address of the Owner, where the Owner, which the Owner, where the Owner, which the
Adj Asg. Remarks:			TY, CHECK CONSIST IR AMOUNT IF THER					SIS. KIND	SLY LET U	S HAVE
ASSOCIAT	ED MAIL RE	CEIVED					,	/iew All	Compos	e Case Ma
There are no	mail for this	case.								
ALL ASSO	CIATED TAS	KS⊟			- 4	View All S	earch Tasks	Create N	ew Task	Complete
Due Date	Priority	Type Task	Group Subjec	t Handler	Assign	ned By	Completed O	n Cr	eated Or	Done

Merimen e-Claims Page 1 of 2

Claim Documents

*SBS3394U (SNM17D03098C02)

[GBD9668U]

TP

TOWER TRANSIT SINGAPORE PTE LTD

May 23 2017 6:00PM

[M/S ACEWIN SERVICES]

Tower Transit Singapore Pte Ltd

Acc	essment Reports		1.00	page V	La
	Finalized On	Personal Manager Service Control of the Control of	1 per		V
No 1	25/05/17 15:53	Tower Transit Singapore Pte Ltd (HQ) Accident Statement	0	Thumbnall Load HTM	Prin
	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	TASSICITION CONTROL		1 10000 111111	1
Pho	otos/Images		3 per	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	13/06/18 16:32	General View	0	Load PDF	
2	07/09/18 15:04	Odometer Reading	0	Load JPG	Y
3	07/09/18 15:04	Chassis Number	0	Load JPG	3
4	07/09/18 15:04	General View	0	Load JPG	V
5	07/09/18 15:04	General View	0	Load JPG	1
6	07/09/18 15:04	General View	0	Load JPG	V
7	07/09/18 15:04	General View	0	Load JPG	V
8	07/09/18 15:04	General View	0	Load JPG	V
9	07/09/18 15:04	General View	0	Load JPG	V
10	07/09/18 15:04	General View	0	Load 3PG	3
11	07/09/18 15:04	General View	0	Load JPG	V
12	07/09/18 15:04	General View	0	Load JPG	V
13	07/09/18 15:04	General View	0	Load JPG	V
14	07/09/18 15:04	General View	0	Load JPG	V
15	07/09/18 15:04	General View	0	Load JPG	V
16	07/09/18 15:04	General View	0	Load JPG	V
17	07/09/18 15:04	General View	0	Load JPG	V
Doc	cumentation		1 per	page [V]	V
Nα	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	26/05/17 10:51	INSURED SAS REPORT -GBD9668U	0	Load PDF	
2	26/05/17 10:51	THIRD PARTY SBS3394U -FROM TOWER TRANSIT -PRS EMAIL	0	Load PDF	
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)		Thumbnail	Print
1	25/05/17 15:53	Sketch Plan [Linked Accident Report Documents]	0	Load JPG	V
2	25/05/17 15:53	Sketch Pian #2 [Linked Accident Report Documents]	0	Load JPG	V

Linked Accident Report Documents

			View View in Browser V		
Assessment Reports 1 per			page V	₩	
No.	Finalized On	Tower Transit Singapore Pte Ltd (HQ)		Thumbnail	Print
1	25/05/17 15:53	Accident Statement	0	1 Load HTM	
Doc	Documentation		1 per s	age 🔽	V
		al (

Merimen e-Claims Page 2 of 2

Ass	Assessment Reports		I per p	age 🗸	V
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)		Thumbnail	Print
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)		Thumbnail	Print
1	25/05/17 15:53	Sketch Plan	0	Load JPG	V
2	25/05/17 15:53	Sketch Plan #2	0	Load JPG	V

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI17010218/R1QH3Q2

Date:

10/09/2018

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

DMCVSN3072741600

Claimant Vehicle

SBS3394U

Insured Vehicle No:

GBD9668U

No: Date of Loss:

23/05/2017

Nature of Claim: TP

Claim No:

SNM17D03098C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SBS3394U

Make & Model:

VOLVO B9TL, 9.4 D (A)

Reg. Date: Colour:

Green

02/06/2014 (Man. Year: 2013)

Chassis No: Odometer:

Engine No:

YV3S4P921EA166816

D9192683

255916 km

Engine Capacity:

9364 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

275/70 R22.5 Michelin 8 mm Rear Tyre Size: Rear Left Side:

275/70 R22.5 (D) Michelin 8/8 mm

Front Right Side: Michelin 8 mm The above values represent the remaining tyre treads depth Rear Right Side:

Michelin 8/8 mm

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	163.68	163.68	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	200.00	170.00	30.00	15.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	363.68	333.68	30.00	8.25
+ GST 7.00/7.00% (S\$)	25.46	23.36	2.10	8.25
Nett Amount (S\$)	389.14	357.04	32.10	8.25

INSPECTION

Date of Assignment:

26/05/2017

Date Inspected:

29/05/2017 Inspected At:

Tower Transit Singapore Pte Ltd (HQ)

21 Bulim Drive, Bulim Bus Depot

Singapore 648170

Estimated Period of Repair:

1.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

Adjuster Report Page 2 of 4 NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded. $https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster\&fuseaction=gen_...\ \ 10/9/2018$

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Sep 2018)

Parts: N/A VOLVO B9TL 9.4 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBS3394U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*O/S BEZEL LIGHTS COVER	Cracked	163.68 F	*163.68 F
F=Fn	anchise part.		Total Parts (S\$)	163.68	163,68
		Report was unsubmitted	d during this print-out.		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REPLACE THE DAMAGED PARTS (INCLUDING SPRAY PAINTING)	New	200.00	170.00
	Gross Labor	ur Cost (S\$)	200.00	170.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >