

email to Taufiqh
on 22/6/17

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP Claim

To : MSIG Insurance (Singapore) Pte Ltd
Motor Claims Dept

Date : 22 Jun 2017

Dear Sirs :

Fax : 6224 1047

RE : ESTIMATE COST FOR NISSAN JN1MC2E26 - GBD1081P
ALONG TELOK BLANGAH TWRDS PASIR PANJANG RD ON 23.12.2017

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
<u>Labour Charge & Misc</u>			
			300
	To remove, repair, replace & install damaged parts.	}	\$ 400.00
	To door sticker.		\$ 20.00 <i>nee</i>
	To numbering logo.		\$ 450.00 <i>350 300</i>
	To putty & spray painting.		\$ 500.00 <i>400</i>
Total			\$ 1,370.00

All prices quoted are subjected to 7% GST.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

97495749

1070

30 days

This is a computer generated document. No signature is required.