

(A)

22003/2002

ASS. REC. BY:

SMV/evj/v

REC

CC3/AIG17011740/Gvb

Special Instruction:

ASSIGNMENT (Office)

From (Person):

Lee Yung

of

ALG

Date/Time:

16/6/2017

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 7079 M

Insured:

at Workshop m/s

Premium Auto.

Tel:

of

Policy No:

2100387895

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13/6/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

16/6

Person Contacted:

Tony

Vehicle IN / OUT

Date/Time

Action/Instruction () Estimate

SKP 7079 M-X

(08/11/13)

ASS. REC. BY: XnlREF: AG

CC3 / ALH 17011740 / Gvbe2

(3)

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Premium Auto

of _____

Insured: 9653 0326 Chiang

Policy No. _____

Claims No. 2100387895Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$96K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKP 7079M Yr Regn: 30 Sep 2014Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 c.c. 1395Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 47894 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU 888 8V 3EA194216Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55 R16R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 13/6/17 D.O.I. 16-06-17Survey held at W/S 3pmDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orFrt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SKP 7079M - X
19/6/17	Rev in merimen.
19/6/17	Rece approved \$8006 from victor by merimen
20/6/17	Informed Jack CIA ex \$600 by email
18/12/17	Final fig \$9389.36 confirmed by email (Ref 6374-64, 4070)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 25/1- typistDays Of Repair: 5Resurvey No. of Trip: 1Report Format: merimenLump Sum / I.B.I. (\$) 9389.36
Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)
Survey Fee: 200

Transportation: _____

S + RS, SI _____

Photos 10

Others _____

TOTAL 210

A

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jun 2017		19 Jun 2017 10:04 Edit Adj Rpt	S\$9,389.36 Edit Estimates	S\$9,389.36 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHEOK ENG KWEE, ID: [REDACTED], Tel: +[REDACTED]								
Vehicle Reg. No.:	SKP7079M		Date of Loss:	13/06/2017 00:00 - :59					
Claim Type:	OD / 5329994918SG		Policy/Cover Note No.:	2100387895 (Comprehensive)					
			Excess:	S\$600.00					
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/06/2017]								
Driver/Custodian:	YEO TENG TENG (47 / Female), NRIC: [REDACTED], Tel: +[REDACTED]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (18/12/2017): Alert - Adj Mandate Approved (S\$9389.36) - SKP7079M - Claim Handler: Dally Amri,... AIG_SG (14/12/2017): Alert - Adj Mandate Maintained - SKP7079M - Claim Handler: Dally Amri, Mimi Zari... AIG_SG (19/06/2017): Alert - Adj Mandate Approved (S\$8006.00) - SKP7079M - Claim Handler: Dally Amri,... AIG_SG (19/06/2017): SKP7079M / OD / 13/06/2017 / Coverage & Excess update 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

(H)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 19 Jun 2017

Preliminary Advice

Vehicle No	: SKP7079M	Accident Date	: 13/06/2017
Make	: AUDI A3 SPORTBACK	Policy No.	: 2100387895
Assignment Date	: 19/06/2017	Excess	: S\$0.00
Date of Inspection	: 16/06/2017	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,230.00
Revised Amount	:S\$	8,006.00
Check Items (Estimated)	:S\$	679.00
Total	:S\$	8,685.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	96,000.00
COE / PARF Rebate	:S\$	55,703.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,297.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :



Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: [REDACTED]

Vehicle Details

Vehicle No.: SKP7079M

Vehicle to be Exported: No

Intended De-registration Date: 19 Jun 2017

Vehicle Make: AUDI

Vehicle Model: A3 SB 1.4 TFSI AMBIENTE

Primary Colour: Grey

Manufacturing Year: 2014

Engine No.: CXS203932

Chassis No.: WAUZZZ8V3EA194216

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$26,506.00

Original Registration Date: 30 Sep 2014

First Registration Date: 30 Sep 2014

Transfer Count: 0

Actual ARF Paid: \$14,109.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Sep 2024

PARF Rebate Amount: \$10,581.00

Intended COE Rebate Details

COE Expiry Date: 29 Sep 2024

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$74,801.00

COE Rebate Amount: \$45,122.00

Total Rebate Amount: \$55,703.00

The information contained herein is correct as at 19 Jun 2017



Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 11 Jun 2017 at 12:47 AM

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. [REDACTED]



Name

YEO TENG TENG

杨婷婷

Race

CHINESE

Date of Birth

Sex

F

Country of Birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE




Licence Number: [REDACTED]

Name

YEO TENG TENG

Birth Date

Issue Date



NRIC No: [REDACTED]

Blood Group

B+

NRIC No: [REDACTED]

Date: [REDACTED]

No: [REDACTED]

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

02 Apr 1993



NP 428A

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of a man

Licence Number: [REDACTED]
Name: [REDACTED]
CHECK ENG KWEE
Birth Date: [REDACTED]
Issue Date: [REDACTED]

000063756E

[Barcode]

(H)

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. [REDACTED]

Portrait of a man

Name: CHECK ENG KWEE
石榮貴
Race: CHINESE
Date of Birth: [REDACTED]
Country of Birth: SINGAPORE
Sex: M

[Emblem]

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE 19 Dec 1989

NP 428A

[Barcode]

[Barcode]

Portrait of a man

NRIC No: [REDACTED]
Blood Group: B+
Date of issue: [REDACTED]
NRIC No: [REDACTED] Date: [REDACTED] No: [REDACTED]



HOTLINE TEL: (65) 6419 3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100387895-02000

OWN DAMAGE EXCESS S\$600.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value

INSURING WITH COE/PAF Yes

SKP7079M

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

CHEOK ENG KWEE

**3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT**

30 Sep 2016

4) DATE OF EXPIRY OF INSURANCE

29 Sep 2017

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION :All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres(Tel:66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

**HIRE PURCHASE COMPANY
/ EMPLOYER'S LOAN** MayBank

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 2 Sep 2016

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSPQCC

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/06/2017 16:41
Date Of Accident	13/06/2017 12:10
Exact Location Of Accident	BLK 1E PINNACLE @ DUXTON B1 CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP7079M
Insured/Policyholder	
Name Of Registered Owner	CHEOK ENG KWEE
NRIC No	[REDACTED]
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +[REDACTED]
Alternative Phone No	OTHERS-[REDACTED]

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SPORTSBACK 1.4 TFSI (AMBIENTE)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100387895-02000
Cover Note Number	

Driver

Name of Driver	YEO TENG TENG
NRIC No	[REDACTED]
Date Of Birth	[REDACTED]
Occupation	INDOOR
Date Of Driving Pass	02/04/1993
Driving Experience	24 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +[REDACTED]
Fax Number	
Contact Number	
Email Address	LINDAYEO1969@GMAIL.COM

Address BLK 56 BT BATOK STREET 31 #19-18
 Postcode 659445
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION- HEAD TO SIDE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 13/6/2017 AT ABOUT 12.08PM, I WAS TURNING IN FROM NEIL ROAD INTO THE B1 CARPARK AT PINNACLE @DUXTON. WHILE NAVIGATING INSIDE THE DIMLY LIGHTED CAR PARK, LOOKING FOR AN EMPTY LOT, STOPPING AT THE CROSS ROAD, WHILE MOVING OFF, A VEHICLE COMING FROM THE LEFT KNOCKED AGAINST MY LEFT SIDE OF MY CAR. REPORTED BY: JN, SUBMITTED BY: MAS

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJW1533H
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Pinnacle Dutton carpark



A = SKP 7079M

B = SJW 1533H

Sketch Plan #2


Describe Circumstances of the Accident


On 6/6/2016 @ at about 12.08pm I was turning in from Neel Road into the BI car park at Pinnacle @ Oxton.

While ~~was~~ navigating inside the dimly lit car park looking for an empty bay lot, ~~then~~ stopping at the cross road, while moving off, a ~~red~~ vehicle coming from the left knocked against my left side of the car.

Declaration

We declare the foregoing particulars are true in every respect.


13/6/2017 3.20pm
Policyholder's Signature / Date & Time


13/6/2016 3.20pm
Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

(H)

View Received Message

This mail is associated with :

***SKP7079M (5329994918SG)**

OD

Jun 13 2017 12:00AM

[CHEOK ENG KWEE]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on **19/06/2017 15:44 PM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$8006.00) - SKP7079M - Claim Handler: Dally Amri, Mimi Zarina

Approved:8006.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 20 June, 2017 10:00 AM
To: claims@premiumauto.com.sg; SUR
Subject: SKP 7079M-DOA: 13/6/2017 (AIG OD)

Dear Jack,

As instructed by our client AIG, please proceed to repair the insured vehicle **SKP 7079M (excess \$600)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

Any supplementary items are subjected to further approval from our client.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKP 7079 M.

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer Assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper, lhs front fender, headlight and bonnet. Re-organise front crash management components, Reinstall all parts removed.	\$ 2,700.00 1250 ✓
3	To respray front bumper, lhs front fender and bonnet.	\$ 2,400.00 1700 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>5,652.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 7079 M.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER / Re	\$ 1,546.00	1236.80
2	FRONT BUMPER GUIDE SECTION - LH - BT	\$ 51.00	40.80
3	FRONT AIR GUIDE GRILLE - LH NA / MC	\$ 90.00	71.92
4	FRONT FENDER - LH / MC	\$ 708.00	566
5	FRONT FENDER ATTACHMENT PARTS X NN	\$ 56.00	
6	FRONT FENDER BRACKET - LH/ REAR X / MC	\$ 23.00	18.16
7	FRONT FENDER BRACKET - LH X / MC	\$ 40.00	31.60
8	POP RIVET / MC	8 \$ 23.00	17.92
9	FRONT FENDER CLOSING ELEMENT X / BT	\$ 52.00	40.96
10	FRONT FENDER BRACE X / BT	\$ 81.00	64.80
11	WHEEL HOUSING LINER - LH X / Re	\$ 146.00	116.80
12	SEALING WASHER / MC NN	\$ 24.00	X
13	WHEEL HOUSING LINER ATTACHMENT PARTS / MC	\$ 75.00	59.44
14	GAS DISCHARGE HEADLIGHT - LH / CPA	\$ 1,708.00	1366.40
15	HEADLIGHT WASHER LIFT CYLINDER - LH / DM	\$ 160.00	127.60
16	BONNET X repair	\$ 2,372.00	
17	EDGE PROTECTION - FRONT X NN	\$ 23.00	
18	SUNDRIES X / MC	\$ 400.00	61.76
TOTAL SPARE PARTS CHARGES		: \$ 7,578.00	
TOTAL LABOUR CHARGES		: \$ 5,652.00	
GRAND TOTAL		: \$ 13,230.00	15,764

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Gino Qian - 82880282
Surveyed Date : 5 Days.
Authorised Date : 16/6/17
Excess Cost :
Liability :
Remarks : Not Authorised.

[Handwritten signature]
26/6/17

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

[Handwritten signature]
Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0581/2017/JN 22-Jun-17 Chang 1 of 1 SKP 7079 M Audi A3 SB 1.4 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To repair frontal horn wiring harness. S/N	\$ 280.00	\$ 280.00
Parts			
1	WASH WATER RESERVOIR / WASH D:5	\$ 173.00	\$ 138.40
2	WATER RESERVOIR SEAL & BUNGS X NN	\$ 20.00	
3	SIGNAL HORN - LH / BR	\$ 173.00	\$ 138.40
4	LHS HEADLIGHT BALLAST	\$ 1,002.00	\$ 801.60
5	LHS HEADLAMP POWER MODULE / WASH NN	\$ 492.00	\$ 393.20
6	LHS HEADLAMP BULB	\$ 394.00	\$ 314.80
GRAND TOTAL :		\$ 2,534.00	\$ 2,066.40

For Premium Automobiles Pte Ltd

Authorised Signature

15316 40

②

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183
Email: claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop :
Contact No :
Fax No :
Reference : PA/OD/0581/2017/JN
Date : 15-Jun-17

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Guo Qiang

5 DAYS - OK - JB - 7/11

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Cheok Eng Kwee
Address :
Singapore 659445
Telephone : HP ()
Type of Claim : Own Damage Claim
Policy No. : 2100387895-02000
Vehicle No : **SKP 7079 M**
Model Code : Audi A3 SB 1.4 TFSI
Model / Year : Sep-14
Engine No : CXS 203932
Chassis No : WAUZZZ8V3EA194216
Mileage : -
Date In : 13-Jun-17
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Jun-17
Place of Accident : Blk 1E Pinnacle @ Duxton B1 Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKP 7079 M.

S/n	Nature of Jobs	Estimated Charges	
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew front bumper, lhs front fender, headlight and bonnet. Re-organise front crash management components, Reinstall all parts removed.	\$ 2,700.00	\$ 1,250.00
3	To respray front bumper, lhs front fender and bonnet.	\$ 2,400.00	\$ 1,700.00
4	Added Labour charges - see attached	S/N \$ 280.00	\$ 280.00
5	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		5,932.00	3,782.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 7079 M.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
1	FRONT BUMPER	\$ 1,546.00	\$ 1,236.80
2	FRONT BUMPER GUIDE SECTION - LH	\$ 51.00	\$ 40.80
3	FRONT AIR GUIDE GRILLE - LH	\$ 90.00	\$ 71.92
4	FRONT FENDER - LH	\$ 708.00	\$ 566.00
5	FRONT FENDER ATTACHMENT PARTS	\$ 56.00	
6	FRONT FENDER BRACKET - LH/ REAR	\$ 23.00	\$ 18.16
7	FRONT FENDER BRACKET - LH	\$ 40.00	\$ 31.60
8	POP RIVET	8 \$ 23.00	\$ 17.92
9	FRONT FENDER CLOSING ELEMENT	\$ 52.00	\$ 40.96
10	FRONT FENDER BRACE	\$ 81.00	\$ 64.80
11	WHEEL HOUSING LINER -LH	\$ 146.00	\$ 116.80
12	SEALING WASHER	\$ 24.00	
13	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 75.00	\$ 59.44
14	GAS DISCHARGE HEADLIGHT - LH	\$ 1,708.00	\$ 1,366.40
15	HEADLIGHT WASHER LIFT CYLINDER - LH	\$ 160.00	\$ 127.60
16	BONNET	\$ 2,372.00	
17	EDGE PROTECTION - FRONT	\$ 23.00	
18	SUPPLEMENTARY	\$ 2,534.00	\$ 1,786.40
20	SUNDRIES	\$ 400.00	\$ 61.76
TOTAL SPARE PARTS CHARGES		\$ 10,112.00	\$ 5,607.36
TOTAL LABOUR CHARGES		\$ 5,932.00	\$ 3,782.00
GRAND TOTAL		\$ 16,044.00	\$ 9,389.36

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

R

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120Our File No: CC3/AIG17011740/GVBE2 /
Date: 26/01/2018 /

REFERENCE

Insured/Claimant: CHEOK ENG KWEE / Policy No: 2100387895 /
Date of Loss: 13/06/2017 / Nature of Claim: OD / Claim No: 5329994918SG /

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKP7079M /
Make & Model: AUDI A3 SPORTBACK, 1.4 TFSI (A) Engine No: CXS203932 /
Reg. Date: 30/09/2014 (Man. Year: 2014) Chassis No: WAUZZZ8V3EA194216 /
Colour: Grey / Odometer: 47894 km /
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$96,000.00 /
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 / Rear Tyre Size: 205/55 R16 /
Front Left Side: Continental 6 mm / Rear Left Side: Continental 6 mm /
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,384.40	5,607.36	3,777.04	40.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,932.00	3,782.00	2,150.00	36.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,316.40 /	9,389.36 /	5,927.04	38.70
- Excess (S\$)	600.00 /	600.00 /	0.00	0.00
(S\$)	14,716.40	8,789.36	5,927.04	40.28
+ GST 7.00/7.00% (S\$)	1,030.15 /	615.26 /	414.89	40.27
Nett Amount (S\$)	15,746.55	9,404.62	6,341.93	40.28

INSPECTION

Date of Assignment: 19/06/2017
Date Inspected: 16/06/2017 Inspected At:Premium Automobiles Pte Ltd (HQ) /
55 Ubi Road 1
Singapore 408699 /

Estimated Period of Repair: 5.0 days /

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed /	✓ 1,546.00 FS	*1,236.80 FS
2	1		*FRONT BUMPER GUIDE SECTION - LH	Bent /	✓ 51.00 FS	*40.80 FS
3	1		*FRONT AIR GUIDE GRILLE - LH	Necessary /	✓ 90.00 FS	*71.92 FS
4	1		*FRONT FENDER - LH	Buckled /	✓ 708.00 FS	*566.00 FS
5	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary /	✓ 56.00 FS	*- FS
6	1		*FRONT FENDER BRACKET - LH / REAR	Necessary /	✓ 23.00 FS	*18.16 FS
7	1		*FRONT FENDER BRACKET - LH	Necessary /	✓ 40.00 FS	*31.60 FS
8	✓ 8		*POP RIVET	Necessary /	✓ 23.00 FS	*17.92 FS
9	1		*FRONT FENDER CLOSING ELEMENT	Bent /	✓ 52.00 FS	*40.96 FS
10	1		*FRONT FENDER BRACE	Bent /	✓ 81.00 FS	*64.80 FS
11	1		*WHEEL HOUSING LINER - LH	Deformed /	✓ 146.00 FS	*116.80 FS
12	1		*SEALING WASHER	Not Necessary /	✓ 24.00 FS	*- FS
13	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary /	✓ 75.00 FS	*59.44 FS
14	1		*GAS DISCHARGE HEADLIGHT - LH	Cracked /	✓ 1,708.00 FS	*1,366.40 FS
15	1		*HEADLIGHT WASHER LIFT CYLINDER - LH	Damaged /	✓ 160.00 FS	*127.60 FS
16	1		*BONNET	Repair /	✓ 2,372.00 FS	*- FS
17	1		*EDGE PROTECTION - FRONT	Not Necessary /	✓ 23.00 FS	*- FS
18	1		*SUNDRIES	Necessary /	✓ 400.00 FS	*61.76 FS
19	1		*WASH WATER RESERVOIR	Distorted /	✓ 138.40 FS	*138.40 FS
20	1		*WATER RESERVOIR SEAL & BUNGS	Not Necessary /	✓ 20.00 FS	*- FS
21	1		*SIGNAL HORN - LH	Broken /	✓ 138.40 FS	*138.40 FS
22	1		*LHS HEADLIGHT BALLAST	Not Working /	✓ 801.60 FS	*801.60 FS
23	1		*LHS HEADLAMP POWER MODULE	Not Working /	✓ 393.20 FS	*393.20 FS
24	1		*LHS HEADLAMP BULB	Not Working /	✓ 314.80 FS	*314.80 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 9,384.40 5,607.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	New	2,400.00	1,700.00
3	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
4	TO REPAIR FRONTAL HORN WIRING HARNESS	New	280.00	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, HEADLIGHT AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED	New	2,700.00	1,250.00
Gross Labour Cost (S\$)			5,932.00	3,782.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >