

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 43144
Date Estimated : 22/06/2017
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
Chin Yah Ling, Michelle
201 Petir Road
#02-693

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 670201

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKJ3306R	NT39183	04/02/2016	318iA/4Dr	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	231.00
Total Parts :	0.00
Total Labour & Parts :	231.00