

\$ 9256

BALANCE B/FORWARD PAGE 2

S \$
53294.50

✓ 106	1PC	FRT BEARING RH	Hec	✓ 430.00
✓ 107	1PC	FRT CROSS MEMBER	✓ BT	✓ 3000.00
✓ 108	1PC	STEERING RACK AND PINION	BT	✓ 3260.00
✓ 109	1PC	STEERING TIE ROD	Buc (A) (A)	✓ 148.00
✓ 110	1PC	FRT STEERING TIE ROD RH	BT	✓ 230.00
✓ 111	1PC	FRT STEERING BOOT COVER RH	NEC	✓ 55.00
✓ 112	1PC	NUMBER PLATE BASE	MIS	✓ 188.00
✓ 113	1PC	START STOP FUSEBOX	DA (A) (A)	✓ 1200.00
✓ 114	1PC	START STOP FUSEBOX BRACKET	(A) DIS (A)	✓ 95.00
✓ 115	1PC	START STOP BATTERIE	DA (A)	✓ 300.00
✓ 116	1PC	START STOP SUPPORT BRACKET	Buc (A)	✓ 100.00
✓ 117	1PC	CARRIER TOP SUPPORT	DIS (A)	✓ 210.00
✓ 118	1PC	COOLANT	NEC	✓ 20.00
✓ 119	1PC	INNER BOOT CLAMP	Buc (A)	✓ 20.00

COST PLUS 10%
GST 7%

68005.35

62550.50
6255.05
4378.535
73184.09

NET ITEMS

1PC NUMBER PLATE AND HOUSING BT 45 80.00

LABOUR CHARGES

CHECKING OF WIRING AND FOCUS HEADLAMPS AND BUMPER FOG LAMP. 50 250.00

TO STRAIGHTEN AND PANEL BEATING FRONT SUPPORT PANEL INNER. TO CUT/WELD FRONT PANEL. TO REMOVE AND RE-FIT FRONT PARTS. 1000 2500.00

TO REMOVE AND RE-FIT FRONT RH SIDE UNDERCARRIAGES, RACK AND PINION, CROSS MEMBER. 400 800.00

TO CONDUCT ELETRONIC WHEEL ALIGNEMENT TESTS 120 200.00

TO PUTTY, RE-SPRAY PAINTING ON FRONT AFFECTED PORTION, FRONT RH/LH FENDERS, FRONT REINFORCEMENT AND POLISH AFFECTED AREAS 1600 4000.00

TO CHECK AND RECTIFY WIRING SYSTEM. 120 400.00

TO RUST PROOF AFFECTED AREAS X 90.00

TOWING CHARGES 2 TRIPS 230 240

GRAND TOTAL

81744.09

*REMARK: SUPPLEMENTARY PARTS EXPECTED
ESTIMATE PREPARE BY MR WONG, HP:96876875/96601347

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

82,223.78#