

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD Ref : CS/CTI17013796/M1rbs2				
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date: 03-08-2017	
SPRINGLEAF TOWERSINGAPORE 0/9909			Code: CTI	
4				
1.				
	Insured Veh.	XD 1826Y	Veh. Inspected	SH 8536B
	Policy No.	DMCVSN1621871600	Coverage (\$)	0.00
	Claim No.	SNM17D01542C02/6	Excess (\$)	0.00
	Assign From	ALFRED TOH	Assign Date	11/07/2017
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JTDKB3FU703529197	Colour	BLUE
	Odometer	122856	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65R15	BRIDGESTONE	8 mm
	L/H Front Tyre	195/65R15	BRIDGESTONE	8 mm
	R/H Rear Tyre	195/65R15	BRIDGESTONE	8 mm
	L/H Rear Tyre	195/65R15	BRIDGESTONE	8 mm
4.	Description of Damages			
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.			
	REPAIR CONDITION SEE DETAILS.			
5.	General Information			
	Accident Date	13/03/2017	Inspection Date	19/07/2017
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD			
	383 SIN MING DRIVE SINGAPORE 575717			
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			