

Estimate

Vehicle: S2P 4194X

Make & Model: Toyota v105

Year: _____

Chassis No: _____

	Parts / Labour	Condition	Price	recommend
	Rear bumper	oo/pe	581.50	✓
1set	Rear bumper clips	neu	30.00	✓
2p/s	Rear bumper retainers @132.10	n1	264.20	X
	Rear bumper reinforcement frame	R	374.50	X
1set	Rear panel inner garnish clips	n1	20.00	X
	Rear Bootlid inner lock	n1	371.50	X
		(25%)	1641.70	611.5
	S. Netf			
1set	Rear bumper reverse sensor	shokh	200.00	✓
	To check wiring		50.00	20
	To spray ant. rust proofing	n1	50.00	X
	Panel beating		300.00	280
	To putty & spray painting		480.00	400
			2721.70	

Not Afford
 2/2/20
 P/P 1358.62
 2/2/20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: