

M/S INDIA INT'L INS PTE LTD
64 CECIL STREET
#05-01 IOB BUILDING
SINGAPORE 049711

ESTIMATE

DATE : 17/07/2017
ACCT DATE : 14/07/2017
REF NO. : VFIX-TP20170284
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO.SGW7011T TOYOTA AXIO

DESCRIPTION	AMOUNT S\$
1 1 FRONT DOOR LH <i>Painted</i>	1,165.20 ✓
2 1 REAR DOOR LH	955.40 ✓
3 1 REAR FENDER LH <i>Rpr</i>	911.00 *
	\$ 3,031.60
LESS 25%	\$ 757.90
	\$ 2,273.70

DESCRIPTION (SPECIAL NETT)	AMOUNT S\$
1 2 DOOR HINGE REAR DOOR <i>new</i>	95.00 190.00 SN

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove/replace damaged parts with all necessary components/ attachments repair dented panel	1,000.00 400
2 To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	1,000.00 600
3 To remove,install rear boot compartment garnishes	100.00 *
4 To remove,install rear windscreen glass and water test	150.00 *
	\$ 2,250.00

GRAND TOTAL : \$ 4,713.70

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SINGAPORE DOLLARS FOUR THOUSAND SEVEN HUNDRED THIRTEEN & CENTS SEVENTY ONLY

Vfix Auto Service Pte Ltd
Acknowledged by Repairer



4/5 Adrian Lj
19/07/17.
\$250
04 Days.