

22/03/2002

ASS. REC. BY:

REF: CS/FC117015124/Tirbo2 Special Instruction:Survivor: Taufik**ASSIGNMENT (Office)**From (Person): Luraneof FC1

Date/Time:

04/8/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJB 66364

Insured:

SHA 8467J

at Workshop m/s

Sg Ah Txx

Tel:

8268 6183

of

Policy No:

Claim No:

D17007425 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/7/17

CA / REV / REP. / REV 24 HRS

DS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SJB 66364 xSHA 8467J x25/11/33amConfirmed LE \$4000 with Sharon thru email. (Red 6874.54, 63%)

Taufik

REF:


FCL

ASSIGNMENT

From: Date:
Estimated Cost:
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No:
at Workshop m/s
of
Insured:
Policy No.
Claims No.
Sum Insured. Excess:
(Client's Record)
Make of Veh.

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$16K
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 8 days Res: Yes or No
Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: STB 66364 Yr Regn: 2008 / Jan
Type: M.Cy / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Hyundai Sonata cc 1998
Colour: Black A.C: Insured / Std / NI / NA
Sp. Reading: 128856 T Radio: Insured / Std / NI / NA
Eng No:
C/No: KMHCU41BR6A 265896
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/60R16
R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Falken

Front Rear
R.Bal: 6 mm R.Bal: 6 mm
L.Bal: 6 mm L.Bal: 6 mm
D.O.A. D.O.I. 4/8/17
Survey held at Sing Ah Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Inform u/s repair unit \$6K. thru email.

RECEIVED 20 JAN 2018

Date/Time File Pass to?

☐

: Preli. Report

1: 26/1 Typist

☐

: Final Report

Date/Time File Return to?

2:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

170

50

50

415

315

Report Format: TP

Lump Sum / I.B.I: (\$ 4,000)

Survey Department Check List (Case Handler)

Reference No. : CS/FCU17015126/TT/b
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine) : Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Rashid) : Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

Catherine 25/1/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17015124/T1rb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 04-08-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8467J	Veh. Inspected	SJB 6636Y
Policy No.		Coverage (\$)	0.00
Claim No.	D17007425MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	04/08/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	29/07/2017	Inspection Date	04/08/2017
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	31-07-2017	Our Ref No. D17007425MFSH
Accident Date	29-07-2017	Claim Type. Third Party
Insured Vehicle	SHA8467J	Third Party Vehicle. SJB6636Y
Survey Location	BLK 3 PIONEER ROAD NORTH #01-18	
Contact Person.	JANICE CHANG	
Contact No.	62686183/ 0	Fax No. 62681429
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/226348)



PRI Documents



Close



PRI Header Details

Claim No	D17007425MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & SNG AH T SERVICE PTE
Workshop Name	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (Contact Person : JANICE CHANG)	Survey Location & Contact Details	BLK 3 PIONEER ROAD NORTH #01-18 Mobile: 0 , Phone: 62686183 , Fax: 62681429 EmailId: JANICE@SNGAHTTE.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA8467J	TP Vehicle No	SJB6636Y
PRI Recieved Date	03-08-2017 03:25:31 PM	Surveyor Appointed Date	04-08-2017 11:26:08 AM	Surveyor Accept Date	04-08-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-08-2017	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
----------------	----------------------	-------------------------------------

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 6748G

Vehicle Details

Vehicle No.: SJB6636Y

Vehicle to be Exported: No

Intended De-registration Date: 07 Aug 2017

Vehicle Make: HYUNDAI

Vehicle Model: NFSONATA 2.0

Primary Colour: Black

Manufacturing Year: 2006

Engine No.: G4KA6382732

Chassis No.: KMHEU41BR6A265896

Maximum Power Output: 106.3 kW (142 bhp)

Open Market Value: \$15,818.00

Original Registration Date: 21 Jan 2008

First Registration Date: 21 Jan 2008

Transfer Count: 0

Actual ARF Paid: \$17,400.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 20 Jan 2018

PARF Rebate Amount: \$8,700.00

Intended COE Rebate Details

COE Expiry Date: 20 Jan 2018

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$15,802.00

COE Rebate Amount: \$713.00

Total Rebate Amount: \$9,413.00

The information contained herein is correct as at 07 Aug 2017

OK

Land transport  Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 30 Jul 2017 at 12:58 AM

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

Get \$20 when you refer a friend to GrabHitch!

*Terms Apply


Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Sept 2013 Mercedes 7G-Tronic \$135K Negotiable.

 Excellent Condition, C&C
 Maintained, Accident Free. Nice
 Bided Number.
 Direct Owner

 click here
 our

Browse by Category

Sort by Date

3 vehicles

hyundai sonata

Advanced S

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	hyundai sonata		Any	Any	2008	Any	Any
	Hyundai Sonata 2.0A NF		\$20,800	\$9,280 /yr	06-Nov-2008	1,998 cc	112,75
	Posted: 24-Jul-2017 Tags: 2008 Hyundai Sonata, Hyundai Sonata, Hyundai, Sonata, Used Hyundai						
	Hyundai Sonata 2.0A NF		\$15,800	\$13,780 /yr	11-Feb-2008	1,998 cc	139,00
	Impeccable Condition, Good For 6 Months And Beyond, View To Believe. Posted: 18-Jul-2017 Tags: 2008 Hyundai Sonata, Hyundai Sonata, Hyundai, Sonata, Used Hyundai						
	Hyundai Sonata 2.0A NF		\$17,800	\$17,080 /yr	11-Feb-2008	1,998 cc	-
	Comfortable Short Term Drive. Warranty Till End Of Time! Price Negotiable! Call Now! Don't Hesitate. Posted: 10-Jun-2017 Tags: 2008 Hyundai Sonata, Hyundai Sonata, Hyundai, Sonata, Used Hyundai						

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
------	-------	-------	--------------	----------	---------	---------

For old advertisements, view **Expired ads**

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, to stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car bans, low mileage cars, car brands, carpark rates & hyundai sonata Singapore, used hyundai sonata Singapore, used hyundai sonata, used vehicles Singapore or even buy used hyundai sonata Singapore. We have authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

Compare

mation displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reli

10 Sin Ming Drive Singapore 575701
Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

21 Jan 2008

Our ref 2101080101N004227402

HAWK ASIA PACIFIC PTE LTD
32A HILLVIEW TERRACE
HILLVIEW INDUSTRIAL ESTATE
SINGAPORE 669251

000101/1



RECEIVED

MV 422

Dear Sir/Madam

NOTIFICATION ON REGISTRATION OF VEHICLE AND ROAD TAX

We wish to inform you that you have successfully registered vehicle SJB6636Y on 21 Jan 2008. The details of the registration are as follows:

A) Owner Particulars

- | | | |
|----|-------------------------|--|
| 1. | Name | : HAWK ASIA PACIFIC PTE LTD |
| 2. | Identification No. Type | : Company |
| 3. | Identification No. | : 200306748G |
| 4. | Place Of Passport Issue | : - |
| 5. | Registered Address | : 32A HILLVIEW TERRACE
HILLVIEW INDUSTRIAL ESTATE
SINGAPORE 669251 |
| 6. | Mailing Address | : - |

B) Vehicle Particulars

- | | | |
|-----|--------------------------------------|---|
| 1. | Vehicle No. | : SJB6636Y |
| 2. | Previous Vehicle No. | : - |
| 3. | Effective Date of Ownership | : 21 Jan 2008 |
| 4. | Original Registration Date | : 21 Jan 2008 |
| 5. | First Registration Date | : 21 Jan 2008 |
| 6. | Vehicle Type | : R10 - Private Hire (Self-Drive) Motor Car |
| 7. | Vehicle Scheme | : Normal |
| 8. | Attachment 1 | : No Attachment |
| 9. | Attachment 2 | : - |
| 10. | Attachment 3 | : - |
| 11. | Vehicle Make | : HYUNDAI |
| 12. | Vehicle Model | : NFSONATA 2.0 |
| 13. | Year of Manufacture | : 2006 |
| 14. | Primary Colour | : Black |
| 15. | Secondary Colour | : - |
| 16. | Passenger Capacity | : 4 |
| 17. | Chassis/Trailer Chassis No. | : KMHEU41BR6A265896 / - |
| 18. | Propellant | : Petrol |
| 19. | Engine No./Motor No. | : G4KA6382732 / - |
| 20. | Engine Capacity(cc)/Power Rating(kw) | : 1998 / - |
| 21. | Unladen Weight(kg) | : 1552 |

22.	Maximum Laden Weight(kg)	: 2030
23.	Open Market Value	: \$15,818.00
24.	PARF Eligibility	: Yes
25.	PARF Eligibility Expiry Date	: 20 Jan 2018
26.	Minimum PARF Benefit	: \$8,700.00
27.	No. of Transfers	: 0
28.	IU Label No.	: -
29.	COE No.	: 2008010103001753W
30.	COE Expiry Date	: 20 Jan 2018
31.	COE Category	: B - Car (1601cc & above)
32.	Quota Premium/Prevailing Quota Premium	: \$15,802.00
33.	Actual Quota Premium/PQP Paid	: \$15,802.00
34.	Actual ARF Paid	: \$17,400.00
35.	Vehicle Lifespan Expiry Date	: -
36.	Road Tax Amount	: \$712.00
37.	Road Tax Start Date	: 21 Jan 2008
38.	Road Tax End Date	: 20 Jul 2008
39.	Remarks	: This is a public service vehicle. This vehicle is eligible for PARF. To renew the COE, the Prevailing Quota Premium payable is that of Category B.

2. Enclosed is the validated road tax disc for your use.

3. You may use your NRIC and SingPass or User ID and Password (for non-Singaporeans/PRs) to login to <http://www.onemotoring.com.sg> and see the details of the above transaction. For non-Singaporeans/PRs who do not have a User Password, please visit our office at 10 Sin Ming Drive, Singapore-575701, Vehicle Registration & Licensing Division to request for one. Please note that a separate Transaction PIN is required for the following transactions via the Internet or at our Electronic Service Agents. Before you perform these transactions, please request for your Transaction PIN. You may find out more information on how to obtain your Transaction PIN via <http://www.onemotoring.com.sg> > LTA Information & Guidelines > Transaction PIN & User Account.

- a. Vehicle PIN - Transfer of Ownership and De-registration of Vehicle
- b. TCOE PIN - Transfer of TCOE (For Category C and E COE bid under individual)
- c. Rebate PIN - Transfer and Splitting of PARF/COE Rebate

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/07/2017 17:40
Date Of Accident	29/07/2017 10:55
Exact Location Of Accident	X-JUNC OF QUEEN ST & BRAS BASAH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJB6636Y
Insured/Policyholder	
Name Of Registered Owner	HAWK ASIA PACIFIC PTE LTD
Co Reg No	200306748G
Email Address	MUHD.NASRI@HAWKRENTACAR.COM.SG
Mobile Phone No	(LOCAL) +65-83324095
Alternative Phone No	OFFICE-64662366

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA NF-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5083541150
Cover Note Number	

Driver

Name of Driver	SHPORT NINA
Passport No/FIN	G6200837M
Date Of Birth	25/12/1972
Occupation	INDOOR
Date Of Driving Pass	11/12/2009
Driving Experience	7 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81831622
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 355 BT TIMAH RD #10-02
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

I WAS DRIVING ALONG QUEEN ST TWDS BUGIS. ON THE CONJUNCTION WITH BRAS BASAH RD ONCE THE TRAFFIC LIGHTS TURNED GREEN, I STARTED CROSSING THE CONJUNCTION. AT THAT MOMENT I WAS HIT ON THE LEFT SIDE BY A TAXI (HYUNDAI SONATA REGISTRATION SHA8467J). I HAVE A WITNESS, THE DRIVER BEHIND THE TAXI WHO CAN CONFIRM THAT THE TRAFFIC LIGHT WAS RED FOR THEM. HIS NUMBER IS 96544706(RYAN). THE TAXI DRIVER HAD A CAMERA IN HIS CAR AND THE CONJUNCTION ALSO HAS A CAMERA.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA8467J
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver LEE SAI POH
NRIC/Passport Number S1464138F
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name RYAN
Phone Number 96544706
Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan

Refer to Attachment

Sketch Plan Pg. 2

Describe Circumstances of the Accident

I was driving along Queen Street towards Bugis. On the conjunction with Bras Basah Rd once the traffic lights turned green, I started crossing the conjunction. At that moment I was hit on the left side bay a taxi. (Hyundai Sonata registration SHA 8467J)

I have a witness, the driver behind the taxi who can confirm that the traffic light was red for them. His number is 96544766 (Ryan)

The taxi driver had a camera in his car and the conjunction also has a camera.

☐ Claim own policy
☒ Claim third party
☐ Claim OD/TP at other's expense
☐ For record purposes only

Policy No 5083541150
Insurer NTUC (T) Policy No. 57B66364

Declaration

We declare the foregoing particulars are true in every respect.




Policyholder's Signature / Date &
Time



Driver's Signature (If driver is not the policyholder) / Date
& Time

John

Witnessed by Reporting Centre
Personnel



Celine Fong (LKKAUTO)

From: Celine Fong (LKKAUTO)
Sent: Thursday, 25 January 2018 11:33 AM
To: 'Sharon Sng'
Cc: Taufikh (LKKAUTO); SUR
Subject: RE: SJB6636Y repair limit

Dear Sharon,

Confirmed Lump Sum \$4,000.00

No of days: 8 days.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng [mailto:sharon@sngahtee.com]
Sent: Tuesday, 26 December 2017 5:37 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SJB6636Y repair limit

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Taufikh (LKK Auto) [mailto:taufikh@lkkauto.com]
Sent: Monday, August 7, 2017 9:16 AM
To: 'ADMIN SNGAHTEE'
Cc: 'Sharon Sng'; 'Darren Sng'
Subject: SJB6636Y repair limit

Hi All,

Please take note the repair limit for this vehicle is \$6000.

Thank you.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ002990

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION:

CONTACT: 6222 2311

FAX NO: 6507 3849

DATE 3/8/2017

ACCIDENT DATE : 29/7/2017

VEHICLE NO : SJB6636Y

CHASSIS/ENG.NO :

VEHICLE MODEL : HYUNDAI SONATA

CLAIM NO :

POLICY NO :

REMARK 6636FIRST TP AGST
SHA8467J

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	486.30	20	389.04	Rx 389.04
2	10	PC	REAR BUMPER CLIPS	5.84	20	4.67	all 46.70
3	1	PC	REAR BUMPER SIDE RETAINER(LH)	28.20	20	22.56	all 22.56
4	1	PC	REAR DOOR(LH)	786.60	20	629.28	bt 629.28
5	2	PC	REAR DOOR HINGE(LH)	77.10	20	61.68	bt 123.36
6	1	PC	REAR DOOR PROTECTOR(LH)	58.30	20	46.64	de 46.64
7	1	PC	REAR DOOR LOCK(LH)	201.80	20	161.44	? 161.44 X
8	1	PC	REAR DOOR WEATHERSTRIPE(LH)	110.20	20	88.16	all 88.16
9	1	PC	REAR DOOR TRIMBOARD(LH)	1,010.80	20	808.64	? 808.64 X
10	2	PC	REAR DOOR FRAME STICKER(LH)	22.20	20	17.76	all 35.52
11	1	PC	REAR DOOR SPEAKER(LH)	220.10	20	176.08	? 176.08 X
12	1	PC	REAR DOOR GLASS(LH)	201.10	20	160.88	? 160.88 X
13	1	PC	RR DOOR GLASS OUTER CHROME MLD	78.70	20	62.96	? 62.96 X
14	1	PC	REAR DOOR RUN CHANNEL(LH)	88.20	20	70.56	? 70.56 X
15	1	PC	REAR DOOR GLASS MOTOR(LH)	168.20	20	134.56	? 134.56 X
16	1	PC	REAR DOOR GLASS REGULATOR(LH)	188.20	20	150.56	? 150.56 X
17	1	PC	FRT DOOR(LH)	786.60	20	629.28	bt 629.28
18	2	PC	FRT DOOR HINGE(LH)	77.10	20	61.68	? 123.36 X
19	1	PC	FRT DOOR PROTECTOR(LH)	66.20	20	52.96	de 52.96
20	1	PC	FRT DOOR LOCK(LH)	201.80	20	161.44	? 161.44 X
21	1	PC	FRT DOOR WEATHERSTRIPE(LH)	110.20	20	88.16	all 88.16
22	1	PC	FRT DOOR OUTER HANDLE(LH)	67.20	20	53.76	Rx 53.76 X
23	1	PC	FRT DOOR TRIMBOARD(LH)	1,010.80	20	808.64	? 808.64 X
24	1	PC	FRT DOOR SPEAKER(LH)	220.10	20	176.08	? 176.08 X

JANICE

PAGE: 1 of 3

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ002990

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION:

CONTACT: 6222 2311

FAX NO: 6507 3849

DATE 3/8/2017

ACCIDENT DATE : 29/7/2017

VEHICLE NO : SJB6636Y

CHASSIS/ENG.NO :

VEHICLE MODEL : HYUNDAI SONATA

CLAIM NO :

POLICY NO :

REMARK : 6636FIRST TP AGST
SHA8467J

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
25	1	PC	FRT DOOR FRAME STICKER(LH)	22.20	20	17.76 <i>we</i>	17.76 ✓
26	1	PC	FRT DOOR GLASS OUTER MOULDING(L	78.70	20	62.96 ?	62.96 X
27	1	PC	FRT DOOR GLASS REGULATOR(LH)	188.20	20	150.56 ?	150.56 X
28	1	PC	FRT DOOR GLASS MOTOR (LH)	168.20	20	134.56 X	134.56 X
29	1	PC	FRT DOOR GLASS RUN CHANNEL(LH)	88.20	20	70.56 ?	70.56 X
30	1	PC	FRT SIDE MIRROR LAMP(LH)	280.70	20	224.56 <i>cu</i>	224.56 ✓
31	1	PC	ROCKER PANEL(LH)	551.70	20	441.36 ?	441.36 X
32	1	PC	SIDE SKIRT(LH)	251.70	20	201.36 <i>de</i>	201.36 ✓
33	10	PC	SIDE SKIRT CLIP	7.20	20	5.76 <i>cu</i>	57.60 ✓
34	1	PC	REAR SCUFF PLATE(LH)	67.20	20	53.76 ?	53.76 X
35	1	PC	FRT SCUFF PLATE(LH)	67.20	20	53.76 ?	53.76 X
36	1	PC	CENTER PILLAR INNER TRIM(LH)	97.80	20	78.24 <i>de</i>	78.24 ✓
37	1	PC	CENTER PILLAR(LH)	871.10	20	696.88 ?	696.88 X

SUB-TOTAL: 7,444.54

52342.14

** WORK LABOUR **

TO REMOVE & FIX 2 DOOR GLASS	120.00	<i>80.</i>	120.00
TO REMOVE & FIX RR DOOR QUARTER GLASS(LH)	30.00	✓	30.00
TO REMOVE & REFIT FRONT SEAT	<i>\$80</i> ↑ 100.00	<i>40.</i>	100.00
TO REMOVE & REFIT REAR SEAT	<i>\$80</i> ↑ 100.00	<i>40.</i>	100.00
TO REMOVE & REFIT FLOOR MAT	80.00	<i>40</i>	80.00

JANICE

PAGE: 2 of 3

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ002990

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION:

CONTACT: 6222 2311

FAX NO: 6507 3849

DATE: 3/8/2017
ACCIDENT DATE: 29/7/2017
VEHICLE NO: SJB6636Y
CHASSIS/ENG.NO:
VEHICLE MODEL: HYUNDAI SONATA
CLAIM NO:
POLICY NO:
REMARK: 6636FIRST TP AGST
SHA8467J

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	MISC/MARKUP	TOTAL AMT
			TO REMOVE & REFIT PETROL TANK			100.00	100.00
			TO KNOCK REAR FENDER(LH),FRT PILLAR(LH),FRT PANEL(LH),WELD,			0.00	0.00
			REMOVE & FIX ABOVE PARTS			1500.00	1,500.00
			TO SPRAY PAINTING ON FRT DOOR(LH),REAR DOOR(LH),REAR BUMPER,			0.00	0.00
			REAR FENDER(LH),FRT WINDSCREEN PILLAR(LH),CENTRE PILLAR(LH),			0.00	0.00
			REAR WINDSCREEN PILLAR(LH),ROCKER PANEL(LH),FLOOR PANEL			1400.00	1,400.00
						SUB-TOTAL	3,430.00

limit repair
\$6000/-

Tan Jiah 97495749 \$2710.00

4/8/17 @ 1730

Lumpsum

Repair after repair

Boys

See @ Tikaute.com

* To check Repair limit

total \$5000.00

less 200 = \$4800.00

\$2000.00 - 45

OK? pls revert. Shann 16/11/2017

JANICE

PAGE: 3 of 3

SUB-TOTAL: S\$ 10,874.54

ADD 7% GST. S\$ 761.22

GRAND TOTAL: S\$ 11,635.76

Jan

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O.E

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ002990

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

DATE 3/8/2017

ACCIDENT DATE : 29/7/2017

VEHICLE NO : SJB6636Y

CHASSIS/ENG.NO :

VEHICLE MODEL : HYUNDAI SONATA

CLAIM NO :

POLICY NO :

REMARK 6636FIRST TP AGST

SHA8467J

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	486.30	20	389.04	Rx 389.04
2	10	PC	REAR BUMPER CLIPS	5.84	20	4.67	nei 46.70
3	1	PC	REAR BUMPER SIDE RETAINER(LH)	28.20	20	22.56	nei 22.56
4	1	PC	REAR DOOR(LH)	786.60	20	629.28	bt 629.28
5	2	PC	REAR DOOR HINGE(LH)	77.10	20	61.68	bt 123.36
6	1	PC	REAR DOOR PROTECTOR(LH)	58.30	20	46.64	de 46.64
7	1	PC	REAR DOOR LOCK(LH)	201.80	20	161.44	nn? X 161.44
8	1	PC	REAR DOOR WEATHERSTRIPE(LH)	110.20	20	88.16	nei 88.16
9	1	PC	REAR DOOR TRIMBOARD(LH)	1,010.80	20	808.64	nn? X 808.64
10	2	PC	REAR DOOR FRAME STICKER(LH)	22.20	20	17.76	nei 35.52
11	1	PC	REAR DOOR SPEAKER(LH)	220.10	20	176.08	X 176.08
12	1	PC	REAR DOOR GLASS(LH)	201.10	20	160.88	X 160.88
13	1	PC	RR DOOR GLASS OUTER CHROME MLD	78.70	20	62.96	X 62.96
14	1	PC	REAR DOOR RUN CHANNEL(LH)	88.20	20	70.56	nn? X 70.56
15	1	PC	REAR DOOR GLASS MOTOR(LH)	168.20	20	134.56	X 134.56
16	1	PC	REAR DOOR GLASS REGULATOR(LH)	188.20	20	150.56	X 150.56
17	1	PC	FRT DOOR(LH)	786.60	20	629.28	bt 629.28
18	2	PC	FRT DOOR HINGE(LH)	77.10	20	61.68	nn? X 123.36
19	1	PC	FRT DOOR PROTECTOR(LH)	66.20	20	52.96	de 52.96
20	1	PC	FRT DOOR LOCK(LH)	201.80	20	161.44	nn? X 161.44
21	1	PC	FRT DOOR WEATHERSTRIPE(LH)	110.20	20	88.16	nei 88.16
22	1	PC	FRT DOOR OUTER HANDLE(LH)	67.20	20	53.76	Rx 53.76
23	1	PC	FRT DOOR TRIMBOARD(LH)	1,010.80	20	808.64	nn? X 808.64
24	1	PC	FRT DOOR SPEAKER(LH)	220.10	20	176.08	nn? X 176.08

JANICE

PAGE: 1 of 3

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ002990

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

DATE 3/8/2017

ACCIDENT DATE : 29/7/2017

VEHICLE NO : SJB6636Y

CHASSIS/ENG.NO :

VEHICLE MODEL : HYUNDAI SONATA

CLAIM NO :

POLICY NO :

REMARK : 6636FIRST TP AGST
SHA8467J

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
25	1	PC	FRT DOOR FRAME STICKER(LH)	22.20	20	17.76	we ✓ 17.76
26	1	PC	FRT DOOR GLASS OUTER MOULDING(L	78.70	20	62.96	?nm x 62.96
27	1	PC	FRT DOOR GLASS REGULATOR(LH)	188.20	20	150.56	?nm x 150.56
28	1	PC	FRT DOOR GLASS MOTOR (LH)	168.20	20	134.56	x nm 134.56
29	1	PC	FRT DOOR GLASS RUN CHANNEL(LH)	88.20	20	70.56	?nm x 70.56
30	1	PC	FRT SIDE MIRROR LAMP(LH)	280.70	20	224.56	nm 224.56
31	1	PC	ROCKER PANEL(LH)	551.70	20	441.36	?nm x 441.36
32	1	PC	SIDE SKIRT(LH)	251.70	20	201.36	de ✓ 201.36
33	10	PC	SIDE SKIRT CLIP	7.20	20	5.76	we ✓ 57.60
34	1	PC	REAR SCUFF PLATE(LH)	67.20	20	53.76	?nm x 53.76
35	1	PC	FRT SCUFF PLATE(LH)	67.20	20	53.76	?nm x 53.76
36	1	PC	CENTER PILLAR INNER TRIM(LH)	97.80	20	78.24	de ✓ 78.24
37	1	PC	CENTER PILLAR(LH)	871.10	20	696.88	?nm x 696.88

SUB-TOTAL: 7,444.54

** WORK LABOUR **

TO REMOVE & FIX 2 DOOR GLASS	120.00	80.	120.00
TO REMOVE & FIX RR DOOR QUARTER GLASS(LH)	30.00	✓	30.00
TO REMOVE & REFIT FRONT SEAT	100.00	80/40	100.00
TO REMOVE & REFIT REAR SEAT	100.00	80/40	100.00
TO REMOVE & REFIT FLOOR MAT	80.00	40	80.00

JANICE

PAGE: 2 of 3

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ002990

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

DATE : 3/8/2017
ACCIDENT DATE : 29/7/2017
VEHICLE NO : SJB6636Y
CHASSIS/ENG.NO :
VEHICLE MODEL : HYUNDAI SONATA
CLAIM NO :
POLICY NO :
REMARK : 6636FIRST TP AGST
SHA8467J

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
			TO REMOVE & REFIT PETROL TANK	100.00			100.00
			TO KNOCK REAR FENDER(LH),FRT PILLAR(LH),FRT PANEL(LH),WELD,	0.00			0.00
			REMOVE & FIX ABOVE PARTS	1500.00			1,500.00
			TO SPRAY PAINTING ON FRT DOOR(LH),REAR DOOR(LH),REAR BUMPER,	0.00			0.00
			REAR FENDER(LH),FRT WINDSCREEN PILLAR(LH),CENTRE PILLAR(LH),	0.00			0.00
			REAR WINDSCREEN PILLAR(LH),ROCKER PANEL(LH),FLOOR PANEL	1400.00			1,400.00
SUB-TOTAL							3,430.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tan Jiah 97495749
WP
4/8/17 @ 1730
Lumpsum
Resurvey after repair
Endays
Sub @ lkkauto.com
* To check repair limit

JANICE

PAGE: 3 of 3

SUB-TOTAL : S\$ 10,874.54

ADD 7% GST. S\$ 761.22

GRAND TOTAL : S\$ 11,635.76

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O.E



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17015124/T1rbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8467J	Veh. Inspected	SJB 6636Y	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17007425MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	04/08/2017	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI SONATA	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	KMHEU41BR6A265896	Colour	BLACK	
Odometer	128856	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	FALKEN	6 mm	
L/H Front Tyre	215/60 R16	FALKEN	6 mm	
R/H Rear Tyre	215/60 R16	FALKEN	6 mm	
L/H Rear Tyre	215/60 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/07/2017	Inspection Date	04/08/2017	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 6636Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	486.30	-
10	REAR BUMPER CLIPS @\$5.84	NECESSARY	58.40	58.40
1	REAR BUMPER SIDE RETAINER (LH)	NECESSARY	28.20	28.20
1	REAR DOOR (LH)	BENT	786.60	786.60
2	REAR DOOR HINGE (LH) @\$77.10	BENT	154.20	154.20
1	REAR DOOR PROTECTOR (LH)	DEFORMED	58.30	58.30
1	REAR DOOR LOCK (LH)	NOT NECESSARY	201.80	-
1	REAR DOOR WEATHERSTRIP (LH)	NECESSARY	110.20	110.20
1	REAR DOOR TRIMBOARD (LH)	NOT NECESSARY	1,010.80	-
2	REAR DOOR FRAME STICKER (LH) @\$22.20	NECESSARY	44.40	44.40
1	REAR DOOR SPEAKER (LH)	NOT NECESSARY	220.10	-
1	REAR DOOR GLASS (LH)	NOT NECESSARY	201.10	-
1	RR DOOR GLASS OUTER CHROME MLD	NOT NECESSARY	78.70	-
1	REAR DOOR RUN CHANNEL (LH)	NOT NECESSARY	88.20	-
1	REAR DOOR GLASS MOTOR (LH)	NOT NECESSARY	168.20	-
1	REAR DOOR GLASS REGULATOR (LH)	NOT NECESSARY	188.20	-
1	FRT DOOR (LH)	BENT	786.60	786.60
2	FRT DOOR HINGE (LH) @\$77.10	NOT NECESSARY	154.20	-
1	FRT DOOR PROTECTOR (LH)	DEFORMED	66.20	66.20
1	FRT DOOR LOCK (LH)	NOT NECESSARY	201.80	-
1	FRT DOOR WEATHERSTRIPE (LH)	NECESSARY	110.20	110.20
1	FRT DOOR OUTER HANDLE (LH)	TO REPAIR SEE LABOUR	67.20	-
1	FRT DOOR TRIMBOARD (LH)	NOT NECESSARY	1,010.80	-
1	FRT DOOR SPEAKER (LH)	NOT NECESSARY	220.10	-
1	FRT DOOR FRAME STICKER (LH)	NECESSARY	22.20	22.20
1	FRT DOOR GLASS OUTER MOULDING (LH)	NOT NECESSARY	78.70	-
1	FRT DOOR GLASS REGULATOR (LH)	NOT NECESSARY	188.20	-
1	FRT DOOR GLASS MOTOR (LH)	NOT NECESSARY	168.20	-
1	FRT DOOR GLASS RUN CHANNEL (LH)	NOT NECESSARY	88.20	-

Report Ref No. CS/FCI17015124/T1rbe2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT SIDE MIRROR LAMP (LH)	CRACKED	280.70	280.70
1	ROCKER PANEL (LH)	NOT NECESSARY	551.70	-
1	SIDE SKIRT (LH)	DEFORMED	251.70	251.70
10	SIDE SKIRT CLIP @\$7.20	NECESSARY	72.00	72.00
1	REAR SCUFF PLATE (LH)	NOT NECESSARY	67.20	-
1	FRT SCUFF PLATE (LH)	NOT NECESSARY	67.20	-
1	CENTER PILLAR INNER TRIM (LH)	DEFORMED	97.80	97.80
1	CENTER PILLAR (LH)	NOT NECESSARY	871.10	-
	LESS 20% DISCOUNT		-1,861.16	-585.54
			7,444.54	2,342.16
	LABOUR			
	TO REMOVE & FIX 2DOOR GLASS.		120.00	80.00
	TO REMOVE & FIX RR DOOR QUARTER GLASS (LH).		30.00	30.00
	TO REMOVE & REFIT FRONT SEAT.		100.00	80.00
	TO REMOVE & REFIX REAR SEAT.		100.00	80.00
	TO REMOVE & FIX FLOOR MAT.		80.00	40.00
	TO REMOVE & REFIX PETROL TANK.	NOT NECESSARY	100.00	-
	TO KNOCK REAR FENDER (LH), FRT PILLAR (LH), FRT PANEL (LH), WELD, REMOVE & FIX ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND FRT DOOR OUTER HANDLE (LH).		1,500.00	1,200.00
	TO SPRAY PAINTING ON FRT DOOR (LH), REAR DOOR (LH), REAR BUMPER, REAR FENDER (LH), FRT WINDSCREEN PILLAR (LH), CENTRE PILLAR (LH), REAR WINDSCREEN PILLAR (LH), ROCKER PANEL (LH), FLOOR PANEL.		1,400.00	1,200.00
			3,430.00	2,710.00
GRAND TOTAL			10,874.54	5,052.16

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00
---	--	--	-----------------

Report Ref No. CS/FCI17015124/T1rbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.