

REPAIR DETAILS*Supplementary***Reference****Part Source:** (Last Synchronised: 09 May 2018)**Parts:** N/A HINO XZU710R-HKFMS3 4.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for YN7881H)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR CLEANER BOX BRACKET	0.00	0.00	<i>bt</i> *95.00 F
2	1		*FRT CABIN BRACKET	0.00	0.00	<i>bt</i> *1,250.00 F
3	1		*FRT WINDSCREEN INNER TRIM (RH)	0.00	0.00	<i>dec</i> *60.00 F
4	1		*REAR DECK CANOPY ASSY	0	0.00	<i>mis</i> *2,200.00 FS
5	1		*DIESEL RETURN HOSE	0.00	0.00	<i>bt</i> *120.00 F
6	1		*CABIN TILT SENSOR	0.00	0.00	<i>dis</i> *325.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,050.00
+ Margin on L,N Items 5.00% (\$\$)	92.50
Total Parts (\$\$)	4,142.50

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**