A.	SSIGNMENT
From: Date:	Veh No: SLI8757C Yr Regn: 2016 1Pec
stimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
o Inspect Vehicle No:	Make: Audi AH c.c 1395
t Workshop m/s	Colour Buck A/C: Insured / Std / NI / NA
f	Sp.Reading /32 42 T/Radio: Insured / Std / NI / NA
nsured:	Eng/No:
Policy No. 210049534	C/No: WAUZZZFH3HAOSS959.
Claims No. 694021160056	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: \$60 o	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
-	Tyre Size: F: 205/60 RHb-
(Policy Condition)	R: 205/60816
An interest of the Marine Control of the Control of	D/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO or Continental
Bal. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
GIA / PR Seen: M Consistent?: Yes or No	L/Bal. 06 mm L/Bal. 06 mm
Est. Repairs: Of days Res.: Yes or No	D.O.A. D.O.I. 30/08/17
Lum Sum: % 3 Val.: Yes or No	Survey held at Premium -
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN /	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
od Alg	
X - DFEFE E15	
Confirm \$4551.20, 4 days	
Red: \$11154.80, 717.	
RECEIVED 1 6 Pull	2018.
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 4
: Final Report	Resurvey No. of Trip: - Survey Fee: 200
1) Date/Time, File Return to?	Transportation: 10
	d Fee: : Site Insp (\$ )S+RS,SI
	: Interview (\$ ) Photos
Report Format : Pp	: Tech. Invs (\$ ) 5/4
Lump Sum-/ I.B.I: (\$ 4551 - 20 )	: Weekend (\$
SWINDOW CONTROL WASHINGTON TO THE STATE OF T	TOTAL 210



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Inte	rnationale Des Experts En Autor	
AIG ASIA PACIFIC INS	URANCE PTE LTD	Ref : CC3/AIG17016	6876/Arb
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date: 30-08-2017  Code: AIG	
1.	Policy Par	ticulars :- OWN DAMAGE	
Insured Veh.		Veh. Inspected	SLJ 8757C
Policy No.	2100495345	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	30/08/2017
2.	Vehicle	Particulars & Condition	
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3.	Co	onditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	7		mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4.	Des	cription of Damages	
	C.	eneral Information	
5	A THE PROPERTY OF THE PROPERTY	Inspection Date	30/08/2017
Accident Date	27/08/2017 PREMIUM AUTOMOBILE		00/00/2017
Survey held at		SFIELIU	
	55 UBI ROAD 1 . SINGAPORE 408699		
5a.	THE RESIDENCE OF THE PARTY	Remarks	

A)THE MARKET VALUE IS S\$-----(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.





Licence Number S8006159E

KUI SONG CHIN (OIU SONGZHENG)

Birth Date 23 Feb 1980 Issue Date 01 Sep 2003



#### REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$8006159E





KUI SONG CHIN (QIU SONGZHENG)

松 IE 丘

CHINESE

1938 80088

Date of birth 23-02-1980 M

Country of birth SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)

PASS DATE

Class 3

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

16-08-2010

APT BLK 316B PUNGGOL WAY #11-713

SINGAPORE 822316 NRIC No: \$8006159E

Date: 01/04/2017

NP 428A



#### **COVER NOTE**

Cover Note No. 2100495345

Date 22 Dec 2016

The following risk described in the Schedule is hereby HELD COVERED in the terms of the applicable Company's policy issued to the Policyholder.

	CH.	-	~;		_
- 31			w	и.	_

Policy Age C

KUI SONG CHIN (Q\()SONGZHENG) /

Policy Type

Effective Date

**Expiry Date** 

Excess

All Age Condition

24 Dec 2016

17 Dec 2017

S\$600.00

AUDI AUTO PROTECTOR

Registration No. Make/Model

SLJ8757 C

AUDI A4 1.4 TFSI S tronic

1,395.00 CC/Tonnage CVNQ21878 Engine No.

Chassis No

WAUZZZF43HA055959

Year of Registration

2016

Hire Purchase Company

United Overseas Bank Limited



This policy is subject to driver's age condition. The policy will indemnify the insured or any authorised driver only if he/she meets the age condition. Please refer to policy terms and conditions.

In addition to the Policy Excess, a Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00 (before GST) will apply to You or Your Authorised Driver who is below the age of 23 (in case of All Age Condition policies) and/or has less than 2 years' driving experience. The YIDR Excess is not applicable to Named Driver policies.

Usage of vehicle only for the following purposes:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business and use for social, domestic or pleasure purposes.

Please note that acceptance of the risk is subject to our final acceptance and terms and conditions applicable to the policy. Should you require any change to the insurance, please contact us immediately. Otherwise, any change will not be covered under the policy.

The Company may cancel this cover by notice in writing and the insurance will be terminated and a proportionate part of the annual premium for the insurance will be charged for the time the Company has been on risk.

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

#### CERTIFICATE OF INSURANCE

I/We hereby certify that this cover note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Issued in SINGAPORE

AIG Asia Pacific Insurance Pte. Ltd.

IMPORTANT NOTICE THIS COVER NOTE IS VALID FOR 60 DAYS FROM THE FIRST DAY OF THE POLICY PERIOD. APPLICABLE TO CORPORATE POLICIES ONLY.

**AUTHORISED REPRESENTATIVE** 

ORIGINAL

PRLYCO

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

#### Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1

Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/OD/0848/2017/NK

Date : 28-Aug-17

Vehicle not in workshop. Kindly arrange for survey.

#### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Kui Song Chin

Address : Blk 316B Punggol Way

#11-713

Singapore 822316 **Telephone** : HP +65 97588577

Type of Claim : Own Damage Claims

Policy No. : 2100495345 Vehicle No : SLJ 8757 C

Model Code : Audi A4 SEDAN 1.4 TFSI

Model / Year : Dec-16
Engine No : CVN 021878

Chassis No : WAUZZZF43HA055959

Mileage : Date In :
Liability : Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 27-Aug-17

Place of Accident : Blk 316B Punggol Way Rd Carpark

# Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

# Estimated Labour Charges for Accident Vehicle SLJ 8757 C

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	//
2	To dismantle and renew front bumper, lhs front fender and lhs head light. Reorganise front crash management components. Reinstall all parts removed.		\$ 2,100.00	1003/
3	To respray front bumper and lhs front fender.		\$ 1,500.00	1135/
4	To carry out diagnostic check.	S/N	\$ 192.00	//
	TOTAL LABOUR CHARGES	:	\$ 4,152.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

# Material List for Accident Vehicle Regn No. SLJ 8758 C

/NETT REMARKS
1,703.00 - 1362,40
67.00 *
303.00 🛧
29.00 +
643.00 - 514.40
29.00 %
29.00 🕏
42.00 🛠
28.00 3/22 140
100.00 🕅
32.00 🔀
61.00 *
208.00
76.00 *.
7,861.00 🕆 .
19.00 *
24.00 *-
300.00
11,554.00
4,152.00
15,706.00

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### **Telefax**

Name

Adrian Li

Surveyed Date

: 30/08/17.

**Authorised Date** 

:

**Excess Cost** 

:

Liability

•

Remarks

: Authorised Payis, 040ys

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd LICK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
   To dealer dearers and to dealer dealers.
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" besis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to finel approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept

Yr Ref: SLJ 8757 C

6768 9911 6841 1183 Nora.khai@premiumauto.com.sg Body & Paint Dept PA/OD/0848/2017/MAS from
Telephone +65Telefax +65EMail
Our department
Our Ref
Your Ref
Date

13 March 2018

Norah Khai

Dear Sir,

RE: INSURANCE CLAIM FOR SLJ 8757 C, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. SLJ 8757 C, claimant, Mr. Kui Song Chin, please find the related document per attached.

- A copy of the Original invoice no. 85012234 \$\$4,227.78
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encls

AIG - SLJ 8757 C

total pages

Premium Automobiles Pte Ltc Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	31 Aug 2017		30 Aug 2017 16:36 Edit Adj Rpt	S\$4,551.20 Edit Estimates	<b>S\$4,551.20</b> View Rpt			
	Main	Refe	rence	Claim Det	ails ]	Documents	Show All	
CLAIM S	UBFOLDER DET	TAILS	A Strain of the Strain of the		ALTERNATION OF THE PARTY OF THE	[Created by i	nsurer]	
Insured:		KUI SONG CH	IN, ID: 580061	59E, Tel: +65975	588577, Email: Z	HENG2302@HOTI	MAIL.COM	
Vehicle R	Reg. No.:	SLJ8757C		Date of	Loss:	27/08/2017 16	:00 - :59	
Claim Tv	laim Type: OD / 694021160		OD / 6940211600SG Policy/Cover Note No.:			2100495345 (0	Comprehensive)	
				Excess:		S\$600.00		
Repairer		Premium Auto	omobiles Pte Lte	d (UBI) 55 Ubi Roa	ad 1, 408699 Ubi -	- Tel: 67689828/9827/9911		
Handling	Insurer:	TongShing.Loo	@aig.com		Decel State of the	[Handled by Loo, Tong Shing]		
Adjuster	1	11/09/2017		I (HQ) - Tel: 6256	-3561 [Handled	by ADRIAN LIN	G] [Final Rpt due	
Driver/C	ustodian:	KUI SONG CHI	N (37 / Male),	NRIC: S8006159E,	Tel: +65975885	77		
ASSOCI	ATED MAIL REG	CEIVED				View All	Compose Case Mail	
• AIG S	G (31/08/2017):	SL18757C / OD	/ 27/08/2017	Coverage & Exc	ess update			
• AIG_S	0 (51)00/2017).	555,576,50						
E ALL ASS	SOCIATED TAS	KS		View /	All   Search Task	cs   Create N	lew Task   Complete	

Merimen e-Claims Page 1 of 2

#### **Claim Documents**

\*SLJ8757C (6940211600SG) OD
Aug 27 2017 4:00PM
[KUI SONG CHIN]
Premium Automobiles Pte Ltd

	Upload Documents	Upload Photos Compose New Letter Upload Video Up	load Audio	View Use Viewe	r
Pho	tos/Images		3 p	er page 🔻	1
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/08/17 10:28	General View	€	Load JPG	J
2	31/08/17 10:28	General View	•	Load JPG	V
3	31/08/17 10:28	General View	•	Load JPG	V
4	31/08/17 10:28	General View	€	Load JPG	1
5	31/08/17 10:28	General View	€	Load JPG	V
6	31/08/17 10:28	General View	•	Load JPG	V
7	31/08/17 10:28	General View	•	Load JPG	7
8	31/08/17 10:28	General View	•	Load JPG	V
9	31/08/17 10:28	General View	•	Load JPG	<b>V</b>
10	31/08/17 10:28	General View		Load JPG	V
11	31/08/17 10:28	General View	€	Load JPG	7
12	31/08/17 10:28	General View	€	Load JPG	V
13	31/08/17 10:28	General View	•	Load JPG	1
14	31/08/17 10:28	General View	€	Load JPG	1
Doc	cumentation		1 p	1 per page ▼	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/08/17 10:25	Insurance Cover Note	€	Load PDF	
2	31/08/17 10:25	W/S ESTIMATE	€		
3	31/08/17 10:25	Singapore Accident Statement	€		
4	31/08/17 10:25	NRIC & DL	€		
5	19/03/18 12:21	WORKSHOP INVOICE	•		
6	19/03/18 12:21	DISCHARGE VOUCHER	€	Load PDF	

#### **Linked Accident Report Documents**

			V	iew Use Viewe	r
Ass	essment Report	s	1 per	page 🔻	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/08/17 13:47	Accident Statement	0	Load HTM	
Pho	tos/Images		3 per	page 🕶	7
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/08/17 13:45	Accident Photo	0	Load JPG	1
2	28/08/17 13:45	Accident Photo	0	Load JPG	V
3	28/08/17 13:45	Accident Photo	0	Load JPG	V
4	28/08/17 13:45	Accident Photo	0	Load JPG	<b>V</b>
5	28/08/17 13:45	Accident Photo	0	Load JPG	V
6	28/08/17 13:45	Accident Photo	0	Load JPG	V
7	28/08/17 13:45	Accident Photo	0	Load JPG	V
8	28/08/17 13:45	Accident Photo	0	Load JPG	V
Doc	cumentation		1 per	page 🔻	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/08/17 13:24	Sketch Plan	0	Load JPG	1

2 28/08/17 13:24 Sketch Plan #2	0	Load JPG	V
Documents Checklist			
DOCUMENTS CHECKLIST		Reset Sa	ve Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
*			
· ·			
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.			

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way #07-16

Singapore 079120

CC3/AIG17016876/ARBN2

Date:

Our File No:

19/03/2018

REFERENCE

Date of Loss:

Insured/Claimant:

KUI SONG CHIN

27/08/2017

Policy No: Nature of Claim: 2100495345

OD

Claim No:

6940211600SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SLJ8757C

Make & Model:

AUDI A4, 1.4 T (A)

28/12/2016 (Man. Year: 2016)

Engine No: Chassis No:

Odometer:

CVN021878

WAUZZZF43HA055959

Reg. Date: Colour:

Black

1395 cc

Engine Capacity: Market Value/New Car Price:

S\$140,000.00

13242 km

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

205/60R16

Rear Tyre Size:

205/60R16

Front Left Side:

Continental 6 mm

Rear Left Side:

Continental 6 mm

Front Right Side:

Continental 6 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,554.00	1,899.20	9,654.80	83.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,152.00	2,652.00	1,500.00	36.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,706.00	4,551.20	11,154.80	71.02
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	15,106.00	3,951.20	11,154.80	73.84
+ GST 7.00/7.00% (S\$)	1,057.42	276.58	780.84	73.84
Nett Amount (S\$)	16,163.42	4,227.78	11,935.64	73.84

INSPECTION

Date of Assignment:

30/08/2017

Date Inspected:

30/08/2017 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

4.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

		nended Parts Part No. Particulars	Condition	Repairer's	Amount
1 2	1	*FRONT BUMPER *AIR GUIDE LH	Deformed Not Necessary	1,703.00 FS 67.00 FS	*1,362.40 FS *- FS
3	1	*AIR GUIDE GRILLE LH *GUIDE SECTION LH	Not Necessary Not Necessary	303.00 FS 29.00 FS	*-FS *-FS
5	1	*FRONT FENDER LH *FRONT FENDER CLOSING ELEMENT LH	Dented Not Necessary	643.00 FS 29.00 FS	*514.40 FS *- FS
7	1	*FRONT FENDER BRACKET LH *FRONT FENDER TOP BRACKET LH	Not Necessary Not Necessary	29.00 FS 42.00 FS	*- FS *- FS
9	10	*POP RIVET *FRONT FENDER BRACE FRONT LH	Necessary Not Necessary	28.00 FS 100.00 FS	*22.40 FS *- FS
11	2	*DOUBLE COLLARD STUD *WHEEL SPOILER LH	Not Necessary Not Necessary	32.00 FS 61.00 FS	*-FS *-FS
13	1	*WHEEL HOUSING LINER LH *WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary Not Necessary	208.00 FS 76.00 FS	*-FS *-FS
15	1	*LED HEADLIGHT LH *COVER LH	Not Necessary Not Necessary	7,861.00 FS 19.00 FS	*-F8 *-F8
17 18	1	*COVER RH *SUNDRIES	Not Necessary Not Necessary	24.00 FS 300.00 FS	*-F8 *-F8
	anchise pa	rt. S=SpcNett.	Total Parts (S\$)	11,554.00	1,899.20

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recom	man	hah	l al	nour
Recom	men	ueu	Lai	Jour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEAD LIGHT.REORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	1,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour Cost (S\$)		4,152.00	2,652.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >

#### Janice Lee (LKKAuto)

From: Sent: Boo seng yak <boojohnny@gmail.com>

Thursday, October 19, 2017 8:24 AM

To:

Adrian Ling (LKKAuto); Janice Lee (LKKAuto); SUR; Carrine Leong; Nora Khai

Subject:

FINAL REVISION SLI8757C - OD AIG - SURVEYED 30 AUG 17

Attachments:

PA08482017 - SLJ 8757 - A4 SEDAN 1.4 TFSI - FRONT (AIG).xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$4551.20 @ 4 days of repairs.

Your early closure is well appreciated.

Best regards - jb

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

#### Telefax

**Estimate** 

Accident Repairs

Workshop

Ubi Road 1

Contact No

6366 2323

Fax No

6841 1183

Reference

PA/OD/0848/2017/NK

Date

: 28-Aug-17

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

Mr. Kui Song Chin

Address

Blk 316B Punggol Way

#11-713

Singapore 822316

Telephone

HP +65 97588577

Type of Claim

Own Damage Claims

Policy No.

2100495345

Vehicle No

SLJ 8757 C

Model Code

Audi A4 SEDAN 1.4 TFSI

Model / Year

Dec-16

Engine No

CVN 021878

Chassis No

: WAUZZZF43HA055959

Mileage

•

Date In

:

Liability

:

**Excess Cost** 

Johnny Boo / Allan Wu

Estimated By Accident Date

: 27-Aug-17

Place of Accident

: Blk 316B Punggol Way Rd Carpark

Hi Adrian

4 days - ok - jb - 19/10

