STATES REC. BY.		REF CS/M	5917017539/Rlrb	N> Speci	al instruction.	
milimen From (Person)	Rosul Monita	_A	SCICNMENT (Office)	Ř	Date/Time 11/9/	17 10-17 am
To Inspect Vehical Workshop in of 168 Per Folicy No Sum Insured Make of Vehical's Record	sole No. andein 100 80 423	57311QMY	Claim No Excess	529 7 @ after	D.O.A. 08/8	09
Date Time	Action/lestr) Estimate		77	
26/10/1	SET 66	68 H- (B)	nig 0900 9749/j -	D.O.A.	1/12/2005	
1000	Confirm	J	34, 3 days			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation		
SIG I	NSURANCE (SIN	GAPORE) PTE LTD	Ref : CS/MSG17017539	9/R1rb
: D \ E	ELES OLIAY	BLDG SINGAPORE 048581	Date: 11-09-2017 Code: MSG	
1997		Policy Particulars	:- THIRD PARTY CLAIM	
	nsured Veh.	SFT 6668H	Veh. Inspected	SKT 5224C
	Policy No.	80423734QMY	Coverage (\$)	0.00
_	Claim No.	529716	Excess (\$)	0.00
	Assign From	MERIMEN (MONICA CHUNG)	Assign Date	11/09/2017
	BEET CHENCH	Vehicle Parti	culars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
_	Chassis No.		Colour	
	Odometer	1.5 2.5	Steering	
	Brakes		Modification	
	General			
3.		Condi	tions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Descrip	tion of Damages	
5.	Engine No.	THE RELIGIOUS AND RESERVED TO SERVED STATES	ral Information	
	Accident Date	08/09/2017	Inspection Date	
	Survey held at	CYCLE & CARRIAGE INDUST	IRIES (1986) PL	
		188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a.		ON WAS CONDUCTED ON A"V	Remarks	

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	11 Sep 2017		23 Oct 2017 16:25 Assign				New Assign Cancel Case	
	Main	Re	ference	Clai	m Details	Docume	ents	Show All
CLAIM S	UBFOLDER DET	TAILS	THE RESERVE OF THE PERSON NAMED IN COLUMN	DE 30 / DE 20		[Created b	y insurer]	
Insured:		LIM KENG HU	AT, ID: S802488	33				
Main Cla	imant:	SEAH SWEE E	E, ID: S1169550	10.00		00/00/2017	00.00 - 50	
Vehicle I	Reg. No.:	SKT5224C Dat			ALCO ALCO ALCO ALCO ALCO ALCO ALCO ALCO		00:00 - :59	nsivel
Claim Type: TP / 529716			Po	Policy/Cover Note No.: 80423734QMY (Comprehensis Coverage: 04/02/2017 - 03/0				
Vehicle Reg. No.		SFT6668H PO		olicy No. (Claimant)	:			
(Insured):					cess:			
Repaire	r:	Cycle & Carri	age Industries P	e Ltd (Panda	in Loop) 188 Pandan	Loop, 128378 We	est Coast - Tel:	91865300
Handling	g Insurer:	6594 25521) - Tel: +65 6827 788			ig Pei Zhen -
Adjuste	rı	LKK Auto Cor	sultants Pte Ltd	(HQ) - Tel: 6	256-3561 [Imm.	Advice due 24	/10/2017]	
Adj Asg	Remarks:	ON WP.						
ASSOCI	ATED MAIL RE	CEIVED				View	All Comp	ose Case Mail
MSIG	SG (23/10/2017): Cancellation o	f Assignment: Sk	T5224C				
Е							2-00	27 26 505
	SOCIATED TAS	KS			View All Sear	ch Tasks Cr	eate New Task	Complete
Due D		Type Task	Group Subjec	t Handler	Assigned By	Completed O	n Create	d On Done

Catherine Chong (LKK Auto)

From:

Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>

Sent:

Monday, 11 September, 2017 10:17 AM

To:

'chanhoe.yik@cyclecarriage.com.sg'; 'Ashley Chong (LKK Auto)'

Cc:

Monica Chung; Rashitha Binte Shahuthuman

Subject:

FW: Accident involving motor vehicle nos. SKT 5224 C & SFT 6668 H // Propose for

Direct Settlement

Attachments:

img-908164433-0001.pdf

3.5+pm

Dear LKK,

VED.

Please call workshop to arrange for survey. We will grant rights to you in merimen soon. Thank you.

Estint.

Rashitha

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha_shahuthuman@sg.msig-asia.com

MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on

----Original Message-----

From: Yik Chan Hoe [mailto:chanhoe.yik@cyclecarriage.com.sg]

Sent: Monday, 11 September, 2017 10:14 AM

To: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>

Cc: Monica Chung < Monica_Chung@sg.msig-asia.com>

Subject: RE: Accident involving motor vehicle nos. SKT 5224 C & SFT 6668 H // Propose for Direct Settlement

Dear Rashitha,

Our choice of surveyor will be LKK Auto Consultants Pte Ltd.

Thanks & Regards,

Yik Chan Hoe

Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd

Pandan Loop Service Center

Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg

----Original Message-----

From: Rashitha Binte Shahuthuman

Sent: Monday, 11 September, 2017 9:56 AM

To: 'chanhoe.yik@cyclecarriage.com.sg' <chanhoe.yik@cyclecarriage.com.sg>

Cc: Monica Chung <Monica_Chung@sg.msig-asia.com>; Rashitha Binte Shahuthuman

<rashitha_shahuthuman@sg.msig-asia.com>

Subject: FW: Accident involving motor vehicle nos. SKT 5224 C & SFT 6668 H // Propose for Direct Settlement

OUR REF - SFT6668H

WITHOUT PREJUDICE

Dear Mr Yik,

We propose one of the motor surveyor name in the list below to conduct the joint pre-repair survey as the single joint expert.

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for any of the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 9 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong
- 3) Marcus Chua
- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You Han
- 8) Gary Soon
- 9) Chow Bo Xiong

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

Thank you.

Rashitha

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha_shahuthuman@sg.msig-asia.com

MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on

----Original Message-----

From: Monica Chung

Sent: Monday, 11 September, 2017 9:00 AM

To: Yik Chan Hoe <chanhoe.yik@cyclecarriage.com.sg>

Cc: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>

Subject: FW: Accident involving motor vehicle nos. SKT 5224 C & SFT 6668 H // Propose for Direct Settlement

WITHOUT PREJUDICE

Dear Mr Yik,

Our insured has not reported the accident. We will assign surveyor for the survey first.

Thank you.

Regards,

Monica Chung

Assistant Executive, Claims Services (Motor) Direct line +65 6594 2552 | Direct fax +65 6225 7402 | monica_chung@sg.msig-asia.com

MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | http://www.msig.com.sg/ | Follow us on

----Original Message-----

From: Joslin Lim

Sent: Friday, September 08, 2017 5:31 PM

To: Monica Chung <Monica_Chung@sg.msig-asia.com>; Rashitha Binte Shahuthuman

<rashitha shahuthuman@sg.msig-asia.com>

Cc: Christopher Chionh <christopher_chionh@sg.msig-asia.com>; Foo Ai Ngoh <aingoh_foo@sg.msig-asia.com>;

Jason Sim <Jason_Sim@sg.msig-asia.com>

Subject: FW: Accident involving motor vehicle nos. SKT 5224 C & SFT 6668 H // Propose for Direct Settlement

Hi Monica and Rashita

FYNA

----Original Message-----

From: Koh Lay Hoon

Sent: Friday, 8 September, 2017 5:20 PM To: Joslin Lim <joslin_lim@sg.msig-asia.com>

Subject: FW: Accident involving motor vehicle nos. SKT 5224 C & SFT 6668 H // Propose for Direct Settlement

----Original Message-----

From: Yik Chan Hoe [mailto:chanhoe.yik@cyclecarriage.com.sg]

Sent: Friday, September 08, 2017 5:15 PM To: Claims <claims@sg.msig-asia.com>

Subject: Accident involving motor vehicle nos. SKT 5224 C & SFT 6668 H // Propose for Direct Settlement

To: MSIG

Attn: Motor Claims Dept

RE: Accident involving motor vehicle nos. SKT 5224 C & SFT 6668 H along Jalan Eunos, Accident date: 08/09/2017

Dear Officer In-Charge,

This email is with regards to the above accident which has been reported by our customer. We have since been instructed by him/her (motor vehicle number SKT 5224 C), to submit a claim on his/her behalf as we are the authorised repair workshop for his/her car.

We note that you are the insurer (3rd party) of the (motor vehicle number SFT 6668 H) involved. As such we are proposing for a Direct Settlement with regards to the repair costs and other consequential losses.

We appreciate your assistance in this matter and look forward to your agreement on this direct settlement.

I can be reached at chanhoe.yik@cyclecarriage.com.sg

Thanks & Regards,

Yik Chan Hoe Mercedes-Benz Body Care & Repair Center Cycle & Carriage Industries Pte Ltd Pandan Loop Service Center Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available afor esaid.

ACCIDENT STATEM	-	

08/09/2017 14:32 Date Of Report

08/09/2017 08:25 Date Of Accident

JALAN EUNOS Exact Location Of Accident

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

SKT5224C Vehicle Registration Number

Insured/Policyholder

SEAH SWEE EE Name Of Registered Owner

S1169550G NRIC No NOEMAIL Email Address

(LOCAL) +65-98305992 Mobile Phone No

OFFICE-98305992 Alternative Phone No

Vehicle Particulars

MERCEDES-BENZ Manufacturer

E250 Model

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage

NO

Fleet Policy Policy Number

2100416558-02000

COMPREHENSIVE

Cover Note Number

Driver

SEAH SWEE EE Name of Driver

S1169550G NRIC No 07/08/1955 Date Of Birth

INDOOR Occupation 21/08/1978 Date Of Driving Pass

39 YEARS AND 0 MONTHS Driving Experience

FEMALE Gender

(LOCAL) +65-98305992 Mobile Number

Fax Number

OFFICE-98305992 Contact Number

NOEMAIL EMail Address

Address

44 JALAN ANGIN LAUT

Postcode

489252

W adriver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Ty pe Of Accident

COLLISION - HEAD TO REAR

W eather Conditions

CLEAR

Road Surface

DRY

Other Information

Wasany foreign vehicle involved in this accident?

NO

Wasany body injured in the Accident?

NO YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

REFER YK

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SFT6668H

Vehicle Make/Model/Colour

TOYOTA HARRIER SILVER

Details Of Properties

Name of Driver

LIM CHENG WAI

NRIC/Passport Number

S0795593F

Contact Number

Address

Postcode

Insurance Company Name

MSIG INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

I MPORTANT NOTICE

- Pease report correctly the details of the accident to speed up the claims process.
- This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3 . Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may a library insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Sngapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 . Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose a nd/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Planeses (27)

Cycle & Carrier Repair Centers (873.13)

Policyholder's Signature / Date &

) = 8/9/1.

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

HAL		

Describe Circumstances of the Accident

my cor was stationary ciety after the
yellow cox, car B was in the yellow ox trying to turn into the gight
lane, but the driver of car B grazad
A my car while doing so.

Declaration

I/We declare for foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

Cycle & Cariage Industric Carries Controls

HB 11 Chart From Carries Of 100 Fast 6872 1272

HB 21 Chart May 100 Fast 6872 1272

Witnessed by Reporting Centre

Personnel



CERTIFICATE OF INSURANCE

MOTORVEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189) MOTORVEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD RANSPORT ACT, 1987 (MALAYSIA) MOTOR/EHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

MERCEDES-BENZ MOTOR INSURANCE

OWN DAMAGE EXCESS WINDSCREEN EXCESS

S\$800.00(I) \$\$100.00

CERTIFICATE NO. 2100416558-02000

SUM INSURED INSURING WITH COE/PARF Market Value Yes

1) VEHICLE REGISTRATION NO.

2 NAME OF INSURED

SKT5224C Senh Swee Ee

3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT 12 Jun 2017

4) DATE OF EXPIRY OF INSURANCE

11 Jun 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *

SUBJECT TO AGE CONDITION :All Age Condition

b) Any other person who is driving on the Insured's order or with his permission.
This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions. A Young and/or Inexperienced Driver Excess ("YIDR") of \$\$3,000.00, in additional to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience,

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / MERCEDES-BENZ AUTHORISED REPAIRERS

1. Cycle & Carriage Pandan Loop Service Center - 188 Pandan Loop (Tel : 6777 8388)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. Ethoz - 30 Bukit Batok Cres(Tel:66547777)

4. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only 5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560)

6. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110) 7. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892)

8. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336) 9. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE 15 Days Replacement Car only for repairs at C &C - Refer to policy wordings for details

NAMED DRIVER

HIRE PURCHASE COMPANY

MayBank

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore

19 May 2017

AIG Asia Pacific Insurance Pte. Ltd.

CYCLE & CARRIAGE - HAL 239 ALEXANDRA ROAD SINGAPORE 159930 ANSP-NONLIFE

AUTHORISED REPRESENTATIVE

DRIVINGLICENCE



Licence Number: S1169550G Name:

SEAH SWEE EE

Birth Date: 07 Aug 1955 Issue Date: 10 Mar 2004

FORCACUSEONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Motor Cars and Motor Tractors the weight of Class 3

21 Aug 1978

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

Licence No: S1169550G

NP 428A



ESTIMATE FOR SKT5224C

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Vehicle & Document Information

Mdm Seah Swee Ee

44 Jalan Angin Laut Singapore 489252

84844040 fanny

16936

Reg No/Reg Date

SKT5224C

/ 12/06/2015 11-0-00

Date In/Mileage

Chassis No

WIP No

WDD2120362B145973

Engine No

27492030371892

Make/Model

MB/E 250 2.0 CGI SEDAN (W212

Colour/Trim

028 890 Cavansit B1/ 042 258 Basalt Grey

Date/Time Printed CSE Operator Terms Account No 395 / Yik Chan Hoe YK 08/09/2017/ 16:42 CRDVCH WCV01663 Amount Qty Unit Price Disc% Description of Goods / Services

M BPNSUN POLICY NO/ACC DATE : 2100416558 // 08/09/2017 : 08/09/2017 // TP VEH NO SFT6668H MSIG DRIVE IN/EXCESS

DATE IN/DATE SURVEY: BY/AUTHRIZED ON

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.

A BPIRES

RESPRAY REAR BUMPER

A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.

A BPILAB

CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT

REAR BUMPER LOWER

1.00

235.61 00.00

0.10

960 1200.00

750.00

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd Body Care & Repair Center DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chanhoe.yik@cyclecarriage.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

· Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is a lowed

Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Nett

2.685.61

7% GST on

2685.61

187.99

Total Payable

2,873.60

Authorized signatory and company stamp


Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worm or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Confirmed & accepted by

WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



ESTIMATE FOR SKT5224C

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

SUPPLEMENTARY

TO A DESCRIPTION OF THE PARTY O MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT 16 RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581 66431303

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

16936

SKT5224C / 12/06/2015

24/10/2047 44374 WDD2120362B145973

27492030371892

MB/E 250 2.0 CGI SEDAN (W212

028 890 Cavansit Bl/ 042 258 Basalt Grey

Account No WI000558

Tems 09/11/2017/ 13:35 Credit

Date/Time Printed

CSE

Operator

395 / Yik Chan Hoe

Description of Goods / Services

Qty

Unit Price Disc%

Amount

M BPNSUN HOLIC ROZACO DATE DRIVE TWEEKCHSS : 2100116558 // 08(09)2017 OF FICIAL : 008/09/2017 // 4P Ven No SE 6668H ISIGICIAL TAX

DATE IN/DATE SURVEY: 24/10/2017 @ 1700 // RASUL LKK BY/AUTHRIZED ON : DIRECT SETTLEMENT // MONICA MSIG

LEFT REAR BUMPER CHROME MOULDING

RIGHT REAR BUMPER CHROME MOULDING

124.67 00.00 124.67 00.00

124.67 196 124.67 MEC

STIMA A

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd Body Care & Repair Center DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272 Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett

249.34

7% GST on

249.34

17.45

Total Payable

266.79

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worm or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscrees in the event of inadvertent breakage in the course of removing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Page 1 of 1



兴趣 過

ESTIMATE FOR SKT5224C

MOTOR CLAIM DEPARTMENT

16 RAFFLES QUAY #24-01

HONG LEONG BUILDING

SINGAPORE 048581

66431303

MSIG INSURANCE (S'PORE) PTE LTD

Finalization

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

WIP No

16936

Reg No/Reg Date

SKT5224C / 12/06/2015

Vehicle & Document Information

Date In/Mileage

24/10/2017 44374 WDD2120362B145973

Chassis No Engine No

27492030371892

Make/Model

MB/E 250 2.0 CGI SEDAN (W212

Colour/Trim

028 890 Cavansit Bl/ 042 258 Basalt Grey

CSE Operator - Date/Time Printed Account No. Terms 395 / Yik Chan Hoe 09/11/2017/ 13:35 YK WI000558 Credit Amount Description of Goods / Services Qty M BPNSUN HOLICY NO ACC GATE DRIVE INVEXCESS ₩o shué DATE IN/DATE SURVEY: 24/10/2017 @ 1700 // RASUL LKK : DIRECT SETTLEMENT // MONICA MSIG BY/AUTHRIZED ON 960.00 A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH. 600.00 A BPIRES RESPRAY REAR BUMPER 0.10 380.00 A BPILAR

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESEL MEMO STANDARD SETTINGS.

A BPILAB CEAKAGE . NETT CHECK REAR LIGHTING SYSTEM AND CONDUC

X LEFT REAR BUMPER CHROME MOULDING RIGHT REAR BUMPER CHROME MOULDING

124.67 00.00 1.00 1.00 124.67 00.00 124.67 AL 124.67 ne

120.00

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272 Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 2309.34 2,309.34

7% GST on

161.65

Total Payable

2,470.99

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally wern or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50k of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inodvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG17017539/R1RBN2

Date:

04/12/2017

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

80423734QMY

Claimant Vehicle No:

SKT5224C

Insured Vehicle No:

SFT6668H

Date of Loss:

08/09/2017

Nature of Claim:

TP

Claim No: 529716

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKT5224C

Make & Model:

MERCEDES-BENZ E250, 2.0 SEDAN (R18) (A)

Engine No: 27492030371892 Chassis No: WDD2120362B145973

Reg. Date: Colour:

Blue

Engine Capacity:

1991 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

12/06/2015 (Man. Year: 2015)

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Odometer: 44374 km

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

265/35 ZR18

Rear Tyre Size:

265/35 ZR18

Front Tyre Size: Front Left Side: Front Right Side:

Michelin 6 mm Michelin 6 mm Rear Left Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts	Repairer's 484.95 0.00	Adjuster's 249.34 0.00	Difference 235.61 0.00	Diff % 48.58
Miscellaneous Items Labour Paintwork Labour	2,450.00 0.00	2,060.00 0.00	390.00 0.00	15.92
Towing	0.00	0.00	0.00	
Gross Total (S\$) + GST 7.00/7.00% (S\$)	2,934.95 205.45	2,309.34 161.65	625.61 43.80	21.32 21.32
Nett Amount (S\$)	3,140.40	2,470.99	669.41	21.32

INSPECTION

Date of Assignment:

23/10/2017

Date Inspected:

24/10/2017 Inspected At:

Cycle & Carriage Industries Pte Ltd

(Pandan Loop) 188 Pandan Loop Singapore 128378

Estimated Period of Repair:

3.0 days

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 04 Dec 2017) Part Source: MRM-SG

MERCEDES-BENZ E250 2.0 SEDAN (R18) (A) (Catalogue:Merimen Singapore 1.0) 143 Parts:

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for SKT5224C)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

		Part No.	Particulars	Condition	Repairer's	Amount
-			*REAR BUMPER LOWER	Not Necessary	235.61 FS	*-FS
1	1			Necessary	124 67 FS	*124.67 FS
2	1		*LEFT REAR BUMPER CHROME MOULDING			
3	1		*RIGHT REAR BUMPER CHROME MOULDING	Necessary	124.67 FS	*124.67 FS
F=Fra	inchise	part. S=SpcN	Nett.	Total Parts (S\$)	484.95	249.34
				Total Parts (5\$)	404.55	243.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommend	led	lak	our
Recommend	Eu	Lak	Jour

Re No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items	1994	4 000 00	960.00
1	PANEL BEATING TO REPAIR AFFECTED AREAS,REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	1,200.00	
2	RESPRAY REAR BUMPER	New	750.00	600.00
3	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
4	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
	Gross Lal	oour Cost (S\$)	2,450.00	2,060.00
	Report was unsubmitted of	luring this print-out.		

< END OF ESTIMATES >