

REF: CS/FCI/7017854/Knb02

Special Instructions

Summary

CS

ASSIGNMENT (Office)

From (Person): Karen Tan

of FC1

Date/Time 15/9/17 10:48am

Estimated Cost:

Bill to

OD / FP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SQR 8515 B

Insured: SHD 7046 G

at Workshop m/s

Cheng Hae Motor

Tel: 67556142

of Blk 1019 Yishun Ind. Park A # 01-374

Policy No.

Claim No.

D17008805 MFSH

Sum Insured

Excess

Make of Veh:

D.O.A. 13/9/17

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement

Date/Time: 15/9/17 11:40 am

Person Contacted

June

Vehicle IN/OUT

Date/Time

Action/Instruction	(✓)	Estimate
--------------------	-----	----------

SHD-7046G-ES/FC117008762/Gib-D.O.A: 27/4/2017

SGR 8515B-NJA / INC 09027555 / y1 - D.O.A: 7/12/2009

17/1 11 Sp. 8 36 cal. Continuous E. bed (Red 1768.18, 37%)

ASS. REC. BY:

REF: PC21

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Cheng Hoe

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$37k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

2/22

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGR 8515B Yr Regn: 02, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or MPVMake: Toy with c.c. 1794Colour: M. Maroon A/C: Insured / Std / NI / NASp. Reading: 200188 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ENE10 - 0353774Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 13/9/17Survey held at ✓

Rear

R/Bal. 7 mmL/Bal. 7 mmD.O.I. 19/9/17Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/8 File pass to Catherine21/9/17 email preli to Karen.\$37,000 (MV)\$23,032 (LTA)\$13,968 (Net)

Date/Time, File Pass to?

1) 18/1/2018 - 19/1/18 ☒ : Preli. Report ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

TOTAL

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: T/PLump Sum / I.B.I: (\$ 3600)1405050 + 5025315



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17008805MFSH

Date: 21-09-2017

Our Ref: CS/FCI17017857/Kgb

The Motor Claims Department
First Capital Insurance Ltd

Without Prejudice

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGR 8515B.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19-09-2017 at the premises of M/s CHENG HOE MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ 5,743.93
Revised Estimate Amount	: S\$ 2,469.86
"Check" Items Amount	: S\$ 2,638.98
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Kenneth Kong
Automotive Assessor

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	14-09-2017	Our Ref No. D17008805MFSH
Accident Date	13-09-2017	Claim Type. Third Party
Insured Vehicle	SHD7046G	Third Party Vehicle. ^R SGE8515B
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/228029)



PRI Documents



Close



PRI Header Details

Claim No	D17008805MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & CHENG HO
Workshop Name	CHENG HOE MOTOR PTE LTD (Contact Person : JUNE)	Survey Location & Contact Details	BLK 1019 YISHUN IND. PARK A #01-374 Mobile: 0 , Phone: 67556142 , Fax: 67557719 EmailId: CHMOTOR@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD7046G	TP Vehicle No	SGB8515B
PRI Recieved Date	14-09-2017 08:30:30 PM	Surveyor Appointed Date	15-09-2017 10:49:13 AM	Surveyor Accept Date	15-09-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	15-09-2017	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Survey Department Check List (Case Handler)

Reference No. : CS/FCI/7017857/Knb
Policy Type: OD / (TP) / TP RES / TL / EVA

Case Handler

Typist

Admin () : Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	/			
C	Customer Code	/			
N	Assign From	/			
C	Assign Date	/			
C	Veh No (Inspected)	/			
C	Veh No (Insured)	/			
C	D.O.A	/			
C	Policy No	/			
C	Claim No	/			
C	Insurance Authorisation (CA /REV/REP)	/			
C	Report Type	/			
C	Weekend Charges	/			
N	Survey held at/Repairer	/			
C	Excess	/			

Surveyor () : Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	/			
C	Regn Month/Year	/			
N	Vehicle Type	/			
N	Make & Model	/			
C	Engine Capacity. (C.C)	/			
N	Colour	/			
C	Odometer. (Sp.Reading)	/			
C	Chassis No	/			
N	General Condition	/			
N	Steering	/			
N	Brake	/			
N	Modification (Modi)	/			
C	Tyre Size	/			
N	Tyre Make	/			
C	Tyre Balance	/			
C	Date of Inspection	/			
N	Survey held	/			
N	Des.of Damages	/			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded				
---	--------------------------------------	--	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition				
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: Rite 17/1/2018
Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17017857/Kgb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-09-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 7046G	Veh. Inspected	SGR 8515B
Policy No.		Coverage (\$)	0.00
Claim No.	D17008805MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	15/09/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/09/2017	Inspection Date	
Survey held at	CHENG HOE MOTOR SERVICE BLK 1019, YISHUN INDUSTRIAL PARK A #01-374 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Norrita (LKKAUTO)

From: Charlene <Charlene@msfirstcapital.com.sg>
Sent: Tuesday, 16 January 2018 10:38 AM
To: Reports (LKKAUTO)
Cc: SUR
Subject: RE: SURVEY ASSESSMENT - D17008805MFSH/1 tp: SGR 8515B (Kenneth)

Dear Sir,

Please let us have your bill and report for the assignment as to enable to process payment.

Thanks & Regards,

Charlene Garcia

Motor Claims Department

First Capital Insurance Ltd

A Member of MS&AD Insurance Group

36 Robinson Road #16-01 City House | Singapore 068877 | Reg. No. 195000106C

D: 6507 3848 | F: 6507 3849

email: www.first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received

From: Ai Phing (LKKAUTO) [mailto:aiphing@lkkauto.com]
Sent: Thursday, September 21, 2017 2:43 PM
To: CWS Motor Claims <cwsmotorclaims@first-insurance.com.sg>
Cc: Karen Tan <karentan@first-insurance.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17008805MFSH/1

Dear Karen,

Enclosed herewith preliminary advise of vehicle SGR 8515B.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 15 September, 2017 12:10 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17008801MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]

Sent: Friday, 15 September, 2017 11:27 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; KARENTAN@FIRST-INSURANCE.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D17008801MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Thursday, 21 September, 2017 2:43 PM
To: 'Claim Workflow System'
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17008805MFSH/1
Attachments: SGR 8515B.pdf

Dear Karen,

Enclosed herewith preliminary advise of vehicle SGR 8515B.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 15 September, 2017 12:10 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17008801MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Friday, 15 September, 2017 11:27 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; KARENTAN@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17008801MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,



Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 3331A

Vehicle Details

Vehicle No.: SGR8515B

Vehicle to be Exported: Yes

Intended De-registration Date: 13 Sep 2017

Vehicle Make: TOYOTA

Vehicle Model: WISH 1.8 A

Primary Colour: Maroon

Manufacturing Year: 2006

Engine No.: 1ZZ2836235

Chassis No.: ZNE100353774

Maximum Power Output: 97.0 kW (130 bhp)

Open Market Value: \$17,280.00

Original Registration Date: 16 Feb 2007

First Registration Date: 16 Feb 2007

Transfer Count: 4

Actual ARF Paid: \$19,008.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date:

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 15 Feb 2022

COE Category: E - Open Category

COE Period(Years): 5

PQP Paid: \$26,039.00

COE Rebate Amount: \$23,032.00

Total Rebate Amount: \$23,032.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Sep 2017

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SGR8515B

TP/FC

M/S : FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: ES1791045/WL

Date: 19 Sep 2017

Policy No: 5091402215

Veh Reg No: SGR8515B

Make/Model: TOYOTA TOYOTA
WISH 1.8 A

Chassis No: ZNE100353774

Engine No: 1ZZ2836235

Reg. Date: 16/02/2007

WS Ref: TP/FC/WL

Claim Type: Third Party

Accident Date: 13/09/2017

TP Veh Reg No: SHD7046G

Not Authored

1/1 Sep 8 360d

Recovery After Party

5 days

Estimate Repair Cost to Vehicle No :SGR8515B

PAGE:1/1

Description	U/Price	Quantity	List Price SS	Amount SS
List Price				
1 REAR BUMPER	470.70	1 PC	470.70	✓
2 REAR BUMPER LH SIDE RETAINER	57.50	1 PC	57.50	✓
3 REAR BUMPER CLIPS	3.89	6 PCS	23.34	✓
4 REAR BUMPER REFLECTOR	56.90	1 PC	56.90	X
5 REAR TAILGATE	1,329.20	1 PC	1,329.20	✓
6 TAILGATE LOGO	53.20	1 PC	53.20	✓
7 TAILGATE INNER LOCK	443.50	1 PC	443.50	✓
8 REAR END PANEL OUTER	441.20	1 PC	441.20	✓
9 REAR WINDSCREEN GLASS MOULDING	79.20	1 PC	79.20	✓
10 TAILGATE OUTER MOULDING	239.10	1 PC	239.10	X
11 REAR EXHAUST PIPE	683.70	1 PC	683.70	✓
			3,877.54	
		Less 25%	969.39	2,908.16
Special Net				
12 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
13 REVERSE SENSOR	200.00	1 SET	200.00	✓
14 REVERSE CAMERA	380.00	1 PC	380.00	X
			620.00	620.00
Labour				
15 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
16 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE & ATTACHMENT, REAR WIPER ASSY, CUT, WELD & RENEW REAR PANEL OUTER, KNOCK & REPAIR REAR FLOOR BOARD	780.00	1 LA	780.00	✓
17 PUTTY & RESPRAY ON REAR END PANEL, TAILGATE, REAR BUMPER & REAR AFFECTED	780.00	1 LA	780.00	✓
18 RUSTPROOFING	60.00	1 LA	60.00	✓
19 TO STRAIGHTEN REAR EXHAUST & CHECK LEAKING	60.00	1 LA	60.00	✓
20 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	60.00	1 LA	60.00	✓
			1,840.00	1,840.00

Total SS 5,368.16

Add GST @ 7% 375.77

Total Amount Payable SS 5,743.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17017857/Knbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 7046G	Veh. Inspected	SGR 8515B	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17008805MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	15/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	ZNE100353774	Colour	METALLIC MAROON	
Odometer	200188	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	TOYO	7 mm	
L/H Front Tyre	195/65 R15	TOYO	7 mm	
R/H Rear Tyre	195/65 R15	TOYO	7 mm	
L/H Rear Tyre	195/65 R15	TOYO	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/09/2017	Inspection Date	19/09/2017	
Survey held at	CHENG HOE MOTOR SERVICE BLK 1019, YISHUN INDUSTRIAL PARK A #01-374 SINGAPORE 768761			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 8515B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED / CRACKED	470.70	470.70
1	REAR BUMPER LH SIDE RETAINER	DISTORTED	57.50	57.50
6	REAR BUMPER CLIPS @\$3.89	NECESSARY	23.34	23.34
1	REAR BUMPER REFLECTOR	SERVICEABLE	56.90	-
1	REAR TAILGATE	BENT	1,329.20	1,329.20
1	TAILGATE LOGO	NECESSARY	53.20	53.20
1	TAILGATE INNER LOCK	DENTED	443.50	443.50
1	REAR END PANEL OUTER	BENT	441.20	441.20
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	79.20	79.20
1	TAILGATE OUTER MOULDING	SERVICEABLE	239.10	-
1	REAR EXHAUST PIPE	BENT	683.70	683.70
	LESS 25% DISCOUNT		-969.38	-895.39
			2,908.16	2,686.15
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN GLASS GUM (SN)	NECESSARY	40.00	40.00
1	SET REVERSE SENSOR (SN)	SHORTED	200.00	200.00
1	REVERSE CAMERA (SN)	SERVICEABLE	380.00	-
			620.00	240.00
<u>LABOUR</u>				
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		100.00	100.00
	REMOVE AND REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE & ATTACHMENT, REAR WIPER ASSY, CUT, WELD & RENEW REAR PANEL OUTER, KNOCK & REPAIR REAR FLOOR BOARD.		780.00	600.00
	PUTTY & RESPRAY ON REAR END PANEL, TAILGATE, REAR BUMPER & REAR AFFECTED.		780.00	700.00
	RUSTPROOFING.		60.00	60.00
	TO STRAIGHTEN REAR EXHAUST & CHECK WIRING.		60.00	60.00
	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM.		60.00	60.00
			1,840.00	1,580.00



GRAND TOTAL		5,368.16	4,506.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,600.00

Report Ref No. CS/FCI17017857/Knbn2

MARKET VALUE: \$37,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$23,032.00=NETT VALUE: \$13,968.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.