

ASS. REC. BY:

REF: CS/FCI17018636 / Atb

Special Instruction:

Surveyor
(WS)

Resul

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time 27/9/17 5:52pm

Estimated Cost

Bill to:

OD (H) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKL 9110 M

Insured: SHD 4726 Y

at Workshop m/s:

Kah Motor

Tel: 90721769

of

GA Mandai Estate

Policy No:

Claim No: D17009173 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23/09/17

CA / REV / REP. / REV 24 HRS

'DS'

02.10.2017 @ after 10 am at 255 Alexandra Rd

H.O.D. Endorsement:

Date/Time: 28/9/17 9:30 am

Person Contacted

Mr. Ng

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKL 9110 M

SHD 4726 Y - CS / FCI 1500 2540 / Avb42-D.O.A: 6/02/15

Part by Part \$5491.59 (Red: 4550.08: 45%)

Ram

REF: FCI

21761

ASSIGNMENT

From: _____ Date: 02/10/17

Estimated Cost: _____

OD: ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKL 9110 M

at Workshop no: Kah Motor

of: 255 Alexandra Road

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

after 10 am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Sal. or Market Value: _____

D&D Accident Report: _____ Consistent? Yes or No

GIA PR Seen: _____ Consistent? Yes or No

Est. Repairs: _____ days Res. Yes or No

Lum Sum: _____ % 3 Val Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time: _____ Action / Instruction: _____

Veh No: SKL 9110 M Yr Reg: 2017 / APR

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey 2.4 CC: 2356

Colour: GREY A.C. Insured / Std / NI / NA

Sp Reading: 010559 T.Radio Insured / Std / NI / NA

Eng No: _____

C/Vo: JHMRC 1890GC209955

Gen. Cond: Good ☒ Fair / Poor / Burnt

Steering: ☒ Worder / Jammed / Leaked / Burnt or

Brake: ☒ Worder / Jammed / Leaked / Burnt or

Mod: Nil / ☒ STD A/Rim or

Tyre Size: F: 215/55R17 R: _____

BS: ☒ DUN EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R.Ba: 6 mm R.Ba: 6 mm

L.Ba: 6 mm L.Ba: 6 mm

D.O.A: 23/09/17 D.O.I: 02/10/17

Survey held at: Kah Motor

Des. of Damages: Fnt / Rear / O/S / NIS / U/C / Rooftop or

Rear of

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 03 APR 2019

Date/Time For Pass to: _____

54 Typst

Date/Time For Return to: _____

☐ Preli. Report

☒ Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: _____

Transporter: _____

Site Insp: ☐ \$

Interview: ☐ \$

Tech. Invs: ☐ \$

Weekend: ☐ \$

Report Format: TP

Lump Sum / I.B.I: 5491.59

54

170

50

50

31

TOTAL: 301



LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17018636/R1tb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-09-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4726Y	Veh. Inspected	SKL 9110M
Policy No.		Coverage (\$)	0.00
Claim No.	D17009173MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	28/09/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/09/2017	Inspection Date	02/10/2017
Survey held at	255 ALEXANDRA RD		
Repairer	KAH MOTOR.CO.SDN.BHD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Color		Cubic Capacity	
-------	----------------------	----------------	----------------------

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/09/2017 18:58
Date Of Accident	23/09/2017 14:10
Exact Location Of Accident	KIM SENG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL9110M
Insured/Policyholder	
Name Of Registered Owner	YOW WAI HOE
NRIC No	S7032176I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81612178
Alternative Phone No	OTHERS-97601887

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10739141
Cover Note Number	

Driver

Name of Driver	YOW WAI HOE
NRIC No	S7032176I
Date Of Birth	09/09/1970
Occupation	INDOOR
Date Of Driving Pass	15/05/1997
Driving Experience	20 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81612178
Fax Number	
Contact Number	OTHERS-97601887
EMail Address	NOEMAIL

Vehicle No. SKL 9110M

SKETCH PLAN

Annex D

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to renege policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)**
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



REPUBLIC OF SINGAPORE DRIVING LICENCE

Identification No. **S70321761**

YOW WAI HOE

Birth Date: **09 Sep 1970**
Issue Date: **03 Oct 2016**

002615614F



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S70321761



Name
YOW WAI HOE

Race
CHINESE

Date of birth
09-09-1970

Country/Place of birth
SINGAPORE

Sex
M

S70321761



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$

EFFECTIVE DATE

15 May 1997

NP 428A



5659214

NRIC No. **S70321761**



Date of issue
26-09-2016

Address

**APT BLK 727 WOODLANDS CIRCLE
#12-110
SINGAPORE 730727**

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No: S60FC1380G

Customer	: FIRST CAPITAL INSURANCE LTD	Document No.	: SQT17003984	Page	1
	36 ROBINSON ROAD	Date	: 27. Sep 2017		
	#16-01 CITY HOUSE	Customer No.	: WZF002		
	SINGAPORE 068877	Svc Advisor	: NG SIN HAI		
Registration No	: SKL9110M	Engine No	: K24W72013993		
Chassis No	: JHMRC1890GC209955	Date Time	: 27. Sep 2017 12:56:47 PM		
Model	: ODYSSEY 2.4 EXV-S 16YM	Surveyor Name	:		
Owner's Name	: YOW WAI HOE	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 23/9/2017				

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:YOW WAI HOE						
	OWNER INSURER:AVIVA LTD						
	ACC DATE:23/09/2017						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:FIRST CAPITAL INSURANCE LTD						
	TP VEH:SHD4726Y						
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00		80.00	5.60	85.60
BML02I	INSPECT RR LIGHTING MECHANISMS, PERFORM WATER	1	180.00		180.00	12.60	192.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE, ADJUST &	1	560.00		560.00	39.20	599.20
BG02D	REMOVE & INSTALL RR, WINDSCREEN (N)	1	560.00		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00		80.00	5.60	85.60
BKRP02M	CUT OFF & RENEW RR PANEL	1	3000.00		3000.00	210.00	3210.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2500.00		2500.00	175.00	2675.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR (N)	1	100.00		100.00	7.00	107.00
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	100.00		100.00	7.00	107.00
	Sum Labor				8000.00	560.00	8,560.00
RS-TMP3040L	VPC 4PCS REAR SENSORS	1	320.00		320.00	22.40	342.40
68100-T6A-Q10ZZ	TAILGATE COMP	1	1049.80	25	787.35	55.11	842.46
74440-T6A-003	WEATHERSTRIPTAILGATE	1	115.10	25	86.32	6.04	92.36
91513-T6A-003	CLIPTAILGATE SPOILER	6	2.40	25	10.80	0.76	11.56

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

Registration No : SKL9110M

Chassis No : JHMRC1890GC209955

Model : ODYSSEY 2.4 EXV-S 16YM

Owner's Name : YOW WAI HOE

Ins Policy No. :

Date of Accident : 23/9/2017

Document No. : SQT17003984 Page 2

Date : 27. Sep 2017

Customer No. : WZF002

Svc Advisor : NG SIN HAI

Engine No : K24W72013993

Date | Time : 27. Sep 2017 12:56:47 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
75701-T6A-000	EMBLEMH	1	25.80	25	19.35	1.35	20.70
04715-T6A-900ZZ	FACERR.BUMPER	1	557.20	25	417.90	29.25	447.15
33505-SLJ-013	REFLECTOR ASSY.RR.	1	44.50	25	33.37	2.34	35.71
71502-T6A-003ZB	FACER.RR.BUMPER GARNISH	1	75.30	25	56.47	3.95	60.42
71512-T6A-921ZB	SPOILER ASSY.RR.SIDE	1	111.90	25	83.92	5.87	89.79
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	18.70	25	14.02	0.98	15.00
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	17.60	25	26.40	1.85	28.25
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM	1	3.60	25	2.70	0.19	2.89
73226-SZW-000	DAMPERSTD 5X5	2	8.30	25	12.45	0.87	13.32
76711-T6A-003	CAPPVOT	1	4.70	25	3.52	0.25	3.77
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
Sum Item					2041.67	142.91	2,184.58

Survey By RASUL - Hp 90010068Date & Time 02/10/17 @ 1120

Excess

Status

Signature

Total Amount 10,041.67 702.91 10,744.58

Total (Inclusive of GST) 10,744.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 27/9/2017 1:05:26 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / FIRST CAPITAL
Chassis No: JHMRC1890GC209955
License No: SKL9110M
Mileage: 5811
Engine No: K24W72013993

Document No: SVO17063007
Printed By: SHNG
Order Date: 2. October 2017
Order Time: 1:50:27 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:YOW WAI HOE OWNER INSURER:AVIVA LTD ACC DATE:23/09/2017 SURVEYED BY:RASUL (LKK) DATE:02/10/2017 REF NO: TP INSURER:FIRST CAPITAL INSURANCE LTD TP VEH:SHD4726Y						
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,049.80	25	787.35	55.11	842.46
91513-T6A-003	CLIPTAILGATE SPOILER	8	2.40	25	10.80	0.76	11.56
75701-T6A-000	EMBLEMH	1	25.80	25	19.35	1.35	20.70
04715-T6A-900ZZ	FACERR.BUMPER	1	557.20	25	417.90	29.25	447.15
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	18.70	25	14.02	0.98	15.00
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	17.60	25	26.40	1.85	28.25
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER A WINDSHIELD DAM	1	3.60	25	2.70	0.19	2.89
73226-SZW-000	DAMPERSTD 5X5	2	8.30	25	12.45	0.87	13.32
76711-T6A-003	CAPPVOT	1	4.70	25	3.52	0.25	3.77
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
	SUM PARTS:				1,781.59	124.71	1,906.30
BOSUN	0701 SUNDRIES	1	30.00		30.00	2.10	32.10
BA02R	0671 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BML02I	0671 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	180.00		180.00	12.60	192.60
BKTG02R	0671 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	560.00		560.00	39.20	599.20
BG02D	1757 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	560.00		560.00	39.20	599.20
BODAMKIT	0701 WINDSCREEN DAM KIT.	1	80.00		80.00	5.60	85.60
BKRP02M	0671 CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.	1	1,120.00		1,120.00	78.40	1,198.40
BP06R	0924 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION	1	900.00		900.00	63.00	963.00



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / FIRST CAPITAL
Chassis No: JHMRC1890GC209955
License No: SKL9110M
Mileage: 5811
Engine No: K24W72013993

Document No: SVO17063007
Printed By: SHNG
Order Date: 2, October 2017
Order Time: 1:50:27 PM
Service Advisor: NG SIN HAI

BKBU01R	0671	1	100.00	100.00	7.00	107.00
	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA					
			SUM LABOUR:	3,710.00	259.70	3,969.70
			TOTAL SGD	5,491.59	384.41	5,876.00
Total Payable (SGD)						5,876.00

GST Amount is calculated from individual line(s)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17018636/R1tbq2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4726Y	Veh. Inspected	SKL 9110M	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17009173MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	27/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY 2.4	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMRC1890GC209955	Colour	GREY	
Odometer	010559	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	DUNLOP	6 mm	
L/H Front Tyre	215/55 R17	DUNLOP	6 mm	
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/09/2017	Inspection Date	02/10/2017	
Survey held at	255 ALEXANDRA RD			
Repairer	KAH MOTOR.CO.SDN.BHD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 9110M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	SEALANT FOR REAR END PANEL (SN)	NOT NECESSARY	80.00	-
4	REAR SENSORS (SN)	NECESSARY	320.00	320.00
1	TAILGATE COMP (SN)	BENT	787.35	787.35
1	WEATHERSTRIP TAILGATE (SN)	NOT NECESSARY	86.32	-
6	CLIPTAILGATE SPOILER (SN)	NECESSARY	10.80	10.80
1	EMBLEMH (SN)	NECESSARY	19.35	19.35
1	FACERR BUMPER (SN)	DEFORMED	417.90	417.90
1	REFLECTOR ASSYR.RR (SN)	NOT NECESSARY	33.37	-
1	FACER.RR BUMPER GARNISH (SN)	NOT NECESSARY	56.47	-
1	SPOILER ASSYR.RR.SIDE (SN)	NOT NECESSARY	83.92	-
1	SPACERRR.BUMPER SIDE (SN)	NECESSARY	14.02	14.02
7	CLIPBUMPER (SN)	NECESSARY	10.50	10.50
2	MOLDINGRR.WINDSHIELD SIDE (SN)	NECESSARY	26.40	26.40
1	MOLDINGR.RR.WINDSHIELD CORNER (SN)	NECESSARY	12.45	12.45
1	MOLDINGL.RR.WINDSHIELD CORNER (SN)	NECESSARY	12.45	12.45
4	SPACERRR.W/SHIELD (SN)	NECESSARY	11.70	11.70
1	RUBBER AWINDSHIELD DAM (SN)	NECESSARY	2.70	2.70
2	DAMPERSTD 5X5 (SN)	NECESSARY	12.45	12.45
1	CAPPIVOT (SN)	NECESSARY	3.52	3.52
2	WINDSCREEN SEALANT (SN)	NECESSARY	120.00	120.00
			2,221.67	1,811.59
LABOUR				
REMOVE & RENEW REVERSE SENSORS .			180.00	180.00
INSPECT RR LIGHTING MECHANISMS .PERFORM WATER.			180.00	180.00
REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK.		NOT NECESSARY	560.00	-
REMOVE & TRANSFER ITEMS TO NEW TAILGATE .ADJUST & .			560.00	560.00
REMOVE & INSTALL RR .WINDSCREEN.			560.00	560.00

Report Ref No. CS/FCI17018636/R1tbq2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WINDSCREEN DAM KIT.		80.00	80.00
	CUT OFF & RENEW RR PANEL .		3,000.00	1,120.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		2,500.00	900.00
	REMOVE & RENEW RR FLOOR INSULATOR .	NOT NECESSARY	100.00	-
	REMOVE ,RE-FIX AND ALIGN REAR VIEW CAMERA.		100.00	100.00
			7,820.00	3,680.00
GRAND TOTAL			10,041.67	5,491.59
RECOMMENDED COST OF REPAIRS				5,491.59

Report Ref No. CS/FCI17018636/R1tbq2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.