

ASS. REC. BY: Adrian Ling

REF:

CC3 / ALH17018691 / Arb02

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / W3 / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2100376520

Claims No. 587958 3989 SG

Sum Insured: _____ Excess: \$600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 85K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 88% days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SK44547J

Yr Regn: 2014 / June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 Sedan

C.C. 1395

Colour: Bronze

A/C: Insured / Std / NI / NA

Sp. Reading: 59628

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZ28VXE1039498

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40 R18

R: 225/40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

D.O.I. 28/09/17

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 A16

SKN 4547J - X

29/9/17 Sent preli through neman ; seek mandate
 3/10/17 Authorise repair ; Inform Premium authorise repair

Confirm \$14,591.76, 12 days

Red: \$5577.24, 28%

RECEIVED 18 MAR 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) typist

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 12

Resurvey No. of Trip: -

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS: SI

Photos:

Others:

TOTAL

Report Format: 00

Lump Sum / I.B.I.: (\$ 14591.76)

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG17018691/Arb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 29-09-2017



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SKN 4547J
Policy No. 2100376520	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	28/09/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 22/09/2017	Inspection Date 28/09/2017
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699	

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, December 11, 2017 9:06 AM
To: Adrian Ling (LKKAUTO); Janice Lee (LKKAUTO); SUR; Carrine Leong
Subject: FINAL REVISION SKN4547T - OD AIG - SURVEYED 28 SEP 17
Attachments: PA09362017 -SKN 4547 J - A3 SEDAN 1.4 TFSI - RH REAR (AIG).xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$14,591.76 @ 12 days of repairs exclude 1 Public Holiday and 2 Sundays.

Your early closure is well appreciated.

Best regards - jb

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2451C

Vehicle Details

Vehicle No.: SKN4547J

Vehicle to be Exported: No

Intended De-registration Date: 29 Sep 2017

Vehicle Make: AUDI

Vehicle Model: A3 SEDAN 1.4 TFSI (AMBIENTE)

Primary Colour: Grey

Manufacturing Year: 2014

Engine No.: CXS097787

Chassis No.: WAUZZZ8VXE1039498

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$27,213.00

Original Registration Date: 16 Jun 2014

First Registration Date: 16 Jun 2014

Transfer Count: 0

Actual ARF Paid: \$15,099.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 15 Jun 2024

PARF Rebate Amount: \$11,324.00

Intended COE Rebate Details

COE Expiry Date: 15 Jun 2024

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$63,190.00

COE Rebate Amount: \$42,423.00

Total Rebate Amount: \$53,747.00

The information contained herein is correct as at 29 Sep 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 17 Sep 2017 at 12:38 AM

Print Received Message

This mail is associated with :

***SKN4547J (5879583989SG)**

OD

Sep 22 2017 8:00AM

[HOE YIN CHUANG, RAYMOND]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 02/10/2017 14:04 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$15557.00) - SKN4547J - Claim Handler: Dally Amri, Mimi Zarina

Approved:15557.00:Re-inspection to be done for damage check and supplementary items / labour.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 29 Sep 2017

Preliminary Advice

Vehicle No	: SKN4547J	Accident Date	: 22/09/2017
Make	: AUDI A3	Policy No.	: 2100376520
Assignment Date	: 29/09/2017	Excess	: S\$0.00
Date of Inspection	: 28/09/2017	Est. Duration of Repair	: 12.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,169.00
Revised Amount	:S\$	15,521.00
Check Items (Estimated)	:S\$	820.00
Total	:S\$	16,341.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	53,747.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,253.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorization.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 29 Sep 2017

Preliminary Advice

Vehicle No	: SKN4547J	Accident Date	: 22/09/2017
Make	: AUDI A3	Policy No.	: 2100376520
Assignment Date	: 29/09/2017	Excess	: S\$0.00
Date of Inspection	: 28/09/2017	Est. Duration of Repair	: 12.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,169.00
Revised Amount	:S\$	15,557.00
Check Items (Estimated)	:S\$	820.00
Total	:S\$	16,377.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	53,747.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,253.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorization.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Tuesday, October 03, 2017 11:02 AM
To: claims@premiumauto.com.sg
Cc: SUR
Subject: SKN 4547J

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKN 4547J (excess \$TBA/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/09/2017 13:48
Date Of Accident	22/09/2017 08:25
Exact Location Of Accident	BEFORE CARNIE EXIT AT PIE TOWARDS STEVENS ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN4547T J
Insured/Policyholder	
Name Of Registered Owner	HOE YIN CHUANG, RAYMOND
NRIC No	S7332451C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97740989
Alternative Phone No	OFFICE-97740989

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.4 TFSI
Exact Purpose for which vehicle was being used at time of accident	PERSONAL
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	21000376520-03000

Driver

Name of Driver	HOE YIN CHUAN, RAYMOND
NRIC No	S7332451C
Date Of Birth	05/09/1973
Occupation	INDOOR
Date Of Driving Pass	18/10/1994
Driving Experience	22 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96740989
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name BUKIT PANJANG
Police Station Address ROAD: 1 SEGAR ROAD , POSTCODE: 677738 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-8929999 - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Tanay Fong
NRIC/FIN No: 620447X

REFER TO POLICE REPORT


Policyholder's Signature

HL

THE AUTOGRAPH STORE

Page 4 of 18

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7332451C



Name

HOE YIN CHUANG, RAYMOND
(HE XIANZHUANG, RAYMOND)

何 賢 壯

Race
CHINESE

Date of birth
05-09-1973

Sex
M

Country/Place of birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number
Name S7332451C

HOE YIN CHUANG, RAYMOND
(HE XIANZHUANG, RAYMOND)

Birth Date: 05 Sep 1973

Issue Date: 24 Sep 2003



5681130



NRIC No. S7332451C



Date of issue
19-12-2016

Address

APT BLK 542 JELAPANG ROAD
#09-42
SINGAPORE 670542

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 18 Oct 1994

NP 428A





HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100376520-03000

(The below excess is subject to GST)

OWN DAMAGE EXCESS S\$600.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes

1) VEHICLE REGISTRATION NO.

SKN4547J

2) NAME OF INSURED

HOE YIN CHUANG, RAYMOND (HE

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

XIANZHUANG, RAYMOND)
16 Jun 2017

4) DATE OF EXPIRY OF INSURANCE

15 Jun 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

SUBJECT TO AGE CONDITION : 40 years old and above

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days (up to 2000cc) - Refer to policy wordings for details

* NAMED DRIVER NA

HIRE PURCHASE COMPANY United Overseas Bank Limited
EMPLOYER'S LOAN

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 8 Jun 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-220
PREMIUM LEASING - MH
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCGUK



**SINGAPORE
POLICE FORCE**



T/20170922/2186

1 of 3

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No. T/20170922/2186

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/09/2017 20:29	Vide Report No.:	Station Diary No.: 88
--------------------------------------------	------------------	--------------------------

Informant's Particulars			
Name of Informant: HOE YIN CHUANG, RAYMOND		Address: APT BLK 542 JELAPANG ROAD #09-42 SINGAPORE 670542	
ID Type / ID No.: NRIC NO / S7332451C		Contact No.: Home/Office: Mobile: 96740989	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 44	Date of Birth: 05/09/1973	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: ARCHITECT OTHERS		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 22/09/2017 08:25	Type of Location: Expressway
Location: Along Road 1 PAN ISLAND EXPRESSWAY STEVENS ROAD PIE towards Steven Road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PC161M	Bus/Coach/Minibus					0
SKN4547J	Car	AUDI	A3 SEDAN 1.4 TFSI (AMBIENTE)	Grey	Slightly Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKN4547J	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100376520	16/06/2017	15/06/2018



**SINGAPORE
POLICE FORCE**



T/20170922/2186

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

2 of 3

Report No. T/20170922/2186

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	HOE YIN CHUANG, RAYMOND	ID No.	S7332451C
Related Vehicle	SKN4547J (Car)	Contact No.	96740989
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 22/9/2017 at about 0825hrs I was travelling in my car (SKN4547J) along PIE towards Stevens road. I was driving on lane number 5 at about 40km/h. The traffic was moving slow as I believe there was an accident ahead and it was also peak hour at that time. After which I decided to switch lane from the 5th to the 4th lane to the right side. I signaled right promptly and checked my side mirrors and rear mirror. I noticed a coach bus behind me slowing down and thus I decided to switch to the coach's lane on the 4th. All of a sudden I noticed from the side mirror that the coach increased speed and that was when, I felt that the car jerked and also felt an impact coming from the rear of my car and I checked my rear mirror. The coach bus had hit onto my right passenger side however the coach did not honk or alert me about it. I decided to continue my journey thinking that the driver may stop somewhere ahead. However the driver did not stop and I only managed to access the damage after reaching my destination which was at Bras Basah. There was a dent at the right hand side of the passenger seat. The number plate of the coach is PC161M and it is a white coach with the wordings stated on it as "GOLDEN DRAGON". I do not have a in-built camera and I am not sure if there is any CCTV camera along the incident area. I am not sure of the cost of the repair of my damaged car and will only be sending it to the workshop on 23/9/2017.



**SINGAPORE
POLICE FORCE**



T/20170922/2186

3 of 3

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No. T/20170922/2186

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Sgt 1 PREM S/O RENGASAMY

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / HRT /

Sr Staff Sgt LIM WOON TIONG

Contact No.: 65476418

Signature Of Informant:

Date/Time:

22/09/2017 20:29

Classification Of Case:

SN 117

Authentication Stamp
NP168



Signature :

Singapore Police Force

Premium Automobiles Pte Ltd

281 Alexandra Road Singapore 159938
RCB No. 199902271W
Telephone 6836 2223 Sales 6838 2223 Fax 6471 0523



Audi

SA 31053

SALES AGREEMENT

Particulars of Customer

Full name as in NRIC/PASSPORT (underline surname)

Name: HOE YIN CHUANG, RAYMOND (HE XIANZHUANG)Date: 2/6/14Address: Blk 542 JELAPANG ROADNRIC / Passport No.: S 7332451C

#09-42

Telephone No.: 6168 7611Postal Code: 670542Email: hoe-raymond@yahoo.com

Vehicle Details

Year Of Manufacture:

Chassis No.:

Make / Model: A3 SEDAN 1.4TFSI "AMBIENTE"

Engine No.:

Registration Type: PRIVATE

Vehicle Regn:

Colour: DAKOTA / CHESTNUT GREY / BROWN

Purchase Details

Basic Price with Std specifications, Imp Duty, ARF, Regn and COE \$ 180,550Road Tax for 12 months \$ (6 INCLUSIVE)Accessories: CEVS REBATES \$ (15,000)

Remarks / For Office Use

Warranty - 3 yrs / 100,000km (whichever comes first)

4 Bids non-guaranteed

- COE REBATE (A) \$60,000

- FINANCE SUBSIDY OF \$19,550

- FOC 3m SOLAR FILM CLASSIC.

Finance Details

Finance Company: UOBFor 60 mths at 2-28 % loan \$ 73,000

Total Purchase Price: \$

Deposit Paid \$

Visa/Cash/Cheque No.:

Receipt No. / Date:

(Non-Refundable)

- IMPORTANT:**
- The above prices and specifications are subject to change without notice.
 - Full car booking deposit must be made on the date of this Sales Agreement, failing which this Sales Agreement shall be deemed cancelled by both parties and any deposit received by the Company shall be forfeited by the Company henceforth.
 - The purchaser must register the vehicle if available within the month of obtaining the COE and full payment must be made before registration.
 - The company's Official Receipt will acknowledge and evidence any payment made by the purchaser for the vehicle.
 - Cheques must be crossed and made payable to the Company.
 - The Company is not responsible for any payments made for the purchase of motor accessories unless the purchases are stated in this Agreement and substantiated by the Company's Official Receipt.
 - This Agreement is not transferable and not assignable and only the name stated herein is recognised for registration of the vehicle. The Company reserves the right to refuse to register the vehicle in any name other than that given in this Agreement.
 - In the event the purchaser does not proceed with the purchase of the motor vehicle, the deposit paid by the purchaser to the Company, any advance payment and any other payment shall not be refunded to the purchaser.
 - In the event the purchase of the motor vehicle is not completed, by reason of the failure of the Company to obtain a COE the deposit paid by the purchaser to the Company, any advance payment and any other payment shall be refunded to the purchaser.
 - This Agreement is subject to the Conditions of Sale overleaf.
 - Car performance data e.g. fuel consumption figures, power and torque, acceleration, etc can only be treated as indicative figures provided by test bodies under test conditions which cannot be interpreted as a guarantee to the performance during actual usage.
 - Engine oil consumption up to 1 litre per 1,000km is an accepted characteristics depending on the type of engine oil used.
 - The contract will be void if full documentations for COE bidding and deposit is not submitted prior to the COE Bidding Exercise.

I hereby accept the abovementioned terms and conditions detailed above and on the overleaf, and confirm there is no other oral and unwritten warranty in this agreement

Witnessed by
Sales ExecutiveMATTHEW WENG

Date

2/6/14

Signature

Agreed on behalf of Premium Automobiles Pte Ltd

Management

Signature

Date

Purchaser's Signature

Date

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0936/2017/NK
Date : 26-Sep-17

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Hoe Yin Chuang, Raymond
Address : Blk 542 Jelapang Road
#09-42
Singapore 670542
Telephone : HP +65 96740989
Type of Claim : Own Damage Claims
Policy No. : 2100376520-03000
Vehicle No : **SKN 4547 T**
Model Code : Audi A3 SEDAN 1.4 TFSI
Model / Year : Jun-14
Engine No : CXS097787
Chassis No : WAUZZZ8VXE1039498
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Sep-17
Place of Accident : Before Carnie Exit at PIE Towards Stevens Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKN 4547 T

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00	✓ /
2	To renew rhs 1/4 glass and rear windscreen to facillitate fender renewal.	S/N \$ 600.00	✓ /
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00	✓ /
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00	✓ /
5	To dismantle rear bumper and rear lid. Cut out and weld rhs rear fender. Renew rear bumper. Reinstall all parts removed.	\$ 4,800.00	3000 /
6	To respray rear bumper, rhs rear fender, rhs sill panel, door entrance, drain channel, roof channel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 4,100.00	2200 /
7	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓ /
8	To install rear windscreen and rear lh 1.4 glass solar film	S/N \$ 400.00	✓ /
9	To carry out diagnostic check.	S/N \$ 192.00	✓ /
TOTAL LABOUR CHARGES		: \$ 13,452.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKN 4547 J

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>torn</i>	\$ 1,567.00	✓ 1253.60
2	REAR BUMPER GUIDE INNER SECTION RH <i>new</i>	\$ 13.00	+
3	LOCKING MECHANISM <i>new</i>	\$ 25.00	✓
4	REAR BUMPER GUIDE OUTER SECTION RH <i>new</i>	\$ 54.00	✓
5	SECTIONAL PART RH <i>Dented</i>	\$ 1,938.00	✓ 1550.40
6	WHEEL HOUSING LINERS <i>new</i>	\$ 208.00	✓
7	WHEEL HOUSING LINERS ATTACHMENTS PARTS <i>new</i>	\$ 75.00	✓
8	1/4 GLASS <i>new</i>	\$ 455.00	✓ 363.60
9	REAR WINDSCREEN <i>new</i>	\$ 675.00	✓ 540.00
10	PRIMER FOR GLASS AND SEALANT <i>not new</i>	2 \$ 36.00	✓
11	SOUND ABSORBER <i>new</i>	2 \$ 54.00	✓ 42.56
12	GROMMET <i>new</i>	4 \$ 37.00	✓
13	REAR WINDSCREEN SEALANT <i>new</i>	S/N \$ 200.00	✓ 200.00
14	1/4 GLASS SEALANT <i>new</i>	S/N \$ 100.00	✓ 100.00
15	ACRYLIC SEALER <i>new</i>	S/N \$ 180.00	✓ 180.00
16	CAVITY WAX <i>new</i>	S/N \$ 140.00	✓ 140.00
17	STONE CHIP <i>new</i>	S/N \$ 180.00	✓ 180.00
18	METAL FILLER POWDER <i>new</i>	S/N \$ 280.00	✓ 280.00
19	SUNDRIES <i>new</i>	\$ 500.00	✓ 9.60
TOTAL SPARE PARTS		\$ 6,717.00	
TOTAL LABOUR CHARGES		\$ 13,452.00	
GRAND TOTAL		\$ 20,169.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian L*
Surveyed Date : *28/09/17.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 12 Days*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0936/2017/NK
Date : 26-Sep-17

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

12 days exclude 1 PH and 2 Sundays

11 Dec - jb

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Hoe Yin Chuang, Raymond
Address : Blk 542 Jelapang Road
#09-42
Singapore 670542
Telephone : HP +65 96740989
Type of Claim : Own Damage Claims
Policy No. : 2100376520-03000
Vehicle No : **SKN 4547 T**
Model Code : Audi A3 SEDAN 1.4 TFSI
Model / Year : Jun-14
Engine No : CXS097787
Chassis No : WAUZZZ8VXE1039498
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Sep-17
Place of Accident : Before Carnie Exit at PIE Towards Stevens Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKN 4547 T

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$	280.00	\$ 280.00
2	To renew rhs 1/4 glass and rear windscreen to facilitate fender renewal.	S/N \$	600.00	\$ 600.00
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	\$ 1,400.00
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00	\$ 1,400.00
5	To dismantle rear bumper and rear lid. Cut out and weld rhs rear fender. Renew rear bumper. Reinstall all parts removed.	\$	4,800.00	\$ 3,000.00
6	To respray rear bumper, rhs rear fender, rhs sill panel, door entrance, drain channel, roof channel and end panelling. To carry out stone chip treatment and joint sealer works.	\$	4,100.00	\$ 2,200.00
7	To renew rhs rear rim and carry out wheel alignment.	S/N \$	280.00	\$ 280.00
8	To install rear windscreen and rear lh 1.4 glass solar film	S/N \$	400.00	\$ 400.00
9	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 13,452.00</u>	<u>\$ 9,752.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKN 4547 J

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,567.00	\$ 1,253.60
2	REAR BUMPER GUIDE INNER SECTION RH	\$ 13.00	
3	LOCKING MECHANISM	\$ 25.00	
4	REAR BUMPER GUIDE OUTER SECTION RH	\$ 54.00	
5	SECTIONAL PART RH	\$ 1,938.00	\$ 1,550.40
6	WHEEL HOUSING LINERS	\$ 208.00	
7	WHEEL HOUSING LINERS ATTACHMENTS PARTS	\$ 75.00	
8	1/4 GLASS	\$ 455.00	\$ 363.60
9	REAR WINDSCREEN	\$ 675.00	\$ 540.00
10	PRIMER FOR GLASS AND SEALANT	2 \$ 36.00	
11	SOUND ABSORBER	2 \$ 54.00	\$ 42.56
12	GROMMET	4 \$ 37.00	
13	REAR WINDSCREEN SEALANT	S/N \$ 200.00	\$ 200.00
14	1/4 GLASS SEALANT	S/N \$ 100.00	\$ 100.00
15	ACYRLIC SEALER	S/N \$ 180.00	\$ 180.00
16	CAVITY WAX	S/N \$ 140.00	\$ 140.00
17	STONE CHIP	S/N \$ 180.00	\$ 180.00
18	METAL FILLER POWDER	S/N \$ 280.00	\$ 280.00
19	SUNDRIES	\$ 500.00	\$ 9.60
TOTAL SPARE PARTS		\$ 6,717.00	\$ 4,839.76
TOTAL LABOUR CHARGES		\$ 13,452.00	\$ 9,752.00
GRAND TOTAL		\$ 20,169.00	\$ 14,591.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKN 4547 J

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0936/2017/MAS

13 March 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SKN 4547 J, Audi A3 Sedan 1.4 TFSI

With reference to the above-mentioned vehicle, no **SKN 4547 J**, claimant, **Mr. Hoe Yin Chuang, Raymond**, please find the related document per attached.

1. A copy of the Original invoice no. 85012235 – S\$14,971.18
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai

Claims Dept

Encls

AIG – SKN 4547 J

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Sep 2017 Edit Reg		28 Sep 2017 00:00 Edit Adj Rpt	S\$14,591.76 Edit Estimates	S\$14,591.76 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

HOE YIN CHUANG, RAYMOND, ID: S7332451C, Tel: +6596740989

Vehicle Reg. No.:

SKN4547J

Date of Loss:

22/09/2017 00:00 - :59

Claim Type:

OD / 5879583989SG

Policy/Cover Note No.:

2100376520 (Comprehensive)
Coverage: 16/06/2017 - 15/06/2018

Excess:

S\$600.00

Repairer:

Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing]
TongShing.Loo@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 10/10/2017]

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

- AIG_SG (19/10/2017): SKN4547J / OD / 22/09/2017 / Coverage & Excess update
- AIG_SG_EXPRESS (02/10/2017): Alert - Adj Mandate Approved (S\$15557.00) - SKN4547J - Claim Handler: Dally Amri...

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKN4547J (5879583989SG)
OD
Sep 22 2017 12:00AM
[HOE YIN CHUANG, RAYMOND]
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View Use Viewer ▼		
Assessment Reports										1 per page ▼		<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print		
1	29/09/17 16:08	Adjuster Immediate Advice						1 Load HTM				
Photos/Images										3 per page ▼		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print		
1	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
2	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
3	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
4	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
5	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
6	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
7	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
8	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
9	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
10	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
11	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
12	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
13	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
14	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
15	29/09/17 16:29	General View						1 Load JPG		<input checked="" type="checkbox"/>		
Documentation										1 per page ▼		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print		
1	29/09/17 16:25	Certificate of Insurance						1 Load PDF				
2	29/09/17 16:25	ESTIMATE						1 Load PDF				
3	29/09/17 16:25	Singapore Accident Statement						1 Load PDF				
4	29/09/17 16:25	NRIC AND DL						1 Load PDF				
5	29/09/17 16:25	Police Report						1 Load PDF				
6	20/03/18 14:46	WORKSHOP INVOICE						1 Load PDF				
7	20/03/18 14:46	DISCHARGE VOUCHER						1 Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid #ccc; height: 100px; width: 100%;"></div>				
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17018691/ARBN2

Date: 20/03/2018

REFERENCE

Insured/Claimant: HOE YIN CHUANG, RAYMOND

Policy No: 2100376520

Date of Loss: 22/09/2017

Nature of Claim: OD

Claim No: 5879583989SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKN4547J
Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A) Engine No: CXS097787
Reg. Date: 16/06/2014 (Man. Year: 2014) Chassis No: WAUZZZ8VXE1039498
Colour: Bronze Odometer: 59628 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$85,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,717.00	4,839.76	1,877.24	27.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,452.00	9,752.00	3,700.00	27.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,169.00	14,591.76	5,577.24	27.65
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	19,569.00	13,991.76	5,577.24	28.50
+ GST 7.00/7.00% (S\$)	1,369.83	979.42	390.41	28.50
Nett Amount (S\$)	20,938.83	14,971.18	5,967.65	28.50

INSPECTION

Date of Assignment: 28/09/2017

Date Inspected: 28/09/2017 Inspected At:

Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Torn	1,567.00 FS	*1,253.60 FS
2	1	*REAR BUMPER GUIDE INNER SECTION RH	Not Necessary	13.00 FS	*- FS
3	1	*LOCKING MECHANISM	Not Necessary	25.00 FS	*- FS
4	1	*REAR BUMPER GUIDE OUTER SECTION RH	Not Necessary	54.00 FS	*- FS
5	1	*SECTIONAL PART RH	Dented	1,938.00 FS	*1,550.40 FS
6	1	*WHEEL HOUSING LINERS	Not Necessary	208.00 FS	*- FS
7	1	*WHEEL HOUSING LINERS ATTACHMENTS PARTS	Not Necessary	75.00 FS	*- FS
8	1	*1/4 GLASS	Necessary	455.00 FS	*363.60 FS
9	1	*REAR WINDSCREEN	Necessary	675.00 FS	*540.00 FS
10	2	*PRIMER FOR GLASS AND SEALANT	Not Necessary	36.00 FS	*- FS
11	2	*SOUND ABSORBER	Necessary	54.00 FS	*42.56 FS
12	4	*GROMMET	Not Necessary	37.00 FS	*- FS
13	1	*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
14	1	*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
15	1	*ACRYLIC SEALER	Necessary	180.00 FS	*180.00 FS
16	1	*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
17	1	*STONE CHIP	Necessary	180.00 FS	*180.00 FS
18	1	*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
19	1	*SUNDRIES	Necessary	500.00 FS	*9.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 6,717.00 4,839.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	New	600.00	600.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
4	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS,SEAT BELTS.DISLODGE ROOF LINER AND DISENGAGE CURTAON AIRBAG ETC	New	1,400.00	1,400.00
5	TO DISMANTLE REAR BUMPER AND REAR LID.CUT OUT AND WELD RHS REAR FENDER.RENEW REAR BUMPER.REINSTALL ALL PARTS REMOVED	New	4,800.00	3,000.00
6	TO RESPRAY REAR BUMPER,RHS REAR FENDER,RHS SILL PANEL,DOOR ENTRANCE,DRAIN CHANNEL,ROOF CHANNEL AND END PANELLING.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	4,100.00	2,200.00
7	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
8	TO INSTALL REAR WINDSCREEN AND REAR LH 1/4 GLASS SOLAR FILM	New	400.00	400.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			13,452.00	9,752.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >