

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT17004200	Page	1
	3 ANSON ROAD #16-00	Date	: 12. Oct 2017		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	:		
Registration No	: SLC6602R	Engine No	: L15B31021120		
Chassis No	: JHMGK5850GX202764	Date Time	: 12. Oct 2017 11:22:25 AM		
Model	: JAZZ 1.5VTIR CVT 16YM	Surveyor Name	:		
Owner's Name	: TSANG WENHAO FREDERICK	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 28/9/2017				

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
	SUPPLEMENTARY						
BKRP02M	CUT OFF & RENEW RR PANEL AND LHR GUTTER	1	1680.00		1680.00	117.60	1797.60
BOJSE	SEALANT FOR REAR END PANEL	1	80.00		80.00	5.60	85.60
	Sum Labor				1760.00	123.20	1,883.20
63320-T5A-300ZZ	GUTTER COMPR.RR.	1	75.30	25	56.47	3.95	60.42
71502-T5A-000	GARNISHR.RR.BUMPER	1	6.30	25	4.72	0.33	5.05
73211-T5A-J01	GLASS SETRR.WINDSHIELD	1	625.60	25	469.20	32.84	502.04
33500-T5A-J02	TAILLIGHT ASSYR.	1	212.50	25	159.37	11.16	170.53
34150-T5A-J01	LIGHT ASSYR.LID	1	77.50	25	58.12	4.07	62.19
90650-SZT-003	GROMMETRR.COMBINATION LIGHT	1	2.50	25	1.87	0.13	2.00
90650-TX6-A01	CLIPRR.COMBINATION LIGHT	1	1.90	25	1.42	0.10	1.52
84601-TAR-Z03ZA	LINING ASSYR.TRUNK	1	165.70	25	124.27	8.70	132.97
74890-T5B-911	GARNISH ASSYRR.LICENSE	1	190.40	25	142.80	10.00	152.80
	Sum Item				1018.24	71.28	1,089.52

Survey By

Date & Time

Excess

Status

Total Amount 2,778.24 194.48 2,972.72

Total (Inclusive of GST) 2,972.72