

ASS. REC. BY: REF: CS/SMO17019152/T196 n2 Special Instruction

Surveyor: Taufikah ASSIGNMENT (Office)

From (Person): Sheng Wong of SMO Date/Time: 6/10/17 9:04 am

Estimated Cost Bill to

OD (TP) WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SJU 5042S Insured: SKY 1477 K

at Workshop m/s: SNGAHTEE Tel: 62686183

of Blk 3 Pioneer Road North # 01-18, 628457

Policy No: Claim No: CMTD1703430/AGC

Sum Insured Excess:

Make of Veh: D.O.A: 30/09/2017  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time: 6/10/17 9:12am Person Contacted: Sharon H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

| Date/Time         | Action/Instruction              |
|-------------------|---------------------------------|
|                   | (✓) Estimate                    |
|                   | SJU 5042S - X                   |
|                   | SKY 1477 - X                    |
| 11/10/17@ 10:28am | revised to Sheng Wong by email. |
|                   |                                 |
|                   |                                 |
|                   |                                 |

Taufman

REF: 502 SMO

ASSIGNMENT

From: \_\_\_\_\_ Date: 6/10/17

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GY8908P

at Workshop/s: Motoway Car Care

of: 109H Lower Delta Rd, Motoway Building

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Ven: \_\_\_\_\_

Policy Condition: 3 Apr Owner working

Remark: The veh had commenced its repair at the time of inspection.

Bar or Market Value: \_\_\_\_\_

DAC Accident Report Consistent? Yes or No

GIA PR Seen Consistent? Yes or No

Est. Repairs: 7 days Res. Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val. Yes or No

CA / REV / REP. / 24 HRS Pass

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SJ45042S Yr Reg: 2009, May

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mitsubishi Lancer 1.6M cc: 1584

Colour: white A/C: \_\_\_\_\_ Insured / Std / NI / NA

Sp Reading: 121420 T Read: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C No: JmySNC S3A 94004567

Gen Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Mod: Nil / S Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R Ba: 6 mm R Ba: 6 mm

L Ba: 6 mm L Ba: 6 mm

D O A: \_\_\_\_\_ D O I: 6/10/17

Survey held at: Singapore

Des. of Damages: ☒ FR / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

7/11/18 4/5 @ 3700, 7 days - e-mail to Sharon

(Red \$1497.62, 29%)

RECEIVED 23 APR 2018

Date/Time File Pass to: 13/4/18

Date/Time File Return to: \_\_\_\_\_

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee: \_\_\_\_\_

Transcription: \_\_\_\_\_

Y. Photos: \_\_\_\_\_

Y. Others: \_\_\_\_\_

TOTAL: 250

Report Format: TP

Lump Sum / I.B.A. (S): 3700

Add Fee: ☐ Site Insp (S)

☐ Interview (S)

☐ Tech. Invs (S)

☐ Weekend (S)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17019152/T1qb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 06-10-2017



Code : SMO

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                  |                |            |
|--------------|------------------|----------------|------------|
| Insured Veh. | SKU 1477K        | Veh. Inspected | SJU 5042S  |
| Policy No.   |                  | Coverage (\$)  | 0.00       |
| Claim No.    | CMTD17034300/AGC | Excess (\$)    | 0.00       |
| Assign From  | SHERY WONG       | Assign Date    | 06/10/2017 |

## 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |   |                 |            |
|----------------|---|-----------------|------------|
| Accident Date  | 30/09/2017  | Inspection Date | 06/10/2017 |
| Survey held at | SNG AH TEE MOTOR & PANEL SERVICE PTE LTD<br>BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457. |                 |            |

## 5a. Remarks

|  |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1703430/AGC

Date: 11<sup>th</sup> October 2017

Our Ref: CS/SMO17019152/T1qb

Without Prejudice

The Motor Claims Department  
Sompo Insurance

Attn: Shery

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SJU 5042S .**


We thank you for the instruction on 06/10/2017.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/10/2017 at the premises of M/s SNG AH TEE and have the following to report:-

|                          |                         |
|--------------------------|-------------------------|
| Workshop Estimate Amount | : S\$ <u>5,017.62</u> . |
| Revised Estimate Amount  | : S\$ <u>3,515.00</u> . |
| "Check" Items Amount     | : S\$ <u>1,192.50</u> . |
| Market Value             | : S\$ <u>-</u> .        |
| LTA Reimbursement Value  | : S\$ <u>-</u> .        |
| Nett Value               | : S\$ <u>-</u> .        |

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 7 days.

We have NOT authorized repair.

Yours faithfully

Taufikh  
Automobile Assessor

## Nivitha (LKK Auto)

---

**From:** Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>  
**Sent:** Friday, 6 October, 2017 9:04 AM  
**To:** assignments@lkkauto.com  
**Cc:** Catherine Chong (LKK Auto)  
**Subject:** FW: Accident involved with our client's vehicle SJU5042S your insured SKU1477K on 30/09/2017  
**Attachments:** SJU5042S.PDF; estimate.pdf

Our Claim Reference : CMTD1703430/AGC

Hi ,

We acknowledged receipt of your claim documents.

Aside to **LKK AUTO**, ~

Kindly assign your motor surveyor to conduct motor survey of the mentioned (SJU5042S).

Thank you.

Best Regards

**Shery Wong**

Claims Division

D: 6329 5339 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

---

**From:** SAMANTHA TAN [<mailto:sam@sngahtee.com>]

**Sent:** Thursday, October 05, 2017 4:59 PM

**To:** Motor Survey

**Subject:** Accident involved with our client's vehicle SJU5042S your insured SKU1477K on 30/09/2017

Hi,

Kindly arrange survey on 06/10/2017 for above vehicle.

Thank you.

Best Regards

---

Samantha Tan | [sam@sngahtee.com](mailto:sam@sngahtee.com)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457  
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 11 October, 2017 10:28 AM  
**To:** 'Wong, Shi Yi Shery'; assignments  
**Cc:** SUR  
**Subject:** RE: Accident involved with our client's vehicle SJU5042S your insured SKU1477K on 30/09/2017  
**Attachments:** CSSMO17019152T1qb.pdf

Dear Shery,

Enclosed herewith preliminary advice of SJU 5042S.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Friday, 6 October, 2017 9:15 AM  
**To:** 'Wong, Shi Yi Shery' <[Shery.Wong@sompo.com.sg](mailto:Shery.Wong@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: Accident involved with our client's vehicle SJU5042S your insured SKU1477K on 30/09/2017

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Wong, Shi Yi Shery [<mailto:Shery.Wong@sompo.com.sg>]  
**Sent:** Friday, 6 October, 2017 9:04 AM  
**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** Catherine Chong (LKK Auto)  
**Subject:** FW: Accident involved with our client's vehicle SJU5042S your insured SKU1477K on 30/09/2017

Our Claim Reference : CMTD1703430/AGC

Hi ,

We acknowledged receipt of your claim documents.

## **Enquire PARF/COE Rebate for Registered Vehicle**

### **Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 9420Z

### **Vehicle Details**

Vehicle No.: SJU5042S

Vehicle to be  
Exported: No

Intended De-  
registration Date: 31 Oct 2017

Vehicle Make: MITSUBISHI

Vehicle Model: LANCER 1.6 M

Primary Colour: White

Manufacturing  
Year: 2009

Engine No.: 4G18KC4566

Chassis No.: JMYSNCS3A9U004567

Maximum Power  
Output: 79.0 kW (105 bhp)

Open Market  
Value: \$11,669.00

Original  
Registration Date: 28 May 2009

First Registration  
Date: 28 May 2009

Transfer Count: 1

Actual ARF Paid: \$11,669.00

### **Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility  
Expiry Date: 27 May 2019

PARF Rebate  
Amount: \$6,417.00

### **Intended COE Rebate Details**

COE Expiry Date: 27 May 2019

COE Category: A - Car (1600cc & below)

COE  
Period(Years): 10

QP Paid: \$9,501.00

COE Rebate  
Amount: \$1,494.00

**Total Rebate  
Amount: \$7,911.00**

The information contained herein is correct as at 03 Oct 2017



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |   |
|----------------------------|---|
| Date Of Report             | 02/10/2017 09:39                              |
| Date Of Accident           | 30/09/2017 16:00                              |
| Exact Location Of Accident | 52 BUKIT BATOK EAST AVE 5 @ REGENT HEIGHT C/P |
| Country/State of Loss      | SINGAPORE                                     |

### DETAILS OF OWN VEHICLE

|                             |                       |
|-----------------------------|-----------------------|
| Vehicle Registration Number | SJU5042S              |
| <b>Insured/Policyholder</b> |                       |
| Name Of Registered Owner    | NANJAPPAN UDAYKUMAR   |
| NRIC No                     | S2749420Z             |
| Email Address               | UDAYKUMAR_N@YAHOO.COM |
| Mobile Phone No             | (LOCAL) +65-96355519  |
| Alternative Phone No        | OFFICE-NOPHONE        |

### Vehicle Particulars

|              |                |
|--------------|----------------|
| Manufacturer | MITSUBISHI     |
| Model        | LANCER-1.6 (M) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

|                           |   |
|---------------------------|---|
| Name of Insurance Company | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage          | COMPREHENSIVE                                 |
| Fleet Policy              | NO  |
| Policy Number             | DMPCSN3019911706                              |
| Cover Note Number         |   |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | NANJAPPAN UDAYKUMAR   |
| NRIC No              | S2749420Z             |
| Date Of Birth        | 04/11/1962            |
| Occupation           | INDOOR                |
| Date Of Driving Pass | 29/01/2007            |
| Driving Experience   | 10 YEARS AND 8 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-96355519  |
| Fax Number           |                       |
| Contact Number       | OFFICE-NOPHONE        |
| Email Address        | UDAYKUMAR_N@YAHOO.COM |

|   |                                  |
|---|----------------------------------|
| Address   | 52 BUKIT BATOK EAST AVE 5 #03-02 |
| Postcode  | 659802                           |
| Was driver an employee of the Insured's Company     | NO                               |
| If No, Relationship of the Driver with the Insured  | OWNER                            |
| Vehicle Registration Number of Driver's Own Vehicle | -                                |
|   | -                                |
| Insurance Company of Driver's Own Vehicle           | -                                |
|   | -                                |
|   | -                                |

#### General Information of the Accident

|                    |   |
|--------------------|---|
| Type Of Accident   | HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED |
| Weather Conditions | CLEAR   |
| Road Surface       | DRY   |

#### Other Information

|   |     |
|---|-----|
| Was any foreign vehicle involved in this accident?  | NO  |
| Was any body injured in the Accident?   | NO  |
| Was any other material or property damaged?   | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)   | 0   |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

ON 30/09/2017 AT AROUND 1600HRS, MY VEHICLE WAS PARKED AT MY HOME 52 BUKIT BATOK EAST AVE 5 CAR PARK LOT. MY CONDO SECURITY GUARD CAME UP TO MY APARTMENT AND SAID THAT MY VEHICLE WAS BEING HIT BY VEHICLE B. I WENT DOWN VEHICLE B DRIVER IS STILL AT THE SCENE AND I NOTICE THAT VEHICLE B HAD COLLIDED ONTO MY VEHICLE FRONT PORTION AND THE IMPACT I THINK WAS BIG AND PUSHED MY VEHICLE BACKWARDS AND HIT ONTO THE WALL. THIS ACCIDENT CAUSED MY FRONT AND REAR PORTION DAMAGES.

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |                     |
|-------------------------------------|---------------------|
| Vehicle Registration Number         | SKU1477K            |
| Vehicle Make/Model/Colour           |                     |
| Details Of Properties               |                     |
| Name of Driver                      | KHANT KYAW LIN KHIN |
| NRIC/Passport Number                | S9574893G           |
| Contact Number                      | 92392624            |
| Address                             |                     |
| Postcode                            |                     |
| Insurance Company Name              |                     |
| Nature Of Damage                    |                     |
| No. Of Passenger (Including Driver) |                     |

#### Details of Witness

|               |  |
|---------------|--|
| Name          |  |
| Phone Number  |  |
| Email Address |  |


## Sketch Plan Pg. 1


### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

#### Sketch Plan



Sketch Plan Pg. 2

Describe Circumstances of the Accident

Refer to Accident Circumstances

Declaration


I/We declare the foregoing particulars are true in every respect.

☐ Claim own policy  
☒ Claim third party  
☐ Claim OD / TP at other workshop  
☐ For record purpose  
Policy No. BMPCN3019911706  
Insurer Am Veh.No. JB450420



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

# 孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003180

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE #05-01/06

SINGAPORE LAND TOWER(S)048623

ATTENTION :

CONTACT : -

FAX NO: 62213302

DATE : 4/10/2017

ACCIDENT DATE : 30/9/2017

VEHICLE NO : SJU5042S

CHASSIS/ENG.NO :

VEHICLE MODEL : MIT LANCER

CLAIM NO :

POLICY NO :

REMARK : 5042SOMPO TP AGST  
SKU1477K

| S/N.                            | QTY | UNIT | DESCRIPTION                | PRICE  | DISC % | DISC/MARKUP | TOTAL AMT   |
|---------------------------------|-----|------|----------------------------|--------|--------|-------------|-------------|
| <b>** LIST PRICE **</b>         |     |      |                            |        |        |             |             |
|                                 |     |      |                            |        |        | SUB-TOTAL:  | 0.00        |
| <b>** SPECIAL NETT PRICE **</b> |     |      |                            |        |        |             |             |
| 1                               | 1   | PC   | FRT NUMBER PLATE           | 35.00  |        | 35.00       | h f 35.00   |
|                                 |     |      |                            |        |        | SUB-TOTAL   | 35.00       |
| <b>** COST PLUS MARKUP **</b>   |     |      |                            |        |        |             |             |
| 1                               | 1   | PC   | FRT NUMBER PLATE GARNISH   | 28.00  | -25.00 | 35.00       | de 35.00    |
| 2                               | 1   | PC   | FRT BUMPER                 | 430.00 | -25.00 | 537.50      | one 537.50  |
| 3                               | 2   | PC   | FRT BUMPER SIDE RETAINER   | 28.00  | -25.00 | 35.00       | ne 70.00    |
| 4                               | 10  | PC   | FRT BUMPER CLIPS           | 2.50   | -25.00 | 3.13        | ne 31.30    |
| 5                               | 1   | PC   | FRT BUMPER LOWER GRILLE    | 50.00  | -25.00 | 62.50       | de 62.50    |
| 6                               | 2   | PC   | FRT BUMPER CLIPS (SQUARE)  | 3.00   | -25.00 | 3.75        | ne 7.50     |
| 7                               | 1   | PC   | FRT GRILLE                 | 110.00 | -25.00 | 137.50      | one 137.50  |
| 8                               | 1   | PC   | FRT GRILLE COVER LH        | 60.00  | -25.00 | 75.00       | Run 75.00 X |
| 9                               | 1   | PC   | FRT GRILLE COVER RH        | 60.00  | -25.00 | 75.00       | Run 75.00 X |
| 10                              | 4   | PC   | FRT GRILLE CLIP            | 2.50   | -25.00 | 3.13        | ne 12.52    |
| 11                              | 1   | PC   | FRT FOGLAMP COVER(LH)      | 20.00  | -25.00 | 25.00       | Run 25.00 X |
| 12                              | 1   | PC   | FRT HEADLAMP LH            | 380.00 | -25.00 | 475.00      | one 475.00  |
| 13                              | 1   | PC   | FRT BONNET                 | 430.00 | -25.00 | 537.50      | ht 537.50   |
| 14                              | 1   | PC   | FRT BONNET RUBBER SEAL     | 18.00  | -25.00 | 22.50       | ne 22.50    |
| 15                              | 1   | PC   | FRT BONNET LOCK            | 36.00  | -25.00 | 45.00       | Run 45.00 X |
| 16                              | 1   | PC   | FRT BONNET LOCK CABLE      | 18.00  | -25.00 | 22.50       | Run 22.50 X |
| 17                              | 1   | PC   | FRT SUPPORT PANEL COMPLETE | 400.00 | -25.00 | 500.00      | ht 500.00   |
| 18                              | 10  | PC   | REAR BUMPER CLIPS          | 2.50   | -25.00 | 3.13        | ne 31.30    |
| 19                              | 1   | PC   | AIRCON CONDENSER           | 280.00 | -25.00 | 350.00      | ht 350.00   |

SAM

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E

# 孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003180

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE #05-01/06

SINGAPORE LAND TOWER(S)048623

ATTENTION :

CONTACT : -

FAX NO: 62213302

DATE : 4/10/2017  
ACCIDENT DATE : 30/9/2017  
VEHICLE NO : SJU5042S  
CHASSIS/ENG.NO :  
VEHICLE MODEL : MIT LANCER  
CLAIM NO :  
POLICY NO :  
REMARK : 5042SOMPO TP AGST  
SKU1477K

| S/N.              | QTY | UNIT | DESCRIPTION                            | PRICE  | DISC % | DISC/MARKUP | TOTAL AMT          |
|-------------------|-----|------|--|--------|--------|-------------|--------------------|
|                   |     |      |  |        |        |             | -----              |
|                   |     |      |  |        |        |             | SUB-TOTAL 3,052.62 |
|                   |     |      |  |        |        |             |                    |
| ** WORK LABOUR ** |     |      |  |        |        |             |                    |
|                   |     |      | TO CHECK WIRING                        | 30.00  |        |             | 30.00              |
|                   |     |      | TO REFILL AIRCON GASS                  | 100.00 |        |             | 100.00             |
|                   |     |      | TO APPLY ANTI RUST COATING             | 150.00 |        |             | 150.00             |
|                   |     |      | TO KNOCK RR BUMPER,WELD,REMOVE & REFIX | 0.00   |        |             | 0.00               |
|                   |     |      | ON ABOVE PARTS                         | 800.00 |        |             | 800.00             |
|                   |     |      | TO PUTTY & SPRAY PAINTING RR BUMPER &  | 0.00   |        |             | 0.00               |
|                   |     |      | AFFECTED AREAS                         | 850.00 |        |             | 850.00             |
|                   |     |      |  |        |        |             | -----              |
|                   |     |      |  |        |        |             | SUB-TOTAL 1,930.00 |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 97495749.  
- wp' 6/10/17  
lumpsum @ 1745  
Repair after repair  
7 days  
14/10/17

SAM

PAGE: 2 of 2

SUB-TOTAL : S\$ 5,017.62  
ADD 7% GST. S\$ 351.23  
GRAND TOTAL : S\$ 5,368.85

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E

5147.50

# SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3 Pioneer Road North #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

ATTN:THE MOTOR CLAIMS DEPT  
SOMPO INSURANCE SINGAPORE PTE LTD

Our Ref:  
Date : 11/04/2018

## SUPPLEMENTARY ESTIMATE COST OF REPAIR

Vehicle Reg No. SJU5042S  
Date of Accident 30-Sep-17  
Type of Claim TP SOMPO  
Survey By \_\_\_\_\_

Model / Year

Policy No.

Prepared By

Chassis No.

MIT. LANCER

SHARON

**S/NO Description**

**Qty**

**List Price**

**Amount**

1 REAR BUMPER REVERSE SENSOR

1

\$

180.00

\$

180.00

SNETT

*CAJNW* ✓



# 孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003180

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE #05-01/06

SINGAPORE LAND TOWER(S)048623

ATTENTION :

CONTACT : -

FAX NO: 62213302

DATE 4/10/2017

ACCIDENT DATE : 30/9/2017

VEHICLE NO : SJU5042S

CHASSIS/ENG.NO :

VEHICLE MODEL : MIT LANCER

CLAIM NO :

POLICY NO :

REMARK : 5042SOMPO TP AGST

SKU1477K

| S/N.                            | QTY | UNIT | DESCRIPTION                | PRICE  | DISC % | DISC/MARKUP | TOTAL AMT               |
|---------------------------------|-----|------|----------------------------|--------|--------|-------------|-------------------------|
| <b>** LIST PRICE **</b>         |     |      |                            |        |        |             |                         |
|                                 |     |      |                            |        |        |             | -----                   |
|                                 |     |      |                            |        |        |             | SUB-TOTAL: 0.00         |
|                                 |     |      |                            |        |        |             |                         |
|                                 |     |      |                            |        |        |             |                         |
| <b>** SPECIAL NETT PRICE **</b> |     |      |                            |        |        |             |                         |
| 1                               | 1   | PC   | FRT NUMBER PLATE           | 35.00  |        | 35.00       | h f / 35.00             |
|                                 |     |      |                            |        |        |             | -----                   |
|                                 |     |      |                            |        |        |             | SUB-TOTAL \$35.00 35.00 |
| <b>** COST PLUS MARKUP **</b>   |     |      |                            |        |        |             |                         |
| 1                               | 1   | PC   | FRT NUMBER PLATE GARNISH   | 28.00  | -25.00 | 35.00       | de / 35.00 ✓            |
| 2                               | 1   | PC   | FRT BUMPER                 | 430.00 | -25.00 | 537.50      | con / 537.50 ✓          |
| 3                               | 2   | PC   | FRT BUMPER SIDE RETAINER   | 28.00  | -25.00 | 35.00       | ne / 70.00 ✓            |
| 4                               | 10  | PC   | FRT BUMPER CLIPS           | 2.50   | -25.00 | 3.13        | ne / 31.30 ✓            |
| 5                               | 1   | PC   | FRT BUMPER LOWER GRILLE    | 50.00  | -25.00 | 62.50       | de / 62.50 ✓            |
| 6                               | 2   | PC   | FRT BUMPER CLIPS (SQUARE)  | 3.00   | -25.00 | 3.75        | ne / 7.50 ✓             |
| 7                               | 1   | PC   | FRT GRILLE                 | 110.00 | -25.00 | 137.50      | ag / 137.50 ✓           |
| 8                               | 1   | PC   | FRT GRILLE COVER LH        | 60.00  | -25.00 | 75.00       | ? 75.00 X               |
| 9                               | 1   | PC   | FRT GRILLE COVER RH        | 60.00  | -25.00 | 75.00       | ? 75.00 X               |
| 10                              | 4   | PC   | FRT GRILLE CLIP            | 2.50   | -25.00 | 3.13        | ne / 12.52 ✓            |
| 11                              | 1   | PC   | FRT FOGLAMP COVER(LH)      | 20.00  | -25.00 | 25.00       | ? 25.00 X               |
| 12                              | 1   | PC   | FRT HEADLAMP LH            | 380.00 | -25.00 | 475.00      | con / 475.00 ✓          |
| 13                              | 1   | PC   | FRT BONNET                 | 430.00 | -25.00 | 537.50      | h f / 537.50 ✓          |
| 14                              | 1   | PC   | FRT BONNET RUBBER SEAL     | 18.00  | -25.00 | 22.50       | ne / 22.50 ✓            |
| 15                              | 1   | PC   | FRT BONNET LOCK            | 36.00  | -25.00 | 45.00       | ? 45.00 X               |
| 16                              | 1   | PC   | FRT BONNET LOCK CABLE      | 18.00  | -25.00 | 22.50       | ? 22.50 X               |
| 17                              | 1   | PC   | FRT SUPPORT PANEL COMPLETE | 400.00 | -25.00 | 500.00      | ? 500.00 ✓              |
| 18                              | 10  | PC   | REAR BUMPER CLIPS          | 2.50   | -25.00 | 3.13        | ne / 31.30 ✓            |
| 19                              | 1   | PC   | AIRCON CONDENSER           | 280.00 | -25.00 | 350.00      | ? 350.00 ✓              |

SAM

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E



孫亞弟汽車燒焊私人有限公司  
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003180

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE #05-01/06

SINGAPORE LAND TOWER(S)048623

ATTENTION :

CONTACT : -

FAX NO: 62213302

DATE : 4/10/2017  
ACCIDENT DATE : 30/9/2017  
VEHICLE NO : SJU5042S  
CHASSIS/ENG.NO :  
VEHICLE MODEL : MIT LANCER  
CLAIM NO :  
POLICY NO :  
REMARK : 5042SOMPO TP AGST  
SKU1477K

| S/N. | QTY | UNIT | DESCRIPTION | PRICE | DISC % | DISC/MARKUP | TOTAL AMT |
|------|-----|------|-------------|-------|--------|-------------|-----------|
|      |     |      |             | ----- |        | SUB-TOTAL   | 3,052.62  |
|      |     |      |             |       |        | \$2810.12   |           |
|      |     |      |             |       |        | ✓           |           |
|      |     |      |             |       |        | ?           |           |
|      |     |      |             |       |        | 40          |           |
|      |     |      |             |       |        | 700         |           |
|      |     |      |             |       |        | 750         |           |
|      |     |      |             |       |        | -----       |           |
|      |     |      |             |       |        | SUB-TOTAL   | 1,930.00  |
|      |     |      |             |       |        | \$1600      |           |

\*\* WORK LABOUR \*\*

TO CHECK WIRING  
TO REFILL AIRCON GASS  
TO APPLY ANTI RUST COATING  
TO KNOCK RR BUMPER, WELD, REMOVE & REFIX  
ON ABOVE PARTS  
TO PUTTY & SPRAY PAINTING RR BUMPER &  
AFFECTED AREAS

Tanjah 97495749.

- wp' 6/10/17

lumpsum @ 1745

Repair after repair

7 days

lumpsum

total \$4645.12

less 20% = \$3716.10

20% of lumpsum

ok. pls revert.

Sharon 11/11/2018

SAM

PAGE: 2 of 2

SUB-TOTAL : S\$ 5,017.62

ADD 7% GST: S\$ 351.23

GRAND TOTAL : S\$ 5,368.85

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O.E

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17019152/T1qbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 25-04-2018



Code : SMO

**1. Policy Particulars :- THIRD PARTY CLAIM**

|              |                 |                |            |
|--------------|-----------------|----------------|------------|
| Insured Veh. | SKU 1477K       | Veh. Inspected | SJU 5042S  |
| Policy No.   |                 | Coverage (\$)  | 0.00       |
| Claim No.    | CMTD1703430/AGC | Excess (\$)    | 0.00       |
| Assign From  | SHERY WONG      | Assign Date    | 06/10/2017 |

**2. Vehicle Particulars & Condition**

|              |                        |              |            |
|--------------|------------------------|--------------|------------|
| Make & Model | MITSUBISHI LANCER 1.6M | c.c          | 1584       |
| Engine No.   | HIDDEN                 | Year of Reg. | 2009       |
| Chassis No.  | JMYSNCS3A9U004567      | Colour       | WHITE      |
| Odometer     | 121420                 | Steering     | IN ORDER   |
| Brakes       | IN ORDER               | Modification | SPORTS RIM |
| General      | GOOD                   |              |            |

**3. Conditions of Tyres**

|                | Size       | Make     | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 185/65 R15 | YOKOHAMA | 6 mm    |
| L/H Front Tyre | 185/65 R15 | YOKOHAMA | 6 mm    |
| R/H Rear Tyre  | 185/65 R15 | YOKOHAMA | 6 mm    |
| L/H Rear Tyre  | 185/65 R15 | YOKOHAMA | 6 mm    |

**4. Description of Damages**

|  |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.<br>DAMAGES SEE DETAILS. |
|--|

**5. General Information**

|                |   |                 |            |
|----------------|---|-----------------|------------|
| Accident Date  | 30/09/2017  | Inspection Date | 06/10/2017 |
| Survey held at | SNG AH TEE MOTOR & PANEL SERVICE PTE LTD<br>BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457. |                 |            |

**5a. Remarks**

|   |
|---|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|---|

**5b. Estimate Days of Repair**

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>7 Working Days</b> |
|-------------------------------------|-----------------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 5042S

| Qty                                | Description of Parts                                   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|---------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |  |               |                           |                   |
| 1                                  | FRT NUMBER PLATE GARNISH (WCP)                         | DEFORMED      | 28.00                     | 28.00             |
| 1                                  | FRT BUMPER (WCP)                                       | CRACKED       | 430.00                    | 430.00            |
| 2                                  | FRT BUMPER SIDE RETAINER @\$28.00 (WCP)                | NECESSARY     | 56.00                     | 56.00             |
| 10                                 | FRT BUMPER CLIPS @\$2.50 (WCP)                         | NECESSARY     | 25.00                     | 25.00             |
| 1                                  | FRT BUMPER LOWER GRILLE (WCP)                          | DEFORMED      | 50.00                     | 50.00             |
| 2                                  | FRT BUMPER CLIPS (SQUARE) @\$3.00 (WCP)                | NECESSARY     | 6.00                      | 6.00              |
| 1                                  | FRT GRILLE (WCP)                                       | CRACKED       | 110.00                    | 110.00            |
| 1                                  | FRT GRILLE COVER LH (WCP)                              | NOT NECESSARY | 60.00                     | -                 |
| 1                                  | FRT GRILLE COVER RH (WCP)                              | NOT NECESSARY | 60.00                     | -                 |
| 4                                  | FRT GRILLE CLIP @\$2.50 (WCP)                          | NECESSARY     | 10.00                     | 10.00             |
| 1                                  | FRT FOGLAMP COVER (LH) (WCP)                           | NOT NECESSARY | 20.00                     | -                 |
| 1                                  | FRT HEADLAMP LH (WCP)                                  | CRACKED       | 380.00                    | 380.00            |
| 1                                  | FRT BONNET (WCP)                                       | BENT          | 430.00                    | 430.00            |
| 1                                  | FRT BONNET RUBBER SEAL (WCP)                           | NECESSARY     | 18.00                     | 18.00             |
| 1                                  | FRT BONNET LOCK (WCP)                                  | NOT NECESSARY | 36.00                     | -                 |
| 1                                  | FRT BONNET LOCK CABLE (WCP)                            | NOT NECESSARY | 18.00                     | -                 |
| 1                                  | FRT SUPPORT PANEL COMPLETE (WCP)                       | BENT          | 400.00                    | 400.00            |
| 10                                 | REAR BUMPER CLIPS @\$2.50 (WCP)                        | NECESSARY     | 25.00                     | 25.00             |
| 1                                  | AIRCON CONDENSER (WCP)                                 | BENT          | 280.00                    | 280.00            |
|                                    | COST PLUS 25%  |               | 610.50                    | 562.00            |
|                                    |  |               | 3,052.50                  | 2,810.00          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |  |               |                           |                   |
| 1                                  | FRT NUMBER PLATE (SN)                                  | BENT          | 35.00                     | 35.00             |
| 1                                  | REAR BUMPER REVERSE SENSOR (ADDITIONAL)(SN)            | NOT WORKING   | 180.00                    | 180.00            |
|                                    |  |               | 215.00                    | 215.00            |
| <b><u>LABOUR</u></b>               |  |               |                           |                   |
|                                    | TO CHECK WIRING.                                       |               | 30.00                     | 30.00             |
|                                    | TO REFILL AIRCON GAS.                                  |               | 100.00                    | 100.00            |
|                                    | TO APPLY ANTI RUST COATING.                            |               | 150.00                    | 40.00             |
|                                    | TO KNOCK RR BUMPER,WELD,REMOVE & REFIX ON ABOVE PARTS. |               | 800.00                    | 700.00            |

Report Ref No. CS/SMO17019152/T1qbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty   | Description of Parts                                  | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|-----------|---------------------------|-------------------|
|   | TO PUTTY & SPRAY PAINTING RR BUMPER & AFFECTED AREAS. |           | 850.00                    | 750.00            |
|   |   |           | 1,930.00                  | 1,620.00          |
|   | GRAND TOTAL   |           | 5,197.50                  | 4,645.00          |
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |   |           |                           | 3,700.00          |

Report Ref No. CS/SMO17019152/T1qbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.