

EC BY:

REF: CS/FCI17019507 R1rbn2

Special Instruction:

SUBJECT

cus

R6511

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time: 10/10/17 @ 5:14 pm

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFB 1397S

Insured:

SHD 6518 T

at Workshop m/s

Vantage Automotive

Tel:

6319 0174

of

305 Alexandra Rd

Policy No:

Claim No:

N17009338 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 2/10/17

CA / REV / REP. / REV 24 HRS

Ds'

13.10.2017 @ 11:30am owner waiting

H.O.D. Endorsement

Date/Time: 11/10/17 @ 9:40am

Person Contacted:

Caroline

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SFB1397S - NBA/CAI15006195/e1 - D.O.A. = 11/04/2015
	SHD6518T - CS/FCI16019216/Kgh3q2 - D.O.A. = 28/9/2016
	confirm with Gao Xiang \$9055.10 @ 7 days
	Red: \$2248.40, 2017

(08/11/13)

A.E.S. REC. BY:

REF:

FCI

2019

ASSIGNMENT

From:

Date:

13/10/17

Estimated Cost:

Veh No:

SFB1397S

Yr Regn:

2013 / July

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SFB1397S

at Workshop m/s

Vantage Automotive

of

305 Alexandra Road

Make:

HONDA STREAM 1.8 A x c.c. 1799

Colour:

Brown

A/C: Insured / Std / NI / NA

Sp. Reading

193639

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

R561064846

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F:

F:

205/55R16

R:

22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

02/10/17

D.O.I.

13/10/17

Survey held at

Vantage

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:


11:30am owner waiting

(Policy Condition)

owner arrived 12:00hrs

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

17K 18K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

mv: \$18K, LTA: \$8344, NV: \$9656.00

RECEIVED 17 MAY 2018

Date/Time, File Pass to?



Preli. Report

1)

typus



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

215: 30

170+30

50

50

55

355

Report Format:

TP

Lump Sum / L.B.I: (\$ 9055.10)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17019527/R1rb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-10-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6518T	Veh. Inspected	SFB 1397S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17009338MFSH	Excess (\$)	0.00	
Assign From	CWS (EILEEN LEE)	Assign Date	11/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/10/2017	Inspection Date		
Survey held at	VANTAGE AUTOMOTIVE LTD 305 ALEXANDRA ROAD SINGAPORE 155942			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	03-10-2017	Our Ref No. D17009338MFSH
Accident Date	02-10-2017	Claim Type. Third Party
Insured Vehicle	SHD6518T	Third Party Vehicle. SFB1397S
Survey Location	305 ALEXANDRA ROAD	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	VANTAGE AUTOMOTIVE LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

HONDA STREAM Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Honda Stream 1.8A X	\$16,800	\$10,300 /yr	14-Jul-2008	1,799 cc	-	Benefit Auto Enterprise Pte Ltd	Available
1 Owner Unit! Perfect For Short Term Usage! Ideal For COE Renewal! Lowest Depreciation In The Market! Hurry Call Now Before Its Gone! Office No. - 68444161 Chew - 90603343							
Honda Stream 1.8A	\$20,800	\$14,110 /yr	03-Jul-2008	1,799 cc	-	Dickson Automobile	Available
\$0 Down Payment! Free Insurance, Road Tax And Unlimited Warranty! Well Maintained! 1 Owner! A Powerful And Stylish MPV Built With Versatile Yet Practical Interior For Your Usage. Buy It From Us With A... Office No. - 68447667 Ricky Eng - 91853390 Jonathan Quah - 91901666 Eric Lee - 91827304							
Honda Stream 1.8A	\$19,800	\$14,040 /yr	12-Jun-2008	1,799 cc	290,000 km	Carro	Available
Excellent Conditions, All Wear And Tear And Parts Are Changed. Vicom Inspection Passed! Office No. - 67146652 Pei Yi - 88768187							
Honda Stream 1.8A	\$19,800	\$13,390 /yr	09-Jun-2008	1,799 cc	112,025 km	Dickson Automobile	Available
Low Interest At 1.99%, Very Low Mileage! Extended Warranty Available! Well Kept By Previous Owner In Spectacular Good Condition, Test It And It Will Show You! Buy It From Us With A Peace Of Mind, A Co... Office No. - 68447667 Jonathan Quah - 91901666 Ricky Eng - 91853390 Eric Lee - 91827304							
Honda Stream 1.8A X (OPC)	\$16,800	\$11,810 /yr	02-Jun-2008	1,799 cc	91,524 km	Yin Auto	Available
1 Owner. Low Mileage Done. Just Arrived! Beautiful And Sporty White In Black Honda Stream 1.8A. Reliable And Low Maintenance Cost. Own By Careful Owner. Most Popular Honda MPV For Your Family Usage! 1... Office No. - - Joyce - 83397445 Miss Ng - 93742759							
Honda Stream 1.8A X	\$16,800	\$12,970 /yr	29-May-2008	1,799 cc	-	360 VR Cars	Available
1 Owner, Accidental Free. 17 Ins Sport Rims, Alpine Multi Media Head Unit, Blackvue 2 Channels In-car Camera, Reverse Sensor And Camera, Newly Replaced Aircon Compressor. Office No. - 68170836 James Tan - 90700005							
Honda Stream 1.8A RSZ	\$19,800	\$13,530 /yr	21-May-2008	1,799 cc	-	Dickson Automobile	Available
A Powerful MPV Designed To Give You Excellent Handling And Stability Enhancing Your Driving Experience. Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Excellent Aft... Office No. - 68447667 Jonathan - 91901666 Ricky - 91853390 Eric - 91827304							
Honda Stream 1.8A Sunroof	\$16,588	\$9,700 /yr	28-Apr-2008	1,799 cc	121,000 km	Car Design Motor	Available
Lowest Price In The Market, Low Mileage Of 121k Km Only, Accident Free, Tip Top Condition. Call Our Friendly Sale Advisor, Buy With A Peace Of Mind, View To Appreciate. Call Now Before This Beauty Is ... Office No. - 67468820 Anson - 88183368 David Tan - 83338363 Sunny Ang - 90468282 Roy Ong - 81888837							
Honda Stream 1.8A	\$17,300	\$12,880 /yr	23-Apr-2008	1,799 cc	-	ValueCars Auto Traders	Available
Selling \$17300, Get Back Parf \$10243! Personal Name Registering PHC For Uber /grab Driving Makes Easier Now! Come View And Buy This Reliable Japan Honda Stream 1.8A 7seater For Either Personal Family ... Office No. - 68410062 Alex - 96370341 Audrey - 96528822 Richard - 88222308							
Honda Stream 1.8A X	\$15,800	-	03-Apr-2008	1,799 cc	164,800 km	G.S.T. Automobile Trading	Available

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8249G

Vehicle Details

Vehicle No.: SFB1397S

Vehicle to be Exported: No

Intended De-registration Date: 04 Oct 2017

Vehicle Make: HONDA

Vehicle Model: STREAM 1.8X A

Primary Colour: Grey

Manufacturing Year: 2008

Engine No.: R18A1772080

Chassis No.: RN61064846

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$17,562.00

Original Registration Date: 29 Jul 2008

First Registration Date: 29 Jul 2008

Transfer Count: 3

Actual ARF Paid: \$13,969.00

17,000
8,344

8,656
//

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 Jul 2018

PARF Rebate Amount: \$6,984.00

Intended COE Rebate Details

COE Expiry Date: 28 Jul 2018

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$16,700.00

COE Rebate Amount: \$1,360.00

Total Rebate Amount: \$8,344.00

The information contained herein is correct as at 04 Oct 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 17 Sep 2017 at 12:38 AM

Vantage Automotive Limited
305 Alexandra Road S'pore 159942

Date : 07.08.2017

RE: VEHICLE REPAIR QUOTATION

Insurance Company
Vehicle Reg No
Name of Insured
Policy Number
Date of Accident
Tyre of Claim
Model
Chassis No

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SFB1397S
CHUA BENG TAT
02.10.2017
TP CLAIM
HONDA STREAM 1.8X
RN61064846

Rasul
Hp 90010068
7 days
13/10/17 @ 1200
Resurvey by print

We are please to submit our estimate of repairs to the above mention vehicle.

	Parts	Labour
1 FRT RHS FENDER	\$ 486.20 <i>R</i>	
2 FRT RHS DOOR	\$ 860.00 <i>PH</i>	<i>1885.10</i>
3 FRT RHS DOOR TAPE	\$ 48.60 <i>na</i>	
4 FRT RHS DOOR OUTER WEATHERSTRIP	\$ 102.20 <i>new</i>	<i>20%</i>
5 REAR RHS DOOR	\$ 836.60 <i>PH</i>	
6 REAR RHS DOOR TAPE	\$ 37.70 <i>na</i>	<i>1508.08</i>
7 REAR RHS DOOR OUTER WEATHERSTRIP	\$ 102.20 <i>Xsue</i>	

Total Parts = \$ 2,473.50

1	SUNDRIES <i>new</i>	\$	100.00 <i>30</i>
2	REPLACE / REPAIR FRT RHS FENDER, FRT RHS DOOR REAR RHS DOOR, REAR RHS QUARTER PANEL	\$	<i>1000</i> 2,400.00 <i>1800 + 600</i>
3	RESpray FRT RHS FENDER, FRT RHS DOOR, REAR RHS DOOR, REAR RHS QUARTER PANEL	\$	<i>1000</i> 3,000.00 <i>2400 + 600</i>
4	WIRING CONNECTION & CHECK	\$	150.00 <i>120</i>
5	TO TRANSFER FRT RHS DOOR MECHANISM & DOOR GLASS	\$	300.00 <i>5970</i>
6	TO TRANSFER REAR RHS DOOR MECHANISM & DOOR GLASS	\$	300.00
7	WHEEL ALIGNMENT	\$	600.00 <i>300</i>
8	TO REMOVE & REPLACE REAR RHS SUSPENSION SYSTEM	\$	750.00 <i>? 600 ? X 100</i>
9	TUFF KOTE @ \$60 PER PANEL	\$	240.00 <i>120</i>
10	SEALANT FOR BODY PANEL @ \$90 PER PANEL	\$	270.00 <i>180</i>
11	WHEEL BALACING @ \$60 PER PCS	\$	120.00
10	COMPUTER DIAGNOSTIC CHECK & REPROGRAMME	\$	600.00 <i>300</i>
Total (Labour)		\$	8,830.00
Sub Total :		\$	11,303.50 <i>12503.50</i>
GST 7%		\$	791.25
Grand Total :		\$	12,094.75

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

WONG GUO XIANG (64777409 / 83833190)

Vantage Automotive Limited

305 Alexandra Road S'pore 159942

Date : 07.08.2017

RE: VEHICLE REPAIR QUOTATION

Insurance Company
Vehicle Reg No
Name of Insured
Policy Number
Date of Accident
Tyre of Claim
Model
Chassis No

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SFB1397S

CHUA BENG TAT

02.10.2017

TP CLAIM

HONDA STREAM 1.8X

RN61064846

Rasul
Hp 90010068
7 days
13/10/17 P1200
Resurvey by print

We are please to submit our estimate of repairs to the above mention vehicle.

	Parts	Labour
1 FRT RHS FENDER	\$ 486.20 R	
2 FRT RHS DOOR	\$ 860.00 PH	1885.10
3 FRT RHS DOOR TAPE	\$ 48.60 ne	
4 FRT RHS DOOR OUTER WEATHERSTRIP	\$ 102.20 ne	20%
5 REAR RHS DOOR	\$ 836.60 PH	
6 REAR RHS DOOR TAPE	\$ 37.70 ne	1508.08
7 REAR RHS DOOR OUTER WEATHERSTRIP	\$ 102.20 X	

Total Parts = \$ 2,473.50

1	SUNDRIES	\$	100.00 300
2	REPLACE / REPAIR FRT RHS FENDER, FRT RHS DOOR, REAR RHS DOOR, REAR RHS QUARTER PANEL	\$	2,400.00 1800 2400
3	RESPRAY FRT RHS FENDER, FRT RHS DOOR, REAR RHS DOOR, REAR RHS QUARTER PANEL	\$	3,000.00 2400 3000
4	WIRING CONNECTION & CHECK	\$	150.00 120
5	TO TRANSFER FRT RHS DOOR MECHANISM & DOOR GLASS	\$	300.00 5970
6	TO TRANSFER REAR RHS DOOR MECHANISM & DOOR GLASS	\$	300.00
7	WHEEL ALIGNMENT	\$	600.00 300
8	TO REMOVE & REPLACE REAR RHS SUSPENSION SYSTEM	\$	750.00 7600 8
9	TUFF KOTE @ \$60 PER PANEL	\$	240.00 120
10	SEALANT FOR BODY PANEL @ \$90 PER PANEL	\$	270.00 180
11	WHEEL BALACING @ \$60 PER PCS	\$	120.00
10	COMPUTER DIAGNOSTIC CHECK & REPROGRAMME	\$	600.00 300
Total (Labour)		\$	8,830.00
Sub Total :		\$	11,303.50
GST 7%		\$	791.25
Grand Total :		\$	12,094.75

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

WONG GUO XIANG (64777409 / 83833190)

Business Registration No. 53055563L GST Registration No. M2-0000551-1
305 Alexandra Road Singapore 159942
Tel: 64777409 Fax: 64777398



Date: 13.11.2017

NO.	Supplementary / Check Items Parts	Part Number	Price
			\$ -

Price

	TO REPAIR RHS ROCKER PANEL	\$ 600.00
	TO RESPRAY RHS ROCKER PANEL	\$ 600.00
	Total Parts And Labour	\$ 1,200.00

Raised By Technician	Approved By CSA	Acknowledge By Parts Assistant	Resurvey by	BO Parts: Yes / No ETA: _____
---------------------------------	----------------------------	---	--------------------	--

VANTAGE AUTOMOTIVE LIMITED

(A Sime Darby Motors Company)

Co. Regs. No. 192600045M GST Regs. No. M2-0000551-1

305 Alexandra Road

Vantage Automotive Centre

Singapore 159942

Service Booking: 6477 7368

Vantage 24-Hour Assist: 6473 8588

Fax: 6477 7300

**SERVICE TAX INVOICE**

RE-PRINT

REPAIR ORDER NO. B9 37203	Date IN 30/10/2017	Invoice Number	Page No. 1 of 1
	Payment Term 30 Days From Invoice	Invoice Date	
	Customer Service Advisor Wong Guo Xiang	Invoice By Wong Guo Xiang	

CUSTOMER INFORMATION	INVOICE TO 14356
Chua Beng Tat	First Capital Insurance Limited
Blk 370H Alexandra Road	36 Robinson Road
#13-07	#16-01 City House
	Singapore 068877
Singapore 159961	

REGISTRATION No.	CHASSIS No.	STOCK No.	REGISTRATION DATE	MODEL	MILEAGE
SF81397S	RN61064846	527210	29/07/2008	HONDA STREAM	194329

CODE	DESCRIPTION	UNITS	NETT
	SUNDRIES	1	30.00
	REPLACE/REPAIR FRT RHS FENDER,FRT RHS DOOR,REAR RHS DOOR,REAR RHS QUARTE PANE;	1	2,400.00
	RESPRAY FRT RHS FENDER,FRT RHS DOOR,REAR RHS DOOR,REAR RHS QUARTER PANEL	1	3,000.00
	WIRING CONNECTION & CHECK	1	120.00
	TRANSFER FRT RHS DOOR MECHANISM & DOOR GLASS	1	300.00
	TRANSFER REAR RHS DOOR MECHANISM & DOOR GLASS	1	300.00
	WHEEL ALIGNMENT	1	300.00
	TUFF KOTE @ \$60 PER PANEL	1	120.00
	SEALANT FOR BODY PANEL @ \$90 PER PANEL	1	180.00
	WHEEL BALANCING @ \$60 PER PCS	1	120.00
	COMPUTER DIAGNOSTIC CHECK & REPROGRAMME	1	300.00
Sub-Total :			7,170.00

CODE	DESCRIPTION	UNITS	NETT
N H67010-SMC-000ZZ	FRT RHS DOOR	1	860.00
N H67324-SMC-003	FRT RHS DOOR TAPE	1	48.60
N H67510-SMC-000ZZ	REAR RHS DOOR	1	836.60
N H67824-SMC-003	REAR RHS DOOR TAPE	1	37.70
N H72410-SMA-003	FRT RHS DOOR OUTER WEATHERSTRIP	1	102.20
Sub-Total :			1,885.10

Attending CSO : Wong

Should you require further explanation, please reach me at 64777409

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	9,055.10
Labour Charges	7,170.00	Less Insurance Excess	S\$	0.00
Parts Charges	1,885.10	GST @ 7%	S\$	633.86
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	9,688.96
		Less Deposit/Voucher	S\$	0.00
Computer generated invoice. No signature is required.			Amount Payable	S\$ 9,688.96

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17019527/R1rbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 22-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6518T	Veh. Inspected	SFB 1397S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17009338MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	10/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM 1.8X A	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	RN61064846	Colour	BROWN	
Odometer	193639	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/10/2017	Inspection Date	13/10/2017	
Survey held at	VANTAGE AUTOMOTIVE LTD 305 ALEXANDRA ROAD SINGAPORE 155942			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFB 1397S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT RHS FENDER (SN)	TO REPAIR SEE LABOUR	486.20	-
1	FRT RHS DOOR (SN)	BENT	860.00	860.00
1	FRT RHS DOOR TAPE (SN)	NECESSARY	48.60	48.60
1	FRT RHS DOOR OUTER WEATHERSTRIP (SN)	NECESSARY	102.20	102.20
1	REAR RHS DOOR (SN)	BENT	836.60	836.60
1	REAR RHS DOOR TAPE (SN)	NECESSARY	37.70	37.70
1	REAR RHS DOOR OUTER WEATHERSTRIP (SN)	SERVICEABLE	102.20	-
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
			2,573.50	1,915.10
LABOUR				
	REPLACE/REPAIR FRT RHS FENDER,FRT RHS DOOR,REAR RHS DOOR,REAR RHS QUARTER PANEL.		3,000.00	2,400.00
	RESPRAY FRT RHS FENDER,FRT RHS DOOR,REAR RHS DOOR,REAR RHS QUARTER PANEL.		3,600.00	3,000.00
	WIRING CONNECTION & CHECK.		150.00	120.00
	TO TRANSFER FRT RHS DOOR MECHANISM & DOOR GLASS.		300.00	300.00
	TO TRANSFER REAR RHS DOOR MECHANISM & DOOR GLASS.		300.00	300.00
	WHEEL ALIGNMENT.		600.00	300.00
	TO REMOVE & REPLACE REAR RHS SUSPENSION SYSTEM.	NOT NECESSARY	750.00	-
	TUFF KOTE.		240.00	120.00
	WHEEL BALANCING.		120.00	120.00
	COMPUTER DIAGNOSTIC CHECK & REPROGRAMME.		600.00	300.00
	SEALANT FOR BODY PANEL.		270.00	180.00
	-		-	-
	-		-	-
	-		-	-
			9,930.00	7,140.00
GRAND TOTAL			12,503.50	9,055.10

Report Ref No. CS/FCI17019527/R1rbn2



RECOMMENDED COST OF REPAIRS			9,055.10
-----------------------------	--	--	----------

Report Ref No. CS/FCI17019527/R1rbn2

MARKET VALUE: \$18,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$8,344.00=NETT VALUE: \$9,656.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.