




SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim	S7M002W5
Reference	None 
Loss Date	11 October 2017
Request Date	16 October 2017
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Accelerated survey and authorize

Actions

Next Step Wait for: Approve
invoice

[Add Invoice](#)

Vehicle Information

Incident SKX9661B
Vehicle
Registration #

Make TOYOTA

Model HARRIER 2.0

Service Address

Blk 1008, , , 159722

Primary Contact/Insured

TEO CHIANG KEI ANDREW
BLK 59 STRATHMORE AVENUE, 142059,
Singapore

ANDREW_CK@HOTMAIL.COM

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions Excess 400

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Add

REFERENCE #	DESCRIPTION	TOTAL AMOUNT	SUBMITTED	STATUS	PAID DATE	WITHDRAW
AC1804337	Final Invoice	\$160.50	25/4/18 5:02 PM	Waiting for Approval		<div></div>

Totals

Outstanding Invoices	\$160.50	Rejected and Withdrawn	\$0.00
Payments Made	\$0.00		
Total	\$160.50		