

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref: CS3/LPC17013103/Stbs2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date: 26-12-2017 Code: LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	GBA 390U	Veh. Inspected	FBJ 741T
	Policy No.	Z/16/VC00/099044	Coverage (\$)	0.00
	Claim No.	16/17/17/VC00/019961	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	17/10/2017
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA	c.c	134
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	MH355S004DK126018	Colour	PURPLE
	Odometer	182826	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	70/90-17	DUNLOP	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	90/80-17	DUNLOP	6 mm
	L/H Rear Tyre			mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	28/06/2017	Inspection Date	06/07/2017
	Survey held at	ENG SOON PAINTING SVC		
		BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	3 Working Days	