Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE Licence Number S 8 7 0 4 0 0 9 G Name MUHAMMAD IBNU'ATTAILLAH Birth Date 21 Feb 1987 TISSUE Date 05 Aug 2014

Driving License YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES) EFFECTIVE DATE Motor Cars=< 3000kg with =<7 passengers, exclusive 07 Oct 2009 of the driver; and other motor vehicles =< 2500kg Class 3 Licence No: S8704009G NP 428A

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00 Singapore 048580 Tel (65) 6224 0010 Fax (65) 6224 0030 Operating Hours : Monday to Friday, 09:00 - 17:00 UEN: \$665500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre

with whom you submitted the Original Report. **ADDENDUM** (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS: _Vehicle Registration No: _GBF9602Z Original Report No : M8HH17133173 Name(as shown in NRIC): DAIMLER FLEET MANAGEMENT SINGAPORE NRIC/FIN/Passport No : 199803778Z (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate Singapore() Address Mobile No.: 91728488 Contact (Tel) . too_tong.tan@daimler.com Email Address _Time of Accident : 14:30 05/08/2017 Date of Accident Place of Accident : ALONG WEST COAST RD Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD (B) ADDITIONALINFORMATION / AMENDMENTS: I have made a report on the above mentioned accident and would like to include additional information or make the following amendments: AMEND TO OWN DAMAGED CLAIMS My Reporting Centre Personnel's Signature Policyholder / Driver's Signature

Name: NOR ATIKA

NRIC/FIN No.: G2055450P Date: 11/10/2017

Date:



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M Z 400

(1)

COMPREHENSIVE COMMERCIAL MOTOR

CERTIFICATE NO. 999995177/100805919-00003

(The below excess is subject to GST) OWN DAMAGE EXCESS \$\$1200.00

WINDSCREEN EXCESS S\$100.00

SUM INSURED S\$1.00 INSURING WITH COE/PARF Yes

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

GBF9602Z

Daimler Fleet Management Singapore Pte Ltd

3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT

4) DATE OF EXPIRY OF INSURANCE

31 Dec 2017

02 May 2017

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*

Any person who is driving on the Insured's order or with their permission

Please refer to policy terms and conditions.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE*

Use for the carriage of passengers or goods in connection with the Insured's business. Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired.

The Policy does not cover: 1) Use for tuition, driving test, racing, pace-making, reliability trial or speed-testing. 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle. 3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired. 4) Use for any purpose in connection with the Motor Trade.

SOLE AGENT'S WORKSHOP: For new vehicles less than 3 years from initial registration, you have the option for claims-related repairs to be done at Sole Agent's workshop.

- repairs to be done at Sole Agent's workshop.

 APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

 1. ComfortDelgro Engrg 205 Braddell Rd (Tel: 63837118) 2 / Glass-Fix 52 Ubi Ave 3 (Tel: 62780887) For windscreen only

 3. Ethoz 30 Bukit Batok Cres(Tel:66547777) 4. DPS Body & Paint (Subsidiary of C&C) 209 Pandan Gardens (Tel: 65684501)

 5. Kan Fook Sing Motor 61 Defu Lane 12 (Tel: 67479560) 6. Lai Huat (Meng Kee) Motor 21 Sin Ming Ind (Tel: 64538110)

 7. Mova Automotive 1008 Bukit Merah Lane 3 (Tel: 62723892) 8. Progressive Automotive 3022A Ubi Rd 1 (Tel: 67415336)

9, SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Not Included

* NAMED DRIVER NA

HIREPURCHASE COMPANY NA

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 15 Jun 2017

030023-000 JARDINE LLOYD THOMPSON PTE LTD 138 MARKET STREET #07-01 CAPITAGREEN SINGAPORE 048946

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCDSK



ESTIMATE FOR GBF9602Z*M

AIG Asia Pacific Insurance Pte.

MOTOR CLAIM DEPARTMENT

78 SHENTON WAY #08-16

AIG BUILDING

64191000

SINGAPORE 079120

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Vehicle & Document Information

34049 WIP No

GBF9602Z*M / 02/05/2017 Reg No/Reg Date

07/08/2017/ 6285 Date In/Mileage

WDF44760323272799 Chassis No.

Engine No

R9MA503C016413 MBCV/Vito 109KA/ L 4X2 3200 Ma Make/Model

Colour/Trim

914 Arctic White / NA NOT APPLICABLE

Operator CSE Account No Date/Time Printed Terms 610 / Philip Cheong WS 13/10/2017/ 12:18 WA000007 Credit Amount Unit Price Disc% Qty Description of Goods / Services 120.00

VEHICLE TOWING FROM 4 WOOLLERTON PARK TO 188 PANDAN LOOP

A 26100501 CHECK TRANSMISSION OPERATION

VEHICLE AFTER WARM UP, AFTER ENGAGE GEAR, PRESS ACCELERATE BUT

VEHICLE CANNOT MOVE

A 00000099 Add job to remove front bumper

A 20400002

Ltd

REPLACE RADIATOR

A 20114001

REPLACE COOLANT INCLUDING ANTIFREEZE, CHECK FOR LEAKS

A 88115701

BUMPER WITH INTEGRATED FRONT RADIATOR GRILLE REPLACE

A 88185801

BRACKET FOR FRONT BUMPER REPLACE (BUMPER REMOVED)

A 88193601

UPPER CROSSMEMBER REMOVE / INSTALL (BUMPER REMOVED)

A 09820001

ENGINE AIR INTAKE DUCT UPSTREAM OF AIR FILTER REPLACE

A 09881001

REPLACE AIR DUCT

A 83176201

EXTRACT REFRIGERANT, CHECK FOR LEAKS, REFILL (WHEN WORKING ON AIR CONDITIONING)

A 83654303

CONDENSER REMOVE/INSTALL AND, IF NECESSARY, REPLACE (WITH SYSTEM DRAINED) ALL AIR CONDITIONERS

A 83662201

DRIER CARTRIDGE REPLACE

M FREON GAS

FREON GAS

S SUBADJ

100.00

60.00

120.00 /00

249.00200

120.00/00

12.00 XM

120,00/00

60.00

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6771 4389 Fax: 6775 6310 www.mercedes-benz.com.sg



ESTIMATE FOR GBF9602Z*M

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Vehicle & Document Information

WIP No

34049

Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16

AIG Asia Pacific Insurance Pte.

GBF9602Z*M / 02/05/2017 Reg No/Reg Date 07/08/2017/ 6285 Date In/Mileage

AIG BUILDING

WDF44760323272799

SINGAPORE 079120

R9MA503C016413

64191000

MBCV/Vito 109KA/ L 4X2 3200 Ma

Make/Model Colour/Trim

Chassis No

Engine No

914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Prin	ited	CSE	Operator				
WA000007	Credit	13/10/2017/	12:18	WS	610 / Philip Cheong				
		Description	n of Goods	/ Services		Qty	Unit Price	Disc%	Amount
REFER PO (adjust M BRACKET M BRACKET M COOLANT M CROSS ME M SUPPORT M SCREW M RIVET M AIR DUCT M AIR DUCT M MOUNTING M REFRIGER M TRIM BUN M TRIM PAN M TRIM PAN M RADIATOR M COVER HO M STUD M *P NUT M BRACKET M BRACKET M LOCK M NUT	RADIATOR RADIATOR MBER T T T G FRAME RANT CONDEI MPER NEL WHEEL NEL WHEEL R ANTIFREE OOD	NSER HOUSING HOUSING ZE	TA	Ho	FFICIAL 90010068 Fdays 17 81550 CHS:TBA Honsed on 64 report	1.00 1.00 1.00 1.00 1.00 3.00 4.00 1.00 1.00 1.00 1.00 1.00 1.00 1	23.59 23.59 408.11 216.44 90.12 1.49 4.16 53.85 53.56 97.59 90.31 540.36 651.08 129.47 129.47 45.18 398.81 3.08 1.91 16.78 1.21 20.19 1.30 2.23 88.88 8.36	10.00 10.00 10.00 10.00 10.00 10.00 10.00 10.00 10.00 10.00 10.00 10.00	21.23 21.23 367.30 81.11 4.02 48.46 48.20 87.83 81.28 14.98 87.83 16.52 17.46 18.32 18.32 19.48 10.48 10.58 10
200 02 00 00 00 00 00 00 00 00 00 00 00	& accepted b	y d company stam	the F To r To r Par Thir No	Repairer of I esurvey before display damage its prices are si diparty survey dilegal modifical plementary its	Iltanta hence notify the following: Inafter spray painting ad part(s) during resurvey Inafter to confirmation Is on a "Without Prejudice" basis Inafter spray and Inafter spray and	7% (200-00-00	Net 4202.04 Payable	294.14

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Validity or this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6771 4389 Fax: 6775 6310 www.mercedes-benz.com.sg

4705.59



- Picture -

Mode

MD mode

Mod. des. overview PANEL VAN WHEELBASE 3200 MM, LONG OVERHANG

FIN/MD

WDF 44760323272799 Catalog

VIN

WDF44760323272799

Major assembly:

Sales designation 109KAV L 4X2 3200

Major assembly MD

Assortment class

Van

Group

62 - COWL, FRONT PANEL

Market

Europe


Subgroup

090 - FRONT END CENTER PIECE

PANELING

Picture number

B62090000180.160323



- Picture -

Mode

MD mode

Mod. des. overview PANEL VAN WHEELBASE 3200 MM, LONG OVERHANG

FIN/MD

WDF 44760323272799 Catalog

60V

VIN

WDF44760323272799

Major assembly:

Sales

designation 109KA/ L 4X2 3200

Major assembly MD

88 - BUMBER/FENDER/ENGINE HOOD

Assortment class

Group

Market


Europe

Subgroup

060 - FRONT BUMPER

Picture number

B88060000171.150910



- Picture -

Mode

MD mode

Mod. des. overview PANEL VAN WHEELBASE 3200 MM, LONG OVERHANG

FIN/MD

WDF 44760323272799 Catalog

60V

VIN

WDF44760323272799

Major assembly: Major assembly MD

Sales designation 109KA/ L 4X2 3200 Assortment class

50 - RADIATOR

Van

Group

Market

Europe

Subgroup

030 - RADIATOR

Picture number

B50030000044.170321

