



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917937 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liubro@ymail.com

Invoice/Ref No: GBB8426T171008

Estimate

Customer

Name: EQ Insurance Company Limited

Address: Motor Claims Department

5 Maxwell Road #17-00

Tower Block MND Complex Singapore 069110

Date: 17-10-17

Vehicle No: GBB8426T

Model/Make: Fiat Doblo Cargo

1.9 MJTD

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Lh Fender <i>464.08</i>	\$ 780.00	<i>500.50</i> <i>one</i> <i>11</i> <i>20</i> <i>280</i> <i>320</i>
2	Fender Signal Lamp <i>45.32</i>	\$ 487.70	
3	Head Lamp	\$ 768.00	
	To check all wiring & electrical component for proper function	\$ 50.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 400.00	
	To putty & spray painting & including touch up paint on accident affected areas	\$ 400.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 2,885.70

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

\$ -

SDLS:

not Affirmed
MLK

L/S \$ 850
3 day.

19/10/17

when the other repair



M/s Liu's Brother Auto Engrg Wks

P- 509.4

102

488.46

1078.46

862.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: