

Vehicle no. : SJQ7855X
 Model : Audi A4 1.8

Estimate – Parts(s)

S/N	Qty	Descriptions	Amount
-----	-----	--------------	--------

LIST ITEMS:-

1.	1 pc	Rear bumper upper	\$1423.80
2.	1 pc	Rear bumper spoiler	\$205
3.	2 pcs	Rear bumper side retainer @\$30each	\$60
4.	1 set	Rear bumper fasteners	\$36
5.	1 pc	Rear bumper towing cover	\$32
6.	1 pc	Rear centre retainer	\$162
7.	1 pc	Rear Reinforcement	\$456.25
8.	2 pcs	Rear reinforcement brackets	\$306
9.	1 pc	Air Vent	\$65.25
10.	1 pc	Bootlid	\$1554.00
11.	1 pc	Bootlid inner lock	\$172.30
12.	1 pc	Bootlid chrome garnish	\$167.25
13.	1 set	Bootlid chrome garnish clips @ \$10 each	\$60
14.	1 pc	Bootlid logo emblem "A4"	\$70.50
15.	1 pc	Bootlid "Audi" emblem	\$92.50
16.	1 pc	Bootlid "1.8" emblem	\$67.25
17.	1 pc	Bootlid lamp (LH/RH)	\$382.00
18.	2 set	Bootlid lamp fasteners	\$36.00
19.	2 pcs	Bootlid hindges garnish	\$195.00
20.	2 pcs	Bootlid spring	\$157.00
21.	2 pcs	Bootlid hinges @ 167x2	\$334
22.	1 pc	Bootlid weatherstrip	\$169.00
23.	1 pc	Bootlid hindge cover	\$18
24.	1 pc	Bootlid lock striker	\$47.50
25.	1 pc	Bootlid inner trim board	\$205.50
26.	1 set	Bootlid inner trim board fasteners	\$36.00
27.	2 pcs	Bootlid rubber damper	\$36.00
28.	2 pcs	Rear license plate lamp @ 38 each	\$76
29.	1 pc	Taillamp LH/RH	\$790.00
30.	1 pc	Taillamp lower panel (LH/RH)	\$391.00
31.	2 sets	Taillamp fasteners	\$45.00
32.	2 pcs	Taillamp gasket	\$70.00
33.	1 pc	Rear end panel assy complete	\$1216.00
34.	1 pc	Rear end panel top garnish	\$235
35.	1 set	Rear end panel top garnish fasteners	\$32
36.	1 pc	Spare tyre panel	\$1412.00
37.	1 pc	Spare tyre panel side extension RH	\$370.00
38.	1 pc	Spare tyre panel board	\$297.00
39.	1 pc	Rear exhaust bracket	\$63
40.	1 pc	Rear exhaust muffler	\$1275
41.	1 pc	Rear exhaust chrome tip	\$230
42.	1 pc	Rear exhaust pipe	\$1272.50
43.	1 pc	Front bumper	\$2890
44.	2 pcs	Front bumper retainer	\$210
45.	1 set	Front bumper clips	\$38
46.	1 pc	Front bumper grille w chrome	\$2190.70

\$19,649.30

Less 5%

\$982.46

Total

\$18,666.84

SPECIAL NETT ITEMS:-

1.	1 pc	Rear number plate	\$60
2.	1 pc	End panel sealant	\$60
3.	4 pcs	Reverse sensor	\$744
4.	1 pc	Front number plate	\$60

\$ 864.00

Vehicle no. : SJQ7855X

Model : Audi A4 1.8

Estimate - Labour(s)

S/N	Qty	Descriptions	Amount
-----	-----	--------------	--------

LABOUR & OTHER CHARGES:-

To panel beat and renewal of all necessary damaged body parts (Rear bumper, Rear end panel, Bootlid, Taillamp panel N/s O/s, Rear fender N/s O/s, Rear fender inner panel N/s O/s)

\$ 1,800.00

To check wiring and rewire

\$ 80.00

To remove and reinstall bootlid components

\$ 80.00

To remove and reinstall rear boot upholstery

\$ 120.00

To remove and reinstall reverse sensor

\$ 140.00

Programme setting

\$ 220.00

To anti-rust

\$ 160.00

To putty and spray-paint of affected areas

\$ 1,600.00

To remove & refix rear exhaust muffler

\$ 120.00

To remove & align rear chassis member

\$ 350.00
