

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Wancong

Date: 31 Oct 2017

Preliminary Advice

Insured Vehicle No	: SGX1030Y	Accident Date	: 24/10/2017
TP Vehicle No	: SHD9924J	Assignment Date	: 30/10/2017
Make	: HONDA STREAM	Est. Duration of Repair	: 3 days
Date of Inspection	: 25/10/2017		
Inspection At	: Trans-cab Auto Services (HQ) NO. 2 ANG MO KIO ST 63 Singapore 569111		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...front O/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,166.53
Revised Amount	:S\$	7,050.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,050.00
Lump Sum Repair	:S\$	7,050.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.