

10/10/17

ASS: REC BY:

REF: CS/MSG17020618/T1rb/V

Special Instructions

Supervisor
Menmen

Taufik

ASSIGNMENT (Office)

From (Person)

Catherine thia

to

MSG

Date/Time

27/10/17 @ 3.42pm

Estimated Cost

Bill to

OD / IP WSY / IP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No.

SLB 4454U

Insured:

FBJ 6426P

at Workshop no.

(France) Cycle & Carriage

Tel:

6568 4501

of

209 Pandan Gardens

Policy No.

MSD / VMT / 16-348522-CA

Claim No.

MSC / V / 17-001243

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.B.

3/8/17

CA / REV / REP. / REV 24 HRS

1up

L.O.D. Estimate

Date/Time

3.49pm @ 27/10/17

Person Contacted

Edwin

Vehicle IN / OUT

Date/Time

Action/Instructions (✓) Estimate

SLB 4454U - NA/MSG17016194/13-D-O-A: 3/8/2017

FBJ 6426P - NA/MSG17016194/13-D-O-A: 3/8/2017

Sent pols thru menmen

11/4/18

Confirm P/P \$6358, 7 days

Red: \$4551.00, 42%.

Surrey

Tanglin

REF:

MS16

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: EdwinVeh No: SLK44545 Yr Regn: 2016, AprilType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Given C4 Cacho cc 1199Colour: white A/C: Insured / Std / NI / NASp. Reading: 285 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF70PHM ZK6ES10816Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 1 2BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 27/10/17Survey held at CSC Roadster GdnDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 11 APR 2018

Date/Time. File Pass to?

☐ : Preli. Report☒ : Final Report1) typist

Date/Time. File Return to?

2) _____

Days Of Repair: 1Resurvey No. of Trip: 1Survey Fee: 360

Transportation: _____

Add Fee:

☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

) S - RS. \$ _____

) Photos _____

) Others _____

TOTAL

Report Format: TPLump Sum / I.B.I: (\$ 6358.00)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17020618/T1rb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 27-10-2017		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBJ 6426P	Veh. Inspected	SLB 4454U	
Policy No.	MSD/VMT/16-348522-CA	Coverage (\$)	0.00	
Claim No.	MSC/V/17-001243	Excess (\$)	0.00	
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	27/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/08/2017	Inspection Date		
Survey held at	CYCLE & CARRIAGE FRANCE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Aug 2017		27 Oct 2017 15:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [\[Created by insurer\]](#)

Insured:	TAN SWEE MENG, ID: S7282466J		
Main Claimant:	LEE CHEE SENG THOMAS, ID: S1741854H		
Vehicle Reg. No.:	SLB4454U	Date of Loss:	03/08/2017 00:00 - :59
Claim Type:	TP / MSC/V/17-001243	Policy/Cover Note No.:	MSD/VMT/16-348522-CA Coverage: 21/08/2016 - 20/08/2017
Vehicle Reg. No. (Insured):	FBJ6426P	Policy No. (Claimant):	
		Excess:	
Repairer:	Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ) 209 PANDAN GARDENS, 609339 West Coast - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/10/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lee Chee Hwee

From: Margaret Loh
Sent: Thursday, 10 August, 2017 8:36 AM
To: Lee Chee Hwee
Cc: Catherine Thia; Jasmine Lok Kheng Kwei; Christopher Chionh; Jason Sim; Foo Ai Ngoh
Subject: FW: SLB4454U / FBJ6426P TP CLAIM DOA;03.08.2017
Attachments: [Untitled].pdf; CIMG7680.JPG; CIMG7681.JPG; CIMG7682.JPG; CIMG7683.JPG; CIMG7686.JPG

Follow Up Flag: Follow up
Flag Status: Flagged

Hi Dan,

FYNA

Best Regards

Margaret Loh
Admin Officer, Claims Services (Motor)
Direct line +65 6594 2553 | Direct fax +65 6225 7402 | margaret_loh@sg.msig-asia.com

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

-----Original Message-----

From: Agnes Lee
Sent: Tuesday, 8 August, 2017 5:37 PM
To: Jasmine Lok Kheng Kwei <jasmine_lok@sg.msig-asia.com>; Margaret Loh <margaret_loh@sg.msig-asia.com>
Cc: Christopher Chionh <christopher_chionh@sg.msig-asia.com>; Jason Sim <Jason_Sim@sg.msig-asia.com>; Foo Ai Ngoh <aingoh_foo@sg.msig-asia.com>
Subject: FW: SLB4454U / FBJ6426P TP CLAIM DOA;03.08.2017

-----Original Message-----

From: Edwin Abcede Caina [<mailto:edwin.caina@cyclecarriage.com.sg>]
Sent: 08 August 2017 13:24
To: Claims <claims@sg.msig-asia.com>
Cc: Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Tay Jian Ye <jianye.tay@cyclecarriage.com.sg>
Subject: SLB4454U / FBJ6426P TP CLAIM DOA;03.08.2017

Officer in Charge,

May check onto the liability of accident on the above mentioned vehicle.

Our client will wait for the liability before he send in his vehicle.

Thank you

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 01 Feb 2018

Preliminary Advice

Insured Vehicle No	: FBJ6426P	Accident Date	: 03/08/2017
TP Vehicle No	: SLB4454U	Assignment Date	: 27/10/2017
Make	: CITROEN C4 CACTUS	Est. Duration of Repair	: 7.00
Date of Inspection	: 27/10/2017		
Inspection At	: CYCLE & CARRIAGE FRANCE PTE LTD (PANDAN GARDENS) (HQ) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,909.00
Revised Amount	:S\$	7,951.00
Check Items (Estimated)	:S\$	1,598.00
Total	:S\$	9,549.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/08/2017 15:22
Date Of Accident	03/08/2017 17:45
Exact Location Of Accident	ALONG TPE TOWARDS SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB4454U
Insured/Policyholder	
Name Of Registered Owner	LEE CHEE SENG THOMAS
NRIC No	S1741854H
Email Address	LEETCS@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96286363
Alternative Phone No	OTHERS-96286363
Vehicle Particulars	
Manufacturer	CITROEN
Model	C4 CACTUS 1.2 PURETECH A/T
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1621481701
Cover Note Number	
Driver	
Name of Driver	LEE CHEE SENG THOMAS
NRIC No	S1741854H
Date Of Birth	27/06/1966
Occupation	INDOOR
Date Of Driving Pass	22/12/1993
Driving Experience	23 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96286363
Fax Number	
Contact Number	OTHERS-96286363
Email Address	LEETCS@SINGNET.COM.SG

Address	BLK 27D FLORA ROAD #04-01
Postcode	509741
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 030817 AT TIME AROUND 1745 WHILE DRIVING AT TPE LANE 1 TOWARDS SLE DIRECTION. SUDDENLY ALL THE VEHICLE IN FRONT BRAKE & STOP. I DID THE SAME & WAS HIT BY A BIKE BEHIND. AFTER WHICH WE SHIFT TO THE ROAD SIDE & EXCHANGE PARTICULAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBJ6426P
Vehicle Make/Model/Colour	MOTORBIKE
Details Of Properties	
Name of Driver	TAN SWEE MENG
NRIC/Passport Number	S7282466J
Contact Number	98325949
Address	APT BLK 508B YISHUN AVE 4 #02-66
Postcode	762508
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	TAN SWEE MENG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBJ6426P
Were seat belts worn?	
Was injured conveyed to hospital by ambulance?	NO
Address	APT BLK 508B YISHUN AVE 4 #02-66
Postcode	762508

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A - SLB44541
B - FBI 6426P

← @

← TPE

TANJONG AVE 12
Exit 3A

Describe Circumstances of the Accident

08/17

ON 03/17 AT TIME AROUND 1745 WHILE DRIVING AT THE LANE 1 TOWARDS SLE DIRECTION. SUDDENLY ALL THE VEHICLE IN FRONT BRAKE & STOP. I DO THE SAME & WAS HIT BY A BIKE BEHIND. AFTER WHICH WE SHIFT TO THE ROAD SIDE & EXCHANGE PARTICULAR.

Declaration

We declare the foregoing particulars are true in every respect.

[Signature] 2:50 PM
4 Aug 2017

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



owner / driver





中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

MX1FR 3H
AN0117A
Cov.Type: C

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DMPCSH1621481701	Engine No : 10W2150249504 Chassis No: VY7CPH012AGE510886
1. Index Mark and Registration Number of Vehicle	SLB44340	
2. Name of Policy Holder	LEE CHEE SEENG THOMAS	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	8 APRIL 2017	NAMED DRIVERS EX SECT. I\$5750.00 ADDITIONAL EX OTHER THAN NAMED DRIVERS: EX SECT. I - AGE <= 25.....\$53,000.00 EX SECT. I - AGE >= 26.....\$5300.00 * AGE AS AT DATE OF ACCIDENT EX ON WINDSCREEN\$4100.00
4. Date of Expiry of Insurance	7 APRIL 2018	
5. Persons or Classes of Persons entitled to drive *	(A) THE POLICYHOLDER. (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION. PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.	
6. Limitations as to use: *	USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS. THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD TUITION DRIVING TEST RACING PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE. EXCESS WHICHEVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS/THEFT) WILL BE DOUBLED. ONE TIME WAIVER OF EXCESS FOR THE FIRST \$5300 WILL APPLY TO THE INSURED AND NAMED DRIVERS IN THE EVENT OF OWN DAMAGE CLAIM AT OUR AUTHORISED WORKSHOPS FOR EACH POLICY YEAR.	
HIRE PURCHASE CO. : MAYBANK AS HP OWNER *Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.		

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).
Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Counterigned By:

Authorised Officer

Authorised Signatory

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-K

Invoice Name & Address				Owner Name & Vehicle Info		
MR LEE CHEE SENG THOMAS				Cust No/Name	/MR LEE CHEE SENG THOMAS	
BLK 27D FLORA ROAD				Reg No/Reg Date	SLB4454U / 08/04/2016	
#04-01				Date In/Mileage	/ 0	
SINGAPORE 509741				Chassis No	VF70PHMZBGE510886	
Contact No Mobile: 96286363				Engine No	10B2150249504	
				Make/Model	CIT/C4 CACTUS 1.2 PURETECH ETG SHINE	
				Colour/Trim	FC4 / 23F	
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
C5M00073	Cash	08/08/2017/ 13:13	QUE	261 / Edwin Caina	12753	
Description of Goods / Services				Qty	Unit Price	Disc% Amount
E PNT88000 RENEW & RE-ALIGN RR DAMAGED PORTION:						1800. 3000.00
RENEW TAILGATE & RR BUMPER						
REPAIR RR FLOOR PNL , RR END PNL & LHR FENDER						1260 2100.00
E PNT98000 RESPRAY RR BUMPER , RR END PNL , TAILGATE , LHR FENDER & RR FLOOR PNL				420		
E PNT88000 REMOVE & REFIT TAILGATE COMPONENTS						✓ 150.00
E PNT88000 REMOVE & REFIT RR FLOOR BOARD,TRIM & CARPET TO FACILITATE REPAIR						✓ 200.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM						30. 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST						✓ 300.00
USING HI-SCAN PRO TEST						
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS						80. 120.00
E PNT88000 REMOVE & REFIT TAILGATE WINDSCREEN GLASS						7. 300.00 X ⁿ
M SUNDRY SUPPLY RR-NUMBER PLATE WITH CASING						✓ 50.00
E PNT88000 RENEW REVERSE SENSOR						80 100.00
M SUNDRY SUPPLY RR WINDSCREEN SEALANT						148 80.00
M SUNDRY Sundries						20. 30.00
M SUNDRY SUPPLY C&C BADGE						✓ 40.00
M REAR BUMPER				1.00	835.00	0.00 de 835.00
M BUMPER SKIRT				1.00	386.00	0.00 de 386.00
M BMPR RUBBR BOOT LH				1.00	178.00	0.00 de 178.00
M BMPR RUBBR BOOT RH				1.00	178.00	0.00 de 178.00

Confirm & accepted by

Authorized signatory and company stamp

validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Company Reg No. 300609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
MR LEE CHEE SENG THOMAS		Cust No/Name	/MR LEE CHEE SENG THOMAS
BLK 27D FLORA ROAD		Reg No/Reg Date	SLB4454U / 08/04/2016
#04-01		Date In/Mileage	/ 0
SINGAPORE 509741		Chassis No	VF70PHMZBGE510886
Contact No Mobile: 96286363		Engine No	10B2150249504
		Make/Model	CIT/C4 CACTUS 1.2 PURETECH ETG SHINE
		Colour/Trim	FC4 / 23F

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	08/08/2017/ 13:13	QUE	261 / Edwin Caina	12753

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BRACKET SET	1.00	78.00	0.00	78.00
M BRACKET SET	1.00	103.00	0.00	103.00
M BUMPER BRACKET	1.00	72.00	0.00	72.00
M BUMPER ABSORBER AR	1.00	263.00	0.00	263.00
M LOW RR PAN FIX	1.00	107.00	0.00	107.00
M TAILGATE ASS	1.00	1141.00	0.00	1141.00
M GLASS WEDGE	12.00	1.00	0.00	12.00
M TAILGATE CAP	1.00	559.00	0.00	559.00
M SEAL WASHER	1.00	50.00	0.00	50.00
M TAILGATE FIX	1.00	223.00	0.00	223.00
M SENSOR	4.00	131.00	0.00	524.00

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Tan Jia 97495749

SURVEYOR SIGNATURE: [Signature]

DATE: 27/11/12 @ 17:15

REMARKS: wp

Repair before paint

7 days

sur@lkkauto.com

Confirm & accepted by

Parts	4,709.00
Labour	6,200.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	320.00
Total (w/o GST)	11,229.00

Authorized signatory and company stamp

Validity of this estimate is 34 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



FINALIZATION

DATE : 26/3/18
VEHICLE NO : SLB4454U
SURVEY BY : TAUFIKH AKK
FINALISE BY : Yusof
WIP NO : 12753

Materials	: \$ <u>2318.00</u>
Labour	: \$ <u>4010.00</u>
Total	: \$ <u>6358.00</u>
Less Excess	: \$ <u>—</u>
Sub - Total	: \$ <u>6358.00</u>
GST	: \$ <u>445.06</u>
Grand Total	: \$ <u>6803.06</u>

☒ REVERT BACK WITHIN 7 DAYS
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEY REPORT REQUIRED

REPAIR TOOK 8 DAYS + 1 Days (2 Weekends)
CLAIM LOR + Days (Public Holidays)
= 12 Days

PRO-FORMA INVOICE

THIS IS NOT AN OFFICIAL TAX INVOICE

Company Reg No. 200606327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR LEE CHEE SENG THOMAS BLK 270 FLORA ROAD #04-01 SINGAPORE 509741 Contact No Mobile: 96286363	Cust No/Name /MR LEE CHEE SENG THOMAS Reg No/Reg Date SLB4454U / 08/04/2016 Date In/Mileage 27/10/2017/ 28570 Chassis/Package VF70PHMZBGE510886 /FS515N Engine No 10B2150249504 Make/Model CIT/C4 CACTUS 1.2 PURETECH ETG SHINE Colour/Trim FC4 / 23F

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00073	Cash	22/03/2018/ 19:58	TLE	447 / YusofH	12753			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1800.00 ✓
RENEW & RE-ALIGN RR DAMAGED PORTION:								
RENEW RR BUMPER								
REPAIR RR END PNL & TAILGATE								
E PNT98000								1260.00 ✓
RESPRAY RR BUMPER , RR END PNL & TAILGATE								
E PNT88000								150.00 ✓
REMOVE & REFIT TAILGATE COMPONENTS								
E PNT88000								200.00 ✓
REMOVE & REFIT RR FLOOR BOARD,TRIM & CARPET TO FACILITATE REPAIR								
A 54900099								30.00 ✓
CHECK WIRING & ELECTRICAL SYSTEM								
A 100289C								300.00 ✓
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								80.00 ✓
APPLY ANTI CORROSION ON AFFECTED AREAS								
E PNT88000								80.00 ✓
REMOVE & REFIT REVERSE SENSOR								
M SUNDRY								20.00 ✓
Sundries								
M SUNDRY								40.00 ✓
SUPPLY C&C BADGE								
Z TEXT								
TP CLAIM-MSIG								
SURV:TAUFIKH 26.10.2017								
DOA:03.08.2017								
7 DAYS								
S SPECIALISTJOB								50.00 ✓
TO SUPPLY ONE PC OF REAR LICENSE PLATE								
RECTANGULAR & BLACK								
X	REAR BUMPER				1.00	835.00	0.00	835.00 ✓
X	BUMPER SKIRT				1.00	386.00	0.00	386.00 ✓

This is not an official tax invoice. This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

THIS IS NOT AN OFFICIAL TAX INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR LEE CHEE SENG THOMAS BLK 27D FLORA ROAD #04-01 SINGAPORE 509741 Contact No Mobile: 96286363	Cust No/Name /MR LEE CHEE SENG THOMAS Reg No/Reg Date SL84454U / 08/04/2016 Date In/Mileage 27/10/2017/ 28570 Chassis/Package VF70PHMZBGE510886 /FS515N Engine No 10B2150249504 Make/Model CIT/C4 CACTUS 1.2 PURETECH ETG SHINE Colour/Trim FC4 / 23F

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	22/03/2018/ 19:58	TLE	447 / Yusoffi	12753

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BMPR RUBBR BOOT LH	1.00	178.00	0.00	178.00 ✓
X LOW RR PAN FIX	1.00	107.00	0.00	107.00 ✓
X GLASS WEDGE	10.00	1.00	0.00	* ALL 10.00 ✓
X TAILGATE CAP	1.00	559.00	0.00	559.00 ✓
X SEAL WASHER	1.00	50.00	0.00	50.00 ✓
X TAILGATE FIX	1.00	223.00	0.00	223.00 ✓

Pro Forma

* PRICE CHANGE

"Guarantee your warranty, maintain with Cycle & Carriage."

Parts	2,348.00	Nett	6,358.00
Labour	3,820.00	7% GST on	445.06
Standard Menu	0.00		
Specialist Job	50.00		
Diagnostics Job	0.00		
Sundry/Others	140.00	Total Payable	6,803.06
Total(w/o GST)	6,358.00		

This is not an official tax invoice. This is a computer generated document, no signature is required.

Janice Lee (LKKAUTO)

From: Yusof Bin Hashim <yusof.hashim@cyclecarriage.com.sg>
Sent: Monday, March 26, 2018 1:57 PM
To: Taufikh (LKKAUTO); Admin A; Admin-D (LKKAUTO)
Cc: Loi Ai Ting; Lauro Araos Songcuan Jr; Ling Jin Hoe; Andre Chow En De
Subject: FINALIZE SLB4454U (CIT)
Attachments: SKM_454e18032613540.pdf; CIMG0396.JPG; CIMG0397.JPG; CIMG0398.JPG; CIMG0399.JPG; CIMG0400.JPG; CIMG0401.JPG

Dear Taufikh,

Please refer to attached files & photos before paint.
Kindly confirm finalized amount of \$ **6358.00** before GST.

Thank you so much.

Regards

Yusof



Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
Hp: +65 91054077 • O: 65684501 • F: +65 65651240 • www.cyclecarriage.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Aug 2017		27 Oct 2017 15:42 Edit Adj Rpt	S\$6,358.00 Edit Estimates	S\$6,358.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	TAN SWEE MENG , ID: S7282466J								
Main Claimant:	LEE CHEE SENG THOMAS , ID: S1741854H								
Vehicle Reg. No.:	SLB4454U	Date of Loss:	03/08/2017 00:00 - :59 [15 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/17-001243		Policy/Cover Note No.:	MSD/VMT/16-348522-CA Coverage: 21/08/2016 - 20/08/2017					
Vehicle Reg. No. (Insured):	FBJ6426P	Policy No. (Claimant):							
		Excess:							
Repairer:	Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ) 209 PANDAN GARDENS, 609339 West Coast - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 26/11/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLB4454U (MSC/V/17-001243)**
[FBJ6426P]

TP

LEE CHEE SENG THOMAS

Aug 3 2017 12:00AM

[TAN SWEE MENG]

Cycle & Carriage France Pte Ltd (Pandan Gardens)

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/08/17 15:15	Accident Statement From: SC - Reg. No: FBJ6426P, Claimant: TAN SWEE MENG	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/18 17:58	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/18 17:59	General View	 Load JPG	☒
2	01/02/18 17:59	General View	 Load JPG	☒
3	01/02/18 17:59	General View	 Load JPG	☒
4	01/02/18 17:59	General View	 Load JPG	☒
5	01/02/18 17:59	General View	 Load JPG	☒
6	01/02/18 17:59	General View	 Load JPG	☒
7	01/02/18 17:59	General View	 Load JPG	☒
8	01/02/18 17:59	General View	 Load JPG	☒
9	01/02/18 17:59	General View	 Load JPG	☒
10	01/02/18 17:59	General View	 Load JPG	☒
11	01/02/18 17:59	General View	 Load JPG	☒
12	01/02/18 17:59	General View	 Load JPG	☒
13	01/02/18 17:59	General View	 Load JPG	☒
14	01/02/18 17:59	General View	 Load JPG	☒
15	01/02/18 17:59	General View	 Load JPG	☒
16	01/02/18 17:59	General View	 Load JPG	☒
17	01/02/18 17:59	General View	 Load JPG	☒
18	01/02/18 17:59	General View	 Load JPG	☒
19	01/02/18 17:59	General View	 Load JPG	☒
20	01/02/18 17:59	General View	 Load JPG	☒
21	01/02/18 17:59	General View	 Load JPG	☒
22	01/02/18 17:59	General View	 Load JPG	☒
23	01/02/18 17:59	General View	 Load JPG	☒
24	01/02/18 17:59	General View	 Load JPG	☒
25	01/02/18 17:59	General View	 Load JPG	☒
26	01/02/18 17:59	General View	 Load JPG	☒
27	01/02/18 17:59	General View	 Load JPG	☒
28	01/02/18 17:59	General View	 Load JPG	☒
29	01/02/18 17:59	General View	 Load JPG	☒
30	01/02/18 17:59	General View	 Load JPG	☒
31	01/02/18 17:59	General View	 Load JPG	☒
32	01/02/18 17:59	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	01/02/18 17:59	General View	Load JPG	☒
34	01/02/18 17:59	General View	Load JPG	☒
35	01/02/18 17:59	General View	Load JPG	☒
36	01/02/18 17:59	General View	Load JPG	☒
37	01/02/18 17:59	General View	Load JPG	☒
38	01/02/18 17:59	General View	Load JPG	☒
39	01/02/18 17:59	General View	Load JPG	☒
40	11/04/18 16:50	Reinspection Photo	Load JPG	☒
41	11/04/18 16:50	Reinspection Photo	Load JPG	☒
42	11/04/18 16:50	Reinspection Photo	Load JPG	☒
43	11/04/18 16:50	Reinspection Photo	Load JPG	☒
44	11/04/18 16:50	Reinspection Photo	Load JPG	☒
45	11/04/18 16:50	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/08/17 15:26	Email from TP checking on liability	Load PDF	
2	10/08/17 15:26	Estimate & TP GIA REPORT	Load PDF	
3	10/08/17 15:26	Photo from TP 1 of 5	Load JPG	☒
4	10/08/17 15:26	Photo from TP 2 of 5	Load JPG	☒
5	10/08/17 15:26	Photo from TP 3 of 5	Load JPG	☒
6	10/08/17 15:26	Photo from TP 4 of 5	Load JPG	☒
7	10/08/17 15:26	Photo from TP 5 of 5	Load JPG	☒
8	10/08/17 15:33	Acknowledgement to TP	Load PDF	
9	14/08/17 15:10	Reserve Sheet & Policy	Load PDF	
10	25/08/17 15:15	TP SLB4454U GIA REPORT From: SC - Reg. No: FB36426P, Claimant: TAN SWEE HENG	Load PDF	
11	13/10/17 17:01	liability clearance	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17020618/T1RBQ2

Date: 12/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/16-348522-CA
Claimant Vehicle No :	SLB4454U	Insured Vehicle No :	FBJ6426P
Date of Loss:	03/08/2017	Nature of Claim:	TP
		Claim No:	MSC/V/17-001243

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB4454U		
Make & Model:	CITROEN C4 CACTUS, 1.2 PureTech 82 (A)	Engine No:	10B2150249504
Reg. Date:	08/04/2016 (Man. Year: 2016)	Chassis No:	VF70PHMZBGE510886
Colour:	White	Odometer:	28570 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,909.00	2,458.00	2,451.00	49.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,320.00	3,900.00	2,420.00	38.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,229.00	6,358.00	4,871.00	43.38
+ GST 7.00/7.00% (S\$)	786.03	445.06	340.97	43.38
Nett Amount (S\$)	12,015.03	6,803.06	5,211.97	43.38

INSPECTION

Date of Assignment:	27/10/2017	
Date Inspected:	27/10/2017 Inspected At:	Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ) 209 PANDAN GARDENS Singapore 609339
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Apr 2018)
Parts:	M1-SUV	CITROEN C4 CACTUS 1.2 PureTech 82 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB4454U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
2	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
3	1		*C&C BADGE	Necessary	40.00 FS	*40.00 FS
4	1		*REAR BUMPER	Deformed	835.00 FS	*835.00 FS
5	1		*BMPR RUBBER BOOT LH	Deformed	178.00 FS	*178.00 FS
6	1		*BUMPER SKIRT	Deformed	386.00 FS	*386.00 FS
7	1		*BMPR RUBBER BOOT RH	Not Necessary	178.00 FS	*- FS
8	1		*SET BRACKET	Not Necessary	78.00 FS	*- FS
9	1		*SET BRACKET	Not Necessary	103.00 FS	*- FS
10	1		*BUMPER BRACKET	Not Necessary	72.00 FS	*- FS
11	1		*BUMPER ABSORBER AR	Not Necessary	263.00 FS	*- FS
12	1		*LOW RR PAN FIX	Necessary	107.00 FS	*107.00 FS
13	1		*TAILGATE ASS	Repair	1,141.00 FS	*- FS
14	1		*GLASS WEDGE (12 PCS)	Necessary	12.00 FS	*10.00 FS
15	1		*TAILGATE CAP	Cut	559.00 FS	*559.00 FS
16	1		*SEAL WASHER	Necessary	50.00 FS	*50.00 FS
17	1		*TAILGATE FIX	Necessary	223.00 FS	*223.00 FS
18	4		*SENSOR	Not Necessary	524.00 FS	*- FS
19	1		*NUMBER PLATE WITH CASING	Dented	50.00 FS	*50.00 FS
Total Parts (S\$)					4,909.00	2,458.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW & RE-ALIGN RR DAMAGED PORTION:RENEW TAILGATE & RR BUMPER REPAIR RR FLOOR PNL,RR END PNL & LHR FENDER	New	3,000.00	1,800.00
2	RESPRAY RR BUMPER ,RR END PNL ,TAILGATE ,LHR FENDER &RR FLOOR PNL	New	2,100.00	1,260.00
3	REMOVE & REFIT TAILGATE COMPONENTS	New	150.00	150.00
4	REMOVE & REFIT RR FLOOR BOARD ,TRIM & CARPET TO FACILITATE REPAIR	New	200.00	200.00
5	CHECK & WIRING & ELECTRICAL SYSTEM	New	50.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	300.00	300.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	80.00
8	REMOVE & REFIT TAILGATE WINDSCREEN GLASS	New	300.00	0.00
9	RENEW REVERSE SENSOR	New	100.00	80.00
Gross Labour Cost (\$\$)			6,320.00	3,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >