

26	1	Rear Exhaust	Best		\$708.50	✓
27	1	Rear Exhaust alumimlum cover	mem		\$64.00	+
28	2	Rear Fender Inner Trim Board	delnd	\$285.00	\$570.00	✓
29	4	Rear Fender Inner Trim Board Clips	x	\$32.00	\$128.00	50
30	1	Rear windscreen moulding	mem		\$158.00	✓
31	1	Rear spare tire panel	Rpr		\$1,045.30	x
32	1	rear spare tyre top board	delnd		\$299.50	✓
33	1	Rear spare tire panel lower cover	2		\$428.00	x
34	2	Rear spare tire panel insulation	for		\$150.00	+
35	1	Rear spare tire panel sealant			\$180.00	+

Rear Bumper Lower Spoiler delnd

65658 SN 570
525264

Subtotal :- \$11,367.60

Labour charges

To Remove & refix cushion	\$150.00	60
To Remove & refix rear windscreen	\$120.00	100
Gum (SN) nec	\$50.00	✓
To Remove & refix rear exhaust	\$280.00	80
To Remove & refix reverse Sensor	\$120.00	50
Tuff kote	\$120.00	50
Towing charges	\$100.00	x
To Check Wiring System	\$80.00	30
Panel beating	\$1,200.00	80
Spray painting	\$1,200.00	80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :- \$3,420.00

Total:- \$14,787.60

15437.60

total: 7000.64
H/S: 6.2K

07 Days