(C3/AU17102V950/AHbaz ASSIGNMENT REF:

From: Date:	Veh No: SCIC6781X Yr Regn: 2017 / Apri
Estimated Cost:	Type M.Can / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To inspect Vehicle No:	Make: Audi A3 Sedan oc 999
at Workshop m/s	Colour Silve(A/C: Insured / Std / NI / NA
of	Sp.Reading /0995 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No. 2100565744	C/No: WAUZZZ8VIH1057165
Claims No. 7564837932SG	Gen. Cond: God / Fair / Poor / Burnt
Sum Insured: Excess: 4000 -	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inforder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
· · · · · · · · · · · · · · · · · · ·	Tyre Size: F: 225/45R17. R: 225/45R17.
(Policy Condition)	R: 225/45R17.
Remark: The veh had commenced its N/S C	BS / DUN / EXNOVA (GY) FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: \20K.	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bai. 06 mm L/Bal. 06 mm
Est. Repairs: 14 H days Res.: Yes or No	D.O.A. D.O.I. D2/11/7.
Lum Sum: % 3 Val.: Yes or No	Survey held at Remium.
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S) / N/S / U/C / Rooftop or
Vehicle: IN /	OUT
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction D A ()	
2(K 61/61X - x	Part by Part \$14935.44 (Red: 4721.51
	23%)
03/11- Revert via Merimen	
3/11-11:59 authorite repair	by Lows
3/14 @12:07 mform premum	authorise repair excess \$600-
	and the second s
	CENTIT I 1 2818
Date/Time. File Pass to? : Preli. Report	Days Of Repair:
1)272 TYPIST Final Report	Resurvey No. of Trip: Survey Fee: 200
Date/Time, File Return to?	Transportation:
2) Add	Fee:: Site Insp (\$)s+Rs,si
_ <i>w</i> 0	: Interview (\$) Photos
Report Format :	:Tech. Invs (\$) Others
Lump Sum / I.B): (\$ 4721 76	.Weekend (\$
	TOTAL 210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

AIG	ASIA PACIFIC IN	SURANCE PTE LTD	Ref : CC3/AIG17020	nobile 0950/Atb						
7 0 (OLIENTONIA (00.40		# 118168111978111881181818						
	SHENTON WAY # ARTIS BUILDING	08-16	Date: 02-11-2017							
	GAPORE 079120		Date . 02-11-2017							
			Code: AIG							
1.		Policy Par	ticulars :- OWN DAMAGE							
	Insured Veh.		Veh. Inspected	SCK 6781X						
	Policy No.	2100506744	Coverage (\$)	0.00						
	Claim No.		Excess (\$)	0.00						
	Assign From	· · · · · · · · · · · · · · · · · · ·	Assign Date	02/11/2017						
2.	i de	Vehicle I	Particulars & Condition							
	Make & Model		c.c	0						
	Engine No.	HIDDEN	Year of Reg.							
Chassis No.			Colour							
	Odometer	-	Steering							
	Brakes		Modification							
	General			· · · · · · · · · · · · · · · · · · ·						
3.	in the second of the second	Co	nditions of Tyres	187 Province Combined						
		Size	Make	Balance						
	R/H Front Tyre			mm						
	L/H Front Tyre			mm						
	R/H Rear Tyre			mm						
	L/H Rear Tyre			mm						
(See S		Desc	ription of Damages							
<u> </u>	The second secon	Ge.	neral Information							
<u></u>	Accident Date	27/10/2017	Inspection Date	02/11/2017						
	Survey held at	PREMIUM AUTOMOBILES		JET 116011						
		55 UBI ROAD 1 . SINGAPORE 408699								
a.:=		Complete Control	Remarks							
	A)THE MARKET V	ALUE IS S\$(EST. A	AVERAGE) S, WE HAVE AUTHORISED R							

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type Singapore NRIC

Owner ID 1169D

Vehicle Details

Vehicle No. SCK6781X

Vehicle to be Exported No

Intended De-registration Date 03 Nov 2017

Vehicle Make AUDI

Vehicle Model A3 SEDAN 1.0 TFSI S TRONIC (LED & NAV)

Primary Colour Silver

Manufacturing Year 2017

Engine No. CHZ318576

Chassis No. WAUZZZ8V1H1057165

Maximum Power Output 85.0 kW (113 bhp)

Open Market Value \$27,479.00
Original Registration Date 17 Apr 2017
First Registration Date 17 Apr 2017

Transfer Count 0

Actual ARF Paid \$20,471.00

Intended PARF Rebate Details

PARF Eligibility Yes

PARF Eligibility Expiry Date 16 Apr 2027
PARF Rebate Amount \$15,353.00

Intended COE Rebate Details

COE Expiry Date 16 Apr 2027

COE Category A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years) 10

 QP Paid
 \$52,000.00

 COE Rebate Amount
 \$49,154.00

 Total Rebate Amount
 \$64,507.00

The information contained herein is correct as at 03 Nov 2017

View Received Message

This mail is associated with:

*SCK6781X (7564837932SG)

OD
Oct 27 2017 9:30AM
[NG KOK YANG]
Premium Automobiles Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From

AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 03/11/2017 11:59 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$\$12163.00) - \$CK6781X - Claim Handler: Chan, Kian Meng

Approved:12163.00:Re-inspection require on hidden part and check item. NOTE: Before Painting photo require (Rear Right Fender) (Photo require after dismantle/remove interior trim and seat)

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Friday, 3 November, 2017 12:07 PM

To:

'Claims Dept'

Cc: Subject: SUR RE: SCK 6781 X Own Damage Claims

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SCK 6781 X (Excess \$600/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

NOTE: Before Painting photo require (Rear Right Fender) (Photo require after dismantle/remove interior trim and seat)

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>denisetay@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]

Sent: Thursday, 2 November, 2017 12:21 PM

To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg

Subject: SCK 6781 X Own Damage Claims

Dear all,

Kindly assist in the Own Damage Claim approval for the above mentioned vehicle.

Survey was carried out earlier this morning.

Many thanks!

Best regards, Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT	
Date Of Report	28/10/2017 12:55	
Date Of Accident	27/10/2017 09:30	
Exact Location Of Accident	25 WEST COAST RISE CARPARK	
Country/State of Loss	SINGAPORE	

Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SCK6781X	
Insured/Policyholder		
Name Of Registered Owner	NG KOK YANG	

NRIC No S2681169D
Email Address NKYANG@OUTLOOK.COM

Mobile Phone No (LOCAL) +65-96488761

Alternative Phone No OTHERS-96488761

Vehicle Particulars

Manufacturer AUDI

Model A3 SEDAN 1.0 TFSI 8V

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 2100506744

Cover Note Number

Driver

Name of Driver NG KOK YANG
NRIC No S2681169D
Date Of Birth 14/11/1967
Occupation INDOOR
Date Of Driving Pass 03/06/1993

Driving Experience 24 YEARS AND 4 MONTHS

Gender MALÉ

Mobile Number (LOCAL) +65-96488761

Fax Number

Contact Number OTHERS-96488761

EMail Address NKYANG@OUTLOOK.COM

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Fores must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that.

- (a) My insurer, my workshop and the General Insurance Association of Singapore ["GIA"] may/are permitted to collect, use, disclose and/or process my personal data/personal information set but in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (4) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' (awyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes, and
- Icl my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/faw firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
 - (c) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders


Policyholder's Signature Date & Time: Oriver's Signature (if driver is not the policyholder)


Oate & Time:

Reporting Centre Personner's Signature Name: \LINTIG ST

HAICHIN NO CESSON PICTO







Accident Photo




Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

(4)		NDUM	
, ,	PARTICULARS OF PERSON M		
		Vehicle Registration No:	1,454 842 X
lame(as shown in NRIC):	No roc 1416		
		Owner) (*) Please delete as app	ropriate
NRIC/Passport No :	52681690		
Address:	MASSON AND SINEAR SPACE.		
Contact (Tel) :	****	(H/P) :	1642876.
(Email) :			
	27/10/2017	Time of Accident :	98CAM
		T FIRE CAPPARE	
Insurance Company:	A		
(B) /	ADDITIONAL INFORMATION	/ AMENDMENTS: and would like to include additi	onal information or
(B) / ave made a report on the e following amendments:	ADDITIONAL INFORMATION	and would like to include additi	onal information or
(B) / ave made a report on the e following amendments:	ADDITIONAL INFORMATION above mentioned accident a	and would like to include additi	onal information or
(B) / ave made a report on the e following amendments:	ADDITIONAL INFORMATION above mentioned accident a	and would like to include additi	onal information or
(B) / ave made a report on the e following amendments:	ADDITIONAL INFORMATION above mentioned accident a	and would like to include additi	onal information or
(B) / ave made a report on the e following amendments:	ADDITIONAL INFORMATION above mentioned accident a	and would like to include additi	onal information or
(B) / ave made a report on the e following amendments:	ADDITIONAL INFORMATION above mentioned accident a	and would like to include additi	onal information or
(B) / ave made a report on the e following amendments:	ADDITIONAL INFORMATION above mentioned accident a	and would like to include additi	onal information or
(B) / ave made a report on the e following amendments:	ADDITIONAL INFORMATION above mentioned accident a	and would like to include additi	onal information or
(B) / ave made a report on the e following amendments:	ADDITIONAL INFORMATION above mentioned accident a	and would like to include additi	onal information or
(B) / ave made a report on the e following amendments:	ADDITIONAL INFORMATION above mentioned accident a	and would like to include additi	onal information or
(B) / ave made a report on the e following amendments:	ADDITIONAL INFORMATION above mentioned accident a	and would like to include additi	onal informa

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65 6224 0010 Fax : +65 6224 0030 Operating Hours : Monday to Friday 9am to 5pm



REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$2681169D





NG KOK YANG

黄 國 揚

CHINESE
Date of Brith
14-11-1967
Country of Brith
MALAYSIA



YOU ARE TRANSPORTED PARK SOURCES FOR SOURCE TO ASSESS

ASS 3 Motor Cars=< 3000kg with =<7 passengers, exclusive 03 Jun 1993 of the driver; and other motor vehicles =< 2500kg

, NP 428A

Licence No: \$2681169D

NRIC No. \$2681169D

Nationally MALAYSIAN

Blood Group Date of issue AB+ 28-04-1998

25 WEST COAST RISE #12-08 SNIGAPORE 127488

NRIC No: \$2681169D

Date: 11-11-2006

No: 5667090



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: NG KOK YANG

Period of Insurance

: 17 Apr 2017 To 16 Apr 2018

Engine No.

: CHZ318576

Chassis No.

: WAUZZZ8V1H1057165

Vehicle No.

: SCK6781X

Policy No.

: 2100506744

Endorsement No. Issued Date

: 23 Aug 2017

: 000000000133286

ABOUT THE COVER

Make/Model

: AUDI A3 Sedan 1.0 TFSI S tronic

Engine Capacity/Tonnage: 999.00 CC

Sum Insured : Market Value

First Year of Registration : 2017

: NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

Driver Restriction

b) Any other person who is driving on the Policyholder's order or with his/her permission. This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$\$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience. This additional sum does not apply if your policy is a Named Driver policy.

Age Condition

: All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act. 1987 (Malaysia), are not to be included under these headings.

EXCESS

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

NG KOK YANG - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1.Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

No.201009404M | Copyright © 2016 AIG Asia Pacific |

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

SSCSAN

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/OD/1064/2017/JT

Date : 30-0ct-17

Vehicle Not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Ng Kok Yang

Address : 25 West Coast Rise

#12-06

Singapore 127468

Telephone : HP +65 9648 8761

Type of Claim : Own Damage Claims

Policy No. : 2100506744

Vehicle No : SCK 6781 X

Model Code : Audi A3 Sedan 1.0 TFSI S-tronic

Model / Year : Apr-17
Engine No : CHZ 318576

Chassis No : WAUZZZ8V1H1057165

Mileage : Date In : Liability : Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 27-Oct-17

Place of Accident : 25 West Coast Rise Carpark

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCK 6781 X.

S/N	Nature of Jobs		 Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N	\$ 280.00	
2	To renew RHS 1/4 glass and rear windscreen to facillitate fender renewal.	S/N	\$ 600.00	
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00	
4	To remove and transfer rhs rear door's multi lock system and power window devices.	S/N	\$ 280.00	
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belt. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,400.00	
	SUBTOTAL LABOUR CHARGES	:	\$ 3,960.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 6781 X.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
6	To dismantle rear bumper and rear lid. Cut out and weld RHS rear fender. Renew rear bumper. Re-organise rear crash management components. Reinstall all removed.		\$ 4,200.00	3000
7	To respray RHS rear door, RHS rear fender, roof channel, RHS rear drain panel, RHS rear entrance, RHS sill panel, and RHS front door.		\$ 4,000,60	2200. 7500
8	To carry out diagnostic check.	S/N	\$ 192.00	(82
	TOTAL LABOUR CHARGES	:	\$ 12,352.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCK 6781 X.

			Damaged Parts & Prices
S/N	Parts Description		 S/Nett Remark
1	REAR DOOR - RHS Pidocte A		\$ 2,079.00 - 1663 20
2	REAR DOOR OUTER SEAL - RHS		\$ 129.00 / [02.30]
3	BONDING AGENT - RHS HAR NUL.		\$ 42.00 ? 7
4	CLEANING SOLUTION THE NIC.		\$ 63.00 ?
5	REAR DOOR CATCH - RHS		\$ 79.00 ×
6	REAR FENDER - RHS Distorted		\$ 1,938.00 - 1550 40
7	REAR QUARTER CHROME GLASS - RHS		\$ 379.00
8	REAR QUARTER GLASS - RHS		\$ 455.00 - 363.W
9	PRIMER Nu-	2	\$ 36.00 - 22KH
10	REAR WINDSCREEN M		\$ 675.00 - 54U
11	ACRYLIC SEALER	S/N	\$ 180.00 / 120
12	CAVITY WAX	S/N	\$ 140.00 - hujo
13	STONE CHIP	S/N	\$ 180.00 ~ (元)
14	REAR WINDSCREEN SEALET Z	S/N	\$ 200.00 - 700
15	REAR QUARTER GLASS SEALENT	S/N	\$ رنن 🗸 100.00
16	METAL FILLER 🔑	S/N	\$ 280.00 < ১৭৩
17	SUNDRIES Ne		\$ 400.00 ? A.®
	TOTAL SPARE PARTS CHARGES	:	\$ 7,355.00
	TOTAL LABOUR CHARGES		\$ 12,352.00
	GRAND TOTAL		\$ 19,707.00

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

Please Note

 Third party survey is on a "Nutricut Prejudice" basis No illegal modification(s) is allowed. Supplementary item sumust be resurveyed and is subject to finar approval from Insurance Company

LKK Auto Consultants hence notify the Repairer of the following:

• To display damaged partisy during resurvey Parts prices are literal to confirm ation.

To resurvey before after spray no nting

Acknowledged by Repairer

Signature: Date:

and Anthonsed, 14 Pays.

This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully.

Premium Automobiles Pte Ltd

Johnny Boo **Body Repair Manager** Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/OD/1064/2017/JT

Date : 30-Oct-17

Vehicle Not iN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Ng Kok Yang
Address : 25 West Coast Rise

#12-06

Singapore 127468

Telephone : HP +65 9648 8761

Type of Claim : Own Damage Claims

Policy No. : 2100506744

Vehicle No : SCK 6781 X

Model Code : Audi A3 Sedan 1.0 TFSI S-tronic

Model / Year : Apr-17
Engine No : CHZ 318576

Chassis No : WAUZZZ8V1H1057165

Mileage : Date In : Liability : Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 27-Oct-17

Place of Accident : 25 West Coast Rise Carpark

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCK 6781 X.

S/N	Nature of Jobs			Estimated Charges	Surveyor's Recommendation		
1	To remove and transfer rear parking aid. Check function.	S/N	\$	280.00	\$	280.00	
2	To renew RHS 1/4 glass and rear windscreen to facillitate fender renewal.	S/N	\$	600.00	\$	600.00	
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$	1,400.00	\$	1,400.00	
4	To remove and transfer rhs rear door's multi lock system and power window devices.	S/N	\$	280.00	\$	280.00	
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belt. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$	1,400.00	\$	1,400.00	
	SUBTOTAL LABOUR CHARGES	:	\$	3,960.00	\$	3,960.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 6781 X.

S/N	Nature of Jobs			Estimated Charges		urveyor's mmendation
3/14	C/F				\$	3,960.00
6	To dismantle rear bumper and rear lid. Cut out and weld RHS rear fender. Renew rear bumper. Reorganise rear crash management components. Reinstall all removed.		\$	4,200.00	\$	3,000.00
7	To respray RHS rear door, RHS rear fender, roof channel, RHS rear drain panel, RHS rear entrance, RHS sill panel, and RHS front door.		\$	4,000.00	\$	2,500.00
	(With roof channel, drain channel, door entrance)	C/N	\$	192.00	\$	192.00
8	To carry out diagnostic check.	S/N	→	192.00	<u>→</u>	192.00
	TOTAL LABOUR CHARGES	:	\$	12,352.00	\$	9,652.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCK 6781 X.

S/N	Parts Description		Damaged Pa		<u>Prices</u> Remark
3/11	Tarta Dodonphon			-	
1	REAR DOOR - RHS		\$ 2,079.00	\$	1,663.20
2	REAR DOOR OUTER SEAL - RHS		\$ 129.00	\$	102.80
3	BONDING AGENT - RHS		\$ 42.00		
4	CLEANING SOLUTION		\$ 63.00		
5	REAR DOOR CATCH - RHS		\$ 79.00		
6	REAR FENDER - RHS		\$ 1,938.00	\$	1,550.40
7	REAR QUARTER CHROME GLASS - RHS		\$ 379.00		
8	REAR QUARTER GLASS - RHS		\$ 455.00	\$	363.60
9	PRIMER	2	\$ 36.00	\$	28.64
10	REAR WINDSCREEN		\$ 675.00	\$	540.00
11	ACRYLIC SEALER	S/N	\$ 180.00	\$	180.00
12	CAVITY WAX	S/N	\$ 140.00	\$	140.00
13	STONE CHIP	S/N	\$ 180.00	\$	180.00
14	REAR WINDSCREEN SEALET	S/N	\$ 200.00	\$	200.00
15	REAR QUARTER GLASS SEALENT	S/N	\$ 100.00	\$	100.00
16	METAL FILLER	S/N	\$ 280.00	\$	280.00
17	SUNDRIES		\$ 400.00	\$	4.80
	TOTAL SPARE PARTS CHARGES	:	\$ 7,355.00	\$	5,333.44
	TOTAL LABOUR CHARGES		\$ 12,352.00	\$	9,652.00
	GRAND TOTAL		\$ 19,707.00	\$	14,985.44

MDR7Y

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Liability

Name :
Surveyed Date :
Authorised Date :
Excess Cost :

Remarks :

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept

Yr Ref: SCK 6781 X

6841 1183 Nora.khai@premiumauto.com.sg Body & Paint Dept PA/OD/1064/2017/MAS

Telephone +65-Telefax **E**Mail Our department Our Ref Your Ref

from

Date

22 Feb 2018

Norah Khai

6768 9911

Dear Sir,

RE: INSURANCE CLAIM FOR SCK 6781 X, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no SCK 6781 X, claimant, Mr. Ng Kok Yang, please find the related document per attached.

- 1. A copy of the Original invoice no. 85012158 S\$15,392.42
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai

Claims Dept

Encls

AIG - SCK 6781 X

total pages

Premium Automobiles Pte Ltc Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 (65) 6471 3733 Telefax

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore 281_Alexandra Road Singapore 159938 Main Telephone 6836 2223 Alexandra Service Centre 281 Alexandra Road Singapore 159938

Ubi Service Centre 55 Ubi Road 1

Service Appointment INS STOPPX 4086 NVOICE hour Breakdown Service

9828 1233 customer.care@premiumauto.com.sg

Main Telefax 6471 3733 Page 14:57 Telephone 6388 2223 Telefax 6475 1023

Company TREATON NG 3881 23902271W Email GST Reg. No. 199902271W

Invoice: 65012158

Order: SCK6781X

Account: A0006

(T 0) AIG ASIA PACIFIC INSURANCE PTE LTD

6366 2323

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT AIG BUILDING

78 SHENTON WAY

Date

: 20/02/2018

MOTOR CLAIM DEPT

AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

#07-16

SINGAPORE 079120 079120

Term : 30

Regn No.: SCK6781X

33230)

Regn Date: 17/04/2017

Mileage: 12173

WIP No.: 42491

Model: A3 SEDAN 1.0 TFSI 8VMANG (NAV,

Chassis: WAUZZZ8V1H1057165

Engine: CHZ 318576

Dept: U

VSB No.:

You have been assisted by :- UB-Carrine

(33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M:	280.00	1.00	280.00
		TO REMOVE AND TRANSFER REAR PARKING AID. CHECK			
		FUNCTION.			
Q	EXC	M: 8888	-686.06	1.00	-600.00
		Insurance Excess/Liability			
S	BODYWORK	M:	600.00	1.00	600.00
		to renew RHS 1/4 Glass and rear Windscreen to			
		FACILITATE FENDER RENEWAL.			
S	BODYWORK	M;	1400.00	1.00	1,400.00
		to dislodge and reinstall rear wire harness for			
		LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS,			
		ELECTRICAL AND AUDIO EQUIPMENT.			
S	Bodywork	M:	280.00	1.00	280.00
		TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI LOCK			
		SYSTEM AND POWER WINDOW DEVICES.			
S	Bodywork	M:	1400.00	1.00	1,400.00
		TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT			
		TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS			

Sub-Total

7% GST

Grand Total

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore 281 Alexandra Road Singapore 159938 Main Telephone 6836 2223 Alexandra Service Centre 281 Alexandra Road Singapore 159938 Telephone 6388 2223

Ubi Service Centre 55 Ubi Road 1

Service Appointment

INS SITTEM X 4086 19 N V O I C Ethour Breakdown Service

6366 2323 9828 1233 customer.care@premiumauto.com.sg

6471 3733 Main Telefax Page 2 14:57

MOTOR CLAIM DEPT

AIG BUILDING

#07-16

78 SHENTON WAY

Company Temporal 63881333902271W Email Telefax 6475 1023 GST Reg. No. 199902271W

Invoice: 85012158

Order : SCK6781X

: 30

Date

Term

Account: A0006

0) (T

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT

AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

Regn No.: SCX6781X

SINGAPORE 079120 079120

33230)

Regn Date: 17/04/2017

Mileage: 12173

WIP No.: 42491

Model: A3 SEDAN 1.0 TFSI BYMANG (NAV.

AIG ASIA PACIFIC INSURANCE PTE LTD

Chassis: WAUZZZ8V1H1057165

20/02/2018

Engine: CHZ 318576

Dept: U

VSB No.:

You have been assisted by :- UB-Carrine

(33)

		Details	Qty	Unit Price	Amount
		AND SEAT BELT, DISLODGE ROOF LINER AND DISENGAGE			
		CURTAIN AIRBAG ETC.			
i	BODYWORK	M:	3000.00	1.00	3,000.00
		TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AN	D		
		WELD RHS REAR FENDER. RENEW RHS REAR DOOR.			
		RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.			
		REINSTALL ALL PARTS REMOVED.			
ì	Bodywork	M:	2500.00	1.00	2,500.00
		TO RESPRAY RHS BOTH DOOR, RHS REAR FENDER, ROOF			
		CHANNEL AND RHS SILL PANEL.			
ì	BODYWORK	M:	192.00	1.00	192.00
		TO CARRY OUT DIAGNOSTIC CHECK.			
;	BODYWORK	M:	1080.00	1.00	1,080.00
		TO SUPPLY ACRYLIC SEALANT, CAVITY WAX, STONE CHIP.	.		
		REAR WINDSCREEN GLASS SEALANT, REAR QUARTER GLASS	•		
		SEALANT AND METAL FILLER.			
	A8V58 0 9838	SUBPART Less 920%	1.00	1938.00	1,550.40
	A8V5845298K NVB	SIDE WINDO Less 020%	1.00	454.50	363.60

Sub-Total

7% GST

Grand Total

Customer

Premium Automobiles Pte Ltd



Audi Centre Singapore 281 Alexandra Road Singapore 159938 Main Telephone 6836 2223

Alexandra Service Centre 281 Alexandra Road Singapore 159938 Telephone 6388 2223

33230)

Ubi Service Centre 55 Ubi Road 1

Service Appointment INS Sing Park 4086 19NUOICE hour Breakdown Service

9828 1233 customer.care@premiumauto.com.sq

6365 2323

0)

Main Telefax 6471 3733 14:57 Page 3

MOTOR CLAIM DEPT

AIG BUILDING

#07-16

78 SHENTON WAY

Company Telephone 6388 223902271W Email Telefax 6475 1023 GST Reg. No. 199902271W

Date

Term

Invoice: 85012158

: 20/02/2018

Order : SCK6781X

: 30

Account: A0006 (T

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT

AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

SINGAPORE 079120 079120

Regn No.: SCK6781X

Regn Date: 17/04/2017

Mileage: 12173

WIP No.: 42491

Model: A3 SEDAN 1.0 TFSI 8VMANG (NAV.

AIG ASIA PACIFIC INSURANCE PTE LTD

Chassis: WAUZZZ8V1H1057165

Engine: CHZ 318576

Dept: U

VSB No.:

You have been assisted by :- UB-Carrine

(33)

		Details	Qty	Unit Price	Amount
X A8V5845501E NVB X A8V5833052A X A8K0837199 X AD 00920002 X A8V5839912C	REARWINDOW DOOR CLIP PRIMER (DG) SEAL	Less 020% Less 020% Less 020% Less 020%	1.00 1.00 6.00 2.00 1.00	675.00 2079.00 1.00 17.90 128.50	540.00 1,663.20 4.80 28.64 102.80

Parts 4, 253, 44 Labour 0.00 Sublet 10,732,00 0.00 Menus Lubricant 0.00

Sub-Total

14, 385, 44

7% GST

1,006.38

Grand Total

15, 392, 42

Received by

For & on behalf of Premium Automobiles Pte Ltd

Telefax

to
AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Motor Claims Dept Yr Ref: SCK6781X Norah Khai 6768 9828 6841 1183

Telephone +65-Telefax +65-Mobile +65-Our department Your Claim Ref Our Ref Date

from

i Building 079120 ims Dept

Body Repair PA/OD/1064/2017/TF 7 Dec 2017

total pages

Showroom

Telefax

Telefax

9 Leng Kee Road

Singapore 159090 Telephone (65) 6566 1111

55 Ubi Road 1

Singapore 408699 Telephone (65) 6366 2323

Service & Parts Centres

Premium Automobiles Pte Ltd

(65) 6471 3733

(65) 6841 1183

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model

Audi A3 SEDAN 1.0 TFS

Vehicle Chassis No.

WAUZZZ8V1H1057165

Vehicle Regn No.

SCK6781X

Vehicle Mileage

12173 KM

Vehicle Owner

Mr. Ng Kok Yang

Certificate No

2100506744

Policy Excess

\$642.00 (Inclusive GST)

Accident Date

27 October 2017

Place

25 West Coast Rise Carpark

Repair Cost

\$ 15,392 42

WIP No.

: 42491

:

:

Repairer's Name

Premium Automobiles Pte Ltd

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.


Owner / Insured Signature


Time

:

Date

17:45 NT







NG KOK YANG

CHINESE Date of Birth 14-11-1967 Country of Birth MALAYSIA

EFFECTIVE DATE Motor Cars=< 3000kg with =<7 passengers, exclusive 03 Jun 1993 of the driver; and other motor vehicles =< 2500kg

. YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Licence No: S2681169D

NRC No. S2681169D



MALAYSIAN

Blood Group Date of issue 28-04-1998

25 WEST COAST RISE #12-06 SINGAPORE 127468

NRIC No: \$2681169D

Date: 11-11-2006 No: 5667090

NP 428A



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: NG KOK YANG

Period of Insurance

: 17 Apr 2017 To 16 Apr 2018

Engine No.

: CHZ318576

Chassis No.

: WAUZZZ8V1H1057165

Vehicle No.

: SCK6781X

Policy No.

: 2100506744

Endorsement No. **Issued Date**

: 00000000133286 : 23 Aug 2017

ABOUT THE COVER

Make/Model

: AUDI A3 Sedan 1.0 TFSI S tronic

Engine Capacity/Tonnage: 999.00 CC

Sum Insured : Market Value

First Year of Registration : 2017

Driver Restriction

: NA

Off Peak Car: No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission. This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$\$3.000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience. This additional sum does not apply if your policy is a Named Driver policy.

Age Condition

: All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving furtion, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Lise

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

NG KOK YANG - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1.Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hottine at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AiG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

SSCSAN

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Submitted	Ins Auth'ed	Status
Main	02 Nov 2017		02 Nov 2017 13:33 Edit Adj Rpt	S\$14,9		S\$14,985.44 View Rpt		Pending for Survey Report
	Main	Refere	nce	Claim	Details		ocuments	Show All
CLAIM SU	JBFOLDER DETA	AILS					[Created by in	surer]
Insured:		NG KOK YAN	G , ID: S268116	59D, Tel: -	65964887	61, Email: NKY	ANG@OUTLOOK.CO	MC
Vehicle Reg	g. No.:	SCK6781X		Dat	e of Loss:		27/10/2017 09:0	00 - :59
Claim Type	::	OD / 75648	37932SG	Poli	cy/Cover N	ote No.;	2100506744 (Comprehens	
				Exc	ess:		S\$600.00	
Repairer:		Premium Au	tomobiles Pte L	td (UBI) 5	Ubi Road	1, 408699 Ubi -	Tel: 67689828/982	27/9911
Handling I	nsurer:	AIG Asia Pac kianmeng.cha		Pte. Ltd. (S	G) - Tel: 65	5-6419-3000	[Handled by Chan,	, Kian Meng}
Adjuster:		LKK Auto Co due 13/11/2		td (HQ) - Te	l: 6256-35	61 [Handled I	y ADRIAN LING]	[Final Rpt
Driver/Cus	todian:	NG KOK YANG	(49 / Male), N	RIC: S2681	169D, Tel	l: +6596488761		
ASSOCIA	TED MAIL RECE	IVED					View All	Compose Case Mai
AIG_SG AIG_SG AIG_SG	(29/01/2018): A (03/11/2017): A	lert - Adj Manda lert - Adj Manda CK6781X / OD /	te Maintained - te Approved (S:	SCK6781X \$12163.00	- Claim Ha) - SCK678 & Excess u	andler: Chan, k BIX - Claim Har update	idler: Chan, Klan Jan Meng Idler: Chan, Klan In Tasks Create N	
Due Date No results.		ype Task Grou	ıp Su bject	Handler	Assigne	ed By Com	oleted On Cr	eated On Done

Claim Documents

*SCK6781X (7564837932SG) OD Oct 27 2017 9:30AM [NG KOK YANG] **Premium Automobiles Pte Ltd**

. Upl					
	essment Reports		1 pe	rpage ▼	2
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/11/17 11:33	Adjuster Immediate Advice	0	Load HTM	
Pho	tos/Images		3 pe	rpage ▼	2
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/11/17 11:34	General View	0	Load JPG	❷
2	03/11/17 11:34	General View	0	Load JPG	2
3	03/11/17 11:34	General View	0	Load JPG	2
4	03/11/17 11:34	General View	0	Load JPG	Ø
5	03/11/17 11:34	General View	0	Load JPG	2
6	03/11/17 11:34	General View	•	Load JPG	☑
7	03/11/17 11:34	General View	0	Load JPG	2
8	03/11/17 11:34	General View	0	Load JPG	2
9	03/11/17 11:34	General View	0	Load JPG	Ø
10	03/11/17 11:34	General View	0	Load JPG	
11	03/11/17 11:34	General View	Ð	Load JPG	€
12	03/11/17 11:34	General View	0	Load JPG	Ø
13	03/11/17 11:34	General View	0	Load JPG	2
14	03/11/17 11:34	General View	0	Load JPG	2
15	03/11/17 11:34	General View	0	Load JPG	Ø
Doc	umentation		1 pe	rpage ▼	2
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/11/17 11:36	Singapore Accident Statement	0	Load PDF	
2	03/11/17 11:36	WORKSHOP ESTIAMTE	0	Load PDF	
3	03/11/17 11:36	Drivers Driving License	0	Load PDF	<u> </u>
4	03/11/17 11:36	Certificate of Insurance	0	Load PDF	
5	30/01/18 09:30	estimate	Ð	Load PDF	. <u> </u>

Linked Accident Report Documents

			•	/iew View in B	rowser ▼
Ass	essment Report	s	1 pe	1 per page ▼	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/10/17 13:18	Accident Statement	0	Load HTM	
2	28/10/17 13:26	Addendum Sheet	0	Load JPG	2
3	28/10/17 13:27	Accident Statement Addm. #1	Ð	Load HTM	
Pho	otos/Images		3 pe	erpage ▼	

			•	☑
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/10/17 13:05	Accident Photo	1 Load JPG	Ø
2	28/10/17 13:05	Accident Photo	1 Load JPG	2
3	28/10/17 13:05	Accident Photo	1 Load JPG	2
4	28/10/17 13:05	Accident Photo	1 Load JPG	Ø
5	28/10/17 13:05	Accident Photo	1 Load JPG	2
6	28/10/17 13:05	Accident Photo	1 Load JPG	2
7	28/10/17 13:05	Accident Photo	1 Load JPG	Ø
Doc	cumentation		1 per page ▼	2
Νo	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/10/17 13:02	Sketch Plan	1 Load JPG	2
2	28/10/17 13:02	Sketch Plan #2	1 Load JPG	2

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
	,	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way #07-16

Our File No:

CC3/AIG17020950/ATBE2

Singapore 079120

Date:

27/02/2018

REFERENCE

Insured/Claimant: NG KOK YANG Policy No:

2100506744

Date of Loss:

27/10/2017

Nature of Claim:

OD

Claim No:

7564837932SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SCK6781X

Make & Model:

AUDI A3, 999cc TFSI (A)

Engine No:

CHZ318576

Reg. Date:

17/04/2017 (Man. Year: 2017) Silver

Chassis No: Odometer:

WAUZZZ8V1H1057165 10995 km

Colour: **Engine Capacity:**

999 cc

Market Value/New Car Price:

S\$120,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Front Right Side: Goodyear 6 mm Goodyear 6 mm Rear Left Side: Rear Right Side: Goodyear 6 mm Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,355.00	5,333.44	2,021.56	27.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,352.00	9,652.00	2,700.00	21.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,707.00	14,985.44	4,721.56	23.96
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	19,107.00	14,385.44	4,721.56	24.71
+ GST 7.00/7.00% (S\$)	1,337.49	1,006.98	330.51	24.71
Nett Amount (S\$)	20,444.49	15,392.42	5,052.07	24.71

INSPECTION

Date of Assignment:

02/11/2017

Premium Automobiles Pte Ltd (HQ)

Date Inspected:

02/11/2017

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

14.0 days

Adjuster:

ADRIAN LING

Manager:

DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Inspected At:

REPAIR DETAILS

R	eco	mr	ner	ded	4 P	arts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - RHS	Distorted	2,079.00 FS	*1,663.20 FS
2	1		*REAR DOOR OUTER SEAL - RHS	Necessary	129.00 FS	*102.80 FS
3	1		*BONDING AGENT - RHS	Not Necessary	42.00 FS	*-FS
4	1		*CLEANING SOLUTION	Not Necessary	63.00 FS	*-FS
5	1		*REAR DOOR CATCH - RHS	Not Necessary	79.00 FS	*-FS
6	1		*REAR FENDER - RH\$	Distorted	1,938.00 FS	*1,550.40 FS
7	1		*REAR QUARTER CHROME GLASS - RHS	Not Necessary	379.00 FS	*-FS
8	1		*REAR QUARTER GLASS - RHS	Necessary	455.00 FS	*363.60 FS
9	2		*PRIMER	Necessary	36.00 FS	*28.64 FS
10	1		*REAR WINDSCREEN	Necessary	675.00 FS	*540.00 FS
11	1		*ACRYLIC SEALER	Necessary	180.00 FS	*180.00 FS
12	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
13	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
14	1		*REAR WINDSCREEN SEALET	Necessary	200.00 FS	*200.00 FS
15	1		*REAR QUARTER GLASS SEALENT	Necessary	100.00 FS	*100.00 FS
16	1		*METAL FILLER	Necessary	280.00 FS	*280.00 FS
17	1		*SUNDRIES	Necessary	400.00 FS	*4.80 FS
F≃Fra	nchise (part, S=SpcNe	ett.	-		
				Total Parts (S\$)	7,355.00	5,333.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Amoun	Repairer's	.ab.Type	Particulars I	io
	·		our Items	ab.
280.00	280.00	New	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	
600.00	600.00	New	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	
1,400.00	1,400.00	New	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	ŀ
280.00	280.00	New	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES	
1,400.00	1,400.00	New	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELT. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	
3,000.00	4,200.00	New	TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND WELD RHS REAR FENDER. RENEW REAR BUMPER. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL REMOVED	
2,500.00	4,000.00	New	TO RESPRAY RHS REAR DOOR, RHS REAR FENDER, ROOF CHANNEL, RHS REAR DRAIN PANEL, RHS REAR ENTRANCE, RHS SILL PANEL, AND RHS FRONT DOOR	
192.00	192.00	New	TO CARRY OUT DIAGNOSTIC CHECK	
9,652.00	12,352.00		Gross Labour C	

Report was unsubmitted during this print-out.